# **OCEANLINK LOGISTICS**

## **INCIDENT REPORT**

Confidential Internal Use Only

Incident ID	IR-1007	Vessel ID	VSL-101
Date	25/10/2025	Port	Belawan
Reported By	Chief Eng. R. Hartono	Weather	Sunny

#### Summary

Maintenance team dispatched upon arrival for urgent inspection. Fuel consumption exceeded expected range due to storm resistance. Incident occurred during Sunny conditions en route to Belawan.

#### **Impact**

Fuel consumption exceeded expected range due to storm resistance.

#### Action Taken

Maintenance team dispatched upon arrival for urgent inspection.

### Recommendation

Schedule hull inspections post-storm to assess structural integrity.

Report generated by OceanLink Logistics Internal Safety Department