OCEANLINK LOGISTICS

INCIDENT REPORT

Confidential Internal Use Only

Incident ID	IR-1019	Vessel ID	VSL-103
Date	22/10/2025	Port	Belawan
Reported By	Capt. M. Prasetyo	Weather	High Wind

Summary

Cargo container re-secured mid-voyage after vibration alert. Estimated delay of 8 hours due to rerouting and low visibility. Incident occurred during High Wind conditions en route to Belawan.

Impact

Estimated delay of 8 hours due to rerouting and low visibility.

Action Taken

Cargo container re-secured mid-voyage after vibration alert.

Recommendation

Install advanced radar calibration system to mitigate heavy weather distortion.

Report generated by OceanLink Logistics Internal Safety Department