# **OCEANLINK LOGISTICS**

## **INCIDENT REPORT**

Confidential Internal Use Only

Incident ID	IR-1016	Vessel ID	VSL-102
Date	21/10/2025	Port	Belawan
Reported By	Chief Eng. R. Hartono	Weather	Storm

#### Summary

Crew switched to manual navigation due to radar interference. Minor cargo damage reported; inspection required at destination. Incident occurred during Storm conditions en route to Belawan.

### Impact

Minor cargo damage reported; inspection required at destination.

#### Action Taken

Crew switched to manual navigation due to radar interference.

#### Recommendation

Upgrade cooling system components to prevent overheating.

Report generated by OceanLink Logistics Internal Safety Department