## Post Experimental Quiz: Experiment 3

- 1. What care may be taken to improve the accuracy of measurement of  $\lambda_a$  and  $\lambda_g$ ?
- 2. Can one utilize maxima values instead of minima values of the standing wave pattern?
- 3. Can one use a plane dielectric sheet in place of the metal sheet?
- 4. List some source of error which may cause a discrepancy between the estimated and measured value of a, the broad dimension of the waveguide.