Test Introduction

Test Cases for Drive

No.	Test cases
1	5G FTP and Speedtest DL/UL,Ping,Attach and Deattach,Web Broswing,Voice Call,Idle Mode


Test UE

Test Software	Huawei PHU,Assistant
Test Device	Huawei Mate30 Pro


Test Case Introduction

No.	Туре	Content		
1	DT FTP/ST Speedtest Download Test	File size is at lease 10GB		
2	DT FTP/ST Speedtest Download Test	File size is at lease 10GB		
3	ST Ping Test	Confirm Ping test to the local sever succeed in 5 times		
4	ST Attach and Deattach Test	Confirm attach and deattach succeed in 5 times		
5	ST Web Broswing Test	Confirm web browsing succeed in 5 times		
6	ST VoLTE Short Call	Succeed in 5 time		
7	Idle Mode Test	Auto mode		

Sheet	Section	Parameter	Remark	Feedback	
Silect Section		Turumeter	Remark	i ceuback	
	Site Information	All		Okay	
SSV Checklist	Site Location on Map	Location		Okay	
Report	Parameter Verification	All		Okay	
	Throughput Verification (Static Test)	Sector 3 Parameters		Okay	
	PCI Distribution	NR PCI MAP	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	FCI Distribution	LTE PCI MAP	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	Static Speed Test Result Distribution	Sector 3 Test Location		Okay	
	Static Speed Test Nesdit Distribution	Sector 3 Throughput		Okay	
	DT SSB Result Distribution	SSB Average RSRP	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Average RSRP Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Average SINR	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Average SINR Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	DT MCS Distribution	DL Average MCS	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		DL Average MCS Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		UL Average MCS	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		UL Average MCS Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	DT BLER Distribution	DL Initial BLER	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		DL Initial BLER Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		UL Initial BLER	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		UL Initial BLER Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	DT Rank Distribution	DL Average RANK	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
SV Test Result		DL Average RANK Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		UL Average RANK	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		UL Average RANK Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	DT MAC Throughput Distribution	NR DL MAC Throughput	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		NR DL MAC Throughput Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	- · · · · · · · · · · · · · · · · · · ·	NR UL MAC Throughput	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		NR UL MAC Throughput Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	Idle Plot	SSB Average RSRP	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Average RSRP Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Average SINR	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Average SINR Chart	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
	Event on Map	NRScellAdd Event	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		NRScellAbnormalRelease	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		NRScellChange Event	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		Normal Release	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		4G Handover Event	Not enough DT routes in serving sector 3 direction.	Re-DT Required	
		SSB Distribution	Not enough DT routes in serving sector 3 direction to identify SSB distribution.	Re-DT Required	
Speed test esult and Ping	Sector 2	Speedtest Result		Okay	
T Attach and Deattach Test	Sector 2	Attach & Detach Results	Check Attach Detach Average Delay and improve	Optimization Required	
Voice Call_VoLTE	Sector 2	Voice Call Parameters	Check Call setup Average Delay. Check for both MOC and MTC scenarios.	Optimization Required	
Ittp Broswing	Sector 2	Browing Parameters		Okay	




Verification Conclusion	
SSV Result	Pass
Detail Item	Pass or not
DT FTP/ST Speedtest Download Test	Pass
DT FTP/ST Speedtest Download Test	Pass
ST Ping Test Funtion Test	Pass
ST Attach and Deattach Test	Pass
ST Web Broswing Funtion Test	Pass
ST VoLTE	Pass
Idle Mode Test	Pass
4G to 5G NrScell ADD	Pass
5G to 4G SCG Normal Relese	Pass
NR Intra-RAT Handover Funtion Test(NrScellChange event)	Pass



Item	Planning Data	Actual Configured	Pass or Not
Longitude	79.866002	79.866002	Pass
Latitude	6.908507	6.908507	Pass
PCI	42/43/44	44	Pass (only 1 Sector commission)

Test Engineer Name	Contact Phone	Test Date
Yashan Kalhara	768211714	6/16/2022



Main KPI on Map

			Static Speed Test	Result Distribution			
Sector 1 Test Location		Sector 1 Throug		Sector 2 Test Location		Sector 2 Throug	hput
	Sample	DL (Mbps)	UL (Mbps)		Sample	DL (Mbps)	UL (Mbps)
	1				1		
	2				2		
	3				3		
	4				4		
	5		1		5		
	Average	#DIV/0!	#DIV/0!		Average		
Sector 3 Test Location	Sector 3 Test Location Sector		Sector 3 Throughput Sector 4 Test Location		Sector 4 Throughput		
© 12-00 (20 mo 112-0)	Sample	DL (Mbps)	UL (Mbps)		Sample	DL (Mbps)	UL (Mbps)
Control State Control	1	1204	63.3		1		
HHRAU B	2	1364	83.4		2		
or Clab	3	1430	73.2		3		
N SOUTH STO SOUTH STORY OUT	4	1438	70.6		4		
TEST (TIDN Helectron street SELLS Many floring Cells C Del Line C	5	1113	77.6		5		
NI .	Average	1309.8	73.62		Average		

