INPUT: DC Motor

```
1 = #include <pl8f4550.h>
 2
   finclude<xc.h>
     unsigned char count = 0;
     bit TIMER, SPEED UP;
 4
 5
 6
    void timer2Init(void)
7 - {
 8
         T2CON=0b00000010;
9
         PR2 = 0x95;
   L }
10
11
     void delay (unsigned int time)
12 - {
13
         unsigned int i,j;
14
          for(i=0;i<time;i++);</pre>
15
             for(j=0;j<1000;j++);
16
18 - void main(void) {
19
20
         unsigned int i;
21
         TRISCbits.TRISC1=0;
22
         TRISCbits.TRISC2=0;
23
         LATCbits.LATC1=0;
24
         CCP1CON =0b00111100;
25
26
         CCPR1L=0x0F;
27
         timer2Init();
28
         TMR2ON=1;
29
30
          while(1)
31
32
              for(i=15;i<150;i++)
33
34
                  CCPR1L=i;
35
                  delay(100);
36
37
              for(i=150;i>15;i--)
38
39
                  CCPR1L=i;
40
                  delay(100);
41
42
43
44
```