

Assignment – Lecture 67

1.

An 8 pole lap connected armature has 40 slots with 12 conductors per slot , and generates a voltage of 200V. Determine the useful flux per pole if the generator is running at 1250 rpm.

PES University