


Liquid Leak Detection – Puddle – Axis ACAP

Camera Requirements:


- Axis Hardware Platform: ARTPEC-8 SoCs only
- Axis Firmware: Axis OS 11 Only

Setup:


1. On the Axis Camera with ARTPEC-8 SOC go to the "Apps" Tab



2. Make sure both "Allow unassigned apps" and "Allow root-privileged app" are enabled



3. Press the "Add App" button and drag in or select .eap App file to install app.



- 4. Wait for app installation to complete (It usually takes a bit, >2min)
- 5. Once the install is complete, enable the LLD App
- 6. Wait for the app to fully stary, then press the yellow "Open" button to open the Web UI for the LLD App




7. LLD Axis ACAP Web UI



Licensing:

For app licensing, please send "Device BLOB" to support@visionaery.com

The Device BLOP can be found on the LLD ACAP App web UI unfer the "License" Tab



Events/Alarms and Telemetry Data

Type:	Data Description	
Events/Alarms:	Message sent when detection meets or exceeds the user set thesholds for each event	
Telemetry:	Message sent at user specified time interval	

Events/Alarms

Event	Description
puddle_detected	Sent when puddle area is above set threshold

There are 3 pathways in which the LLD ACAP App can send out events or telemetry data

- 1. Device Event on Axis Camera using its VMS Integration
- 2. MQTT using Axis Cameras MQTT Connection to Broker
- 3. MQTT directly from the LLD to Broker

LLD MQTT Topics:

Event Pathway	Event/Telemetry	Default MQTT Topic
From Axis MQTT	Event	$axis/MAC_ID/event/tns: axis/Camera Application Platform/Liquid Leak Monitor/Puddle_Detected$
From Axis MQTT	Telemetry	axis/MAC_ID/event/tns:axis/CameraApplicationPlatform/LiquidLeakMonitor/Telemetry
From App MQTT	Event	leak-detector/alarms/puddle_detected
Trom App Mari	Event	icak detector/alarms/paddic_detected
From App MQTT	Telemetry	leak-detector/status

Release Notes:

Pre-Release v1.0.3

- Bug fixes:
 - Bounding Box alignment bug fixed
 - Fixed integration with Axis VMS
 - Fixed display of augmented video stream in NxWitness VMS

Pre-Release v1.0.2

· Bug fixes

Pre-Release v1.0.1

Change port of webserver

Pre-Release v1.0.0

First release

Known issues

 Model is not as accurate as it needs to be. Issue with running on Axis DLPU and Image re-size layer.