# Indian Standard CODE OF PRACTICE FOR SELECTION, INSTALLATION AND MAINTENANCE OF SLUICE VALVES (First Revision)

Sixth Reprint SEPTEMBER 1993

UDC 621.646.5.005

© Copyright 1971

BUREAU OF INDIAN STANDARD S MANAK BHAVAN, 9 BAHADUR SHAH ZAFAR MARG NEW DELHI 110002

# Indian Standard

# CODE OF PRACTICE FOR SELECTION, INSTALLATION AND MAINTENANCE OF SLUICE VALVES

# (First Revision)

Sanitary Appliances and Water Fittings Sectional Committee, BDC 3

Chairman

THE DIRECTOR

Representing

Central Public Health Engineering Research Institute (CSIR), Nagpur

Members

ADVISER

SHRI H. R. BADYAL

SHRI K. D. BISWAS ( Alternate )

SHRI V. D. CHADHA CHIEF ENGINEER

SUPERINTENDING ENGINEER ( Alternate )

CHIEF ENGINEER

Ministry of Health, Family Planning & Works,

Housing & Urban Development The Indian Iron and Steel Co Ltd. Calcutta

Ministry of Railways

Central Public Works Department

Local Self Government Engineering Department, Government of Uttar Pradesh

SUPERINTENDING ENGINEER (Alternate) Municipal Corporation of Delhi CHIEF ENGINEER (WATER)

DRAINAGE ENGINEER (Alternate)

CITY ENGINEER

SHRI Y. H. KAMAT ( Alternate )

SHRI H. N. DALLAS LALA G. C. DAS

SHRI M. K. GANPULE

Bombay Municipal Corporation

The Indian Institute of Architects, Bombay

Engineer-in-Chief's Branch, Army Headquarters Directorate General of Supplies & Disposals

Directorate General of Technical Development

National Test House, Calcutta

All India Pottery Manufacturers' Association, Calcutta

SHRI R. M. MEHRA ( Alternate )

Shri K. C. Jerath Shri J. Thomes (Alternate) Shri M. T. Kanse

SHRI G. S. SUBBARAMAN ( Alternate )

Central Glass & Ceramic SHRI R. V. LELE (CSIR), Calcutta Indian Non-ferrous Metals Manufacturers Associa-

SHRI R. N. MALLICK SHRI N. R. SRINIVASAN ( Alternate ) SHRI R. M. MEHRA

SHRI G. A. LUHAR

Bombay Potteries & Tiles Ltd, Bombay

tion, Calcutta

(Continued on page 2)

Research Institute

### BUREAU OF INDIAN STANDARDS

MANAK BHAVAN, 9 BAHADUR SHAH ZAFAR MARG **NEW DELIHI 110002** 

### IS: 2685 - 1971

### (Continued from page 1)

### Members

SHRI V. P. NARAYANAN NAYAR

SHRI R. PARIKSHIT SHRI A. H. PATEL

DR A. V. R. RAO

SHRI G. T. BHIDE ( Alternate ) REPRESENTATIVE

REPRESENTATIVE \*SHRI B. B. RAU

SHRI R. K. SOMANY

SHRI V. S. BHATT ( Alternate )

SHRI B. ULLAL SHRI T. S. CHINTAMANI ( Alternate )

SHRI D. AJITHA SIMHA, Director (Civ Engg) Rebresenting

Public Health Engineering Department, Government of Kerala

Indian Section of Plastic Institute, New Delhi

Ahmedabad Municipal Corporation

National Buildings Organization (Ministry of Works, Housing & Urban Development)

Central Building Research Institute (CSIR). Roorkee

Hindustan Shipyard Ltd, Visakhapatnam Institution of Engineers (India), Calcutta

Hindustan Sanitaryware Industries Ltd, Bahadurgarh

E. I. D. Parry Ltd. Madras

Director General, ISI (Ex-officio Member)

### Secretary

SHRI C. R. RAMA RAO Deputy Director (Civ Engg). ISI

### Water Works Fittings Subcommittee, BDC 3:5

### Connener

SHELY, H. KAMAT

Bombay Municipal Corporation

The Indian Iron & Steel Co Ltd, Calcutta

Members

SHRI J. R. AGGARWAL

Govardhan Das P. A, Jullundur City SHRI YASH RAJ AGGARWAL ( Alternate )

SHRI H. R. BADYAL

SHRI K. D. BISWAS ( Alternate )

SHRI T. C. BASU SHRI K. K. BHATTACHARYYA

SHRI A. K. BHATTACHARYYA ( Alternate ) SHRI V. D. CHADHA

CHIEF ENGINEER

Ministry of Railways

Burn & Co Ltd, Calcutta

Indian Valve Co Ltd, Calcutta

Local Self Government Engineering Department Government of Uttar Pradesh

Superintending Engineer (Alternate)

Delhi Municipal Corporation CHIEF ENGINEER (WATER)

DEPUTY CHIEF ENGINEER (WATER) (Alternate)

Italab Engineering Pvt Ltd, Bombay SHRI J. D. DAROGA

National Physical Laboratory ( CSIR ), New Delhi SHRI M. K. DAS GUPTA

SHRI M. L MUTALIOK DESAI Kirloska: Brothers Ltd, Kirloskarwadi

SHRI V. P. HAVALDAR ( Alternate )

(Continued on page 7)

<sup>\*</sup>He is also alternate to the adviser, Ministry of Health, Family Planning & Works, Housing & Urban Development.

# Indian Standard

# CODE OF PRACTICE FOR SELECTION, INSTALLATION AND MAINTENANCE OF SLUICE VALVES

# (First Revision)

### O. FOREWORD

- 0.1 This Indian Standard (First Revision) was adopted by the Indian Standards Institution on 30 July 1971, after the draft finalized by the Sanitary Appliances and Water Fittings Sectional Committee had been approved by the Civil Engineering Division Council.
- 0.2 This standard was first published in 1964. The Sectional Committee has revised the standard after reviewing it in the light of experience gained in the usage of the same and has incorporated the necessary modifications to facilitate the use of valves conforming to IS: 780-1969\*.
- 0.3 For the purpose of deciding whether a particular requirement of this standard is complied with, the final value, observed or calculated, expressing the result of a test or analysis, shall be rounded off in accordance with IS: 2-1960†. The number of significant places retained in the rounded off value should be the same as that of the specified value in this standard.

### 1. SCOPE

1.1 This code covers the selection, installation and maintenance of sluice valves conforming to IS: 780-1969\*.

### 2. SELECTION

- 2.1 The aspects governing the selection of sluice valves are listed below:
  - a) Nominal bore of pipe.
  - b) Nature of Pipe whether it is made of cast iron, cast steel, asbestos-cement or steel coated with concrete.
  - c) Situation whether distribution or rising main.

<sup>\*</sup>Specification for sluice valves for water-works purposes (50 to 300 mm size) (fourth revision).

<sup>†</sup>Rules for rounding off numerical values ( revised ).

### IS: 2685 - 1971

- d) Location whether underground or above.
- e) Nature of location of the valve which would depend upon the following factors:
  - 1) Whether centre line of spindle is vertical or horizontal, and
  - 2) Whether inside or in a terminal position in a pipe line.
- f) Nature of end connections, namely, flanged, socketed or plained ended.
- g) Quality of water:
  - 1) Whether raw unfiltered or filtered;
  - 2) Acidic or alkaline, if possible pH value (hydrogen-ion concentration); and
  - 3) Temperature.
- h) Pressure of water, both working and unbalanced, and the static head at the centre of the valve.

Note — Unbalanced pressure is the difference between the pressures on the two sides of the door with the valve shut. This determines the resultant unbalanced thrust against which the valve has to be operated.

- j) For headstock operation only:
  - 1) Distance, between the centre line of waterway and the base of headstock, that is level of operating platform;
  - 2) Distance between the centre line of extension spindle and the face of wall or masonry; and
  - 3) Headroom available on the operating platform.

### 3. INSTALLATION

- 3.1 Sluice valves shall normally be installed with spindle vertical on horizontal pipes except on vertical pipes where spindle shall be horizontal. On slopes, the sluice valves may preferably be kept vertical if slope is nominal and gradient can be adjusted with the help of connecting pipes on either sides.
- 3.1.1 It shall be ensured while fixing sluice valves in pipe lines below ground level that a clear space of about 200 mm is available between the top of the sluice valve spindle and surface box, so that valve cap may be easily provided when surface box is kept in flush with road level.
- 3.2 It is most important to ensure that:
  - a) all grit and foreign matters are removed from the inside of the valves before placing in pipes, and

- b) all the four faces are thoroughly cleaned and coated with a thin layer of mineral grease.
- 3.3 It is important to check tightening of gland with a pair of inside calipers. Clearance between the top of the stuffing box and the underside of the gland should be uniform on all the sides.
- 3.4 Gland should not be tightened too hard. The pressure applied should be just enough to stanch leakage.
- 3.5 Hemp packing should be adequately soaked in grease and should not be allowed to remain dry.
- 3.6 The valves should be tightly closed when being installed, as this keeps the valve rigid and prevents any foreign matter from getting in between the working parts of the valve.
- 3.7 While installing flanged valves, each flange bolt should be tightened a little at a time, taking care to tighten diametrically opposite bolts alternately. The practice of fully tightening the bolts one after the other is highly undesirable.
- 3.8 After installation of the valve, the valve and the pipe line should be flushed with water to remove any foreign matter that may be present in them.
- 3.9 If any leak is detected at the valve seats, applying extra torque on the valve spindle to set right the valve is not good practice. The valve seats should be examined and, if necessary, repaired by scraping or replacing where necessary.
- 3.10 Valves in exposed positions should be protected in cold weather where there is a likelihood of their becoming frozen and bursting.
- 3.11 Surface boxes conforming to IS: 3950-1966\* should be provided to cover the valve chamber for the safety and easy indentification of the valves.
- 3.12 The direction of opening and closing should be clearly indicated.
- 3.13 Suitable identification plate should be provided as near to the actual location of valves as possible.
- 3.14 Care should be taken to ensure that the joining material sits squarely between the flanges of the valves and pipe lines or tails without obstructing the waterway. It is equally important to ensure that there are no kinks in the jointing material as might allow leakage in service.

<sup>\*</sup>Specification for surface boxes for sluice valves.

### IS: 2685 - 1971

### 4. MAINTENANCE

- 4.1 A valve normally kept open or shut in a pipe should be operated once every three months to full travel of gate and any jamming that may have developed due to its remaining unused is to be freed.
- 4.2 It should be ensured that packings inside stuffing box are in good trim and impregnated with grease. It may be necessary to change the packing as often as necessary to ensure these requirements.
- 4.3 For T-key operation the end of the key should have good fit on the square taper at the top of spindle. It is dangerous to operate valves by oversize keys fitted direct to the spindle as this practice may result in rounded square top and the key may eventually slip.
- 4.4 Partial opening of valves frequently in a pipe is dangerous particularly against high unbalanced pressures. Where frequent partial opening of a valve is necessary against high unbalanced pressures a duplicate valve may be provided on the upstream side of the operating valve which should be kept fully open all the time. This will enable isolation of the pipe section for repairing the operative valve when it becomes defective.
- 4.4.1 Where a valve has been fully opened, the back-lash should be taken out and the valve slightly eased so that it will not stick.
- 4.5 The valve should be regularly inspected internally and externally, preferably, at intervals of not more than a year, the frequency of inspections depending upon the service conditions and the frequency of valve operations. The stuffing box packing should be adjusted or replaced soon after leakage past the spindle is detected.

### (Continued from page 2)

### Members

SHRI S. K. GAMBHIR Directorate General of Supplies & Disposals

Shri M. C. Aich ( Alternate )
Shri A. Ghosh
Shri M. M. Munshi
Shri M. M. Munshi
Shri M. M. Munshi
Shri M. M. Munshi

SHRI M. M. MUNSHI
SHRI S. J. REGE (Alternate)
SHRI V. P. NARAYANAN NAYAR

Public Health Engineering Department, Government of Kerala

Representing

of Kerala
Shri Rameshchandra H. Thakkar Geeta Iron & Brass Works, Baroda
Shri Nand Kumar H. Thakkar ( Alternate )

REPRESENTATIVE Central Public Health Engineering Research Institute (CSIR), Nagpur

SHRI V. RAMAN ( Alternate )
SHRI A. K. RAY
Annapurna Metal Works, Calcutta

## BUREAU OF INDIAN STANDARDS

Headquarters:	
Manak Bhavan, 9 Bahadur Shah Zafar Marg, NEW DELHI 110002	
Telephones: 331 01 31, 331 13 75  Telegrams: Ma ( Common to	anaksanstha
Regional Offices:	Telephone
Central: Manak Bhavan, 9 Bahadur Shah Zafar Marg, NEW DELHI 110002	(331 01 31 331 13 75
*Eastern : 1/14 C. I. T. Scheme VII M, V. I. P. Road, Maniktola, CALCUTTA 700054	36 24 99
Northern: SCO 445-446, Sector 35-C, CHANDIGARH 160036	{ 2 18 43 } 3 16 41
Southern: C. I. T. Campus, MADRAS 600113	\$\\\\ 41 24 42 \\\ 41 25 19 \\\ 41 29 16 \end{array}\$
†Western: Manakalaya, E9 MIDC, Marol, Andheri (East), BOMBAY 400093	6 32 92 95
Branch Offices:	
'Pushpak', Nurmohamed Shaikh Marg, Khanpur, AHMADABAD 380001	2 63 48 2 63 49
‡Peenya Industrial Area 1st Stage, Bangalore Tumkur Road BANGALORE 560058	(38 49 55 )38 49 56
Gangotri Complex, 5th Floor, Bhadbhada Road, T. T. Nagar, BHOPAL 462003	6 67 16
Plot No. 82/83, Lewis Road, BHUBANESHWAR 751002 53/5, Ward No. 29, R.G. Barua Road, 5th Byelane, GUWAHATI 781003	5 36 27 3 31 77
5-8-56C L. N. Gupta Marg ( Nampally Station Road ), HYDERABAD 500001	23 10 83
R14 Yudhister Marg, C Scheme, JAIPUR 302005	{ 6 34 71 6 98 32
117/418 B Sarvodaya Nagar, KANPUR 208005	{21 68 76 {21 82 92
Patliputra Industrial Estate, PATNA 800013 T.C. No. 14/1421. University P.O., Palayam TRIVANDRUM 695035	6 23 05
Inspection Offices ( With Sale Point ):	
Pushpanjali, First Floor, 205-A West High Court Road, Shankar Nagar Square, NAGPUR 440010	2 51 71
Institution of Engineers (India) Building, 1332 Shivaji Nagar PUNE 411005	, 5 24 35

<sup>\*</sup>Sales Office in Calcutta is at 5 Chowringhee Approach, P. O. Princep 27 68 00 Street, Calcutta 700072

<sup>†</sup>Sales Office in Bombay is at Novelty Chambers, Grant Road, 89 65 28 Bombay 400007

<sup>‡</sup>Sales Office in Bangalore is at Unity Building, Narasimharaja Square, 22 36 71 Bangalore 560002

# AMENDMENT NO. 1 MARCH 1990

### IS: 2685 - 1971 CODE OF PRACTICE FOR SELECTION, INSTALLATION AND MAINTENANCE OF SLUICE VALVES

### (First Revision)

( Page 3, clause 0.2, last line ) — Substitute 'IS: 780-1984\*' for 'IS: 780-1969\*'.

(Page 3, clause 1.1, last line) — Substitute 'IS: 780-1984\*' for 'IS: 780-1969\*'.

(Page 3, foot-note, first line) — Substitute '(sixth revision)' for '(fourth revision)'.

( Page 5, clause 3.11, first line ) — Substitute 'IS: 3950 - 1979\*' for 'IS: 3950-1966\*'.

( Page 5, foot-note) — Insert '(first revision)' in the end.

(CED 3)

Reprography Unit, BIS, New Delhi, India