

PS.: Flip all back layers, print with white strip (rough side) up, use negative on copper layers