



Connectors




Relay Circuits









AIR- Weld Detection







Shutdown Sensing




BUCK CONVERTER





MICROCONTROLLER





Programming LEDs





I removed the flyback diode for the precharge and AIRs' relays. This should go on the new air mounted board.

