


Genode OS Framework



QEMU -cpu host, virtual NVMe (PCIe), USB passthrough

Podman container (USB flash passthrough: `--device /dev/bus/usb/...`)

Host Linux

- NVMe disk (btrfs): `block0.raw`, `test.5gb.raw`
- USB flash (ext4): trust anchor key, initialization flag

HW: NVMe SSD, USB 2.0 flash drive