

VALUES AND POSITIONS OF THE FACILITIES FOR MONITORING THE "PROCESSES"

In order to monitor all the processes in a factory, we need to control the values and positions of each piece of equipment, which may vary in value, such as (pressure, speed, etc.) or by the position in its regulation (start or stop control sensors, etc.) or their movement, such as (linear displacements, turns, etc.)

When starting up a factory it is very important to have "references of the starting points of all the components" to make checks with time, in case they have been modified with the work or there have been changes, without notifying them.

For this we need to mark/signal and have all the information updated in all processes.

EXTRUDER

General :

Pressure signalling general, regulator for extruder feed.

PUSH CHAIN

Signalling :

List Trolleys.

Anti-lifting cylinder piston detectors.

Pressure on pressure regulator manometer anti-lift system

Measurements:

Situation of each Polycord of the Trolleys.

Measurements between pushers on both sides.

Tensioners on both sides of the push chain

TILE CUTTING SYSTEM

Signalling in the cutting system :

Positioning of push chain axis with carriage arm plate.

Positioning of the cutting cam.

Positioning of detector on safety piston.

Positioning of reduction axis with up and down cutting carriage disc.

Measurements :

Distance between cutting arm bearings from eccentric to cutting carriage axis.

Distance between the sides of the cutting carriage in the cutting position.

FRESH TILE/MOULD CONVEYORS

EXTRUDER T1 OUTPUT CONVEYOR

Write down :

Speed of the T1 polycord.

TRANSPORTER OUTPUT Extruder T2

Write down :

Speed of the T2 polycore.

Signalling:

Pressure on pressure gauge regulator, system blowers cleaning surface Tile

ROTARY

General :

Pressure signalling general, regulator for Rotary.

RACKER CONVEYOR

Write down :

Speed of the Racker polycord input conveyor.

Signalling:

Positioning of transmitter and receiver photocell supports (length, height and inclination) on conveyor.

RACKER STACKER CHAIN

Write down :

Time to go up.

Signaling:

List angles of right side of stacking chain

Positioning of the input photocell supports for the chain, transmitter and receiver (length, height and inclination)

Disc and cams detector upstacker stop.

Stacker stop detector (height)

Positioning of the safety limit switch during the ascent.

Measurement:

Polycord plane on angle flats on each side

Positioning of the fixing studs of the support guides of the stacker chain.

Studs for tensioning the stacking chain on each side.

STEP GATE

Signalling:

Cylinder detector for open and closed gates.

Cylinder axis positioning / gate system bearing.

Cylinder clamping bolt positioning.

FIXED STEP STACKER

Signalling:

Detector or photocell pass Tile/mould SQ37.8

Pressure regulator for gate cylinder supply.

STACKER PUSHER ARM

Signalling:

Cylinder supply pressure regulator.

Cylinder up and down arm pressure regulator.

Positioning of the arm at the front and at the back.

RACKER UNSTACKING CHAIN

Write down :

Time of descent.

Signaling:

List angles of the left or right side (depending on the assistance area) of the destacking chain

Disk and cams detecting the lowering of the destacker (height)

Unloaded destacker chain positioning detector (height)

Safety end of stroke positioning at the destacking chain infeed.

Measurement:

Polycord plane on flats of the unloading chain angles on each side

Positioning of the fixing studs of the support guides of the destacking chain.

Denester chain tensioning studs on each side.

ROTARY TURNING SYSTEM

Write down :

Rotary turn advance time.

Oil control unit pressure for feed.

Signaling:

List centering plates of the Rotary.

Positioning of each plate , to evaluate evolution.

Feed position and arrival of the rotary slide.

Positioning of the left, central and right detector of the turning carriage.

Position of the detector in front and behind the locking cylinder

Switchboard maintenance oil level.

Measurement:

Diameter of support wheels , for each plate.

Cylinder axis , Rotary

Cylinder shaft in and out.

PUSHER-DESTACKER ARM

Signalling:

Positioning of the arm in front and behind.

Positioning of the forward and backward arm limit switch.

Positioning of the denester arm detector.

UNSTACKING CONVEYOR

Write down :

Speed of the Polycord unstacking conveyor.

Signalling:

Lateral centering guides of the mould exit conveyor.

Positioning of the transmitter and receiver photocell supports. (length, height and inclination) jamming on the conveyor.

TILE / MOULD CONVEYORS

EXIT CONVEYOR DESTACKER

Write down :

Speed of the polycarrier exit destacker.

CONVEYOR ENTRANCE UNSTACKER

Write down :

Speed of polycord conveyor for demoulding input.

MOULD CONVEYORS

DEMOULDING MOULDS EXIT CONVEYOR I

Write down :

Speed of the polycord conveyor for tile outlet moulds I.

DEMOULDING MOULDS EXIT CONVEYOR II

Write down :

Speed of the polycord conveyor for tile outlet moulds II.