Cluster Progress

March 25, 2019

Component Incorporation

- Renaming the Nodes
 - The nodes in cabinet 0 have been renamed.
 They now belong to cabinet 2.
- Incorporating the SE
 - The SE has been added as compute-0-10.




Figure: The nodes in cabinet "0" have been renamed.

NAS-0 Issues

- The OS RAID array is degraded.
- One of the two mirrored drives has failed.
- NAS-0 failed to recognize the replacement drive.
- Both drives are being tested.