







- 1) (username=admin,password=pass@123)
- 2) For helping purpose click on contact or manual

Model Screen

Platform	Model Code	Part Name	CheckPoints	Connection Screen	Employee Master	Shift	04/06/2024 12:38:25	Logout
 Platform Platform 2								
Sr. No.	Model Code	Model Description				Edit	Delete	
1	AS22GPEW5T403C00	MX3						
2	AS22HPEW5T403C00	AX5L						
3	AS22PPEW5T103C00	MX2 PRO						

- 1) Add model to click on (Top's add(+)) button) but first select platform in dropdown
- 2) Added data show in table.
- 3) Add edit button for edit data ,delete button for delete data.

PlatForm	Model Code	Part Name	CheckPoints	Connection Screen	Employee Master	Shift	04/06/2024 12:44:11	Logout
----------	------------	-----------	-------------	-------------------	-----------------	-------	---------------------	--------

+

Sr. No.	PartNo	Part Name	Image	Edit	Delete
1	19	Antenna	No Image		
2	21	C- Pillar	No Image		
3	25	Console Top finisher	No Image		
4	18	Driver Panel	No Image		
5	16	Fog Lamp	No Image		
6	13	Front Camera	No Image		
7	3	Gear Knob	No Image		
8	7	Hand Brake	No Image		
9	15	Headlamp	No Image		

Contact

- 1) Add part to click on (Top's add(+) button)
- 2) Added data show in table.
- 3) Add edit button for edit data delete button for delete data.
- 4) part no, part name, image_path, severity, attribute, highlight, location, ocr_operation
- 5) For part same part with different model duplicate part number.

Checkpoint Screen

PlatForm	Model Code	Part Name	CheckPoints	Connection Screen	Employee Master	Shift	04/06/2024 13:08:45	Logout
----------	------------	-----------	-------------	-------------------	-----------------	-------	---------------------	--------

+

Select a Part:

Model Name Badge

Sr. No.	Part Name	Checkpoint	Edit	Delete
1	Model Name Badge	seat lader colour white		

Contact

- 1) Add model to click on (Top's add(+) button) but first select part in dropdown
- 2) Added data show in table.
- 3) Add edit button for edit data ,delete button for delete data.

Select ModelSelect PartConnectView

Select/Deselect All

AS22GPEWST403C00

☒ AS22HPEWST403C00

AS22PPEWST103C00

WYE546DHYEKD7777

Model Name

View

Delete

data not available

1. Select model for selection of models.

2. Select part for selection of parts.

3. If you want to connect so first select model then, select part and click on connect button.

4. If you want to check how many parts are connected to a particular model, select the model from the dropdown menu and then click on the view button.

5. Connected or viewed data show in table Show model name , part name, view(for see image), delete button.

6. If you want to delete record click on delete button.

Employee Screen

PlatFormModel CodePart NameCheckPointsConnection ScreenEmployee MasterShift04/06/2024 13:42:52Logout

+

Sr. No.	Token no	Employee Name	User Level	Edit	Delete
1	1	Dustine	Operator		
2	3	Mike	Operator		
3	2	Steve	Supervisor		

Contact

1. For adding employee click on top's (+) button.
2. In that dropdown select user level
Supervisor, oprator.
3. Add token no and employee name.
4. Added data show in table
5. Add edit button for edit data.
add delete button for delete data.

Caution:-

1. Please Be Careful while deleting the platform once you delete the platform its related models and connections will be deleted so be Careful.
2. Careful while deleting parts when you delete part check that part not connected in any connections.
3. When you delete the part its related checkpoint also deleted.

Mobile And Server IP Address

PROJECT	IP	SUBNET
SERVER		
App Based QC Tab for Model Verification		

- 1) Varient server contruction equipment app
username
- 2) Varient server contruction equipment app
password
- 3) In chrome's search bar search localhost.

admin

[pass@123](#)