

NOTES:

1. Voltage Calibration
   Adjust ZMPT101B gain for 1 Vmv = 1 Vrms
   VOLTAGE_SCALE = 1.0f
2. Current Calibration
   CT 1000:1 Rburden = 68 || 120 = 43.4
   CURRENT_SCALE = CTratio / Rburden / 1000
   CURRENT_SCALE = 0.023f

W4KRL		
EV Charge Monitor 16 A		
K W Berger	Rev 1.4 8/31/2026	Page 1 of 1