

Sop Sop - facility report

1. Identification

Facility	Sop Sop
Named on the programme list	Sop Sop
Type	School
Local government	Tororo District
Region / sub-region	Eastern / Bukedi
Date of visit	2026-08-29
Team members present	Kayongo Tonny, Lydia Nakiganda
Informant interviewed	None recorded
Supervisor	Kassim Luminsa
Supervisor's contact	+256 702 806116
Date of submission	

2. Entry

The team reached St Joseph Sop Sop Seed School on 29 August. A hand-filled register is on file together with 168 photographs. Nobody is named as having received the team.

3. Condition and status

The four things the exercise exists to establish. Only what was established on site appears here; the rest is marked as not reported, not guessed.

Dimension	What was established on site
Ownership	Not reported.
Functionality	Established on the hand-filled register. Desks, chairs, laboratory stools and office tables are recorded in good condition with one broken stool.
Usage / performance	Partly established. The school has no electricity, one camera is nonfunctional, and no functionality records are kept.
Location	Recorded on the register and shown in the photographs across classroom blocks, the ICT room, library, staff housing and latrines.

4. Supplied against found

The hand-filled register is the found side and nothing was counted on the day.

5. Engraving and identification

The register records engraved but not numbered on most furniture.

6. Obsolete, unserviceable or for disposal

One laboratory stool is broken; nothing was named for disposal.

7. Operation and maintenance

The discussion guide was answered. The school is under defect liability, keeps no functionality records, and asks for electricity, more teachers and more classrooms.

8. Queries

- The cover block of the hand-filled register was not photographed.
- Nothing here was counted on the day.
- Ownership was not established.