


103.00 ± 0.20 mm
90.50 ± 0.20 mm
CSI-2
1 Extra CSI-2 for expansion
Battery 1
9V-20V DC
Max 3.5A


x4 (Connect each motor)
Each PWM output must be connected to each pin for switching from forward to reverse.
I2C
Black: Ground
Yellow: SCL
Blue: SDA
Red: 3.3V DC
Battery 2
12V DC