## Sea-Bird Electronics, Inc.

## 13431 NE 20th Street, Bellevue, WA 98005-2010 USA

Phone: (+1) 425-643-9866 Fax (+1) 425-643-9954 Email: seabird@seabird.com

SENSOR SERIAL NUMBER: 0019 CALIBRATION DATE: 24-Mar-12 SBE 48 TEMPERATURE CALIBRATION DATA ITS-90 TEMPERATURE SCALE

## **ITS-90 COEFFICIENTS**

a0 = -1.976688e - 004 a1 = 3.072897e - 004 a2 = -4.398809e - 006a3 = 2.053060e - 007

BATH TEMP (ITS-90)	INSTRUMENT OUTPUT	INST TEMP (ITS-90)	RESIDUAL (ITS-90)
1.0000	713694.7	1.0000	0.0000
4.5000	612282.7	4.4999	-0.0001
15.0000	394041.7	15.0001	0.0001
18.5000	342273.4	18.5000	0.0000
24.0000	275914.3	24.0000	-0.0000
29.0000	228172.6	28.9999	-0.0001
32.5000	200406.8	32.5000	0.0000

Temperature ITS-90 =  $1/{a0 + a1[ln(n)] + a2[ln^2(n)] + a3[ln^3(n)]} - 273.15$  (°C)

Residual = instrument temperature - bath temperature

Date, Delta T (mdeg C)



