The O-rings were replaced.

Temperature Calibration Report

Customer:	woods Hole Oceangraphic Institution			
Job Number:	61651	Date of Repo	rt:	12/23/2010
Model Number	SBE 03F	Serial Number	er:	034230
Temperature sensors are normally calibrated 'as received', without adjustments, allowing a determination sensor drift. If the calibration identifies a problem, then a second calibration is performed after work is completed. The 'as received' calibration is not performed if the sensor is damaged or non-functional, or by customer request. An 'as received' calibration certificate is provided, listing coefficients to convert sensor frequency to temperature. Users must choose whether the 'as received' calibration or the previous calibration better represents the sensor condition during deployment. In SEASOFT enter the chosen coefficients using the program SEACON. The coefficient 'offset' allows a small correction for drift between calibrations (consult the SEASOFT manual). Calibration coefficients obtained after a repair apply only to subsequent data.				
'AS RECEIVED O	CALIBRATION'	✓ Peri	formed	☐ Not Performed
Date: 12/8/2010]	Drift since last cal:	-0.00103	Degrees Celsius/year
Comments:				
'FINAL CALIBRA	ATION'	✓ Perí	formed	□ Not Performed
Date: 12/23/2010		Drift since 06 Oct 09	-0.0009	Degrees Celsius/year
Comments:				