

WORLD-LINK SERVICE REPORT

CUSTOMER DETAILS

Report Date	Vessel Name	Customer I	Vame	Location	Engineer's Name/s
25-Feb-19	Atlantis	WHOI		San Francisco Mare Island	Nikolas Nikolaou

SCOPE OF WORK

Та	sk	Task	Tas		Task
•	FX installation	•	•		•
•					•

TRAVEL DETAILS

Date	From	То	Travel Hours	Waiting Hours	Notes	
23-Feb-19	Larnaca	London	5	10		
24-Oct-18	London	LAX	10	4		
24-Oct-18	LAX	San Fran.	1			

WORKING HOURS

Date	Time	# Of Techs	Working	Hours	Travel	Hours	Notes	
25-Feb-19	0800	1	6		1			

SYSTEM DETAILS

EQUIPMENT TYPE	Serial No.	Antenna Serial No.	Firmware Version Sim #	Notes
Sailor GX100				
Choose an item.				
Choose an item.				

GENERAL REMARKS

ENGINEER'S REMARKS		CAPTAIN'S	REMARKS	
Request for static IP assignment o inmarsat/cisco as we do not have configuration.				
Blocking zone set to 340-20 / 0-49 the region of the bridge.	5 elevation to prevent transmission in			
SERVICE DETAILS				
☐ Systems Training to Captain	☐ Reboot Procedure Explain	ed 🗵 Ne	twork Diagram Provided	☐ Cables Labeled
☐ Heat-Shrink Tube on Antenn	a Connectors	aved to .txt	☐ Icafe Internet Browsing	☐Test Voice Call
INSTALLATION PICTU	JRES & SCREENSHOTS			
Pictures				
	□ Devices Cable Connections	☐ Antennas	s 360° from Distance	Antennas Cable Connectio
	☐ Antenna Grounding ☐ Ic	afe Internet B	rowsing	
SPARE PARTS & ADD	ITIONAL WORK			
Spares Used	Additional Work		Additional Work Ti	me Spent

Captain's Signiture and Stamp

