The sign convention for the survey was different from what the phins wants:

SURVEY CONVENTION: (X) forward +

**used in calculations above (Y) STBD +

(Z) Down +

Multibeam Convention: (X) forward +

(Y) STBD + (Z) Down +

Phins Conventions: XV1 forward + vessel horizontal plane, pointing forward to bow ** offsets entered into Phins must XV2 port + vessel horizontal plane, pointing from Stbd to Port

use this convention

XV3 up + is perpendicular to the vessel horizontal plane, pointing upward

The PHINS manual – Part II – Definitions, Conventions & Specifications page 12 defines the lever arm as:

*External sensor lever arm is the distance from PHINS center of measurement P to the center of measurement of the external sensor.

So the offsets to enter into Phins are as follows:

	Phins Offset (meters)
PRIMARY CNAV POSITION: XV1	-10.140 aft is negative
XV2	3.410 port is positive
XV3	27.468 up is positive
1850 (GPS 1 - bridge/aft): XV1	-10.705 aft is negative
XV2	2.819 port is positive
XV3	26.997 up is positive
1850 (GPS#2 - chrm / forward): XV1	-9.665 aft is negative
XV2	2.031 port is positive
XV3	27.686 up is positive