
(a) Eddy-current inspection
AC coil
Crack disturbs current paths
(b) Ultrasonic pulse-echo inspection
Piezoelectric probe
Defect echo
Internal interface / defect