8086 instructions Page 1 of 53

....

Complete 8086 instruction set

Quick reference:

	<u>CMPSB</u>				<u>MOV</u>		
<u>AAA</u>	<u>CMPSW</u>	<u>JAE</u>	<u>JNBE</u>	<u>JPO</u>	<u>MOVSB</u>	<u>RCR</u>	<u>SCASB</u>
AAD	CWD	<u>JB</u>	<u>JNC</u>	<u>JS</u>	MOVSW	REP	<u>SCASW</u>
<u>AAM</u>	DAA	<u>JBE</u>	<u>JNE</u>	<u>JZ</u>	<u>MUL</u>	REPE	SHL
<u>AAS</u>	<u>DAS</u>	<u>JC</u>	<u>JNG</u>	<u>LAHF</u>	<u>NEG</u>	REPNE	SHR
ADC	<u>DEC</u>	<u>JCXZ</u>	<u>JNGE</u>	LDS	NOP	REPNZ	STC
ADD	DIV	<u>JE</u>	$\overline{\text{JNL}}$	<u>LEA</u>	NOT	REPZ	STD
AND	$\underline{\mathrm{HLT}}$	<u>JG</u>	<u>JNLE</u>	<u>LES</u>	<u>OR</u>	RET	STI
CALL	IDIV	<u>JGE</u>	<u>JNO</u>	LODSB	OUT	RETF	STOSB
CBW	IMUL	<u>JL</u>	<u>JNP</u>	LODSW	POP	ROL	STOSW
CLC	<u>IN</u>	<u>JLE</u>	<u>JNS</u>	LOOP	POPA	ROR	SUB
CLD	INC	<u>JMP</u>	\overline{JNZ}	LOOPE	POPF	SAHF	TEST
CLI	INT	<u>JNA</u>	<u>JO</u>	LOOPNE	PUSH	SAL	XCHG
<u>CMC</u>	INTO	<u>JNAE</u>	<u>JP</u>	LOOPNZ	<u>PUSHA</u>	SAR	$\underline{\text{XLATB}}$
<u>CMP</u>	IRET	<u>JNB</u>	<u>JPE</u>	LOOPZ	PUSHF	SBB	<u>XOR</u>
	<u>JA</u>				RCL		

Operand types:

REG: AX, BX, CX, DX, AH, AL, BL, BH, CH, CL, DH, DL, DI, SI, BP, SP.

SREG: DS, ES, SS, and only as second operand: CS.

memory: [BX], [BX+SI+7], variable, etc...(see Memory Access).

immediate: 5, -24, 3Fh, 10001101b, etc...

Notes:

 When two operands are required for an instruction they are separated by comma. For example:

```
REG, memory
```

• When there are two operands, both operands must have the same size (except shift and rotate instructions). For example:

```
AL, DL
DX, AX
ml DB?
AL, ml
m2 DW?
AX, m2
```

• Some instructions allow several operand combinations. For example:

```
memory, immediate
```

8086 instructions Page 2 of 53

```
REG, immediate
memory, REG
REG, SREG
```

 Some examples contain macros, so it is advisable to use Shift + F8 hot key to Step Over (to make macro code execute at maximum speed set step delay to zero), otherwise emulator will step through each instruction of a macro. Here is an example that uses PRINTN macro:

```
include 'emu8086.inc'
ORG 100h
MOV AL, 1
MOV BL, 2
PRINTN 'Hello World!' ; macro.
MOV CL, 3
PRINTN 'Welcome!' ; macro.
RET
```

These marks are used to show the state of the flags:

- 1 instruction sets this flag to 1.
- **O** instruction sets this flag to **O**.
- **r** flag value depends on result of the instruction.
- ? flag value is undefined (maybe 1 or 0).

Some instructions generate exactly the same machine code, so disassembler may have a problem decoding to your original code. This is especially important for Conditional Jump instructions (see "Program Flow Control" in Tutorials for more information).

Instructions in alphabetical order:

Instruction	Operands	Description
		ASCII Adjust after Addition. Corrects result in AH and AL after addition when working with BCD values. It works according to the following Algorithm: if low nibble of AL > 9 or AF = 1 then:

8086 instructions Page 3 of 53

		• AL = AL + 6 • AH = AH + 1
		• AF = 1 • CF = 1
		else
		• AF = 0 • CF = 0
AAA	No operands	in both cases: clear the high nibble of AL.
		Example:
		MOV AX, 15 ; AH = 00, AL = 0Fh AAA ; AH = 01, AL = 05 RET
		CZSOPA r????r
		ASCII Adjust before Division. Prepares two BCD values for division.
		Algorithm:
		• AL = (AH * 10) + AL • AH = 0
AAD	No operands	Example:
		MOV AX, 0105h ; AH = 01, AL = 05 AAD ; AH = 00, AL = 0Fh (15) RET
		CZSOPA ?rr?r?
		ASCII Adjust after Multiplication. Corrects the result of multiplication of two BCD values.
		Algorithm:
		• AH = AL / 10 • AL = remainder

8086 instructions Page 4 of 53

AAM	No operands	Example: MOV AL, 15 ; AL = 0Fh AAM ; AH = 01, AL = 05 RET CZSOPA ?rr?r?
AAS	No operands	ASCII Adjust after Subtraction. Corrects result in AH and AL after subtraction when working with BCD values. Algorithm: if low nibble of AL > 9 or AF = 1 then: • AL = AL - 6 • AH = AH - 1 • AF = 1 • CF = 1 else • AF = 0 • CF = 0 in both cases: clear the high nibble of AL. Example: MOV AX, 02FFh ; AH = 02, AL = 0FFh AAS ; AH = 01, AL = 09 RET CZSOPA r 2 ? ? ? r
ADC	REG, memory memory, REG REG, REG	Add with Carry. Algorithm: operand1 = operand1 + operand2 + CF Example:

8086 instructions Page 5 of 53

	memory, immediate REG, immediate	STC ; set CF = 1 MOV AL, 5 ; AL = 5 ADC AL, 1 ; AL = 7 RET CZSOPA rrrrr
ADD	REG, memory memory, REG REG, REG memory, immediate REG, immediate	Add. Algorithm: operand1 = operand1 + operand2 Example: MOV AL, 5 ; AL = 5 ADD AL, -3 ; AL = 2 RET CZSOPA rrrrrr
AND	REG, memory memory, REG REG, REG memory, immediate REG, immediate	Logical AND between all bits of two operands. Result is stored in operand1. These rules apply: 1 AND 1 = 1 1 AND 0 = 0 0 AND 1 = 0 0 AND 0 = 0 Example: MOV AL, 'a' ; AL = 01100001b AND AL, 11011111b ; AL = 01000001b ('A') RET CZSOP Orror
		Transfers control to procedure, return address is (IP) is pushed to stack. <i>4-byte address</i> may be entered in this form: 1234h:5678h, first value is a

8086 instructions Page 6 of 53

		segment second value is an offset (this is a far call, so CS is also pushed to stack).
		Example:
CALL	procedure name label 4-byte address	ORG 100h ; for COM file. CALL pl ADD AX, 1 RET ; return to OS. pl PROC ; procedure declaration. MOV AX, 1234h RET ; return to caller. pl ENDP
		CZSOPA unchanged
CBW	No operands	Convert byte into word. Algorithm: if high bit of AL = 1 then: • AH = 255 (0FFh) else • AH = 0 Example: MOV AX, 0 ; AH = 0, AL = 0 MOV AL, -5 ; AX = 000FBh (251) CBW ; AX = 0FFFBh (-5) RET CZSOPA unchanged
		Clear Carry flag.
		Algorithm:
		CF = 0

8086 instructions Page 7 of 53

CLC	No operands	0
CLD	No operands	Clear Direction flag. SI and DI will be incremented by chain instructions: CMPSB, CMPSW, LODSB, LODSW, MOVSB, MOVSW, STOSB, STOSW. Algorithm: DF = 0
CLI	No operands	Clear Interrupt enable flag. This disables hardware interrupts. Algorithm: IF = 0 I 0
CMC	No operands	Complement Carry flag. Inverts value of CF. Algorithm: if CF = 1 then CF = 0 if CF = 0 then CF = 1
		Compare. Algorithm: operand1 - operand2

8086 instructions Page 8 of 53

СМР	REG, memory memory, REG REG, REG memory, immediate REG, immediate	result is not stored anywhere, flags are set (OF, SF, ZF, AF, PF, CF) according to result. Example: MOV AL, 5 MOV BL, 5 CMP AL, BL; AL = 5, ZF = 1 (so equal!) RET CZSOPA rrrrr
CMPSB	No operands	Compare bytes: ES:[DI] from DS:[SI]. Algorithm: DS:[SI] - ES:[DI] set flags according to result: OF, SF, ZF, AF, PF, CF if DF = 0 then OSI = SI + 1 ODI = DI + 1 else OSI = SI - 1 ODI = DI - 1 Example: open cmpsb.asm from c:\emu8086\examples
CMPSW	No operands	Compare words: ES:[DI] from DS:[SI]. Algorithm: • DS:[SI] - ES:[DI] • set flags according to result: OF, SF, ZF, AF, PF, CF • if DF = 0 then o SI = SI + 2 o DI = DI + 2 else o SI = SI - 2 o DI = DI - 2

8086 instructions Page 9 of 53

		example: open cmpsw.asm from c:\emu8086\examples CZSOPA rrrrr
CWD	No operands	Convert Word to Double word. Algorithm: if high bit of AX = 1 then: • DX = 65535 (OFFFFh) else • DX = 0 Example: MOV DX, 0 ; DX = 0 MOV AX, 0 ; AX = 0 MOV AX, 0 ; AX = 0 MOV AX, -5 ; DX AX = 00000h:0FFFBh CWD ; DX AX = 0FFFFh:0FFFBh RET CZSOPA unchanged
DAA	No operands	Decimal adjust After Addition. Corrects the result of addition of two packed BCD values. Algorithm: if low nibble of AL > 9 or AF = 1 then: • AL = AL + 6 • AF = 1 if AL > 9Fh or CF = 1 then: • AL = AL + 60h • CF = 1 Example:

8086 instructions Page 10 of 53

		MOV AL, 0Fh; AL = 0Fh (15) DAA; AL = 15h RET CZSOPA rrrrr
		Decimal adjust After Subtraction. Corrects the result of subtraction of two packed BCD values.
		Algorithm:
		if low nibble of AL > 9 or AF = 1 then:
		• AL = AL - 6 • AF = 1
		if AL > 9Fh or CF = 1 then:
DAS	No operands	• AL = AL - 60h • CF = 1
		Example:
		MOV AL, 0FFh ; AL = 0FFh (-1) DAS ; AL = 99h, CF = 1 RET
		CZSOPA
		Decrement.
	REG memory	Algorithm:
		operand = operand - 1
DEC		Example:
		MOV AL, 255 ; AL = 0FFh (255 or -1) DEC AL ; AL = 0FEh (254 or -2) RET
		ZSOPA
		CF - unchanged!

8086 instructions Page 11 of 53

		Unsigned divide.
		Algorithm:
		when operand is a byte :
		AL = AX / operand AH = remainder (modulus)
		when operand is a word : AX = (DX AX) / operand
DIV	REG	DX = remainder (modulus)
	memory	Example:
		MOV AX, 203 ; AX = 00CBh MOV BL, 4
		DIV BL ; AL = 50 (32h), AH = 3 RET
		C Z S O P A ? ? ? ? ?
	No operands	Halt the System.
		Example:
		MOV AX, 5
HLT		HLT
		CZSOPA
		unchanged
	REG memory	
		Signed divide.
		Algorithm:
		when operand is a byte :
		AL = AX / operand AH = remainder (modulus)
IDIV		when operand is a word :
		AX = (DX AX) / operand DX = remainder (modulus)
		Example:
		MOV AX, -203 ; AX = 0FF35h MOV BL, 4
		IDIV BL ; AL = -50 (OCEh), AH = -3 (OFDh) RET
l l	ıı	1

8086 instructions Page 12 of 53

		CZSOPA ??????
		Signed multiply.
		Algorithm: when operand is a byte : AX = AL * operand.
		when operand is a word : (DX AX) = AX * operand.
IMUL	REG memory	Example: MOV AL, -2 MOV BL, -4 IMUL BL ; AX = 8 RET
		CZSOPA r??r?? CF=OF=0 when result fits into operand of IMUL.
IN	AL, im.byte AL, DX AX, im.byte AX, DX	Input from port into AL or AX. Second operand is a port number. If required to access port number over 255 - DX register should be used. Example: IN AX, 4 ; get status of traffic lights. IN AL, 7 ; get status of stepper-motor. CZSOPA unchanged
INC	REG memory	Increment. Algorithm: operand = operand + 1 Example: MOV AL, 4 INC AL ; AL = 5

8086 instructions Page 13 of 53

		ZSOPA rrrr CF - unchanged!
INT	immediate byte	Interrupt numbered by immediate byte (0255). Algorithm: Push to stack: o flags register o CS o IP IF = 0 Transfer control to interrupt procedure Example: MOV AH, 0Eh ; teletype. MOV AL, 'A' INT 10h ; BIOS interrupt. RET CZSOPAI unchanged 0
INTO	No operands	Interrupt 4 if Overflow flag is 1. Algorithm: if OF = 1 then INT 4 Example: ; -5 - 127 = -132 (not in -128127); the result of SUB is wrong (124),; so OF = 1 is set: MOV AL, -5 SUB AL, 127 ; AL = 7Ch (124) INTO ; process error. RET
		Interrupt Return.

8086 instructions Page 14 of 53

IRET	No operands	Algorithm: Pop from stack: O IP OCS O flags register CZSOPA popped
JA	label	Short Jump if first operand is Above second operand (as set by CMP instruction). Unsigned. Algorithm: if (CF = 0) and (ZF = 0) then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 250 CMP AL, 5 JA label1 PRINT 'AL is not above 5' JMP exit label1: PRINT 'AL is above 5' exit: RET CZSOPA unchanged
JAE	label	Short Jump if first operand is Above or Equal to second operand (as set by CMP instruction). Unsigned. Algorithm: if CF = 0 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 5 CMP AL, 5 JAE label1 PRINT 'AL is not above or equal to 5' JMP exit label1:

8086 instructions Page 15 of 53

		PRINT 'AL is above or equal to 5' exit: RET CZSOPA unchanged
JB	label	Short Jump if first operand is Below second operand (as set by CMP instruction). Unsigned. Algorithm: if CF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 1 CMP AL, 5 JB label1 PRINT 'AL is not below 5' JMP exit label1: PRINT 'AL is below 5' exit: RET CZSOPA unchanged
JBE	label	Short Jump if first operand is Below or Equal to second operand (as set by CMP instruction). Unsigned. Algorithm: if CF = 1 or ZF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 5 CMP AL, 5 JBE label1 PRINT 'AL is not below or equal to 5' JMP exit label1: PRINT 'AL is below or equal to 5' exit: RET

8086 instructions Page 16 of 53

		CZSOPA unchanged
JC	label	Short Jump if Carry flag is set to 1. Algorithm: if CF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 255 ADD AL, 1 JC label1 PRINT 'no carry.' JMP exit label1: PRINT 'has carry.' exit: RET CZSOPA unchanged
JCXZ	label	Short Jump if CX register is 0. Algorithm: if CX = 0 then jump Example: include 'emu8086.inc' ORG 100h MOV CX, 0 JCXZ labell PRINT 'CX is not zero.' JMP exit label1: PRINT 'CX is zero.' exit: RET CZSOPA unchanged
		Short Jump if first operand is Equal to second operand (as set by CMP instruction).

8086 instructions Page 17 of 53

		Signed/Unsigned.
		Algorithm:
		if ZF = 1 then jump
		Example:
JE	label	<pre>include 'emu8086.inc' ORG 100h MOV AL, 5 CMP AL, 5 JE label1 PRINT 'AL is not equal to 5.' JMP exit label1: PRINT 'AL is equal to 5.' exit: RET</pre>
		CZSOPA unchanged
JG	label	Short Jump if first operand is Greater then second operand (as set by CMP instruction). Signed. Algorithm: if (ZF = 0) and (SF = OF) then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 5 CMP AL, -5 JG label1 PRINT 'AL is not greater -5.' JMP exit label1: PRINT 'AL is greater -5.' exit: RET
		C Z S O P A unchanged
		Short Jump if first operand is Greater or Equal to second operand (as set by CMP instruction). Signed.
		Algorithm:
ĮI	II I	II I

8086 instructions Page 18 of 53

```
if SF = OF then jump
                                     Example:
                                        include 'emu8086.inc'
                                        ORG 100h
                                       MOV AL, 2
                                       CMP AL, -5
                                       JGE label1
                                       PRINT 'AL < -5'
JGE
             label
                                       JMP exit
                                     label1:
                                       PRINT 'AL >= -5'
                                     exit:
                                       RET
                                     C||Z||S||0||P||A
                                     unchanged
                                     Short Jump if first operand is Less then second
                                     operand (as set by CMP instruction). Signed.
                                     Algorithm:
                                          if SF <> OF then jump
                                     Example:
                                        include 'emu8086.inc'
                                        ORG 100h
                                       MOV AL, -2
JL
             label
                                       CMP AL, 5
                                       JL label1
                                        PRINT 'AL >= 5.'
                                       JMP exit
                                     label1:
                                        PRINT 'AL < 5.'
                                     exit:
                                        RET
                                     unchanged
                                     Short Jump if first operand is Less or Equal to
                                     second operand (as set by CMP instruction).
                                     Signed.
                                     Algorithm:
                                          if SF <> OF or ZF = 1 then jump
                                     Example:
```

8086 instructions Page 19 of 53

JLE	label	<pre>include 'emu8086.inc' ORG 100h MOV AL, -2 CMP AL, 5 JLE label1 PRINT 'AL > 5.' JMP exit label1: PRINT 'AL <= 5.' exit: RET</pre> CZSOPA unchanged
JMP	label 4-byte address	Unconditional Jump. Transfers control to another part of the program. 4-byte address may be entered in this form: 1234h:5678h, first value is a segment second value is an offset. Algorithm: always jump Example: include 'emu8086.inc' ORG 100h MOV AL, 5 JMP label1 ; jump over 2 lines! PRINT 'Not Jumped!' MOV AL, 0 label1: PRINT 'Got Here!' RET CZSOPA unchanged
JNA	label	Short Jump if first operand is Not Above second operand (as set by CMP instruction). Unsigned. Algorithm: if CF = 1 or ZF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2

8086 instructions Page 20 of 53

		CMP AL, 5 JNA label1 PRINT 'AL is above 5.' JMP exit label1: PRINT 'AL is not above 5.' exit: RET CZSOPA unchanged
JNAE	label	Short Jump if first operand is Not Above and Not Equal to second operand (as set by CMP instruction). Unsigned. Algorithm: if CF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2 CMP AL, 5 JNAE label1 PRINT 'AL >= 5.' JMP exit label1: PRINT 'AL < 5.' exit: RET CZSOPA unchanged
JNB	label	Short Jump if first operand is Not Below second operand (as set by CMP instruction). Unsigned. Algorithm: if CF = 0 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 7 CMP AL, 5 JNB label1 PRINT 'AL < 5.'

8086 instructions Page 21 of 53

		JMP exit label1: PRINT 'AL >= 5.' exit: RET CZSOPA unchanged
JNBE	label	Short Jump if first operand is Not Below and Not Equal to second operand (as set by CMP instruction). Unsigned. Algorithm: if (CF = 0) and (ZF = 0) then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 7 CMP AL, 5 JNBE label1 PRINT 'AL <= 5.' JMP exit label1: PRINT 'AL > 5.' exit: RET CZSOPA unchanged
JNC	label	Short Jump if Carry flag is set to 0. Algorithm: if CF = 0 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2 ADD AL, 3 JNC label1 PRINT 'has carry.' JMP exit label1: PRINT 'no carry.' exit:

8086 instructions Page 22 of 53

lı	11	
		CZSOPA unchanged
JNE	label	Short Jump if first operand is Not Equal to second operand (as set by CMP instruction). Signed/Unsigned. Algorithm: if ZF = 0 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2 CMP AL, 3 JNE label1 PRINT 'AL = 3.' JMP exit label1: PRINT 'Al <> 3.' exit: RET CZSOPA unchanged
JNG	label	Short Jump if first operand is Not Greater then second operand (as set by CMP instruction). Signed. Algorithm: if (ZF = 1) and (SF <> OF) then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2 CMP AL, 3 JNG label1 PRINT 'AL > 3.' JMP exit label1: PRINT 'Al <= 3.' exit: RET

8086 instructions Page 23 of 53

		CZSOPA unchanged
JNGE	label	Short Jump if first operand is Not Greater and Not Equal to second operand (as set by CMP instruction). Signed. Algorithm: if SF <> OF then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2 CMP AL, 3 JNGE label1 PRINT 'AL >= 3.' JMP exit label1: PRINT 'Al < 3.' exit: RET CZSOPA unchanged
JNL	label	Short Jump if first operand is Not Less then second operand (as set by CMP instruction). Signed. Algorithm: if SF = OF then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 2 CMP AL, -3 JNL label1 PRINT 'AL < -3.' JMP exit label1: PRINT 'Al >= -3.' exit: RET

8086 instructions Page 24 of 53

		unchanged
		Short Jump if first operand is Not Less and Not Equal to second operand (as set by CMP instruction). Signed.
		Algorithm:
		if (SF = OF) and (ZF = 0) then jump
		Example:
		include 'emu8086.inc'
JNLE	label	ORG 100h MOV AL, 2 CMP AL, -3 JNLE label1 PRINT 'AL <= -3.' JMP exit label1: PRINT 'Al > -3.' exit: RET CZSOPA unchanged
	label	Short Jump if Not Overflow.
		Algorithm:
		if OF = 0 then jump
JNO		<pre>Example: ; -5 - 2 = -7 (inside -128127) ; the result of SUB is correct, ; so OF = 0:</pre>
		include 'emu8086.inc'
		ORG 100h MOV AL, -5 SUB AL, 2 ; AL = 0F9h (-7) JNO label1 PRINT 'overflow!' JMP exit label1: PRINT 'no overflow.' exit: RET

8086 instructions Page 25 of 53

		unchanged
		Short Jump if No Parity (odd). Only 8 low bits of result are checked. Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions.
		Algorithm:
		if PF = 0 then jump
		Example:
		include 'emu8086.inc'
JNP	label	ORG 100h MOV AL, 00000111b ; AL = 7 OR AL, 0 ; just set flags. JNP label1 PRINT 'parity even.' JMP exit label1: PRINT 'parity odd.' exit: RET
		CZSOPA unchanged
	label	Short Jump if Not Signed (if positive). Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions.
		Algorithm:
		if SF = 0 then jump
		Example:
JNS		include 'emu8086.inc'
UND		ORG 100h MOV AL, 00000111b ; AL = 7 OR AL, 0 ; just set flags. JNS label1 PRINT 'signed.' JMP exit label1: PRINT 'not signed.' exit: RET
		CZSOPA unchanged

8086 instructions Page 26 of 53

		Short Jump if Not Zero (not equal). Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions.
		Algorithm:
		if ZF = 0 then jump
		Example:
		include 'emu8086.inc'
JNZ	label	ORG 100h MOV AL, 00000111b ; AL = 7 OR AL, 0 ; just set flags. JNZ label1 PRINT 'zero.' JMP exit label1: PRINT 'not zero.' exit: RET
		CZSOPA unchanged
		Short Jump if Overflow.
		Algorithm:
		if OF = 1 then jump
		Example:
		; -5 - 127 = -132 (not in -128127) ; the result of SUB is wrong (124), ; so OF = 1 is set:
		include 'emu8086.inc'
JO	label	<pre>include 'emu8086.inc' org 100h MOV AL, -5 SUB AL, 127 ; AL = 7Ch (124) JO label1 PRINT 'no overflow.' JMP exit label1: PRINT 'overflow!' exit: RET</pre>
		CZSOPA unchanged

8086 instructions Page 27 of 53

		Short Jump if Parity (even). Only 8 low bits of result are checked. Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions.
		Algorithm:
		if PF = 1 then jump
		Example:
		include 'emu8086.inc'
JP	label	ORG 100h MOV AL, 00000101b ; AL = 5 OR AL, 0 ; just set flags. JP label1 PRINT 'parity odd.' JMP exit label1: PRINT 'parity even.' exit: RET
		CZSOPA unchanged
		Short Jump if Parity Even. Only 8 low bits of result are checked. Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions.
		Algorithm:
		if PF = 1 then jump
		Example:
		include 'emu8086.inc'
JPE	label	ORG 100h MOV AL, 00000101b ; AL = 5 OR AL, 0 ; just set flags. JPE label1 PRINT 'parity odd.' JMP exit label1: PRINT 'parity even.' exit: RET
		CZSOPA unchanged
		Short Jump if Parity Odd. Only 8 low bits of result

8086 instructions Page 28 of 53

JPO	label	are checked. Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions. Algorithm: if PF = 0 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 0000011lb ; AL = 7 OR AL, 0 ; just set flags. JPO label1 PRINT 'parity even.' JMP exit label1: PRINT 'parity odd.' exit: RET CZSOPA unchanged
JS	label	Short Jump if Signed (if negative). Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions. Algorithm: if SF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 10000000b ; AL = -128 OR AL, 0 ; just set flags. JS label1 PRINT 'not signed.' JMP exit label1: PRINT 'signed.' exit: RET CZSOPA unchanged
		Short Jump if Zero (equal). Set by CMP, SUB, ADD, TEST, AND, OR, XOR instructions.

8086 instructions Page 29 of 53

		Algorithm:
JZ	label	<pre>if ZF = 1 then jump Example: include 'emu8086.inc' ORG 100h MOV AL, 5 CMP AL, 5 JZ label1 PRINT 'AL is not equal to 5.' JMP exit label1: PRINT 'AL is equal to 5.' exit: RET CZSOPA unchanged</pre>
LAHF	No operands	Load AH from 8 low bits of Flags register. Algorithm: AH = flags register AH bit: 7 6 5 4 3 2 1 0 [SF] [ZF] [0] [AF] [0] [PF] [1] [CF] bits 1, 3, 5 are reserved. CZSOPA unchanged
		Load memory double word into word register and DS. Algorithm: • REG = first word • DS = second word Example: ORG 100h

8086 instructions Page 30 of 53

l.		
LDS	REG, memory	LDS AX, m RET m DW 1234h DW 5678h END AX is set to 1234h, DS is set to 5678h. CZSOPA unchanged
LEA	REG, memory	Algorithm: • REG = address of memory (offset) Example: MOV BX, 35h MOV DI, 12h LEA SI, [BX+DI] ; SI = 35h + 12h = 47h Note: The integrated 8086 assembler automatically replaces LEA with a more efficient MOV where possible. For example: org 100h LEA AX, m ; AX = offset of m RET m dw 1234h END CZSOPA unchanged
		Load memory double word into word register and ES. Algorithm:

8086 instructions Page 31 of 53

LES	REG, memory	• REG = first word • ES = second word Example: ORG 100h LES AX, m RET m DW 1234h DW 5678h END AX is set to 1234h, ES is set to 5678h. CZSOPA unchanged
LODSB	No operands	Load byte at DS:[SI] into AL. Update SI. Algorithm: • AL = DS:[SI] • if DF = 0 then • o SI = SI + 1 else • o SI = SI - 1 Example: ORG 100h LEA SI, al MOV CX, 5 MOV AH, 0Eh m: LODSB INT 10h LOOP m RET al DB 'H', 'e', 'l', 'l', 'o' CZSOPA unchanged

8086 instructions Page 32 of 53

		Load word at DS:[SI] into AX. Update SI.
		Algorithm:
		• AX = DS:[SI] • if DF = 0 then
		Example:
LODSW	No operands	ORG 100h
		LEA SI, al MOV CX, 5
		REP LODSW ; finally there will be 555h in AX.
		RET
		al dw 111h, 222h, 333h, 444h, 555h
		CZSOPA unchanged
		Decrease CX, jump to label if CX not zero.
		Algorithm:
		• CX = CX - 1
		• if CX <> 0 then o jump
		else o no jump, continue
		Example:
LOOP	label	include 'emu8086.inc'
		ORG 100h
		MOV CX, 5 label1: PRINTN 'loop!' LOOP label1 RET
		CZSOPA unchanged

8086 instructions Page 33 of 53

		Decrease CX, jump to label if CX not zero and Equal (ZF = 1).
		Algorithm:
		 CX = CX - 1 if (CX <> 0) and (ZF = 1) then jump else no jump, continue
		Example:
LOOPE	label	; Loop until result fits into AL alone, ; or 5 times. The result will be over 255 ; on third loop (100+100+100), ; so loop will exit.
		include 'emu8086.inc'
		ORG 100h MOV AX, 0 MOV CX, 5 label1: PUTC '*' ADD AX, 100 CMP AH, 0 LOOPE label1 RET
		CZSOPA unchanged
LOOPNE		Decrease CX, jump to label if CX not zero and Not Equal (ZF = 0).
		; or 5 times. The result will be over 255 ; on third loop (100+100+100), ; so loop will exit. include 'emu8086.inc' ORG 100h MOV AX, 0 MOV CX, 5 label1: PUTC '*' ADD AX, 100 CMP AH, 0 LOOPE label1 RET CZSOPA unchanged Decrease CX, jump to label if CX not zero and Not
	label	
		Example:
		; or 5 times.
		OKG 100H

8086 instructions Page 34 of 53

```
MOV SI, 0
                                       MOV CX, 5
                                    label1:
                                       PUTC '*'
                                       MOV AL, v1[SI]
                                       INC SI
                                                ; next byte (SI=SI+1).
                                       CMP AL, 7
                                       LOOPNE label1
                                       v1 db 9, 8, 7, 6, 5
                                     unchanged
                                    Decrease CX, jump to label if CX not zero and ZF
                                    = 0.
                                    Algorithm:
                                       • CX = CX - 1
                                       • if (CX <> 0) and (ZF = 0) then
                                            o jump
                                         else
                                            o no jump, continue
                                    Example:
                                    ; Loop until '7' is found,
                                    ; or 5 times.
LOOPNZ
             label
                                       include 'emu8086.inc'
                                       ORG 100h
                                       MOV SI, 0
                                       MOV CX, 5
                                    label1:
                                       PUTC '*'
                                       MOV AL, v1[SI]
                                                ; next byte (SI=SI+1).
                                       INC SI
CMP AL, 7
                                       LOOPNZ label1
                                       v1 db 9, 8, 7, 6, 5
                                     unchanged
                                    Decrease CX, jump to label if CX not zero and ZF
                                    = 1.
                                    Algorithm:
                                       \bullet CX = CX - 1
```

8086 instructions Page 35 of 53

```
• if (CX <> 0) and (ZF = 1) then
                                               o jump
                                            else
                                               o no jump, continue
                                       Example:
                                       ; Loop until result fits into AL alone,
                                       ; or 5 times. The result will be over 255
                                       ; on third loop (100+100+100),
                                       ; so loop will exit.
                                          include 'emu8086.inc'
LOOPZ
              label
                                          ORG 100h
                                          MOV AX, 0
                                          MOV CX, 5
                                       label1:
                                          PUTC '*'
                                          ADD AX, 100
                                          CMP AH, 0
                                          LOOPZ label1
                                        unchanged
                                       Copy operand2 to operand1.
                                       The MOV instruction cannot:

    set the value of the CS and IP registers.

    copy value of one segment register to

                                            another segment register (should copy to
                                            general register first).

    copy immediate value to segment register

              REG, memory
                                            (should copy to general register first).
              memory, REG
              REG, REG
              memory, immediate
                                       Algorithm:
              REG, immediate
MOV
                                            operand1 = operand2
              SREG, memory
              memory, SREG
                                       Example:
              REG, SREG
              SREG, REG
                                       ORG 100h
                                       MOV AX, OB800h ; set AX = B800h (VGA memory).
                                       MOV DS, AX ; copy value of AX to DS. MOV CL, 'A' ; CL = 41h (ASCII code).
                                       MOV CH, 01011111b ; CL = color attribute.
                                       MOV BX, 15Eh ; BX = position on screen. MOV [BX], CX ; w.[0B800h:015Eh] = CX.
                                       RET
                                                          ; returns to operating system.
```

8086 instructions Page 36 of 53

		C Z S O P A unchanged
MOVSB	No operands	Copy byte at DS: [SI] to ES: [DI]. Update SI and DI. Algorithm: • ES: [DI] = DS: [SI] • if DF = 0 then • SI = SI + 1 • DI = DI + 1 else • SI = SI - 1 • DI = DI - 1 Example: ORG 100h CLD LEA SI, a1 LEA DI, a2 MOV CX, 5 REP MOVSB RET a1 DB 1,2,3,4,5 a2 DB 5 DUP(0) CZZ SOPA unchanged
		Copy word at DS:[SI] to ES:[DI]. Update SI and DI. Algorithm: • ES:[DI] = DS:[SI] • if DF = 0 then • SI = SI + 2 • DI = DI + 2 else • SI = SI - 2 • DI = DI - 2 Example:

8086 instructions Page 37 of 53

MOVSW	No operands	ORG 100h CLD LEA SI, a1 LEA DI, a2 MOV CX, 5 REP MOVSW RET a1 DW 1,2,3,4,5 a2 DW 5 DUP(0) CZSOPA unchanged
MUL	REG	Unsigned multiply. Algorithm: when operand is a byte: AX = AL * operand. when operand is a word: (DX AX) = AX * operand. Example: MOV AL, 200 ; AL = 0C8h MOV BL, 4 MUL BL ; AX = 0320h (800) RET CZSOPA r??r?? CF=OF=0 when high section of the result is zero.
NEG	REG memory	Negate. Makes operand negative (two's complement). Algorithm: • Invert all bits of the operand • Add 1 to inverted operand Example: MOV AL, 5 ; AL = 05h NEG AL ; AL = 0FBh (-5) NEG AL ; AL = 05h (5)

8086 instructions Page 38 of 53

		CZSOPA rrrrr
NOP	No operands	No Operation. Algorithm: • Do nothing Example: ; do nothing, 3 times: NOP NOP NOP NOP RET CZSOPA unchanged
NOT	REG memory	Invert each bit of the operand. Algorithm: • if bit is 1 turn it to 0. • if bit is 0 turn it to 1. Example: MOV AL, 00011011b NOT AL ; AL = 11100100b RET CZSOPA unchanged
	REG, memory	Logical OR between all bits of two operands. Result is stored in first operand. These rules apply: 1 OR 1 = 1 1 OR 0 = 1 0 OR 1 = 1 0 OR 0 = 0

8086 instructions Page 39 of 53

OR	memory, REG REG, REG memory, immediate REG, immediate	Example: MOV AL, 'A' ; AL = 01000001b OR AL, 00100000b ; AL = 01100001b ('a') RET CZSOPA Orror?
OUT	im.byte, AL im.byte, AX DX, AL DX, AX	Output from AL or AX to port. First operand is a port number. If required to access port number over 255 - DX register should be used. Example: MOV AX, OFFFh; Turn on all OUT 4, AX; traffic lights. MOV AL, 100b; Turn on the third OUT 7, AL; magnet of the stepper-motor. CZSOPA unchanged
POP	REG SREG memory	Get 16 bit value from the stack. Algorithm: • operand = SS:[SP] (top of the stack) • SP = SP + 2 Example: MOV AX, 1234h PUSH AX POP DX ; DX = 1234h RET CZSOPA unchanged
		Pop all general purpose registers DI, SI, BP, SP, BX, DX, CX, AX from the stack.

8086 instructions Page 40 of 53

		SP value is ignored, it is Popped but not set to SP
		register). Note: this instruction works only on 80186 CPU
		and later!
		Algorithm:
POPA	No operands	 POP DI POP SI POP BP POP xx (SP value ignored) POP BX POP DX POP CX POP AX
		CZSOPA unchanged
		Get flags register from the stack.
		Algorithm:
POPF	No operands	• flags = SS:[SP] (top of the stack) • SP = SP + 2
		CZSOPA popped
		Store 16 bit value in the stack.
		Note: PUSH immediate works only on 80186 CPU and later!
		Algorithm:
PUSH	REG SREG memory immediate	• SP = SP - 2 • SS:[SP] (top of the stack) = operand
		Example:
		MOV AX, 1234h PUSH AX POP DX ; DX = 1234h RET

8086 instructions Page 41 of 53

		CZSOPA unchanged
		Push all general purpose registers AX, CX, DX, BX, SP, BP, SI, DI in the stack. Original value of SP register (before PUSHA) is used.
		Note: this instruction works only on 80186 CPU and later!
		Algorithm:
PUSHA	No operands	 PUSH AX PUSH CX PUSH DX PUSH BX PUSH SP PUSH BP PUSH SI PUSH DI
		CZSOPA unchanged
		Store flags register in the stack.
		Algorithm:
PUSHF	No operands	• SP = SP - 2 • SS:[SP] (top of the stack) = flags CZSOPA unchanged
		Rotate operand1 left through Carry Flag. The number of rotates is set by operand2. When immediate is greater then 1, assembler generates several RCL xx, 1 instructions because 8086 has machine code only for this instruction (the same principle works for all other shift/rotate instructions). Algorithm:

8086 instructions Page 42 of 53

RCL	memory, immediate REG, immediate memory, CL REG, CL	shift all bits left, the bit that goes off is set to CF and previous value of CF is inserted to the right-most position. Example: STC
RCR	memory, immediate REG, immediate memory, CL REG, CL	Rotate operand1 right through Carry Flag. The number of rotates is set by operand2. Algorithm: shift all bits right, the bit that goes off is set to CF and previous value of CF is inserted to the left-most position. Example: STC
		Repeat following MOVSB, MOVSW, LODSB, LODSW, STOSB, STOSW instructions CX times. Algorithm: check_cx: if CX <> 0 then • do following chain instruction

8086 instructions Page 43 of 53

REP	chain instruction	• CX = CX - 1 • go back to check_cx else • exit from REP cycle
REPE	chain instruction	Repeat following CMPSB, CMPSW, SCASB, SCASW instructions while ZF = 1 (result is Equal), maximum CX times. Algorithm: check_cx: if CX <> 0 then • do following chain instruction • CX = CX - 1 • if ZF = 1 then:
		Repeat following CMPSB, CMPSW, SCASB, SCASW instructions while ZF = 0 (result is Not Equal), maximum CX times. Algorithm: check_cx: if CX <> 0 then • do following chain instruction

8086 instructions Page 44 of 53

REPNE	chain instruction	• CX = CX - 1 • if ZF = 0 then: o go back to check_cx else o exit from REPNE cycle else • exit from REPNE cycle
REPNZ	chain instruction	Repeat following CMPSB, CMPSW, SCASB, SCASW instructions while ZF = 0 (result is Not Zero), maximum CX times. Algorithm: check_cx: if CX <> 0 then • do following chain instruction • CX = CX - 1 • if ZF = 0 then:
		Repeat following CMPSB, CMPSW, SCASB, SCASW instructions while ZF = 1 (result is Zero), maximum CX times. Algorithm: check_cx: if CX <> 0 then

8086 instructions Page 45 of 53

REPZ	chain instruction	• do following chain instruction • CX = CX - 1 • if ZF = 1 then: o go back to check_cx else o exit from REPZ cycle else • exit from REPZ cycle
RET	No operands or even immediate	Return from near procedure. Algorithm: • Pop from stack: o IP • if immediate operand is present: SP = SP + operand Example: ORG 100h ; for COM file. CALL p1 ADD AX, 1 RET ; return to OS. p1 PROC ; procedure declaration. MOV AX, 1234h RET ; return to caller. p1 ENDP CZSOPA unchanged
RETF	No operands or even immediate	Return from Far procedure. Algorithm: • Pop from stack: • IP • CS • if immediate operand is present:

8086 instructions Page 46 of 53

lı .	1	1
		SP = SP + operand
		CZSOPA unchanged
		Rotate operand1 left. The number of rotates is set by operand2.
		Algorithm:
	memory, immediate	shift all bits left, the bit that goes off is set to CF and the same bit is inserted to the right-most position.
ROL	REG, immediate	Example:
	memory, CL REG, CL	MOV AL, 1Ch ; AL = 00011100b ROL AL, 1 ; AL = 00111000b, CF=0. RET
		CO rr OF=0 if first operand keeps original sign.
		Rotate operand1 right. The number of rotates is set by operand2.
	memory, immediate REG, immediate memory, CL REG, CL	Algorithm:
		shift all bits right, the bit that goes off is set to CF and the same bit is inserted to the left-most position.
ROR		Example:
		MOV AL, 1Ch ; AL = 00011100b ROR AL, 1 ; AL = 00001110b, CF=0. RET
		CO rr OF=0 if first operand keeps original sign.
		Store AH register into low 8 bits of Flags register.
		Algorithm:

8086 instructions Page 47 of 53

		flags register = AH
SAHF	No operands	AH bit: 7 6 5 4 3 2 1 0 [SF] [ZF] [0] [AF] [0] [PF] [1] [CF] bits 1, 3, 5 are reserved. CZSOPA rrrrr
SAL	memory, immediate REG, immediate memory, CL REG, CL	Shift Arithmetic operand1 Left. The number of shifts is set by operand2. Algorithm: • Shift all bits left, the bit that goes off is set to CF. • Zero bit is inserted to the right-most position. Example: MOV AL, 0E0h ; AL = 11100000b SAL AL, 1 ; AL = 11000000b, CF=1. RET COO rr OF=0 if first operand keeps original sign.
SAR	memory, immediate REG, immediate memory, CL REG, CL	Shift Arithmetic operand1 Right. The number of shifts is set by operand2. Algorithm: • Shift all bits right, the bit that goes off is set to CF. • The sign bit that is inserted to the left-most position has the same value as before shift. Example: MOV AL, 0E0h ; AL = 11100000b SAR AL, 1 ; AL = 111100000b, CF=0. MOV BL, 4Ch ; BL = 01001100b SAR BL, 1 ; BL = 01001100b, CF=0. RET

8086 instructions Page 48 of 53

		CO rr OF=0 if first operand keeps original sign.
SBB	REG, memory memory, REG REG, REG memory, immediate REG, immediate	Subtract with Borrow. Algorithm: operand1 = operand1 - operand2 - CF Example: STC MOV AL, 5 SBB AL, 3 ; AL = 5 - 3 - 1 = 1 RET CZSOPA rrrrrr
SCASB	No operands	Compare bytes: AL from ES:[DI]. Algorithm: • AL - ES:[DI] • set flags according to result: OF, SF, ZF, AF, PF, CF • if DF = 0 then o DI = DI + 1 else o DI = DI - 1 CZSOPA rrrrrr
SCASW	No operands	Compare words: AX from ES:[DI]. Algorithm: • AX - ES:[DI] • set flags according to result: OF, SF, ZF, AF, PF, CF • if DF = 0 then o DI = DI + 2

8086 instructions Page 49 of 53

		else o DI = DI - 2 CZSOPA rrrrr
SHL	memory, immediate REG, immediate memory, CL REG, CL	Shift operand1 Left. The number of shifts is set by operand2. Algorithm: • Shift all bits left, the bit that goes off is set to CF. • Zero bit is inserted to the right-most position. Example: MOV AL, 11100000b SHL AL, 1 ; AL = 11000000b, CF=1. RET CO Tr OF=0 if first operand keeps original sign.
SHR	memory, immediate REG, immediate memory, CL REG, CL	Shift operand1 Right. The number of shifts is set by operand2. Algorithm: • Shift all bits right, the bit that goes off is set to CF. • Zero bit is inserted to the left-most position. Example: MOV AL, 00000111b SHR AL, 1 ; AL = 00000011b, CF=1. RET CO Tr OF=0 if first operand keeps original sign.

8086 instructions Page 50 of 53

		I I
STC	No operands	Set Carry flag.
		Algorithm:
		CF = 1
510		
		Set Direction flag. SI and DI will be decremented by chain instructions: CMPSB, CMPSW, LODSB, LODSW, MOVSB, MOVSW, STOSB, STOSW.
		Algorithm:
STD	No operands	DF = 1
	No operands	Set Interrupt enable flag. This enables hardware interrupts.
		Algorithm:
STI		IF = 1
	No operands	Store byte in AL into ES:[DI]. Update DI.
		Algorithm:
		• ES:[DI] = AL
		• if DF = 0 then o DI = DI + 1
STOSB		else o DI = DI - 1
		Example:
		ORG 100h
		LEA DI, al

8086 instructions Page 51 of 53

		MOV AL, 12h MOV CX, 5 REP STOSB RET al DB 5 dup(0) CZSOPA unchanged]
STOSW	No operands	Store word in AX into ES:[DI]. Update DI. Algorithm: • ES:[DI] = AX • if DF = 0 then • DI = DI + 2 else • DI = DI - 2 Example: ORG 100h LEA DI, a1 MOV AX, 1234h MOV CX, 5 REP STOSW RET a1 DW 5 dup(0) CZSOPA unchanged	
SUB	REG, memory memory, REG REG, REG memory, immediate REG, immediate	Subtract. Algorithm: operand1 = operand1 - operand2 Example: MOV AL, 5 SUB AL, 1 ; AL = 4 RET	

8086 instructions Page 52 of 53

		CZSOPA rrrrr
TEST	REG, memory memory, REG REG, REG memory, immediate REG, immediate	Logical AND between all bits of two operands for flags only. These flags are effected: ZF, SF, PF. Result is not stored anywhere. These rules apply: 1 AND 1 = 1 1 AND 0 = 0 0 AND 1 = 0 0 AND 0 = 0 Example: MOV AL, 00000101b TEST AL, 1 ; ZF = 0. TEST AL, 10b ; ZF = 1. RET CZSOP Orror
XCHG	REG, memory memory, REG REG, REG	Exchange values of two operands. Algorithm: operand1 < - > operand2 Example: MOV AL, 5 MOV AH, 2 XCHG AL, AH ; AL = 2, AH = 5 XCHG AL, AH ; AL = 5, AH = 2 RET CZSOPA unchanged
		Translate byte from table. Copy value of memory byte at DS:[BX + unsigned AL] to AL register. Algorithm:

8086 instructions Page 53 of 53

XLATB	No operands	AL = DS:[BX + unsigned AL] Example: ORG 100h LEA BX, dat MOV AL, 2 XLATB ; AL = 33h RET dat DB 11h, 22h, 33h, 44h, 55h CZSOPA unchanged
XOR	REG, memory memory, REG REG, REG memory, immediate REG, immediate	Logical XOR (Exclusive OR) between all bits of two operands. Result is stored in first operand. These rules apply: 1 XOR 1 = 0 1 XOR 0 = 1 0 XOR 1 = 1 0 XOR 0 = 0 Example: MOV AL, 00000111b XOR AL, 00000101b RET CZSOPA Orror