
Waleed Binselim Embedded Linux Assignment 3



fritzing

```
import RPi.GPIO as GPIO
import time
GPIO.setmode (GPIO.BCM)
GPIO.setup(18,GPIO.OUT)
print "PRESS CTRL+C TO QUIT THE INFINITE LOOP"
def Blink():
 for i in range(0,3):
        print "blink number" + str(i + 1)
        GPIO.output (18, True)
        time.sleep(0.1)
        GPIO.output (18, False)
        time.sleep(0.1)
 time.sleep(1)
 for i in range(0,4):
       print "blink number" + str(i + 1)
       GPIO.output (18, True)
       time.sleep(0.1)
       GPIO.output(18,False)
       time.sleep(0.1)
 time.sleep(1)
while True:
      Blink()
print "done"
GPIO.cleanup()
```

