

坐标系A中的惯性张量可以用3*3矩阵表示如下:

$${}^{A}{
m I} = \left[egin{array}{ccc} I_{xx} & -I_{xy} & -I_{xz} \ -I_{xy} & I_{yy} & -I_{yz} \ -I_{xz} & -I_{yz} & I_{zz} \end{array}
ight]$$

矩阵中各元素的计算方法为:

$$egin{aligned} I_{xx} &= \iiint_V \left(y^2 + z^2
ight)
ho dv \ I_{yy} &= \iiint_V \left(x^2 + z^2
ight)
ho dv \ I_{zz} &= \iiint_V \left(x^2 + y^2
ight)
ho dv \ I_{xy} &= \iiint_V (xy)
ho dv \ I_{xz} &= \iiint_V (xz)
ho dv \ I_{yz} &= \iiint_V (yz)
ho dv \end{aligned}$$

已知 $L_1=1m, L_2=0.5m, \rho=7806kg/m^3,$ 宽度 =0.05m,厚度 =0.05m,以两部分机械臂的质心为中心点可以计算惯性张量。

对于第一个机械臂,对x, y, z方向分析,可以计算上述重积分:

$$egin{aligned} I_{xx} &=
ho * \int_{-0.5}^{0.5} \int_{-0.025}^{0.025} \int_{-0.025}^{0.025} (y^2 + z^2) dz dy dx = 0.08 \ I_{yy} &=
ho * \int_{-0.5}^{0.5} \int_{-0.025}^{0.025} \int_{-0.025}^{0.025} (x^2 + z^2) dz dy dx = 1.630 \ I_{zz} &=
ho * \int_{-0.5}^{0.5} \int_{-0.025}^{0.025} \int_{-0.025}^{0.025} (x^2 + z^2) dz dy dx = 1.630 \end{aligned}$$

由于积分的上下界关于0对称,因此易知 $I_{xy}=I_{yz}=I_{zx}=0$ 。

同理,对于第二个机械臂,有:

$$I_{xx} =
ho * \int_{-0.25}^{0.25} \int_{-0.025}^{0.025} \int_{-0.025}^{0.025} (y^2 + z^2) dz dy dx = 0.040$$
 $I_{yy} =
ho * \int_{-0.25}^{0.25} \int_{-0.025}^{0.025} \int_{-0.025}^{0.025} (x^2 + z^2) dz dy dx = 0.815$

 $I_{zz} =
ho * \int_{-0.25}^{0.25} \int_{-0.025}^{0.025} \int_{-0.025}^{0.025} (x^2 + z^2) dz dy dx = 0.815$