

European Union Aviation Safety Agency



INSPECTION INSTRUCTIONS AND PRE-DESCRIBED FINDINGS

Doc # INST.RI.01/006

Approval Date 28/10/2022

On passenger carrying aeroplanes with:

- a maximum certified take-off mass (MCTOM) > 54.500 kg;
- a MCTOM > 45.500 kg and a passenger seating capacity greater than 19; or
- a passenger seating capacity greater than 60.

Inspect the:

- installation and serviceability of the reinforced cockpit door.
- means to monitor the door area from either pilot seat.

Note:

- *Some means will fully satisfy the requirements, such as CCTV systems. However, means, such as the spyhole, do not enable the crew to monitor the door area from their seat and lead to a CAT 2 finding. The visual monitoring of the door area from the cockpit is of paramount importance, therefore alternative procedures such as an audio signalling code in addition to a spyhole are also considered to be not in compliance as they do not provide for an actual visual monitoring; therefore, a CAT 2 finding should be raised in such a situation as well. However, when this has been compensated during critical phases of the flight, e.g. by the use of an additional crew member to monitor the area on behalf of the flight crew or by denying access to the flight deck, it still constitutes a finding, but with a lesser influence on flight safety (hence the CAT 1 finding should be used). The presence in the cockpit of an additional crew member during all phases of the flight is considered to fully meet ICAO requirements.*

PDF Code	Pre-Described Finding	Cat	SAFA CAT Std. ref.	SACA CAT Std. ref.	SAFA GA Std. ref.	SACA NCC Std. ref.
A01-01	One or more door locking/un-locking mechanism not serviceable	1	A6-I-13.2.2	ORO.SEC.100(b)	Not applicable	Not applicable
A01-02	No means provided for crew notification	2	A6-I-13.2.1	ORO.SEC.100(a)	Not applicable	ORO.SEC.100(a)
A01-03	Means to monitor the door area not available from either pilot's station (but alternative operational procedures established for the critical phases of the flight)	1	A6-I-13.2.3	ORO.SEC.100(c)(2)	Not applicable	Not applicable



An agency of the European Union

© European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Page 21 of 304

European Union Aviation Safety Agency



INSPECTION INSTRUCTIONS AND PRE-DESCRIBED FINDINGS

Doc # INST.RI.01/006

Approval Date 28/10/2022

PDF Code	Pre-Described Finding	Cat	SAFA CAT Std. ref.	SACA CAT Std. ref.	SAFA GA Std. ref.	SACA NCC Std. ref.
A01-04	Means to monitor the door area not available from either pilot's station (and no alternative operational procedures established)	2	A6-I-13.2.3	ORO.SEC.100(c)(2)	Not applicable	Not applicable
A01-05	Means to monitor the door area not available or U/S (outside dispatch limits/conditions)	3	A6-I-13.2.3	ORO.SEC.100(c)(2)	Not applicable	Not applicable
A01-06	Cockpit door lock N/A or U/S (outside dispatch limits/conditions)	3	A6-I-13.2.1	ORO.SEC.100(a)	Not applicable	ORO.SEC.100(a)
A01-07	Damage and/or delamination to flight deck windows (outside dispatch limits/conditions)	3	M	M	M	M
A01-08	Interior equipment and/or other object(s) not correctly secured or stowed during flight	3	A8-III-A-4.1.6(c) A8-III-A-4.1.7.1 A8-III-B-4.2(c) A8-III-B-4.6.1 A8-VA-4.2(c) A8-VA-4.6.1	CAT.OP.MPA.160(b)	A8-III-A-4.1.6(c) A8-III-A-4.1.7.1 A8-III-B-4.2(c) A8-III-B-4.6.1 A8-VA-4.2(c) A8-VA-4.6.1	NCC.OP.135(b)
A01-09	Reinforced cockpit door not installed (on passenger flights)	3	A6-I-13.2.2	ORO.SEC.100(b)	Not applicable	Not applicable
A01-10	Lights U/S in warning panel (outside dispatch limits/conditions)	3	A8-II-3.5	CAT.OP.MPA.175(b)(1)	A8-II-3.5	NCC.GEN.106(a)(4)
A01-11	Cockpit installations significantly decreasing pilot's vision	2	A8-III-A-4.1.6(d) A8-III-B-4.2(d) A8-VA-4.2(d)	CAT.IDE.A.100(d)	A8-III-A-4.1.6(d) A8-III-B-4.2(d) A8-VA-4.2(d)	NCC.IDE.A.100(e)
A01-12	Windshield wipers/cleaning/drying system not installed or inoperative (outside dispatch limits/conditions)	3	A8-III-A-4.1.6(d) A8-III-B-4.2(d) A8-VA-4.2(d)	CAT.IDE.A.120	A8-III-A-4.1.6(d) A8-III-B-4.2(d) A8-VA-4.2(d)	A8-III-A-4.1.6(d) A8-III-B-4.2(d) A8-VA-4.2(d)



An agency of the European Union

© European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Page 22 of 304

European Union Aviation Safety Agency



INSPECTION INSTRUCTIONS AND PRE-DESCRIBED FINDINGS

Doc # INST.RI.01/006

Approval Date 28/10/2022

PDF Code	Pre-Described Finding	Cat	SAFA CAT Std. ref.	SACA CAT Std. ref.	SAFA GA Std. ref.	SACA NCC Std. ref.
A01-13	Equipment installations obviously not in compliance with applicable requirements	3	A8-III A-1.4 A8-III A-1.5 A8-III A-8.2 A8-III B-1.4 A8-III B-1.5 A8-III B-6.2 A8-VA-1.3 A8-VA-1.4 A8-VA-6.2	CAT.IDE.A.100 M.A.501	A8-III A-1.4 A8-III A-1.5 A8-III A-8.2 A8-III B-1.4 A8-III B-1.5 A8-III B-6.2 A8-VA-1.3 A8-VA-1.4 A8-VA-6.2	NCC.IDE.A.100
A01-15	Inadvertently exposed electrical cables/wires in the cockpit	2	A8-III A-1.4 A8-III A-1.5 A8-III A-8.2 A8-III B-1.4 A8-III B-1.5 A8-III B-6.2 A8-VA-1.3 A8-VA-1.4 A8-VA-6.2	CAT.IDE.A.100 M.A.201(a)(b)(c)(e)	A8-III A-1.4 A8-III A-1.5 A8-III A-8.2 A8-III B-1.4 A8-III B-1.5 A8-III B-6.2 A8-VA-1.3 A8-VA-1.4 A8-VA-6.2	NCC.IDE.A.100
A01-17	Placard "Crew only" missing or unreadable	1	Not applicable	CAT.IDE.A.215(a)	Not applicable	Not applicable
A01-18	Cockpit seats in poor condition	1	M	M	M	M
A01-19	Marking and/or Placards providing misleading information with major effect on flight safety	3	A8-III A-9.1 A8-III B-7.1 A8-VA-7.1	M.A.901(m) CS 25.677(b) CS 25.1545 CS 25.1547(a)-(c) CS 25.1563 A8-III A-9.1 A8-III B-7.1 A8-VA-7.1	A8-III A-9.1 A8-III B-7.1 A8-VA-7.1	NCC.POL.100(b) A8-III A-9.1 A8-III B-7.1 A8-VA-7.1
A01-20	Marking and/or Placards missing or unreadable	2	A8-III A-9.1 A8-III B-7.1 A8-VA-7.1	M.A.901(m) CS 25.677(b) CS 25.1545 CS 25.1547(a)-(c) A8-III A-9.1 A8-III B-7.1 A8-VA-7.1	A8-III A-9.1 A8-III B-7.1 A8-VA-7.1	NCC.POL.100(b) A8-III A-9.1 A8-III B-7.1 A8-VA-7.1



An agency of the European Union

© European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Page 23 of 304