

European Union Aviation Safety Agency



INSPECTION INSTRUCTIONS AND PRE-DESCRIBED FINDINGS

Doc # INST.RI.01/006

Approval Date 28/10/2022

- Any back-up provision such as hardcopies or an alternative EFB should be considered as acceptable.

Note:

- For General Aviation operations ICAO A6-II-2.4.17.2.2 requires the State of Registry to issue a specific approval for the operational use of the EFB functions to be used for the safe operation of the aeroplanes. In order to maintain a level playing field, inspectors should not raise findings for missing approvals as currently the EASA Air Operations regulation does not foresee such an approval in general aviation operations.

PDF Code	Pre-Described Finding	Cat	SAFA CAT Std. ref.	SACA CAT Std. ref.	SAFA GA Std. ref.	SACA NCC Std. ref.
A03-01	Required equipment installed but not being used during operation by crew	3	A6-I-6.1.1	CAT.IDE.A.100(c) CAT.IDE.A.105	A6-II-2.4.1	NCC.IDE.A.100(d) NCC.IDE.A.105
A03-02	ACAS II N/A or U/S (outside dispatch limits/conditions)	3	A6-I-6.19.1	AUR.ACAS.1005	A6-II-3.6.9.2	AUR.ACAS.1005
A03-04	GPWS/TAWS with forward looking terrain avoidance function not installed or unserviceable (outside dispatch limits/conditions)	3	A6-I-4.3.1(b) A6-I-6.15	CAT.OP.MPA.175(b)(1) CAT.IDE.A.150	A6-II-2.4.11	NCC.GEN.106(a)(4)(iii) NCC.IDE.A.135
A03-05	Radio channel spacing does not meet the airspace requirements for the filed flight plan	3	Regulation (EU) 1079/2012, Art. 5.4	Regulation (EU) 1079/2012, Art. 5.4	Regulation (EU) 1079/2012, Art. 5.4	Regulation (EU) 1079/2012, Art. 5.4
A03-06	Required navigation equipment N/A or U/S (outside dispatch limits/conditions)	3	A6-I-4.3.1(b) A6-I-7.2.1	CAT.IDE.A.105 CAT.IDE.A.345(a)(d)	A6-II-2.2.3.1 A6-II-2.4.3 A6-II-2.4.7 A6-II-2.5.2	NCC.IDE.A.250 NCC.IDE.A.105
A03-07	Cockpit Voice Recorder inoperative (outside dispatch limits/conditions)	3	A6-I-6.3.2.1.1 A6-I-6.3.2.1.3 A6-I-6.3.2.1.4	CAT.IDE.A.185(a)-(d)	A6-II-3.6.3.2	NCC.IDE.A.160
A03-08	EFB functions affecting the safe operation of the aircraft used without back-up	2	A6-I-6.2.3 A6-I-6.25.2.1(c) A6-I-6.25.3(c)	CAT.GEN.MPA.141(a) AMC1 SPA.EFB.100(b)(1)(b)	A6-II-2.4.17	NCC.GEN.131 NCC.GEN.140



An agency of the European Union

© European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Page 30 of 304

European Union Aviation Safety Agency



INSPECTION INSTRUCTIONS AND PRE-DESCRIBED FINDINGS

Doc # INST.RI.01/006

Approval Date 28/10/2022

PDF Code	Pre-Described Finding	Cat	SAFA CAT Std. ref.	SACA CAT Std. ref.	SAFA GA Std. ref.	SACA NCC Std. ref.
A03-09	Headset with boom microphone or equivalent N/A or U/S (outside dispatch limits/conditions)	3	Not applicable	CAT.OP.MPA.215	A6-II-3.6.11	NCC.OP.160
A03-10	Aeroplane not equipped with ACAS II collision avoidance logic version 7.1	3	AUR.ACAS.1005 A10-IV-4.3.5.3.1 A10-IV-4.3.5.3.3	AUR.ACAS.1005	AUR.ACAS.1005 A10-IV-4.3.5.3.1 A10-IV-4.3.5.3.3	AUR.ACAS.1005
A03-11	EFB mounting device or viewable stowage device obstructing forward visual or physical access to controls, display or external vision	3	A6-I-6.25.1	Part-DEF (ae) CAT.GEN.MPA.141(a) AMC1 CAT.GEN.MPA.141(a) (h)	A6-II-2.4.17	NCC.GEN.131(a)
A03-12	The viewable stowage device used does not adequately secure the EFB	2	A6-I-6.25.1	Part-DEF (ae) CAT.GEN.MPA.141(a) AMC1 CAT.GEN.MPA.141(a) (h)(3)	A6-II-2.4.17	NCC.GEN.131(a)
A03-13	No operational approval of EFB functions affecting the safe operation of the aircraft	2	A6-I-6.25.2.2	Part-DEF(120b) SPA.EFB.100(a)	Not applicable	Not applicable
A03-14	EFB charts application used on a portable EFB without a mounting device or a viewable stowage device	2	Not applicable	CAT.GEN.MPA.180(a)(12) CAT.GEN.MPA.141(a) AMC1 CAT.GEN.MPA.141(a) (a)	Not applicable	NCC.GEN.131(a) NCC.GEN.140
A03-15	TDB of TAWS/GPWS with FLTA function outdated with minor or no changes for the authorised operation area(s) (within dispatch limits / conditions)	1	A15-6.3.3 A6-I-6.15.2	CAT.IDE.A.355(b)	A15-6.3.3 A6-II-3.7.3	NCC.IDE.A.260(b)
A03-16	TDB of TAWS/GPWS with FLTA function outdated and significant changes for the authorised operation area(s) within dispatch limits / conditions)	2	A15-6.3.3 A6-I-6.15.2	CAT.IDE.A.355(b) A6-I-6.15.2	A15-6.3.3 A6-II-3.7.3	NCC.IDE.A.260(b)



An agency of the European Union

© European Union Aviation Safety Agency. All rights reserved. ISO9001 Certified
Proprietary document. Copies are not controlled. Confirm revision status through the EASA-Internet/Intranet.

Page 31 of 304