Rev 2 thru 3A

Cut off pins 8 and 9 of 16B, jumper 8 and 9 together on solder side of board

Rev 2A only

Lift pin 12 of 15A, connect to 16B-8 on component side  $\,$ 

Rev 2A thru 3A

On circuit side, cut trace coming from 10A-12 Jumper 2A-10 to feedthrough on end of cut trace Jumper 10A-12 to 2A-8 Jumper 3C-8 to 2A-9

Rev 3 and 3A Lift pin 10A-6 out of socket On circuit side, jumper 10A-6 to 15A-15 Rev 3 and 4 replace the 6331 with a 82S153 On the component side of Rev 3/3A boards lift pin 15A-3 and jumper to 16B-8 /RDSTB replaced with Z80 /RD

Rev 4 PCBs added rework to trace layout

8

9

10 GND

SØ

**S**1

(I7)

(BI0)

(B3) MEMR

(B2) ENINT

(B1) /WM1

13

12

11

I-REFRESH











