## Invoice



## Skyline Mechanical Services LLC

6532 W Flint St. Suite 2 Chandler AZ 85226 480-398-4214 20981399

Account # 100761

Email: daveLewellen@wasserstrom.com; rongillespie@wasserstrom. Invoice #

309839 5/26/2024

Date: Page#

1 of 1

Service At:

The Wasserstrom Company Phx DC 7720 W Olive Avenue Peoria AZ 85345

The Wasserstrom Company Phx DC

7720 W Olive Avenue Peoria AZ 85345

Service Date 5/16/2024 PO#

Job #215800

Contract #

Claim#

Arrived on site and checked in before going to the roof. Once on the roof, found that supply water to the cooler was leaking. Tightened connections with a wrench and stopped the leak for cooler 19.

Description Of Service	Quantity	Unit Price	Extended Price	Tax
Labor	1.5	\$95.00	\$142.50	
Truck Charge	1	\$50.00	\$50.00	
Fuel Charge	1	\$25.00	\$25.00	

**Balance Due** \$217,50

A Service Charge of 3% will be added if payment is made using a Credit Card. Zip code and CCV # Required

		_
Transaction Time Time The Control		
Terms: Due Upon Receipt	Please pay fr	om this In

## Please Detach and Return with Remittance Invoice # 309839 Check Enclosed [ ] Method of Payment Master Card [ ] Visa [ ] AmExp [ ] Date: 5/26/2024 Acct# Exp Date Account # 100761 Name on Card The Wasserstrom Company Phx DC Signature

Remit To:

Skyline Mechanical Services LLC Skyline Mechanical Services 6532 W Flint Street, #2 Chandler AZ 85226

Amount Due

\$217.50

Please pay from this Invoice

Amount Paid



Contractor's License # 284218 - Type K-39 Contractor's License # CR11 299135

DATE	WORK	ORDE	RED:

CUSTOMERS ORDER NO .:

WORK AUTHORIZED BY:

**JOB NUMBER** 

MECHANICAL

6532 W Flint Street, Ste 2 · Chandler, AZ 85226 Phone: 480-398-4214 • Fax: 480-888-8402

PHONE:

	Wasserstrom	SERVICE D	1 leaking
work performed service maintenance model 730	XL SERIAL	9 9000000000011111111111111111111111111	MAKE 1/MP
STATUS: COMPLETE INCOMPLETE MODEL	SERIAL _		MAKE
DESCRIPTION	QTY. PART NO. & DE	ESCRIPTION UNIT PRICE	E AMOUNT SOURCE
Arrived ONS, He and cleated in before			
going on the roof. Once on the			
to the Cooler was leaking. I tightened Conecting with a renen and Stoled to leak.			
	MATERIAL REQUISITION #	FORWARDED	
	2 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	SEADINI	
	DATE TECHNICIAN LABORHOU	RS TAX TOTAL MATERIAL	
	5/16 Avar	SALES TAX	
		RENTAL EQUIPMENT	
RECOMMENDATION		ereign Sub	
		CONTRACT:  EINT MAINT	
		JOFAL AGREEMENT SERVICE TRUCK GEARGE	
		TORANGE : A STRAIGHT : A STRAIG	
WRITTEN REPORT TO FOLLOW		OVERTIME: LABOR	
THE EVENT OF COMMENCEMENT OF SUIT TO CONTROL OF THIS ORDER, PURCHASER SIGNATURE X.	A LATE CHARGE OF 1 1/2% FROM DUE DATE PAID WILL BE CHARGED ON ALL PAST DUE A	UNTIL PAY THIS AMOUNT S	The second of th