



PRELIMINARY PREFLIGHT PROCEDURE

CHOCKS	CHECK SET
BAT SWITCH	ON (GUARDED)
DC METER	BAT (min 24V)
HYD PUMPS	ALL OFF
GND PWR	IF AVAIL , ON
IF GND PWR NOT AVAILABLE >>> START APU PROC.	
OXYG QTY	CHECK (1500 PSI min)
IRU DSPL SEL	CHECK on PPOS
IRU MODE SEL	R & L on NAV
ALIGN TIME ~10MIN. - IF ATT POS SELECTED SHUT DOWN UNIT AND RESTART	
GALLEY PWR	ON
EQUIP COOLING SWITCH	BOTH NORMAL
RECIRC FAN	AUTO
WINGBODY OVHT	TEST
IF USING UNCONDITIONED BLEED AIR (EXTERNAL UNIT)	
APU BLEED	OFF
ISOLATION VALVE	OPEN
L & R PACKS	AUTO or HIGH
TEMP SEL.	as desired
IF USING APU BLEED AIR	
APU BLEED	ON
ISOLATION VALVE	AUTO
L & R PACKS	AUTO or HIGH
TEMP SEL.	as desired
LIGHTS TEST	TEST , CHECK then BRT
ENG OIL QTY TEST	PUSH, CHECK > 0, RELEASE
LANDING GEAR LEVER	DOWN, 3 GREEN
LND HYD QTY	OVER RFL (+88% on EIS display)
FLAPS LEVER	FULLY UP, POS. 0
FLAPS LEVER INDICAT.	CHECK IF LEVER AGREES
PARKING BRAKES	SET, RED LIGHT ON
BRAKES PRESS	APPROX 300 psi
ENG OVHT DET SWITCHES	BOTH NORMAL
ENG OVHT TEST SWITCH	FAULT INOP, OVHT FIRE , RELEASE
ENG EXT TEST	TEST 1, TEST 2, RELEASE
CARGO FIRE DETECT	TEST (Push for 5 secs), CHECK LITS & HORN
MASTER CAUTION	RESET
MIC SEL SWITCHES	LEAVE DEFAULT (or as desire)
> REQUEST REFUELING, CARGO LOAD AND PASSENGER BOARDING <	

FMC SETUP 1/2 (POSITION & ROUTE)

IDENT PAGE	CHECK UPDATED AIRAC DB
	Enter ICAO REF AIRPORT (DEP AIRPORT)
POS INIT PAGE	Enter GATE (optional)
	SET IRS POS (from NEXT PAGE, L GPS)
	Set ORIGIN (Paste from scratchpad)
ROUTE PAGE	Enter DEST, FLT NO
	*Enter CO ROUTE (to recall saved flt)
	Set DEP RWY if known
	Select DEP rwy (if not set yet)
DEP/ARR PAGE	Select SID
	Select TRANS
ROUTE PAGE	Fill all ROUTE AIRWAYS/FIX

	Select APPROACHES
DEP/ARR PAGE	Select STAR
	Select TRANS
ROUTE PAGE	CHECK NO ROUTE-DISCONT
	> ACTIVATE and EXEC

FMC SETUP 2/2 (FLIGHT PERF.)

PERF INIT PAGE	Enter ZFW (loadsheets)
	Enter RES (loadsheets)
	Enter COST INDEX (loadsheets)
	Set GW (automatically filled)
	Enter CRZ ALT (loadsheets)
	Enter CRZ WIND & ISA DEV (from ToC, Flightplan)
	> ACTIVATE and EXEC
	Verify correct OAT
N1 LIMIT PAGE	Enter SEL Temp. (if avail from Perf. Calc.)
	Select DERATE & CLB accordingly
	Enter T/O FLAPS (1° recommended for better perf.)
TAKEOFF REF PAGE	Enter Man/Auto V-REF Speed
	Copy TRIM Value as reference

CAPTAIN'S FLIGHTDECK SETUP

PIC OXYGEN MASK	TEST, RESET
PASS OXYGEN	SWITCH GUARDED, LIGHT OFF
PMC INOP LIGHTS	OFF
LOW IDLE LIGHT	OFF
REVERSER LIGHTS	OFF
SERV. INTERPHONE SWITCH	OFF
STBY HYD LIGHTS	LOW QUANT & LOW PRESS OFF
FLT CONTROL SWITCHES	BOTH ON, GUARDED
ALTERNATE FLAPS SWITCHES	OFF, GUARDED
SPOILERS SWITCHES	BOTH ON, GUARDED
YAW DAMPER SWITCH	ON, CHECK LIT TURN OFF
EFI, IRS SWITCHES	BOTH NORMAL
FUEL VALVE CLOSED LIGHTS	CHECK ON
CROSSFEED VALVE CHECK	OPEN - VALVE OPEN light goes BRIGHT then DIM
	CLOSE - VALVE OPEN light goes BRIGHT then OFF
FUEL PUMPS	L AFT ON, OTHER OFF
STBY POWER SWITCH	AUTO, GUARDED
GEN DRIVE DISCONNECT SWTS	GUARDED
BUS TRANSFER SWITCH	AUTO, GUARDED
EMER EXIT LIGHTS SWITCH	ARMED, GUARDED
NO SMOKING SIGN	ON
FASTEN SEAT BELT SIGN	OFF
WINDOW HEAT SWITCHES	ON, CHECK ON LITS
PITOT TEST	ON, verify lights goes OFF then OFF
MASTER CAUTION	RESET
WING ANTI-ICE	TEST, OFF
HYD PUMPS	ELEC OFF, ENG ON
VOICE RECORDER	TEST
ENGINE START SWITCHES	OFF
IGNITION SEL SWITCHES	R for first day flight, L subsequent flights
AUTOFLIGHT ANNUNCIATOR	TEST
ALTIMETER	SET & CROSSCHECK WITH F/O SIDE

NORMAL PROCEDURE CHECKLIST



STBY AIRSPEED IND.	60
STBY ALTIMETER	SET & CROSSCHECK WITH F/O SIDE
> CHECK AND WAIT FOR REFUELING, CARGO LOAD AND PASSENGER BOARDING <	
FUEL QTY	Verify refueling, if ended - TEST
FUEL FLOW SWITCH	RESET (+1 SEC HOLD)
ENGINE INSTRUMENTS	CHECK
ANTI-SKID SWITCH	GUARDED
AUTO BRAKE SELECTOR	RTO
SPEEDBRAKES LEVER	DOWN POS.
THROTTLES and REVERSE LEVERS	CLOSED AND DOWN
FLAPS LEVER and INDICATOR	MATCH
PARKING BRAKES	CHECK SET (Brakes press > 1000psi)
ENGINE START LEVERS	CUTOFF
STABILIZER TRIM	CHECK IN GREEN BAND & SET IN ACCORD WITH FMC
TAKEOFF WARNING HORN	TEST THROTTLE 1&2 (ADVANCE, HORN, CLOSE)
RADIO	CHECK & SET
RECOMMENDED INITIAL RADIO SETUP	
1.CLR DLV	STBY.GRD
2.TWR	STBY.ATIS
RUDDER / AILERON TRIM	ZERO
STAB TRIM OVRD SWITCH	NORMAL, GUARDED

F/O'S FLIGHTDECK SETUP	
EXT LIGHTS	POS, WINGS, WHEEL WELL - ON (LOGO if needed)
SIDE WINDOWS	CHECK CLOSED
F/O OXYGEN MASK	TEST, RESET
FLIGHT RECORDED	TEST
MACH AIRSPEED WARNING	TEST 1, TEST 2
STALL WARNING	TEST
LE DEVICES	TEST
AIR TEMP SELECTOR	SUPPLY DUCT (DUCT OVHT LIGHTS goes OFF)
TEMPERATURE SELECTOR	SET
DUAL BLEED LIGHT	If APU BLEED CLOSED = OFF Combination of APU/ENG OPEN = ON
RAM DOORS FULL OPEN LIGHTS	ON (Must be full open on ground)
PACK TRIP OFF, BLEED TRIP OFF, & WING-BODY OVERHEAT LIGHTS	Must be OFF
ENGINE BLEED SWITCHES	ON
PRESSUR MODE SELECTOR	AUTO
FLT ALT INDICATOR	SET PLANNED FLIGHT ALTITUDE
LAND ALT INDICATOR	SET LANDING FIELD ALTITUDE
STANDBY CABIN RATE	SET AT INDEX
STANDBY CABIN ALTITUDE	SET AS FOLLOW
STANDBY CABIN ALTITUDE SETUP	
PRESS SETUP DECAL	
CAB -3 .3 .8 1.4 1.9 2.4 2.9 3.4 3.9 4.4 5.0 5.1 5.6 6.0 6.4 6.8 7.2 7.6 8.0 FLT 18 20 22 24 26 28 30 32 34 36 ALTITUDE X 1000 FEET - MAX PRESS SCHEDULE	
Compare actual destination altitude minus 200 feet and the CAB altitude derived from the decal using the projected flight altitude and use the HIGER FIGURE.	
STBY AIRSPEED IND.	60
STBY ALTIMETER	SET & CROSSCHECK WITH CPT SIDE
TAT/SAT/TAS INDICATOR	TAT
GPWS INHIBIT SWITCH	NORMAL, GUARDED
GPWS	TEST

TRANSPONDER/TCAS	TA/RA, STBY
------------------	-------------

FINAL FLIGHTDECK PREPARATION	
> GET ATC CLEARANCE <	
FUEL QUANTITY	CHECK
FMC	CHECK WEIGHTS, DEP/ARR, PERF INIT
START APU PROCEDURE	
APU BLEED	CHECK OFF
L AFT FUEL PUMP	ON (Check LOW PRESS LIGHT goes OFF)
APU SWITCH	ON, MOMENTARY
APU EGT INDICATOR	CHECK RISING
APU GEN OFF BUS LIGHT	ON
APU GEN SWITCHES	BOTH ON, TRANSFER BUS, BUS OFF, STBY PWR> OFF
APU BLEED SWITCH	ON
TRANSPONDER	SET
HSI MODE SELECTOR	MAP
HSI RANGE SELECTOR	RANGE 10 or 20
WEATHER RADAR	ON
MCP SETUP	
COURSES	SET & CROSSCHECK
FLIGHT DIRECTOR SWITCHES	BOTH ON (CPT'S side first)
AUTO THROTTLE SWITCH	OFF
IAS/MACH SELECTOR	SET V2 SPEED
AIRSPEED INDICATOR	CHECK BUGS
HEADING SELECTOR	SET MAG DEP RWY HDG
BANK LIMIT SELECTOR	15° (25°/30° after take-off)
ALTITUDE	SET INITIAL CLEARED ALTITUDE
AUTOPILOT ENGAGE SWITCHES	OFF
AUTOPILOT DISENGAGE BAR	ARMED (UP)

BEFORE PUSHBACK/START PROCEDURE	
FUEL PUMPS	ALL On (Center tank ONLY if with fuel)
FUEL PUMPS LOW PRESSURE LTS	ALL OFF
APU GEN SWITCHES	CHECK ON
FASTEN SEAT BELT SIGN	ON
HYD PUMPS	ELEC A OFF, ELEC B ON
CDU PAGE SELECTED	CPT on T/O page, F/O on INIT REF
> DISCONNECT ALL SERVICES FROM GROUND, CLOSE ALL DOORS - CALL THE P/B SERVICE <	
DOOR LIGHT-PACK	ALL OFF
ANTI-COLLISION LIGHTS	ON
COCKPIT DOOR	LOCK (Check light off)
> GET PUSHBACK/ENGINES START CLEARANCE <	

PUSHBACK/START PROCEDURE	
PARKING BRAKES	RELEASE (START PUSHBACK)
PACK SWITCHES	BOTH OFF
ISOLATION VALVE	AUTO
DUCT PRESSURE	VERIFY
R ENG START SWITCH	GRD
DUCT PRESSURE	"DECREASE"
"A" HYD PRESS INDICATOR	0 (ZERO)
OIL PRESS	"INCREASE"
N2	"25%"
R ENG START LEVER	IDLE

NORMAL PROCEDURE CHECKLIST



N1	"ROTATION"
EGT	INCREASE (in 10 sec)
R ENG START SWITCH	Automatically CUTOFF (at 46% N2)
> START 2ND ENGINE, SAME PROCEDURE <	
PARKING BRAKES	SET (END OF PUSHBACK)

BEFORE TAXI PROCEDURE	
ENG GENERATOR SWITCHES	BOTH ON
HYD PUMPS	ALL ON (Check LOW PRESS LIGHTS go OFF)
APU	OFF
MASTER CAUTION SYSTEM	RECALL
PITOT HEAT SWITCHES	BOTH ON
ENGINE ANTI-ICE	AS REQUIRED (EXT TEMP < 10°, Visible Moisture)
PACK SWITCHES	BOTH AUTO
ISOLATION VALVE SWITCH	AUTO
ENGINE BLEED SWITCHES	BOTH ON
APU BLEED SWITCH	OFF
DUAL BLEED LIGHT	OFF
FLT/GRD SWITCH	FLT
HYD SYS PRESSURE INDICATOR	CHECK
> GET TAXY CLEARANCE <	

TAXI PROCEDURE	
FLIGHT CONTROLS	CHECK
TAXI LIGHTS	ON
PARKING BRAKES	RELEASE (TAXYING - Max 40% N2 / Max 30 Knots)
FLAPS	SET T/O POSITION
YAW DAMPER	CHECK
AUTOTHROTTLE	ARM
ENG START SWITCHES	CONT
MASTER CAUTION SYSTEM	RECALL
TRANSPONDER/TCAS	TA/RA, ON
TRIM	CHECK

CLEARED ONTO ACTIVE RUNWAY	
FLIGHT CONTROLS	CHECK
STROBE LIGHTS	ON
RWY TURNOFF LIGHTS	ON
LANDING LIGHTS	ON
PARKING BRAKES	SET
> BE SURE TO HAVE T/O CLEARANCE <	
HEADING SELECTOR	CHECK MAG RWY HDG
THROTTLE	40% N1 (STABILIZE)
PARKING BRAKES	RELEASE (START T/O)
THROTTLE	ADVANCE
TO/GA SWITCH	PUSH

AFTER TAKE-OFF	
GEAR LEVER	UP (On positive climb)
AT 400'	
ROLL MODE	HDG SEL, LNAV or VOR/LOC
IAS/MACK SELECTOR	SET V2 + 20
AT 800'	
PITCH ATT	REDUCE

FLAPS	RETRACT AS SCHEDULED
IAS/MACK SELECTOR	SET 220/230 KTS
PITCH MODE	VNAV or CLIMB MODE
AT 1000'	
FLAPS	FULL UP
AUTOPILOT ENGAGE SWITCHES ON (PF SIDE)	
ENGINE BLEED SWITCHES	VERIFY ON
WING ANTI-ICE	ON if required
AT 3000'	
IAS/MACK SELECTOR	SET 250 KTS
GEAR LEVER	LOCK
AUTO BRAKE SELECTOR	OFF
BANK LIMIT SELECTOR	25°/30°
ENG START SWITCHES	OFF (CONT if required)

CLIMB			
AT TRANS ALTITUDE			
ALTIMETER		SET QNE & CROSSCHECK WITH F/O SIDE	
SEAT BEALT SIGN SWITCH		OFF	
RADIO		CHECK & SET	
RECOMMENDED CLIMB RADIO SETUP			
1.DEP	STBY.CTR/RDR	2.TWR	STBY.ATIS
PASSING 10000'			
RWY TURNOFF LIGHTS		OFF	
LANDING LIGHTS		OFF	
TAXI LIGHTS		OFF	

CRUISE	
AT ToC	
A/P & FMC	CHECK SETUP & FUEL
MCP ALTITUDE	SET ON LOWER ALTITUDE
FUEL PUMPS	CENTER OFF (WHEN EMPTY), OTHER ON

DESCEND			
BEFORE T/D			
RADIO		CHECK & SET	
RECOMMENDED DESCEND RADIO SETUP			
1.APPR	STBY.CTR/RDR	2.ARR TWR	STBY.ARR ATIS
> GET DESCEND CLEARANCE <			
ENG START SWITCHES		CONT	
AIRSPEED INDICATOR		CHECK	
PASSING 10000'			
RWY TURNOFF LIGHTS		ON	
LANDING LIGHTS		ON	
TAXI LIGHTS		ON	
APPR NAVAID FREQUENCIES		SET	
IAS/MACK SELECTOR		SET 250 KTS	
AT TRANS ALTITUDE			
ALTIMETER		SET ARRIVAL QNH & CROSSCHECK WITH F/O SIDE	
SEAT BEALT SIGN SWITCH		ON	

APPROACH PROCEDURE	
> GET APPROACH CLEARANCE <	
FMC	CHECK ARRIVAL



SPOILERS	ARMED
AIRSPPEED	REDUCE
FLAPS	EXTEND AS NEEDED
AUTOBREAK	SET AS NEEDED
DECISION HEIGHT	SET AS NEEDED
FMC	CHECK ARRIVAL

BEFORE LANDING PROCEDURE	
ON LOC/DME LANDINGS	
VOR/LOC	ARM (When on LOCALIZER intercept heading)
HEADING SELECTOR	SET MAG ARR RWY HDG
GEAR LEVER	DOWN (At glideslope alive), 3 GREEN
FLAPS	EXTEND 15 (At glideslope alive)
AIRSPPEED	REDUCE TO APPROACH SPEED
IAS/MACK SELECTOR	SET APPROACH SPEED
FLAPS	EXTEND TO APPROACH POSITION
AUTOPILOT ENGAGE SWITCHES DISCONNECT ON G/S CAPTURED	
ON ILS/DME LANDINGS	
APP	ARM (When on ILS intercept heading)
AUTOPILOT ENGAGE SWITCHES CHECK A ON (BOTH ON FOR CAT III AUTOLANDING)	
GEAR LEVER	DOWN (At glideslope alive), 3 GREEN
AIRSPPEED	REDUCE TO APPROACH SPEED
IAS/MACK SELECTOR	SET APPROACH SPEED
FLAPS	EXTEND 15 (At glideslope alive)
	EXTEND 25 (At lower DOT)
	EXTEND 30/40 (Approaching glideslope)
CAT II	
AUTOPILOT ENGAGE SWITCHES OFF at MINIMUMS (CAT II Landings)	
AUTOTHROTTLE SWITCH OFF at MINIMUMS (CAT II Landings)	
CAT III	
At 50 ft FLARE, At 27 ft RETARD - Disconnect A/P & A/T on TOUCH	
NOTE: BEFORE LANDING BE SURE TO GET PROPER LANDING CLEARANCE	

LANDING PROCEDURE	
THROTTLE LEVERS	RETARD TO IDLE
SPEED BRAKES LEVER	FULL UP POS. (Verify extended)
REVERSERS	DEPLOY (Do NOT use REVERSERS below 60kts)

AFTER LANDING PROCEDURE	
CLEAR OF ACTIVE RUNWAY	
AUTOFLIGHT ANNUNCIATOR	RESET
FLIGHT DIRECTOR SWITCHES	BOTH OFF
FLAPS	FULL UP
SPEED BRAKES LEVER	FULL DOWN POS. (Verify retracted)
PITOT HEAT SWITCHES	BOTH OFF
WING ANTI-ICE	OFF
ENGINE ANTI-ICE	OFF
ENG START SWITCHES	OFF
APU SWITCH	ON, MOMENTARY
TRANSPONDER/TCAS	TA/RA, STBY
WEATHER RADAR	OFF
RWY TURNOFF LIGHTS	OFF
LANDING LIGHTS	OFF
> GET TAXY CLEARANCE TO GATE/RAMP/PARK <	

SHUTDOWN PROCEDURE	
> ON STAND POSITION REQUEST CARGO UNLOAD AND PASSENGER UNBOARDING <	
PARKING BRAKES	SET
APU GEN SWITCHES	BOTH ON, Verify TRANSFER BUS, BUS OFF, and STANDBY PWR lights are OFF.
R/L ENG START LEVER	CUTOFF
DOORS	OPENED (As needed)
FASTEN SEAT BELT SIGN	OFF
FUEL PUMPS	L AFT ON, OTHER OFF
HYD PUMPS	ALL OFF
YAW DAMPER SWITCH	OFF
RECIRC FAN	AUTO
PACK SWITCHES	BOTH AUTO
ISOLATION VALVE SWITCH	CHECK AUTO
APU BLEED SWITCH	ON
EXT LIGHTS	POS, WINGS, WHEEL WELL - ON (LOGO if needed), OTHER OFF
> WAITING FOR CARGO UNLOAD AND PASSENGER UNBOARDING <	
GND PWR	IF AVAIL, ON
APU SWITCH	OFF
BAT SWITCH	OFF (UNGUARDED)

LIMITS			
WEIGHTS "KGS" (FROM B737 TECHNICAL SITE)			
	300	400	500
MZFW	47625	51256	46720
MTOW	56472	62822	62823
MLW	51710	54885	49895
MAXIMUM OPERATING PRESSURE ALTITUDE			
37000 FEET			
OPERATING SPEED IN TURBULENCE			
1 5000 FEET & ABOVE		BELOW 15000	
280 Kts		250 Kts	
MAXIMUM WIND COMPONENT - T/O & LANDING			
CROSS-WIND 35Kts  10 Kts TAILWIND			

FOR ABNORMAL PROCEDURES REFER TO THE CORRECT CHECKLIST OR TO THE AIRCRAFT MANUAL

FOR FLIGHT SIMULATION ONLY - DO NOT USE FOR REAL WORLD FLIGHT