

Airfoillabs C172 NG Digital		AFTER START		TAKEOFF		APPROACH and LANDING			
Controls - Maint - Loadout+Fuel		Throttle	1000 RPM	Normal		LDG Lights	On		
		Oil Pressure	Check	Flaps	UP or 10°	Cabin Power 12V	Off		
		AMPS M Batt+Batt S	Check	Mixture	Full Rich	Mixture	Full Rich		
		Low Volts Annunc	Check	Throttle	Full	Barometer	Set		
Outside Check	Complete	NAV Lights	On	Rotate at ~55 kts Climb Speed 70-80 kts Flaps UP		Flaps 10°	110 kts		
PREFLIGHT		Avionics BUS	Both On			20° to Full	85 kts		
Externals	Removed	Barometer	Set			Flaps Full for SFL Vref 60-70 kts			
Parking Brake	Set	Coms + Nav	Set						
Control Wheel Lock	Removed	Transponder	Set + STBY						
Rudder Gust Lock	Removed	Flight Plan	Set						
Trim	T/O Position	ALT + HDG	Set	Short Field Flaps 10° Brakes Apply Mixture Full Rich Throttle Full Brakes Release		GO AROUND			
Fuel Selector	Both	CDI Nav Source	As Req						
Fuel Shutoff Valve	On (In)	BEFORE TAKEOFF						AFTER LANDING	
ALT Static Air	Off								
ENGINE START (BATT)				CLIMB		SECURING			
Circuit Breakers	Check In			Parking Brake	Set	Climb Speed	70-85 kts		
All Switches	Off	Doors	Closed	Throttle	Full	Throttle	Idle		
Throttle Open 1/4 Inch Mixture Cutoff STBY Batt Test + Arm		Fuel Quantity	Check	Mixture	Rich/Max RPM	Electrical Equipment	Off		
		Mixture	Full Rich	Engine Parameters	Check	Avionics BUS	Both Off		
		Throttle	1800 RPM	Throttle	1000 RPM	Mixture	Cutoff		
		Magnetos	Check	CRUISE		BATT + ALT Off STBY BATT Off Control Locks Installed Fuel Selector Left or Right Externals Installed			
VAC Indicator	Check	Power	2100-2700 RPM						
Electrics	Check	Mixture	Lean						
Engine Parameters	Check	LDG Lights	Off						
Beacon	On	Throttle	1000 RPM	Cabin Power 12V	As Req	LIMITS			
Priming (If Eng is cold) Fuel Pump On Mixture Full Rich >> Off Fuel Pump Off		Cabin Power 12V	Off	DESCENT					
		Flaps	UP or 10°					Power	As Desired
		Pitot Heat	On					Mixture	Adjust
		Windows	Closed			Barometer	Set		
Magnetos	Start	STROBE Lights	On	Fuel	Check	Best Glide Speed 65 kts Max Xwind TO+LDG 15 kts Never Exceed 163 kts			
Mixture adv smoothly to Rich on Start		LDG Lights	On	Max Oil Temp 118°C Min/Max Oil Press 20/115 PSI					
		Transponder	ALT						
		If Flooded Mixture Cutoff Throttle Half to Full Magnetos Start When Starting - Mix to Rich/Thrtrl Idle							