



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering

Ref. No.: IIT(BHU)/CE/KrKP/25-26/UPRNSS/ITI/ Mirzapur/02

Date: 14/11/2025

Third Party Inspection Report on Construction of Workshop and Residential Buildings in ITI Dist. Mirzapur (UP)

A. General

1	Reference letter no.	592/Work-161/168, Dated: 14/08/2025
2	Date of Inspection	14 th September, 2025
3	Name of Construction Agency	UPRNSS Ltd., Mirzapur
4	Name of Architect	M/s Elevatuns Consultant, Lucknow
5	Name of Structural Consultant	M/s ATS Structures, Lucknow
6	Name of the officials present during site inspection	Er. Ranjeet Singh Rathore, AE, UPRNSS, Mirzapur
7	% progress of work at the time of inspection	80 %
8	Type of work	G Framed structure and Masonry Structure
9	Name of Contractor	M/s Yogidev Construction, Varanasi
10	Foundation	Isolated and strip footing

B. List of the site elements

1. Plastic Processing Lab
2. Type 3 (2 nos.)
3. Type 2 (1 nos.)
4. Rain water harvesting
5. CC road

Krishna Kaur
Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005

C. Progress of the work

Following is the progress of work-



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering

Sr. No.	Elements	Progress	Remark
1	Plastic Processing Lab	Structure work is completed. Flooring and brick koba works are completed. Door window work completed. Plastering, painting and fire fighting works completed. Flooring work completed. Electrical and sanitary works are in progress.	Minor seepage is observed on the walls. It should be rectified. Overall quality of construction is found satisfactory.
2	Type 3 (2 nos.)	Structure work is completed. Plastering is completed. Painting, electrical and sanitary works are in progress.	Overall quality of construction is found satisfactory.
3	Type 2 (1 nos.)	Structure work is completed. Plastering is completed. Door window frame fixing works are in progress. Flooring works are in progress.	Overall quality of construction is found satisfactory.
4	Rain water harvesting	Two numbers of Rain Water harvesting units have been constructed.	Overall quality of construction is found satisfactory.
5	CC road	CC road work is completed as per the specification.	Overall quality of construction is found satisfactory.
Overall Progress		80 %	

D. Material used

1	Concrete	M20 (1:1.5:3) (Nominal Mix)
2	Brick	150 class
3	Cement	PPC- Prism & Ultratech cement
4	Reinforcement	Kamdheni TMT Fe 500
5	Sand	Zone 2

Krishna Kant

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering

E. Routine quality control

1	Material testing report	Testing has been done at IIT(BHU)
2	Quality inspection	Regular inspection by approved committee.
3	Vetted design and drawing details	Approved drawings are available at site.
4	Soil investigation report	Soil investigation reports are available at site.

F. Quality statement

The overall quality of the Workshop and Residential Buildings in ITI Dist. Mirzapur (UP) is found satisfactory.

G. Recommendations

- ❖ Unfilled flooring joints should be completely grouted.
- ❖ Rough surfaces on the ceiling and walls should be rectified.
- ❖ Thickness of the plaster should be maintained as per the norms.
- ❖ Choked water outlets should be cleaned.
- ❖ Back filling of around the buildings should be completed.

K.K. Pathak

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005

Prof. K.K. Pathak
Department of Civil Engineering
Indian Institute of Technology (BHU)



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering



Fig. 1: Plastic processing lab- Front view



Fig. 2: Plastic processing lab-Side view

Krishna Cawt

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering



Latitude: 25.125602
Longitude: 82.567845
Elevation: 103.63±4.65 m
Accuracy: 10.15 m
Time: 09-14-2025 12:02
Note: ITI MIRZAPUR

Fig. 3: Study of documents

Krishna Kant

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering



Fig. 4: Rain water harvesting pit



Fig. 5: Status of type 3 quarters

Krishna Cawt

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering



Fig. 6: Inspection of door fixing



Fig. 7: Checking of documents

Krishna Kaur

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering



Latitude: 25.127658
Longitude: 82.568411
Elevation: 104.84±15.3 m
Accuracy: 3.0 m
Time: 09-14-2025 12:18
Note: ITI MIRZAPUR

Fig. 8: Status of type 2 quarter

Krishna Caut

Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005



भारतीय
प्रौद्योगिकी
संस्थान
काशी हिन्दू विश्वविद्यालय



INDIAN
INSTITUTE OF
TECHNOLOGY
BANARAS HINDU UNIVERSITY

Department of Civil Engineering



Latitude: 25.127746
Longitude: 82.568296
Elevation: 115.54±16.4 m
Accuracy: 2.7 m
Time: 09-14-2025 12:20
Note: ITI MIRZAPUR

Powered by NoteCam

Fig. 9: Inspection of toilet



Latitude: 25.12725
Longitude: 82.567685
Elevation: 105.44±13.9 m
Accuracy: 2.5 m
Time: 09-14-2025 12:15
Note: ITI MIRZAPUR

Powered by NoteCam

Fig. 10: Measurement of dimensions

Krishna Kant
Prof. K.K. PATHAK
Department of Civil Engineering
Indian Institute of Technology
Banaras Hindu University
Varanasi-221005