



TEST REPORT

Departmental Consultancy No.- CE/2224

Sample: Burnt Clay Brick

Source of Sample: Executive Engineer, U.P.R.N.S.S. Ltd, Bahraich (U.P.).

Name of Work: चिकित्सा महाविद्यालय बहराइच से सम्बद्ध महर्षि बालार्क चिकित्सालय (पूर्व में जिला चिकित्सालय पुरुष/महिला के पुराने भवन) में बाउन्ड्रीवाल का निर्माण कार्य।

Reference: 365/बह0/यू0पी0आर0एन0एस0एस0/2024-25/डी0- Dated: 19/03/2025

Tested for: Physical Properties

Tested as per: IS 1077:1992, IS 3495:1992, IS 5454:1976

No. of Sample: One set only.

Identification Mark: GOLD

TEST RESULTS


Sr. No.	Frog Mark	Examination of General Quality and Size	Average Compressive Strength (MPa)
1.	GOLD	The bricks are free from cracks & flaws, have smooth rectangular faces with sharp corners.	16.32

Conditions:

- 1) Results given above refer only to the sample(s) supplied. Since the representative sample has not been taken in our presence, we don't take any responsibility regarding the quality of bulk material from which the sample was sent for testing in the laboratory.
- 2) The report in full or in any part should not be published, advertised, photocopied or used for any legal action unless prior permission has been obtained from the Director, REC, Ambedkar Nagar.
- 3) This report is being issued on the specific understanding that REC, Ambedkar Nagar will in no way be involved in any action following the interpretation of the above results.


(Pooja Pathak)
Lab. Staff


(Amit Kumar Rai)
Co-Principal Investigator


(Avaneesh Kr. Yadav)
Principal Investigator