

Setup Sheet Report

GENERIC HAAS 3 - AXIS VMC

GENER.				
	ΔI I	$N \vdash C \vdash $	' N/I / A I	


PROJECT NAME: CUSTOMER NAME: PROGRAMMER:

DRAWING: REVISION:

DATE: Monday, April 3, 2023

TIME: 10:18 AM

C:\USERS\WESTONSHAKESPEAR\DOWNLOADS\WSHAKESPEAR_MILL 11B_1.EMCAM






1.5049 in Inch

COMMENTS				

-	



STOCK: YES SHAPE: Solid

SIZE: 8.2935, 4.4555, 1.25

RADIUS: LENGTH:

AXIS: NA

FILE:

IDN: 6949

C:\USERS\WESTONSHAKESPEAR\DOCUMENTS\MY

CYCLE TIME: 0 HOURS, 14 MINUTES, 30 SECONDS

OPERATION LIST

OPERATION INFO 1 - Facing

CYCLE TIME: 0 HOURS, 1 MINUTES, 13 SECONDS

COMMENT:

PROGRAM NUMBER: 0

SPINDLE SPEED: 4966 RPM FEEDRATE: 50.0 inch/min

CLEARANCE PLANE: 2.0

RETRACT PLANE: 0.125

FEED PLANE: 0.05

DEPTH: 0.0

STOCK TO LEAVE: 0.0

COMP TO TIP: YES

WORK OFFSET: 0

TOOL INFO 1/2 FLAT ENDMILL


TYPE: Flat endmill

NUMBER: 1
DIAMETER: 0.5
CORNER RADIUS: 0.0
LENGTH OFFSET: 1
DIAMETER OFFSET: 1
MATERIAL: HSS
NUMBER OF FLUTES: 4

FPT: 0.0025 SFM: 650.0

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:01:13



OPERATION INFO 2 - Contour (2D)

CYCLE TIME:

0 HOURS, 1 MINUTES, 29 SECONDS

COMMENT:

PROGRAM NUMBER: 0

SPINDLE SPEED: 4966 RPM FEEDRATE: 45.0 inch/min

CLEARANCE PLANE: 2.0

RETRACT PLANE: 0.125


FEED PLANE: 0.2

DEPTH: -0.8

STOCK TO LEAVE: 0.0

COMP TO TIP: YES

WORK OFFSET: 0



TOOL INFO 1/2 FLAT ENDMILL

TYPE: Flat endmill


NUMBER: 1
DIAMETER: 0.5
CORNER RADIUS: 0.0
LENGTH OFFSET: 1
DIAMETER OFFSET: 1
MATERIAL: HSS
NUMBER OF FLUTES: 4

FPT: 0.0025 SFM: 650.0

MFG CODE:

ASSEMBLY:

HOLDER: Default Holder TIME: 00:01:29



OPERATION INFO 3 - 3D High Speed (Area roughing)


CYCLE TIME: 0 HOURS, 6 MINUTES, 31 SECONDS

COMMENT:

PROGRAM NUMBER: 0

SPINDLE SPEED: 6621 RPM FEEDRATE: 50.0 inch/min

CLEARANCE PLANE: 0.25
RETRACT PLANE: 0.15
FEED PLANE: 0.025
DEPTH: NA
STOCK TO LEAVE: 0.05
COMP TO TIP: YES
WORK OFFSET: 0



TOOL INFO 3/8 BULL ENDMILL 0.0625 RAD

TYPE: Bull endmill

NUMBER: 2
DIAMETER: 0.375
CORNER RADIUS: 0.0625
LENGTH OFFSET: 2
DIAMETER OFFSET: 2
MATERIAL: HSS
NUMBER OF FLUTES: 4

FPT: 0.0015 SFM: 139.9869

FPT: 0.0015 MFG CODE:

ASSEMBLY:

HOLDER: Default Holder TIME: 00:06:31

2.000 -1.000 3.500 2.500

OPERATION INFO 4 - Surface Finish Flowline


CYCLE TIME: 0 HOURS, 5 MINUTES, 6 SECONDS

COMMENT:

PROGRAM NUMBER: 0

SPINDLE SPEED: 6621 RPM FEEDRATE: 55.0 inch/min

CLEARANCE PLANE: 0.25
RETRACT PLANE: 0.125
FEED PLANE: 0.05
DEPTH: NA
STOCK TO LEAVE: 0.0
COMP TO TIP: YES
WORK OFFSET: 0



TOOL INFO 3/8 BALL ENDMILL


TYPE: Ball endmill

NUMBER: 3
DIAMETER: 0.375
CORNER RADIUS: 0.1875
LENGTH OFFSET: 3
DIAMETER OFFSET: 3
MATERIAL: HSS
NUMBER OF FLUTES: 4

FPT: 0.0011 SFM: 139.9869

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:05:06



OPERATION INFO 5 - Contour (3D)

CYCLE TIME:


0 HOURS, 0 MINUTES, 10 SECONDS

COMMENT:

PROGRAM NUMBER: 0

SPINDLE SPEED: 7500 RPM FEEDRATE: 30.0 inch/min

CLEARANCE PLANE: 2.0
RETRACT PLANE: 0.125
FEED PLANE: 0.2
DEPTH: -0.02
STOCK TO LEAVE: 0.0
COMP TO TIP: YES
WORK OFFSET: 0




TOOL INFO 1/8 SPOTDRILL

TYPE: Spot drill NUMBER: 4 DIAMETER: 0.125 **CORNER RADIUS:** 0.0 LENGTH OFFSET: 4 DIAMETER OFFSET: 4 MATERIAL: HSS NUMBER OF FLUTES: 2

FPT: 0.0024 SFM: 162.5

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:00:10



TOOL LIST Sorted: NO

TOOL INFO 1/2 FLAT ENDMILL

TYPE: Flat endmill
NUMBER: 1
DIAMETER: 0.5
CORNER RADIUS: 0.0
LENGTH OFFSET: 1
DIAMETER OFFSET: 1
MATERIAL: HSS
NUMBER OF FLUTES: 4

FPT: 0.0025 SFM: 650.0

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:02:42

USED BY OPERATION: #1 1 - Facing
USED BY OPERATION: #2 2 - Contour (2D)

TOOL INFO 3/8 BULL ENDMILL 0.0625 RAD


TYPE: Bull endmill
NUMBER: 2
DIAMETER: 0.375
CORNER RADIUS: 0.0625
LENGTH OFFSET: 2
DIAMETER OFFSET: 2
MATERIAL: HSS
NUMBER OF FLUTES: 4


FPT: 0.0015 SFM: 139.9869

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:06:31

USED BY OPERATION: #3 3 - 3D High Speed (Area roughing)





TOOL INFO 3/8 BALL ENDMILL


TYPE: Ball endmill

NUMBER: 3
DIAMETER: 0.375
CORNER RADIUS: 0.1875
LENGTH OFFSET: 3
DIAMETER OFFSET: 3
MATERIAL: HSS
NUMBER OF FLUTES: 4

FPT: 0.0011 SFM: 139.9869

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:05:06



USED BY OPERATION: #4 4 - Surface Finish Flowline

TOOL INFO 1/8 SPOTDRILL


TYPE: Spot drill
NUMBER: 4
DIAMETER: 0.125
CORNER RADIUS: 0.0
LENGTH OFFSET: 4
DIAMETER OFFSET: 4
MATERIAL: HSS
NUMBER OF FLUTES: 2

FPT: 0.0024 SFM: 162.5

MFG CODE: ASSEMBLY:

HOLDER: Default Holder TIME: 00:00:10

USED BY OPERATION: #5 5 - Contour (3D)



WORK OFFSETS

OFFSET INFO

NUMBER: 0	PLANE: Top	ORIGIN: 0.0, 0.0, 0.0
USED BY OPERA	TION: #1	1 - Facing
USED BY OPERA	ATION: #2	2 - Contour (2D)
USED BY OPERA	ATION: #3	3 - 3D High Speed (Area roughing)
USED BY OPERA	ATION: #4	4 - Surface Finish Flowline
USED BY OPERA	ATION: #5	5 - Contour (3D)