

CCET 3680 Mill Lesson 5 Second Exercise


I. Wireframe:




II. Dimensions:



III. Solid:




IV. Toolpaths:




V. Name 2D Contour:




VI. Spot Drill:




VII. Peck Drill:




VIII. 2D Contour Outside:




IX. 2D Contour Inside:




X. 2D Chamfer Contour Outside:




XI. 2D Chamfer Contour Inside:




XII: 2D Chamfer Contour:



XIII: 2D Contour:



XIV. Final Solid:



XV. Method:

I just used a basic center anchored rectangle for the perimeter of the geometry. For the wireframe in the center I first created the inner circle then drew a line and manually assigned 30 degrees to the angle, this let me create the equidistant triangle in the center, from there I drew the 3 circles and then used the tangent 2 entities to complete the center.

Then I drew one copy of the radially symmetric portion and used a polar copy to finish the wireframe.

XIV. GCode Changes

To modify my gcode to be compatible with the machine I first made sure the HAAS 3 axis post processor was selected when exporting the gcode. Then I removed the long lines at the beginning and edited the last G28 home command to not zero the x axis.

XV. Finished Part



XVI. Gcode:

%

033005

(WSHAKESPEAR_MILL LESSON 5B)

(DATE=DD-MM-YY - 03-02-23 TIME=HH:MM - 12:01)

(MCAM FILE - C:\USERS\WESTONSHAKESPEAR\DOWNLOADS\WSHAKESPEAR_MILL LESSON
5B.EMC)

(NC FILE - C:\USERS\WESTONSHAKESPEAR\DOWNLOADS\GCODE\WSHAKESPEAR_MILL LESSON 5B)

(MATERIAL - ALUMINUM INCH - 6061)

(T7|1/8 SPOTDRILL|H7|D7|T00L DIA. - .125)

(T3|1/2 SPOTDRILL|H3|D3|TOOL DIA. - .5)

(T5|1/4 DRILL|H5|D5|T00L DIA. - .25)

(T4|1/2 FLAT ENDMILL|H4|D4|TOOL DIA. - .5)

N100 G20

N110 G0 G17 G40 G49 G80 G90

N120 T7 M6

N130 G187 P3 E.001

N140 G0 G90 G54 X-1.0209 Y.32 S5000 M3

- N150 G43 H7 Z.145
- N160 G1 Z.118 F6.4
- N170 X-.9097 Y.2562 F40.
- N180 X-.9707 Y.3703
- N190 X-.9674 Y.3735
- N200 X-.8533 Y.3125
- N210 X-.9172 Y.4237
- N220 Z.138 F6.4
- N230 G0 Z.145
- N240 X-.7552 Y.4131
- N250 G1 Z.118
- N260 X-.811 Y.3572 F40.
- N270 X-.8961 Y.4423
- N280 X-.8403 Y.4982
- N290 Z.138 F6.4
- N300 G0 Z.145
- N310 X-.8028 Y.4542
- N320 G1 Z.118
- N330 X-.8554 Y.4016 F40.
- N340 Z.138 F6.4
- N350 G0 Z.145
- N360 X-.746 Y.5595
- N370 G1 Z.118
- N380 X-.7572 Y.5627 F40.
- N390 X-.7691 Y.5617
- N400 X-.7806 Y.5566
- N410 X-.7909 Y.5482
- N420 X-.8005 Y.5356
- N430 X-.8053 Y.5224
- N440 X-.8052 Y.5098
- N450 X-.7998 Y.4998
- N460 X-.7873 Y.4929
- N470 X-.7854 Y.4926
- N480 X-.7702 Y.4943
- N490 X-.7644 Y.4964
- N500 X-.7339 Y.5136
- N510 X-.7185 Y.5188
- N520 X-.7127 Y.519
- N530 X-.7013 Y.5155
- N540 X-.6974 Y.5124
- N550 X-.6919 Y.5025
- N560 X-.6911 Y.4896

- N570 X-.6955 Y.476
- N580 X-.7055 Y.4628
- N590 X-.7156 Y.4547
- N600 X-.7267 Y.4494
- N610 X-.7379 Y.4478
- N620 X-.7476 Y.4497
- N630 X-.7562 Y.4535
- N640 Z.138 F6.4
- N650 G0 Z.145
- N660 X-.7089 Y.6295
- N670 G1 Z.118
- N680 X-.6226 Y.5432 F40.
- N690 Z.138 F6.4
- N700 G0 Z.145
- N710 X-.7414 Y.5971
- N720 G1 Z.118
- N730 X-.6769 Y.6615 F40.
- N740 Z.138 F6.4
- N750 G0 Z.145
- N760 X-.6145 Y.6384
- N770 G1 Z.118
- N780 X-.6278 Y.6573 F40.
- N790 X-.6283 Y.6585
- N800 X-.6335 Y.6804
- N810 Y.6809
- N820 X-.6309 Y.7007
- N830 X-.6303 Y.7028
- N840 X-.6204 Y.7196
- N850 X-.6182 Y.7219
- N860 X-.6018 Y.7327
- N870 X-.5996 Y.7335
- N880 X-.5799 Y.7368
- N890 X-.5776
- N900 X-.5566 Y.7322
- N910 X-.5552 Y.7316
- N920 X-.5363 Y.7189
- N930 X-.5352 Y.7178
- N940 X-.522 Y.699
- N950 X-.5216 Y.698
- N960 X-.5164 Y.6757
- N970 Y.6756
- N980 X-.5194 Y.6543

N990 X-.5197 Y.6536

N1000 X-.5301 Y.6365

N1010 X-.5315 Y.6351

N1020 X-.5463 Y.6246

N1030 X-.5504 Y.6229

N1040 X-.571 Y.6196

N1050 X-.5723 Y.6197

N1060 X-.5945 Y.6248

N1070 X-.5947 Y.6249

N1080 X-.6131 Y.637

N1090 X-.6145 Y.6384

N1100 Z.138 F6.4

N1110 G0 Z.145

N1120 X-.4716 Y.6942

N1130 G1 Z.118

N1140 X-.5592 Y.7817 F40.

N1150 X-.41 Y.7558

N1160 X-.4976 Y.8433

N1170 Z.138 F6.4

N1180 G0 Z.145

N1190 X-.8266 Y.2088

N1200 G1 Z.118

N1210 X-.8571 Y.1916 F40.

N1220 X-.8727 Y.1876

N1230 X-.8781 Y.1877

N1240 X-.8859 Y.1902

N1250 X-.8925 Y.195

N1260 X-.8979 Y.205

N1270 X-.898 Y.2176

N1280 X-.8932 Y.2308

N1290 X-.8836 Y.2434

N1300 X-.8733 Y.2518

N1310 X-.8618 Y.2569

N1320 X-.8499 Y.2579

N1330 X-.8387 Y.2547

N1340 Z.138 F6.4

N1350 G0 Z.145

N1360 X-.7901 Y.2076

N1370 G1 Z.118

N1380 X-.8019 Y.2137 F40.

N1390 X-.8054 Y.2142

N1400 X-.8154 Y.2132

- N1410 X-.8266 Y.2088
- N1420 X-.8571 Y.1916
- N1430 X-.8727 Y.1876
- N1440 X-.8781 Y.1877
- N1450 X-.8859 Y.1902
- N1460 X-.8925 Y.195
- N1470 X-.8979 Y.205
- N1480 X-.898 Y.2176
- N1490 X-.8932 Y.2308
- N1500 X-.8836 Y.2434
- N1510 X-.8733 Y.2518
- N1520 X-.8618 Y.2569
- N1530 X-.8499 Y.2579
- N1540 X-.8387 Y.2547
- N1550 Z.138 F6.4
- N1560 G0 Z.145
- N1570 X-.7982 Y.158
- N1580 G1 Z.118
- N1590 X-.7882 Y.1712 F40.
- N1600 X-.7838 Y.1848
- N1610 X-.7846 Y.1977
- N1620 X-.7901 Y.2076
- N1630 X-.8019 Y.2137
- N1640 X-.8054 Y.2142
- N1650 X-.8154 Y.2132
- N1660 X-.8266 Y.2088
- N1670 X-.8571 Y.1916
- N1680 X-.8727 Y.1876
- N1690 X-.8781 Y.1877
- N1700 X-.8859 Y.1902
- N1710 X-.8925 Y.195
- N1720 X-.8979 Y.205
- N1730 X-.898 Y.2176
- N1740 X-.8932 Y.2308
- N1750 X-.8836 Y.2434
- 11730 X .0030 1.2434
- N1760 X-.8733 Y.2518
- N1770 X-.8618 Y.2569
- N1780 X-.8499 Y.2579
- N1790 X-.8387 Y.2547
- N1800 Z.138 F6.4
- N1810 G0 Z.145
- N1820 X-.8489 Y.1487

- N1830 G1 Z.118
- N1840 X-.8403 Y.1449 F40.
- N1850 X-.8306 Y.1429
- N1860 X-.8194 Y.1446
- N1870 X-.8082 Y.1499
- N1880 X-.7982 Y.158
- N1890 X-.7882 Y.1712
- N1900 X-.7838 Y.1848
- N1910 X-.7846 Y.1977
- N1920 X-.7901 Y.2076
- N1930 X-.8019 Y.2137
- N1940 X-.8054 Y.2142
- N1950 X-.8154 Y.2132
- N1960 X-.8266 Y.2088
- N1970 X-.8571 Y.1916
- N1980 X-.8727 Y.1876
- N1990 X-.8781 Y.1877
- N2000 X-.8859 Y.1902
- N2010 X-.8925 Y.195
- N2020 X-.8979 Y.205
- N2030 X-.898 Y.2176
- N2040 X-.8932 Y.2308
- N2050 X-.8836 Y.2434
- N2060 X-.8733 Y.2518
- N2070 X-.8618 Y.2569
- N2080 X-.8499 Y.2579
- N2090 X-.8387 Y.2547
- N2100 Z.138 F6.4
- N2110 G0 Z.145
- N2120 X-.7479 Y.2059
- N2130 G1 Z.118
- N2140 X-.8354 Y.2934 F40.
- N2150 Z.138 F6.4
- N2160 G0 Z.145
- N2170 X-.7293 Y.3156
- N2180 G1 Z.118
- N2190 X-.7935 Y.2515 F40.
- N2200 Z.138 F6.4
- N2210 G0 Z.145
- N2220 X-.6837 Y.27
- N2230 G1 Z.118
- N2240 X-.7713 Y.3575 F40.

N2250 Z.138 F6.4

N2260 G0 Z.145

N2270 X-.6638 Y.2899

N2280 G1 Z.118

N2290 X-.716 Y.4128 F40.

N2300 X-.5931 Y.3606

N2310 Z.138 F6.4

N2320 G0 Z.145

N2330 X-.6811 Y.3317

N2340 G1 Z.118

N2350 X-.6349 Y.3779 F40.

N2360 Z.138 F6.4

N2370 G0 Z.145

N2380 X-.6606 Y.4682

N2390 G1 Z.118

N2400 X-.5731 Y.3806 F40.

N2410 Z.138 F6.4

N2420 G0 Z.145

N2430 X-.6027 Y.5261

N2440 G1 Z.118

N2450 X-.6026 Y.4102 F40.

N2460 Z.138 F6.4

N2470 G0 Z.145

N2480 X-.6027 Y.4575

N2490 G1 Z.118

N2500 X-.5123 Y.4414 F40.

N2510 Z.138 F6.4

N2520 G0 Z.145

N2530 X-.4381 Y.5181

N2540 G1 Z.118

N2550 X-.494 Y.4622 F40.

N2560 X-.579 Y.5473

N2570 X-.5232 Y.6031

N2580 Z.138 F6.4

N2590 G0 Z.145

N2600 X-.5384 Y.5066

N2610 G1 Z.118

N2620 X-.4857 Y.5592 F40.

N2630 Z.138 F6.4

N2640 G0 Z.145

N2650 X-.4391 Y.5585

N2660 G1 Z.118

- N2670 X-.4305 Y.5547 F40.
- N2680 X-.4209 Y.5527
- N2690 X-.4096 Y.5544
- N2700 X-.3985 Y.5596
- N2710 X-.3884 Y.5678
- N2720 X-.3784 Y.5809
- N2730 X-.374 Y.5946
- N2740 X-.3748 Y.6074
- N2750 X-.3803 Y.6174
- N2760 X-.3921 Y.6235
- N2770 X-.3956 Y.624
- N2780 X-.4056 Y.6229
- N2790 X-.4169 Y.6185
- N2800 X-.4473 Y.6013
- N2810 X-.4629 Y.5973
- N2820 X-.4684 Y.5975
- N2830 X-.4762 Y.6
- N2840 X-.4828 Y.6048
- N2850 X-.4881 Y.6148
- N2860 X-.4882 Y.6274
- N2870 X-.4834 Y.6406
- N2880 X-.4738 Y.6532
- N2890 X-.4635 Y.6616
- N2900 X-.4521 Y.6667
- N2910 X-.4401 Y.6677
- N2920 X-.4289 Y.6645
- N2930 Z.138 F6.4
- N2940 G0 Z.145
- N2950 X-.3382 Y.6155
- N2960 G1 Z.118
- N2970 X-.4245 Y.7018 F40.
- N2980 X-.3908 Y.7355
- N2990 X-.38 Y.7433
- N3000 X-.3669 Y.7475
- N3010 X-.3533 Y.7465
- N3020 X-.3413 Y.7394
- N3030 X-.3342 Y.7274
- N3040 X-.3332 Y.7139
- N3050 X-.3374 Y.7007
- N3060 X-.3452 Y.6899
- N3070 X-.3789 Y.6562
- N3080 Z.138 F6.4

N3090 G0 Z.145

N3100 X-.2031 Y.7531

N3110 G1 Z.118

N3120 X-.259 Y.6972 F40.

N3130 X-.344 Y.7823

N3140 X-.2882 Y.8381

N3150 Z.138 F6.4

N3160 G0 Z.145

N3170 X-.2507 Y.7942

N3180 G1 Z.118

N3190 X-.3033 Y.7416 F40.

N3200 Z.138 F6.4

N3210 G0 Z.145

N3220 X-.1825 Y.7713

N3230 G1 Z.118

N3240 X-.2346 Y.8942 F40.

N3250 X-.1117 Y.842

N3260 Z.138 F6.4

N3270 G0 Z.145

N3280 X-.1997 Y.8131

N3290 G1 Z.118

N3300 X-.1535 Y.8593 F40.

N3310 Z.138 F6.4

N3320 G0 Z.145

N3330 X-.0917 Y.862

N3340 G1 Z.118

N3350 X-.1779 Y.9482 F40.

N3360 X-.1389 Y.9873

N3370 X-.128 Y.9946

N3380 X-.1157 Y.9978

N3390 X-.1032 Y.996

N3400 X-.0918 Y.9887

N3410 X-.0845 Y.9773

N3420 X-.0825 Y.9647

N3430 X-.0857 Y.9523

N3440 X-.0933 Y.9417

N3450 X-.1323 Y.9026

N3460 Z.138 F6.4

N3470 G0 Z.145

N3480 X-.0983 Y.9366

N3490 G1 Z.118

N3500 X-.0835 Y.9407 F40.

N3510 X-.0682 Y.9397

N3520 X-.0237 Y.93

N3530 Z.138 F6.4

N3540 G0 Z.145

N3550 M5

N3560 G91 G28 Z0.

N3570 M01

N3580 T3 M6

N3590 G187 P3 E.001

N3600 G0 G90 G54 X-1.125 Y1.125 S5000 M3

N3610 G43 H3 Z.25

N3620 M8

N3630 Z.15

N3640 G99 G81 Z-.01 R.15 F40.

N3650 X1.125

N3660 Y-1.125

N3670 X-1.125

N3680 G80

N3690 Z.25

N3700 M5

N3710 G91 G28 Z0. M9

N3720 M01

N3730 T5 M6

N3740 G187 P3 E.001

N3750 G0 G90 G54 X-1.125 Y1.125 S5000 M3

N3760 G43 H5 Z.25

N3770 Z.15

N3780 G99 G83 Z-.155 R.15 Q.075 F20.

N3790 X1.125

N3800 Y-1.125

N3810 X-1.125

N3820 G80

N3830 Z.25

N3840 M5

N3850 G91 G28 Z0.

N3860 M01

N3870 T4 M6

N3880 G187 P3 E.001

N3890 G0 G90 G54 X-2.625 Y-.5 S5000 M3

N3900 G43 H4 Z.25

N3910 M8

N3920 Z.2

N3930 G1 Z0. F6.4

N3940 X-2.125 F40.

N3950 G3 X-1.625 Y0. I0. J.5

N3960 G2 X-1.5968 Y.3014 I1.625 J0.

N3970 G1 X-1.6144 Y.3111

N3980 G2 X-1.875 Y.75 I.2394 J.4389

N3990 G1 Y1.125

N4000 G2 X-1.125 Y1.875 I.75 J0.

N4010 G1 X-.75

N4020 G2 X-.3111 Y1.6144 I0. J-.5

N4030 G1 X-.3014 Y1.5968

N4040 G2 X0. Y1.625 I.3014 J-1.5968

N4050 X.3014 Y1.5968 IO. J-1.625

N4060 G1 X.3111 Y1.6144

N4070 G2 X.75 Y1.875 I.4389 J-.2394

N4080 G1 X1.125

N4090 G2 X1.875 Y1.125 I0. J-.75

N4100 G1 Y.75

N4110 G2 X1.6144 Y.3111 I-.5 J0.

N4120 G1 X1.5968 Y.3014

N4130 G2 X1.625 Y0. I-1.5968 J-.3014

N4140 X1.5968 Y-.3014 I-1.625 J0.

N4150 G1 X1.6144 Y-.3111

N4160 G2 X1.875 Y-.75 I-.2394 J-.4389

N4170 G1 Y-1.125

N4180 G2 X1.125 Y-1.875 I-.75 J0.

N4190 G1 X.75

N4200 G2 X.3111 Y-1.6144 IO. J.5

N4210 G1 X.3014 Y-1.5968

N4220 G2 X0. Y-1.625 I-.3014 J1.5968

N4230 X-.3014 Y-1.5968 IO. J1.625

N4240 G1 X-.3111 Y-1.6144

N4250 G2 X-.75 Y-1.875 I-.4389 J.2394

N4260 G1 X-1.125

N4270 G2 X-1.875 Y-1.125 IO. J.75

N4280 G1 Y-.75

N4290 G2 X-1.6144 Y-.3111 I.5 J0.

N4300 G1 X-1.5968 Y-.3014

N4310 G2 X-1.625 Y0. I1.5968 J.3014

N4320 G3 X-2.125 Y.5 I-.5 J0.

N4330 G1 X-2.625

N4340 Z.2 F6.4

N4350 G0 Z.25

N4360 X-2.375 Y-.5

N4370 Z.2

N4380 G1 Z0.

N4390 X-1.875 F40.

N4400 G3 X-1.375 Y0. I0. J.5

N4410 G2 X-1.3067 Y.428 I1.375 J0.

N4420 G1 X-1.4947 Y.5305

N4430 G2 X-1.625 Y.75 I.1197 J.2195

N4440 G1 Y1.125

N4450 G2 X-1.125 Y1.625 I.5 J0.

N4460 G1 X-.75

N4470 G2 X-.5305 Y1.4947 I0. J-.25

N4480 G1 X-.428 Y1.3067

N4490 G2 X0. Y1.375 I.428 J-1.3067

N4500 X.428 Y1.3067 IO. J-1.375

N4510 G1 X.5305 Y1.4947

N4520 G2 X.75 Y1.625 I.2195 J-.1197

N4530 G1 X1.125

N4540 G2 X1.625 Y1.125 IO. J-.5

N4550 G1 Y.75

N4560 G2 X1.4947 Y.5305 I-.25 J0.

N4570 G1 X1.3067 Y.428

N4580 G2 X1.375 Y0. I-1.3067 J-.428

N4590 X1.3067 Y-.428 I-1.375 J0.

N4600 G1 X1.4947 Y-.5305

N4610 G2 X1.625 Y-.75 I-.1197 J-.2195

N4620 G1 Y-1.125

N4630 G2 X1.125 Y-1.625 I-.5 J0.

N4640 G1 X.75

N4650 G2 X.5305 Y-1.4947 I0. J.25

N4660 G1 X.428 Y-1.3067

N4670 G2 X0. Y-1.375 I-.428 J1.3067

N4680 X-.428 Y-1.3067 IO. J1.375

N4690 G1 X-.5305 Y-1.4947

N4700 G2 X-.75 Y-1.625 I-.2195 J.1197

N4710 G1 X-1.125

N4720 G2 X-1.625 Y-1.125 IO. J.5

N4730 G1 Y-.75

N4740 G2 X-1.4947 Y-.5305 I.25 J0.

N4750 G1 X-1.3067 Y-.428

N4760 G2 X-1.375 Y0. I1.3067 J.428

N4770 G3 X-1.875 Y.5 I-.5 J0.

N4780 G1 X-2.375

N4790 Z.2 F6.4

N4800 G0 Z.25

N4810 M9

N4820 G187 P3 E.001

N4830 X-.1089 Y-.0543

N4840 Z.2

N4850 G3 X.037 Y-.0761 I.1459 J.4783 F40.

N4860 X.0739 Y-.0747 IO. J.5001

N4870 G1 X.0976 Y-.0727 Z.1988

N4880 X.1213 Y-.07 Z.1975

N4890 X.1047 Y-.033 Z.1954

N4900 X.0866 Y.0032 Z.1932

N4910 X.067 Y.0387 Z.1911

N4920 X.046 Y.0734 Z.189

N4930 X.0237 Y.1071 Z.1869

N4940 X0. Y.14 Z.1848

N4950 X-.0283 Y.1005 Z.1822

N4960 X-.0546 Y.0596 Z.1797

N4970 X-.0789 Y.0175 Z.1771

N4980 X-.1011 Y-.0258 Z.1746

N4990 X-.1213 Y-.07 Z.172

N5000 X-.081 Y-.0741 Z.1699

N5010 X-.0405 Y-.0766 Z.1677

N5020 X0. Y-.0774 Z.1656

N5030 X.0405 Y-.0766 Z.1635

N5040 X.081 Y-.0741 Z.1614

N5050 X.1213 Y-.07 Z.1593

N5060 X.1047 Y-.033 Z.1572

N5070 X.0866 Y.0032 Z.155

N5080 X.067 Y.0387 Z.1529

N5090 X.046 Y.0734 Z.1508

N5100 X.0237 Y.1071 Z.1486

N5110 X0. Y.14 Z.1465

N5120 X-.0283 Y.1005 Z.144

N5130 X-.0546 Y.0596 Z.1414

N5140 X-.0789 Y.0175 Z.1389

N5150 X-.1011 Y-.0258 Z.1363

N5160 X-.1213 Y-.07 Z.1338

N5170 X-.081 Y-.0741 Z.1317

N5180 X-.0405 Y-.0766 Z.1295

- N5190 XO. Y-.0774 Z.1274
- N5200 X.0405 Y-.0766 Z.1253
- N5210 X.081 Y-.0741 Z.1232
- N5220 X.1213 Y-.07 Z.1211
- N5230 X.1047 Y-.033 Z.119
- N5240 X.0866 Y.0032 Z.1168
- N5250 X.067 Y.0387 Z.1147
- N5260 X.046 Y.0734 Z.1126
- N5270 X.0237 Y.1071 Z.1104
- N5280 X0. Y.14 Z.1083
- N5290 X-.0283 Y.1005 Z.1058
- N5300 X-.0546 Y.0596 Z.1032
- N5310 X-.0789 Y.0175 Z.1007
- N5320 X-.1011 Y-.0258 Z.0981
- N5330 X-.1213 Y-.07 Z.0956
- N5340 X-.081 Y-.0741 Z.0935
- N5350 X-.0405 Y-.0766 Z.0913
- N5360 X0. Y-.0774 Z.0892
- N5370 X.0405 Y-.0766 Z.0871
- N5380 X.081 Y-.0741 Z.0849
- N5390 X.1213 Y-.07 Z.0828
- N5400 X.1047 Y-.033 Z.0807
- N5410 X.0866 Y.0032 Z.0786
- N5420 X.067 Y.0387 Z.0765
- N5430 X.046 Y.0734 Z.0744
- N5440 X.0237 Y.1071 Z.0722
- N5450 X0. Y.14 Z.0701
- N5460 X-.0283 Y.1005 Z.0675
- N5470 X-.0546 Y.0596 Z.065
- N5480 X-.0789 Y.0175 Z.0624
- N5490 X-.1011 Y-.0258 Z.0599
- N5500 X-.1213 Y-.07 Z.0573
- N5510 X-.081 Y-.0741 Z.0552
- N5520 X-.0405 Y-.0766 Z.053
- N5530 X0. Y-.0774 Z.0509
- N5540 X.0405 Y-.0766 Z.0488
- N5550 X.081 Y-.0741 Z.0467
- N5560 X.1213 Y-.07 Z.0446
- N5570 X.1047 Y-.033 Z.0425
- N5580 X.0866 Y.0032 Z.0403
- N5590 X.067 Y.0387 Z.0382
- N5600 X.046 Y.0734 Z.0361

N5610 X.0237 Y.1071 Z.034

N5620 X0. Y.14 Z.0319

N5630 X-.0283 Y.1005 Z.0293

N5640 X-.0546 Y.0596 Z.0268

N5650 X-.0789 Y.0175 Z.0242

N5660 X-.1011 Y-.0258 Z.0217

N5670 X-.1213 Y-.07 Z.0191

N5680 X-.081 Y-.0741 Z.017

N5690 X-.0405 Y-.0766 Z.0148

N5700 XO. Y-.0774 Z.0127

N5710 X.0405 Y-.0766 Z.0106

N5720 X.081 Y-.0741 Z.0085

N5730 X.1213 Y-.07 Z.0064

N5740 X.1047 Y-.033 Z.0043

N5750 X.0866 Y.0032 Z.0021

N5760 X.067 Y.0387 ZO.

N5770 G3 X0. Y.14 I-.866 J-.5

N5780 X-.1213 Y-.07 I.799 J-.6013

N5790 X0. Y-.0774 I.1213 J.9926

N5800 X.1213 Y-.07 IO. J1.

N5810 X.067 Y.0387 I-.9203 J-.3913

N5820 G1 X.046 Y.0734 Z.0021

N5830 X.0237 Y.1071 Z.0043

N5840 XO. Y.14 Z.0064

N5850 X-.0283 Y.1005 Z.0089

N5860 X-.0546 Y.0596 Z.0115

N5870 X-.0789 Y.0175 Z.014

N5880 X-.1011 Y-.0258 Z.0166

N5890 X-.1213 Y-.07 Z.0191

N5900 X-.081 Y-.0741 Z.0212

N5910 X-.0405 Y-.0766 Z.0234

N5920 XO. Y-.0774 Z.0255

N5930 X.0405 Y-.0766 Z.0276

N5940 X.081 Y-.0741 Z.0298

N5950 X.1213 Y-.07 Z.0319

N5960 X.1047 Y-.033 Z.034

N5970 X.0866 Y.0032 Z.0361

N5980 X.067 Y.0387 Z.0382

N5990 X.046 Y.0734 Z.0403

N6000 X.0237 Y.1071 Z.0425

N6010 X0. Y.14 Z.0446

N6020 X-.0283 Y.1005 Z.0471

- N6030 X-.0546 Y.0596 Z.0497
- N6040 X-.0789 Y.0175 Z.0522
- N6050 X-.1011 Y-.0258 Z.0548
- N6060 X-.1213 Y-.07 Z.0573
- N6070 X-.081 Y-.0741 Z.0594
- N6080 X-.0405 Y-.0766 Z.0616
- N6090 XO. Y-.0774 Z.0637
- N6100 X.0405 Y-.0766 Z.0658
- N6110 X.081 Y-.0741 Z.068
- N6120 X.1213 Y-.07 Z.0701
- N6130 X.1047 Y-.033 Z.0722
- N6140 X.0866 Y.0032 Z.0744
- N6150 X.067 Y.0387 Z.0765
- N6160 X.046 Y.0734 Z.0786
- N6170 X.0237 Y.1071 Z.0807
- N6180 X0. Y.14 Z.0828
- N6190 X-.0283 Y.1005 Z.0854
- N6200 X-.0546 Y.0596 Z.0879
- N6210 X-.0789 Y.0175 Z.0905
- N6220 X-.1011 Y-.0258 Z.093
- N6230 X-.1213 Y-.07 Z.0956
- N6240 X-.081 Y-.0741 Z.0977
- N6250 X-.0405 Y-.0766 Z.0999
- N6260 XO. Y-.0774 Z.102
- N6270 X.0405 Y-.0766 Z.1041
- N6280 X.081 Y-.0741 Z.1062
- N6290 X.1213 Y-.07 Z.1083
- N6300 X.1047 Y-.033 Z.1104
- N6310 X.0866 Y.0032 Z.1126
- N6320 X.067 Y.0387 Z.1147
- N6330 X.046 Y.0734 Z.1168
- N6340 X.0237 Y.1071 Z.119
- N6350 X0. Y.14 Z.1211
- N6360 X-.0283 Y.1005 Z.1236
- N6370 X-.0546 Y.0596 Z.1262
- N6380 X-.0789 Y.0175 Z.1287
- N6390 X-.1011 Y-.0258 Z.1313
- N6400 X-.1213 Y-.07 Z.1338
- N6410 X-.081 Y-.0741 Z.1359
- N6420 X-.0405 Y-.0766 Z.1381
- N6430 X0. Y-.0774 Z.1402
- N6440 X.0405 Y-.0766 Z.1423

- N6450 X.081 Y-.0741 Z.1444
- N6460 X.1213 Y-.07 Z.1465
- N6470 X.1047 Y-.033 Z.1486
- N6480 X.0866 Y.0032 Z.1508
- N6490 X.067 Y.0387 Z.1529
- N6500 X.046 Y.0734 Z.155
- N6510 X.0237 Y.1071 Z.1572
- N6520 X0. Y.14 Z.1593
- N6530 X-.0283 Y.1005 Z.1618
- N6540 X-.0546 Y.0596 Z.1644
- N6550 X-.0789 Y.0175 Z.1669
- N6560 X-.1011 Y-.0258 Z.1695
- N6570 X-.1213 Y-.07 Z.172
- N6580 X-.081 Y-.0741 Z.1741
- N6590 X-.0405 Y-.0766 Z.1763
- N6600 XO. Y-.0774 Z.1784
- N6610 X.0405 Y-.0766 Z.1805
- N6620 X.081 Y-.0741 Z.1827
- N6630 X.1213 Y-.07 Z.1848
- N6640 X.1047 Y-.033 Z.1869
- N6650 X.0866 Y.0032 Z.189
- N6660 X.067 Y.0387 Z.1911
- N6670 X.046 Y.0734 Z.1932
- N6680 X.0237 Y.1071 Z.1954
- N6690 XO. Y.14 Z.1975
- N6700 X-.0141 Y.1209 Z.1988
- N6710 X-.0277 Y.1014 Z.2
- N6720 G3 X-.1015 Y-.0672 I.4134 J-.2814
- N6730 G0 Z.25
- N6740 X-.4255 Y-.2362
- N6750 Z.2
- N6760 G3 X-.2765 Y-.2964 I.2596 J.4274
- N6770 G1 X-.2219 Y-.3075 Z.1971
- N6780 X-.1668 Y-.3162 Z.1942
- N6790 X-.1114 Y-.3224 Z.1912
- N6800 X-.0557 Y-.3261 Z.1883
- N6810 XO. Y-.3274 Z.1854
- N6820 X.0631 Y-.3258 Z.1821
- N6830 X.1261 Y-.321 Z.1788
- N6840 X.1888 Y-.313 Z.1755
- N6850 X.2509 Y-.3019 Z.1721
- N6860 X.3125 Y-.2877 Z.1688

- N6870 X.3732 Y-.2703 Z.1655
- N6880 X.433 Y-.25 Z.1622
- N6890 X.4208 Y-.188 Z.1589
- N6900 X.4054 Y-.1268 Z.1556
- N6910 X.387 Y-.0664 Z.1523
- N6920 X.3655 Y-.007 Z.1489
- N6930 X.3411 Y.0513 Z.1456
- N6940 X.3137 Y.1082 Z.1423
- N6950 X.2835 Y.1637 Z.139
- N6960 X.2505 Y.2176 Z.1357
- N6970 X.2149 Y.2697 Z.1324
- N6980 X.1767 Y.32 Z.1291
- N6990 X.136 Y.3683 Z.1258
- N7000 X.0929 Y.4145 Z.1225
- N7010 X.0475 Y.4584 Z.1192
- N7020 X0. Y.5 Z.1159
- N7030 X-.0511 Y.4551 Z.1123
- N7040 X-.0997 Y.4075 Z.1088
- N7050 X-.1456 Y.3573 Z.1052
- N7060 X-.1888 Y.3048 Z.1016
- N7070 X-.229 Y.2499 Z.0981
- N7080 X-.2661 Y.1929 Z.0945
- N7090 X-.3001 Y.134 Z.0909
- N7100 X-.3309 Y.0733 Z.0873
- N7110 X-.3583 Y.0111 Z.0838
- N7120 X-.3823 Y-.0526 Z.0802
- N7130 X-.4028 Y-.1174 Z.0766
- N7140 X-.4197 Y-.1833 Z.0731
- N7150 X-.433 Y-.25 Z.0695
- N7160 X-.3732 Y-.2704 Z.0662
- N7170 X-.3125 Y-.2877 Z.0629
- N7180 X-.2509 Y-.3019 Z.0596
- N7190 X-.1888 Y-.3131 Z.0563
- N7200 X-.1261 Y-.321 Z.053
- N7210 X-.0631 Y-.3258 Z.0497
- N7220 XO. Y-.3274 Z.0464
- N7230 X.0631 Y-.3258 Z.0431
- N7240 X.1261 Y-.321 Z.0398
- N7250 X.1888 Y-.3131 Z.0365
- N7260 X.2509 Y-.3019 Z.0331
- N7270 X.3125 Y-.2877 Z.0298
- N7280 X.3732 Y-.2704 Z.0265

N7290 X.433 Y-.25 Z.0232

N7300 X.4208 Y-.188 Z.0199

N7310 X.4054 Y-.1268 Z.0166

N7320 X.387 Y-.0664 Z.0133

N7330 X.3655 Y-.007 Z.0099

N7340 X.3411 Y.0513 Z.0066

N7350 X.3137 Y.1082 Z.0033

N7360 X.2835 Y.1637 ZO.

N7370 G3 X0. Y.5 I-1.0825 J-.625

N7380 X-.433 Y-.25 I.799 J-.9613

N7390 X0. Y-.3274 I.433 J1.1726

N7400 X.433 Y-.25 IO. J1.25

N7410 X.2835 Y.1637 I-1.232 J-.2113

N7420 G1 X.2505 Y.2176 Z.0033

N7430 X.2149 Y.2697 Z.0066

N7440 X.1767 Y.32 Z.0099

N7450 X.136 Y.3683 Z.0133

N7460 X.0929 Y.4145 Z.0166

N7470 X.0475 Y.4584 Z.0199

N7480 X0. Y.5 Z.0232

N7490 X-.0511 Y.4551 Z.0268

N7500 X-.0997 Y.4075 Z.0303

N7510 X-.1456 Y.3573 Z.0339

N7520 X-.1888 Y.3048 Z.0374

N7530 X-.229 Y.2499 Z.041

N7540 X-.2661 Y.1929 Z.0446

N7550 X-.3001 Y.134 Z.0481

N7560 X-.3309 Y.0733 Z.0517

N7570 X-.3583 Y.0111 Z.0553

N7580 X-.3823 Y-.0526 Z.0588

N7590 X-.4028 Y-.1174 Z.0624

N7600 X-.4197 Y-.1833 Z.0659

N7610 X-.433 Y-.25 Z.0695

N7620 X-.3732 Y-.2704 Z.0728

N7630 X-.3125 Y-.2877 Z.0761

N7640 X-.2509 Y-.3019 Z.0794

N7650 X-.1888 Y-.3131 Z.0828

N7660 X-.1261 Y-.321 Z.0861

N7670 X-.0631 Y-.3258 Z.0894

N7680 X0. Y-.3274 Z.0927

N7690 X.0631 Y-.3258 Z.096

N7700 X.1261 Y-.321 Z.0993

```
N7710 X.1888 Y-.3131 Z.1026
```

N7720 X.2509 Y-.3019 Z.106

N7730 X.3125 Y-.2877 Z.1093

N7740 X.3732 Y-.2704 Z.1126

N7750 X.433 Y-.25 Z.1159

N7760 X.4208 Y-.188 Z.1192

N7770 X.4054 Y-.1268 Z.1225

N7780 X.387 Y-.0664 Z.1258

N7790 X.3655 Y-.007 Z.1291

N7800 X.3411 Y.0513 Z.1324

N7810 X.3137 Y.1082 Z.1357

N7820 X.2835 Y.1637 Z.139

N7830 X.2505 Y.2176 Z.1423

N7840 X.2149 Y.2697 Z.1456

N7850 X.1767 Y.32 Z.1489

N7860 X.136 Y.3683 Z.1523

N7870 X.0929 Y.4145 Z.1556

N7880 X.0475 Y.4584 Z.1589

N7890 X0. Y.5 Z.1622

N7900 X-.0493 Y.4568 Z.1656

N7910 X-.0962 Y.4111 Z.1691

N7920 X-.1407 Y.363 Z.1725

N7930 X-.1826 Y.3126 Z.1759

N7940 X-.2218 Y.2601 Z.1794

N7950 X-.2582 Y.2056 Z.1828

N7960 X-.2917 Y.1493 Z.1863

N7970 X-.3222 Y.0913 Z.1897

N7980 X-.3497 Y.0317 Z.1931

N7990 X-.3739 Y-.0291 Z.1966

N8000 X-.395 Y-.0912 Z.2

N8010 G3 X-.4174 Y-.2393 I.4776 J-.1481

N8020 X-.4173 Y-.2504 I.5 J0.

N8030 G0 Z.25

N8040 M5

N8050 G91 G28 Z0.

N8060 M01

N8070 T3 M6

N8080 G187 P3 E.001

N8090 G0 G90 G54 X-2.16 Y-.5 S5000 M3

N8100 G43 H3 Z.25

N8110 Z.2

N8120 G1 Z.075 F6.4

- N8130 X-1.66 F40.
- N8140 G3 X-1.16 Y0. I0. J.5
- N8150 G2 X-1.1024 Y.3611 I1.16 J0.
- N8160 G3 X-1.0917 Y.428 I-.2043 J.0669
- N8170 X-1.2037 Y.6167 I-.215 JO.
- N8180 G1 X-1.3918 Y.7193
- N8190 G2 X-1.41 Y.75 I.0168 J.0307
- N8200 G1 Y1.125
- N8210 G2 X-1.125 Y1.41 I.285 J0.
- N8220 G1 X-.75
- N8230 G2 X-.7193 Y1.3918 IO. J-.035
- N8240 G1 X-.6167 Y1.2037
- N8250 G3 X-.428 Y1.0917 I.1887 J.103
- N8260 X-.3611 Y1.1024 IO. J.215
- N8270 G2 X0. Y1.16 I.3611 J-1.1024
- N8280 X.3611 Y1.1024 IO. J-1.16
- N8290 G3 X.428 Y1.0917 I.0669 J.2043
- N8300 X.6167 Y1.2037 IO. J.215
- N8310 G1 X.7193 Y1.3918
- N8320 G2 X.75 Y1.41 I.0307 J-.0168
- N8330 G1 X1.125
- N8340 G2 X1.41 Y1.125 I0. J-.285
- N8350 G1 Y.75
- N8360 G2 X1.3918 Y.7193 I-.035 J0.
- N8370 G1 X1.2037 Y.6167
- N8380 G3 X1.0917 Y.428 I.103 J-.1887
- N8390 X1.1024 Y.3611 I.215 J0.
- N8400 G2 X1.16 Y0. I-1.1024 J-.3611
- N8410 X1.1024 Y-.3611 I-1.16 J0.
- N8420 G3 X1.0917 Y-.428 I.2043 J-.0669
- N8430 X1.2037 Y-.6167 I.215 J0.
- N8440 G1 X1.3918 Y-.7193
- N8450 G2 X1.41 Y-.75 I-.0168 J-.0307
- N8460 G1 Y-1.125
- N8470 G2 X1.125 Y-1.41 I-.285 J0.
- N8480 G1 X.75
- N8490 G2 X.7193 Y-1.3918 IO. J.035
- N8500 G1 X.6167 Y-1.2037
- N8510 G3 X.428 Y-1.0917 I-.1887 J-.103
- N8520 X.3611 Y-1.1024 IO. J-.215
- N8530 G2 X0. Y-1.16 I-.3611 J1.1024
- N8540 X-.3611 Y-1.1024 IO. J1.16

N8550 G3 X-.428 Y-1.0917 I-.0669 J-.2043

N8560 X-.6167 Y-1.2037 IO. J-.215

N8570 G1 X-.7193 Y-1.3918

N8580 G2 X-.75 Y-1.41 I-.0307 J.0168

N8590 G1 X-1.125

N8600 G2 X-1.41 Y-1.125 IO. J.285

N8610 G1 Y-.75

N8620 G2 X-1.3918 Y-.7193 I.035 J0.

N8630 G1 X-1.2037 Y-.6167

N8640 G3 X-1.0917 Y-.428 I-.103 J.1887

N8650 X-1.1024 Y-.3611 I-.215 J0.

N8660 G2 X-1.16 Y0. I1.1024 J.3611

N8670 G3 X-1.66 Y.5 I-.5 J0.

N8680 G1 X-2.16

N8690 Z.2 F6.4

N8700 G0 Z.25

N8710 S4966 M3

N8720 G187 P3 E.001

N8730 X.0723 Y-.5356

N8740 Z.2

N8750 G1 Z.075

N8760 X.2867 Y-.4118 F39.7

N8770 G3 X.5367 Y.0212 I-.25 J.433

N8780 X.4697 Y.2712 I-.5 J0.

N8790 X.1374 Y.6653 I-1.2687 J-.7325

N8800 X0. Y.7149 I-.1374 J-.1653

N8810 X-.1374 Y.6653 IO. J-.2149

N8820 X-.6449 Y-.2137 I.9364 J-1.1266

N8830 X-.648 Y-.25 I.2119 J-.0363

N8840 X-.5075 Y-.4517 I.215 J0.

N8850 XO. Y-.5424 I.5075 J1.3743

N8860 X.5075 Y-.4517 IO. J1.465

N8870 X.648 Y-.25 I-.0745 J.2017

N8880 X.6449 Y-.2137 I-.215 J0.

N8890 X.4697 Y.2712 I-1.4439 J-.2476

N8900 X.0367 Y.5212 I-.433 J-.25

N8910 X-.2133 Y.4542 IO. J-.5

N8920 G1 X-.4277 Y.3304

N8930 Z.2 F6.4

N8940 G0 Z.25

N8950 S5000 M3

N8960 G187 P3 E.001

N8970 X-2.535 Y-.5

N8980 Z.2

N8990 G1 Z-.05

N9000 X-2.035 F40.

N9010 G3 X-1.535 Y0. I0. J.5

N9020 G1 Y1.5

N9030 G2 X-1.5 Y1.535 I.035 J0.

N9040 G1 X1.5

N9050 G2 X1.535 Y1.5 I0. J-.035

N9060 G1 Y-1.5

N9070 G2 X1.5 Y-1.535 I-.035 J0.

N9080 G1 X-1.5

N9090 G2 X-1.535 Y-1.5 IO. J.035

N9100 G1 Y0.

N9110 G3 X-2.035 Y.5 I-.5 J0.

N9120 G1 X-2.535

N9130 Z.2 F6.4

N9140 G0 Z.25

N9150 M5

N9160 G91 G28 Z0.

N9170 M01

N9180 T4 M6

N9190 G187 P3 E.001

N9200 G0 G90 G54 X-2.75 Y-.5 S5000 M3

N9210 G43 H4 Z.25

N9220 Z.2

N9230 G1 Z-.14 F6.4

N9240 X-2.25 F40.

N9250 G3 X-1.75 Y0. I0. J.5

N9260 G1 Y1.5

N9270 G2 X-1.5 Y1.75 I.25 J0.

N9280 G1 X1.5

N9290 G2 X1.75 Y1.5 I0. J-.25

N9300 G1 Y-1.5

N9310 G2 X1.5 Y-1.75 I-.25 J0.

N9320 G1 X-1.5

N9330 G2 X-1.75 Y-1.5 IO. J.25

N9340 G1 Y0.

N9350 G3 X-2.25 Y.5 I-.5 J0.

N9360 G1 X-2.75

N9370 Z.2 F6.4

N9380 G0 Z.25

N9390 M5 N9400 G91 G28 Z0. N9410 G28 X0. Y0. N9420 M30