
(a)
Free joint at f = 200 Hz
measured parameters
renormalized parameters
θ_2 simulated − real (rad)
time (s)
(b)
joint-angle RMSE over 1 s (rad)
same error, 11× faster
measured
renormalized (no fitting)
identified (fitted)
simulation frequency f (Hz)