

Timeline

Parameters

Time

Time	Variable	Value	Context
1.0	coil_MOTupper_A	1.0	MOT

Add parameters by appending columns, e.g. conversions.

...

+

Value_digits
3277

Add operations by appending rows, e.g. ramp coils.

⋮

+

2.0	coil_MOTupper_A	0.9	final ramps
2.1	coil_MOTupper_A	0.45	final ramps
2.2	coil_MOTupper_A	0.0	final ramps

⋮ ⋮ ⋮