



Your Job Packet

What is in here



What you saw

In your own words, kept exactly as you said it.



Your photos

Dated, labelled, pointed at the right part.



The checks you did

Each one with what it ruled out.



A head start on the clock

Less time diagnosing can mean fewer hours on the bill.



HOME MEMORY

Opens already filled in

Your house is an asset with amnesia.

Scan this and everything in this packet is already saved — the model number, the photos, what was wrong and what fixed it.

prn-test-site.vercel.app/demo/sample/k...



TRUST NETWORK

They answer in a tap

You already know someone who knows someone.

Ask your own people who they would send to their sister's house, or send this packet straight to the guy you already trust.

prn-test-site.vercel.app/demo/sample/a...

IF YOU WOULD RATHER CALL SOMEONE

Read this out when they pick up.

"Hi — My AC is running but blowing warm air. It's a Carrier, about eight years old. Started on Tuesday. The thermostat's set to 72 and the room's at 84, the outdoor fan's turning, the filter looks clean to me, and there's no ice I can see. I've got a Job Packet I can send you before you come out."

You stop carrying your home in your head.

You get your life back.

The rest of this packet is written for whoever fixes it. Hand over the whole thing — you don't have to explain it again.

Cooling problem

123 Demo Lane (synthetic) • Fort Wayne, IN 46802 • single-family, 1 storey

AS SOON AS POSSIBLE • SAFETY NOT ESTABLISHED

PACKET #DE00-0000 • v1
6 Sep 2026, 08:00

WHAT THE HOMEOWNER IS DEALING WITH

The homeowner describes it as: “My AC is running but blowing warm air”. Started Tuesday. Thermostat is set at 72°F with the room sitting at 84°F. The outdoor fan is turning. The homeowner reports no visible ice. The homeowner reports that the filter is clean.

THE FACTS WORTH READING FIRST

- Homeowner reports: “My AC is running but blowing warm air” REPORTED
- Outdoor fan is turning REPORTED
- Thermostat: set 72°F, room 84°F REPORTED
- Homeowner reports no visible ice REPORTED
- Homeowner reports the filter is clean REPORTED

Still unknown — and why

- Refrigerant charge — *requires gauges*
- Capacitor condition — *requires meter, not homeowner-safe*
- Coil condition inside air handler — *requires panel removal*
- Line-set temperature split — *requires instrument*
- Model and serial — *not photographed or typed at intake*
- Outdoor fins condition — *not asked*
- Breaker trips, burning smell, water — *not asked*

EQUIPMENT

Type	Unknown	UNKNOWN
Brand		Carrier
Model	Unknown	UNKNOWN
Serial	Unknown	UNKNOWN
Age		~8 yrs
Outdoor unit	Not asked	UNKNOWN
Air handler	Not asked	UNKNOWN
Thermostat	set 72°F, room 84°F	

Technician-only, on arrival

- Capacitor test under load
- Refrigerant pressures, both sides
- Supply/return temperature split
- Contactor and condenser fan draw
- Evaporator coil inspection

7

FACTS CAPTURED

0

PHOTOS

2

CHECKS DONE

1

MADE LESS LIKELY

5

TECH-ONLY LEFT

Timeline

- TUE 1 SEP

Homeowner first notices the problem. "started Tuesday"
- SUN 6 SEP, 08:00

Describes the problem in their own words.
- SUN 6 SEP, 08:00

Reports that the filter is clean.
- SUN 6 SEP, 08:00

Reports the outdoor fan turning.
- SUN 6 SEP, 08:00

Reports no visible ice.
- 6 SEP 2026, 08:00

Packet generated.

Evidence

No photos were captured at intake. UNKNOWN

Checks completed, and what each one changed

CHECK	RESULT	WHAT IT CHANGED
Outdoor unit running?	Yes — fan turning	Rules out total power loss to the condenser
Visible ice reported?	None visible	Records the homeowner's visible-ice observation

Service history, as the homeowner knows it

Ever low on refrigerant or topped up?	Not asked	UNKNOWN
Service in the last two years, and by whom?	Not asked	UNKNOWN
Outdoor unit ever hit, flooded, or worked near?	Not asked	UNKNOWN
Same temperature difference in every room?	Not asked	UNKNOWN
Asked at intake so you don't have to. Anything the homeowner didn't know is shown as a recorded gap, never guessed.		

Where the evidence points

Low refrigerant charge / leak

MOST CONSISTENT

- For — unit running normally, homeowner reports no visible ice.
- Against — the line-set was not inspected for oil staining at intake.

Failing capacitor / compressor not staging

POSSIBLE

- For — fan turning does not confirm the compressor is doing work.
- Against — outdoor fan turning shows the contactor is passing power.

Airflow restriction downstream of the filter

LESS LIKELY

- For — cannot be excluded without inspecting the coil.
- Against — nothing recorded at intake points at the ducts or the blower.

INFERENCE These are reasoning from the evidence above, offered to save discovery time. **They are not a diagnosis** and the technician's own tests decide.

Access and job readiness

optional at intake • blanks are honest, not missing

Occupancy	Not asked	UNKNOWN
Owner present needed?	Not asked	UNKNOWN
Parking	Not asked	UNKNOWN
Pets	Not asked	UNKNOWN
Equipment route	Not asked	UNKNOWN
Preferred window	Not asked	UNKNOWN
Gate or entry code	Not asked	UNKNOWN
Contact	Not asked	UNKNOWN

Scope factors to evaluate

- Unit is ~8 years old — repair-vs-replace conversation may be in scope
- If a leak is confirmed, locating it may need a separate diagnostic step
- No permit or utility involvement indicated

No prices are stated in this packet. These are factors for the provider to price.

How to read the labels in this packet

- REPORTED
- SEEN IN PHOTO / VIDEO
- READ FROM LABEL
- CONFIRMED BY HOMEOWNER
- INFERENCE — VERIFY
- UNKNOWN
- TECHNICIAN-ONLY TEST