

```
{ "status": "SUCCESS", "response": { "activeListCount": "674", "rejectedListCount": "175",  
  "loadedATAList": [ { "ataChapterCode": "08", "ataChapterDesc": "LEVELING & WEI",  
    "ataSections": [ { "ataSectionCode": "20", "ataSectionDesc": "Leveling" } ] },  
    { "ataChapterCode": "11", "ataChapterDesc": "PLACARDS & MAR", "ataSections":  
      [ { "ataSectionCode": "10", "ataSectionDesc": "Color Scheme" }, { "ataSectionCode": "20",  
        "ataSectionDesc": "Exterior Pla" }, { "ataSectionCode": "30", "ataSectionDesc": "Interior  
Pla" } ] }, { "ataChapterCode": "21", "ataChapterDesc": "AIR CONDITIONI", "ataSections":  
      [ { "ataSectionCode": "20", "ataSectionDesc": "Distribution" }, { "ataSectionCode": "21",  
        "ataSectionDesc": "Cabin/Crew R" }, { "ataSectionCode": "22", "ataSectionDesc": "Cargo  
Ductin" }, { "ataSectionCode": "24", "ataSectionDesc": "Gasper/Indiv" },  
        { "ataSectionCode": "26", "ataSectionDesc": "Lavatory, Ga" }, { "ataSectionCode": "28",  
        "ataSectionDesc": "Ground Air C" }, { "ataSectionCode": "30", "ataSectionDesc":  
        "Pressurizati" }, { "ataSectionCode": "41", "ataSectionDesc": "Crew Rest Ar" },  
        { "ataSectionCode": "50", "ataSectionDesc": "Cooling" }, { "ataSectionCode": "59",  
        "ataSectionDesc": "Equipment Co" }, { "ataSectionCode": "61", "ataSectionDesc": "Zone  
Tempera" }, { "ataSectionCode": "70", "ataSectionDesc": "Cabin Air Qu" } ] },  
    { "ataChapterCode": "23", "ataChapterDesc": "COMMUNICATIONS", "ataSections":  
      [ { "ataSectionCode": "11", "ataSectionDesc": "High Frequen" }, { "ataSectionCode": "25",  
        "ataSectionDesc": "Satellite Co" }, { "ataSectionCode": "30", "ataSectionDesc": "Passenger  
Ad" }, { "ataSectionCode": "31", "ataSectionDesc": "Passenger Ad" }, { "ataSectionCode":  
        "32", "ataSectionDesc": "Video (Overh" }, { "ataSectionCode": "33", "ataSectionDesc":  
        "Passenger En" }, { "ataSectionCode": "36", "ataSectionDesc": "Boarding Mus" },  
        { "ataSectionCode": "37", "ataSectionDesc": "Personal Vid" }, { "ataSectionCode": "41",  
        "ataSectionDesc": "Maintenance" }, { "ataSectionCode": "42", "ataSectionDesc": "Cabin  
Interp" }, { "ataSectionCode": "51", "ataSectionDesc": "Flight Inter" }, { "ataSectionCode":  
        "54", "ataSectionDesc": "Hand Microph" }, { "ataSectionCode": "55", "ataSectionDesc":  
        "Cabin and Co" }, { "ataSectionCode": "56", "ataSectionDesc": "Headsets" },  
        { "ataSectionCode": "95", "ataSectionDesc": "Wireless Loc" } ] }, { "ataChapterCode": "24",  
    "ataChapterDesc": "ELECTRICAL POW", "ataSections": [ { "ataSectionCode": "10",  
      "ataSectionDesc": "Generator Dr" }, { "ataSectionCode": "24", "ataSectionDesc": "APU  
Generato" }, { "ataSectionCode": "41", "ataSectionDesc": "External Pow" },  
        { "ataSectionCode": "51", "ataSectionDesc": "AC Power Dis" }, { "ataSectionCode": "58",  
        "ataSectionDesc": "PED power /" } ] }, { "ataChapterCode": "25", "ataChapterDesc":  
    "EQUIPMENT & FU", "ataSections": [ { "ataSectionCode": "00", "ataSectionDesc":  
    "Equipment &" }, { "ataSectionCode": "10", "ataSectionDesc": "Flight Compa" },  
    { "ataSectionCode": "11", "ataSectionDesc": "Flight Deck" }, { "ataSectionCode": "12",  
    "ataSectionDesc": "Ceiling & Si" }, { "ataSectionCode": "13", "ataSectionDesc": "Cockpit  
Floo" }, { "ataSectionCode": "14", "ataSectionDesc": "Cockpit Trim" }, { "ataSectionCode":
```

"15", "ataSectionDesc": "Forward Equi" }, { "ataSectionCode": "16", "ataSectionDesc":
 "Misc. Cockpi" }, { "ataSectionCode": "17", "ataSectionDesc": "All A/C Docu" },
 { "ataSectionCode": "18", "ataSectionDesc": "ACARS Printe" }, { "ataSectionCode": "19",
 "ataSectionDesc": "Pilots Crew" }, { "ataSectionCode": "20", "ataSectionDesc": "Passenger
 Co" }, { "ataSectionCode": "21", "ataSectionDesc": "Tourist Clas" }, { "ataSectionCode":
 "22", "ataSectionDesc": "Ceiling/Wall" }, { "ataSectionCode": "23", "ataSectionDesc":
 "Cabin Floor" }, { "ataSectionCode": "24", "ataSectionDesc": "Partitions/C" },
 { "ataSectionCode": "25", "ataSectionDesc": "Attendant Se" }, { "ataSectionCode": "26",
 "ataSectionDesc": "Stowage Comp" }, { "ataSectionCode": "27", "ataSectionDesc":
 "Passenger Se" }, { "ataSectionCode": "28", "ataSectionDesc": "FC/WBC Passe" },
 { "ataSectionCode": "29", "ataSectionDesc": "Premium Sele" }, { "ataSectionCode": "30",
 "ataSectionDesc": "Buffet/Galle" }, { "ataSectionCode": "31", "ataSectionDesc": "Galley
 Struc" }, { "ataSectionCode": "32", "ataSectionDesc": "Misc. Equipt" }, { "ataSectionCode":
 "33", "ataSectionDesc": "Chillers/A35" }, { "ataSectionCode": "34", "ataSectionDesc":
 "Ovens" }, { "ataSectionCode": "35", "ataSectionDesc": "Bun Warmers" },
 { "ataSectionCode": "36", "ataSectionDesc": "Coffee Maker" }, { "ataSectionCode": "38",
 "ataSectionDesc": "All Beverage" }, { "ataSectionCode": "40", "ataSectionDesc":
 "Lavatories" }, { "ataSectionCode": "41", "ataSectionDesc": "Lavatory Mod" },
 { "ataSectionCode": "42", "ataSectionDesc": "Lavatory Cou" }, { "ataSectionCode": "43",
 "ataSectionDesc": "Cabinets/Soa" }, { "ataSectionCode": "44", "ataSectionDesc": "Toilets
 (Sea" }, { "ataSectionCode": "50", "ataSectionDesc": "Cargo Compar" }, { "ataSectionCode":
 "60", "ataSectionDesc": "Emergency Eq" }, { "ataSectionCode": "61", "ataSectionDesc":
 "Escape Slide" }, { "ataSectionCode": "62", "ataSectionDesc": "Life Vests a" },
 { "ataSectionCode": "63", "ataSectionDesc": "First Aid/Me" }, { "ataSectionCode": "65",
 "ataSectionDesc": "Emergency Eq" }, { "ataSectionCode": "71", "ataSectionDesc": "Main
 Equipme" }, { "ataSectionCode": "73", "ataSectionDesc": "Miscellaneous" },
 { "ataSectionCode": "74", "ataSectionDesc": "Flight Atten" }, { "ataSectionCode": "75",
 "ataSectionDesc": "Interior Sta" }] }, { "ataChapterCode": "26", "ataChapterDesc": "FIRE
 PROTECTIO", "ataSections": [{ "ataSectionCode": "15", "ataSectionDesc": "Cargo
 Smoke/" }, { "ataSectionCode": "17", "ataSectionDesc": "Lavatory Smo" },
 { "ataSectionCode": "19", "ataSectionDesc": "Cabin, Galle" }, { "ataSectionCode": "27",
 "ataSectionDesc": "Crew Rest" }] }, { "ataChapterCode": "27", "ataChapterDesc": "FLIGHT
 CONTROL", "ataSections": [{ "ataSectionCode": "40", "ataSectionDesc": "Horizontal S" },
 { "ataSectionCode": "66", "ataSectionDesc": "Spoiler Rigg" }] }, { "ataChapterCode": "28",
 "ataChapterDesc": "FUEL", "ataSections": [{ "ataSectionCode": "00", "ataSectionDesc":
 "Fuel" }, { "ataSectionCode": "20", "ataSectionDesc": "Distribution" }, { "ataSectionCode":
 "21", "ataSectionDesc": "Refuel/De-Fu" }] }, { "ataChapterCode": "29", "ataChapterDesc":
 "HYDRAULIC POWE", "ataSections": [{ "ataSectionCode": "16", "ataSectionDesc":

"Ground Servi"]] }, { "ataChapterCode": "31", "ataChapterDesc": "INDICATING/REC",
"ataSections": [{ "ataSectionCode": "10", "ataSectionDesc": "Panels" },
{ "ataSectionCode": "14", "ataSectionDesc": "Overhead" }, { "ataSectionCode": "31",
"ataSectionDesc": "Flight Data" }, { "ataSectionCode": "63", "ataSectionDesc":
"EngineIndica" }] }, { "ataChapterCode": "32", "ataChapterDesc": "LANDING GEAR",
"ataSections": [{ "ataSectionCode": "25", "ataSectionDesc": "Links/Braces" },
{ "ataSectionCode": "30", "ataSectionDesc": "Extension &" }, { "ataSectionCode": "40",
"ataSectionDesc": "Wheels & Bra" }, { "ataSectionCode": "70", "ataSectionDesc":
"Supplementar" }] }, { "ataChapterCode": "33", "ataChapterDesc": "LIGHTS",
"ataSections": [{ "ataSectionCode": "10", "ataSectionDesc": "Flight Compa" },
{ "ataSectionCode": "12", "ataSectionDesc": "All Crew Res" }, { "ataSectionCode": "18",
"ataSectionDesc": "Flood/Map/Ov" }, { "ataSectionCode": "19", "ataSectionDesc": "Lighting
Con" }, { "ataSectionCode": "21", "ataSectionDesc": "Cabin Illumi" }, { "ataSectionCode":
"22", "ataSectionDesc": "Passenger Si" }, { "ataSectionCode": "23", "ataSectionDesc":
"Passenger Re" }, { "ataSectionCode": "24", "ataSectionDesc": "Attendant Ca" },
{ "ataSectionCode": "25", "ataSectionDesc": "Entry Door A" }, { "ataSectionCode": "26",
"ataSectionDesc": "All Lavatory" }, { "ataSectionCode": "27", "ataSectionDesc":
"Galley/Close" }, { "ataSectionCode": "31", "ataSectionDesc": "Internal Car" },
{ "ataSectionCode": "32", "ataSectionDesc": "Wheel Well/E" }, { "ataSectionCode": "51",
"ataSectionDesc": "Interior Lig" }] }, { "ataChapterCode": "34", "ataChapterDesc":
"NAVIGATION", "ataSections": [{ "ataSectionCode": "42", "ataSectionDesc": "Weather
Rada" }, { "ataSectionCode": "55", "ataSectionDesc": "VHF Omni Ran" },
{ "ataSectionCode": "64", "ataSectionDesc": "FMS/Nav Data" }] }, { "ataChapterCode":
"35", "ataChapterDesc": "OXYGEN", "ataSections": [{ "ataSectionCode": "11",
"ataSectionDesc": "Crew Oxygen" }, { "ataSectionCode": "21", "ataSectionDesc": "Oxygen
Stora" }, { "ataSectionCode": "32", "ataSectionDesc": "Passenger Po" }] },
{ "ataChapterCode": "36", "ataChapterDesc": "PNEUMATIC", "ataSections":
[{ "ataSectionCode": "13", "ataSectionDesc": "Low Pressure" }, { "ataSectionCode": "14",
"ataSectionDesc": "High Pressur" }, { "ataSectionCode": "20", "ataSectionDesc":
"Indicating/S" }] }, { "ataChapterCode": "38", "ataChapterDesc": "WATER/WASTE",
"ataSections": [{ "ataSectionCode": "12", "ataSectionDesc": "Distribution" },
{ "ataSectionCode": "13", "ataSectionDesc": "Indication" }, { "ataSectionCode": "15",
"ataSectionDesc": "Servicing" }, { "ataSectionCode": "30", "ataSectionDesc": "Waste
System" }, { "ataSectionCode": "31", "ataSectionDesc": "Toilet Flush" }, { "ataSectionCode":
"32", "ataSectionDesc": "Servicing/Se" }, { "ataSectionCode": "33", "ataSectionDesc":
"Drain System" }, { "ataSectionCode": "34", "ataSectionDesc": "Drain System" }] },
{ "ataChapterCode": "44", "ataChapterDesc": "CABIN SYSTEMS", "ataSections":
[{ "ataSectionCode": "11", "ataSectionDesc": "Cabin Servic" }] }, { "ataChapterCode": "45",

```
"ataChapterDesc": "CENTRAL MAINTENANCE", "ataSections": [ { "ataSectionCode": "10",  
"ataSectionDesc": "Health Management", { "ataSectionCode": "41", "ataSectionDesc":  
"Computer" } ] }, { "ataChapterCode": "46", "ataChapterDesc": "INFORMATION SYSTEMS",  
"ataSections": [ { "ataSectionCode": "00", "ataSectionDesc": "Information",  
{ "ataSectionCode": "13", "ataSectionDesc": "RFID Tag Inspection", { "ataSectionCode": "30",  
"ataSectionDesc": "Maintenance", { "ataSectionCode": "41", "ataSectionDesc": "Cabin  
Information" } ] }, { "ataChapterCode": "49", "ataChapterDesc": "AIRBORNE AUXILIARY",  
"ataSections": [ { "ataSectionCode": "16", "ataSectionDesc": "Air Intake/Drainage" } ] },  
{ "ataChapterCode": "52", "ataChapterDesc": "DOORS", "ataSections":  
[ { "ataSectionCode": "10", "ataSectionDesc": "Passenger/Galley", { "ataSectionCode": "11",  
"ataSectionDesc": "Passenger Door", { "ataSectionCode": "12", "ataSectionDesc":  
"Latch/Handle", { "ataSectionCode": "13", "ataSectionDesc": "Insulation/Liner",  
{ "ataSectionCode": "21", "ataSectionDesc": "Overwing Exit", { "ataSectionCode": "22",  
"ataSectionDesc": "Emergency Exit", { "ataSectionCode": "30", "ataSectionDesc":  
"Cargo", { "ataSectionCode": "40", "ataSectionDesc": "Service", { "ataSectionCode":  
"42", "ataSectionDesc": "Electrical/Electronics", { "ataSectionCode": "45", "ataSectionDesc": "Air  
Conditioning", { "ataSectionCode": "46", "ataSectionDesc": "Empennage Access",  
{ "ataSectionCode": "47", "ataSectionDesc": "APU Access Door", { "ataSectionCode": "51",  
"ataSectionDesc": "Flight Compartment", { "ataSectionCode": "52", "ataSectionDesc":  
"Lavatory", { "ataSectionCode": "56", "ataSectionDesc": "Crew Rest Door",  
{ "ataSectionCode": "75", "ataSectionDesc": "Service Door" } ] }, { "ataChapterCode": "53",  
"ataChapterDesc": "FUSELAGE", "ataSections": [ { "ataSectionCode": "12",  
"ataSectionDesc": "Bulkheads", { "ataSectionCode": "20", "ataSectionDesc": "Auxiliary  
Structure", { "ataSectionCode": "51", "ataSectionDesc": "Radome" } ] }, { "ataChapterCode": "56",  
"ataChapterDesc": "WINDOWS", "ataSections": [ { "ataSectionCode": "12",  
"ataSectionDesc": "Sliding", { "ataSectionCode": "21", "ataSectionDesc": "Cabin  
Window" } ] }, { "ataChapterCode": "71", "ataChapterDesc": "POWER PLANT",  
"ataSections": [ { "ataSectionCode": "10", "ataSectionDesc": "Cowling",  
{ "ataSectionCode": "12", "ataSectionDesc": "Fan", { "ataSectionCode": "15",  
"ataSectionDesc": "Hold-Open Device", { "ataSectionCode": "16", "ataSectionDesc": "Open &  
Close" } ] }, { "ataChapterCode": "78", "ataChapterDesc": "EXHAUST", "ataSections":  
[ { "ataSectionCode": "30", "ataSectionDesc": "Thrust Reverser", { "ataSectionCode": "31",  
"ataSectionDesc": "Thrust Reverser", { "ataSectionCode": "32", "ataSectionDesc":  
"Actuation/Cable" } ] }, { "ataChapterCode": "79", "ataChapterDesc": "OIL", "ataSections":  
[ { "ataSectionCode": "19", "ataSectionDesc": "Engine Oil System", { "ataSectionCode": "30",  
"ataSectionDesc": "Indicating" } ] }, { "ataChapterCode": "80", "ataChapterDesc":  
"STARTING", "ataSections": [ { "ataSectionCode": "19", "ataSectionDesc": "Oil  
Servicing" } ] }, "nefititems": [ { "sequenceNumber": "01", "creationDate": "02/22/2012
```

16:48:01", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "08", "ataDesc": "Leveling", "ataSectCode":
"20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "All
parts of the aircraft leveling indication system must be secured. A319, A320, A321,A330,
350 aircraft not covered by the NEF, they are covered in the MEL.", "decisionInd": "A",
"defRemarks": "All parts of the aircraft leveling indication system must be secured. A319,
A320, A321,A330, 350 aircraft not covered by the NEF, they are covered in the MEL.",
"efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "A350 exclusion added
to remarks.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01
07:38:14.415092", "faaReviewStartTms": "2022-03-08 07:38:14.415092", "intExt": "EX",
"itemDesc": "Aircraft Leveling Indication System", "itemNotes": "Aircraft leveling indication
system includes, but is not limited to, lateral and longitudinal inclinometers and a plumb
bob leveling scale, plump bob, plumb bob string, grid plate and grid plate. All parts of the
aircraft leveling indication system must be working to jack the aircraft and required for
alternate fueling procedures.", "itemNotesInd": "Y", "itemNumber": "08-20-01",
"lastUpdate": "2022-03-08 07:38:38.74566", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "1920375",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-02-22 16:38:36.565729",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "082001" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"11", "ataDesc": "Color Schemes/Markings/Paint", "ataSectCode": "10", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Can not apply this NEF
to trim or light plates for Emergency markings. Signage or Lettering must be legible.",
"decisionInd": "A", "defRemarks": "Can not apply this NEF to trim or light plates for
Emergency markings. Signage or Lettering must be legible.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:36:54.88389", "faaReviewStartTms": "2011-12-
09 12:36:54.88389", "intExt": "IP", "itemDesc": "Interior Trim or Light Plates Faded or
Worn", "itemNotes": "Planning should be advised and set up for repair on next convenient
over night maintenance.", "itemNotesInd": "Y", "itemNumber": "11-10-01", "lastUpdate":
"2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "111001" },

```
{ "sequenceNumber": "02", "creationDate": "10/07/2016 10:33:31", "userId":  
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "11", "ataDesc": "Color Schemes/Markings/Paint", "ataSectCode":  
"10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure":  
"Ensure that the remaining lines/degraded lines still outline the perimeter of the affected  
cold-soak fuel frost area. You must be able to clearly see the perimeter of the cold soak  
fuel frost area from the cabin to use this item.", "decisionInd": "A", "defRemarks": "Ensure  
that the remaining lines/degraded lines still outline the perimeter of the affected cold-soak  
fuel frost area. You must be able to clearly see the perimeter of the cold soak fuel frost  
area from the cabin to use this item.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",  
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:20:46.278169",  
"faaReviewStartTms": "2019-02-27 09:20:46.278169", "intExt": "EX", "itemDesc": "Cold  
Soak Fuel Frost Perimeter Marking Degraded -B737 Limited Effectivity", "itemNotes":  
"Applicable to all 737-700 and 737-900 aircraft. Also applicable to the 737-800 post AA  
1120-01158 aircraft. This item does not deviate from FAA exemption no. 14236 to 14 CFR  
121.629(b). This item only covers the degrading of the cold soak fuel frost area perimeter  
line and the perimeter must still be clearly visible from the cabin so the exemption can still  
be used.", "itemNotesInd": "Y", "itemNumber": "11-10-02", "lastUpdate": "2019-02-27  
09:20:53.18525", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N",  
"logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y",  
"rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467",  
"rowInsertTms": "2016-10-07 10:28:54.277461", "sceptreAutoDefRemarks": "Auto  
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":  
"00823179", "legacyFrc": "111002" }, { "sequenceNumber": "06", "creationDate":  
"12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay":  
"Active", "allowableTime": "120", "ataChapterCode": "11", "ataDesc": "Exterior Placards",  
"ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",  
"deactMOProcedure": "Before deferral, you MUST: \r\n\r\nContact the MCC for  
approval\r\n\r\nVerify the placard/marking is NOT FAA/AD required. \r\n\r\n(Ref TOPP 40-40-05  
under Special MCO Procedures, FAA Required Placards/Markings for step-by-step  
instructions to determine if the placard/marking is required.)\r\n\r\n\r\nIf you identify an error  
was made and the plane has been dispatched, immediately contact the MCC and your  
CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under  
SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List  
bottom right of the page.) You may also want to file an ASAP report under SAFETY,  
SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "decisionInd": "A",  
"defRemarks": "Before deferral, you MUST: \r\n\r\nContact the MCC for approval\r\n\r\nVerify the  
placard/marking is NOT FAA/AD required. \r\n\r\n(Ref TOPP 40-40-05 under Special MCO
```

Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "efmTab": "N", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 10/24/13 with description change.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:23:51.433414", "faaReviewStartTms": "2019-02-27 09:23:51.433414", "intExt": "EX", "itemDesc": "Non-Required Exterior Placards - Degraded but Legible", "itemNotes": "Discrepant FAA/AD required placards/markings MUST be addressed per TOPP 40-40-05 in conjunction with technical instructions of EA 10-495655-14.", "itemNotesInd": "Y", "itemNumber": "11-20-06", "lastUpdate": "2019-02-27 09:23:54.600786", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oil": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "112006" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "11", "ataDesc": "Exterior Placards", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Before deferral, you MUST: \r\n\r\nContact the MCC for approval\r\n\r\nVerify the placard/marking is NOT FAA/AD required. \r\n\r\n(Ref TOPP 40-40-05 under Special MCO Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "decisionInd": "A", "defRemarks": "Before deferral, you MUST: \r\n\r\nContact the MCC for approval\r\n\r\nVerify the placard/marking is NOT FAA/AD required. \r\n\r\n(Ref TOPP 40-40-05 under Special MCO Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps

Maintenance ASAP)", "efmTab": "N", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 10/24/13 with description change.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:24:48.593087", "faaReviewStartTms": "2019-02-27 09:24:48.593087", "intExt": "EX", "itemDesc": "Non-Required Exterior Placards - Missing or Illegible", "itemNotes": "Discrepant FAA/AD required placards/markings MUST be addressed per TOPP 40-40-05 in conjunction with technical instructions of EA 10-495655-14. This NEF has a allowable time limit of 365 days.", "itemNotesInd": "Y", "itemNumber": "11-20-07", "lastUpdate": "2019-02-27 09:24:52.905362", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "112007" }, { "sequenceNumber": "08", "creationDate": "08/07/2025 12:39:38", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "11", "ataDesc": "Exterior Placards", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Ensure no sharp edges or protruding raised sections. If data plate is not secure, manually re-form the plate and secure the plate using aluminum Speed Tape. If unable to secure the data plate (AOG situations only), the plate may be removed and stowed in the aircraft AOG Pouch.\n\nRecord all legible data (Part Number, Serial Number, etc.) in the applicable Logpage to facilitate restoration/replacement of the data plate.\n\nThis relief is for IN-SERVICE, INSTALLED COMPONENTS ONLY. Do not remove or defer part identification on spare parts.", "decisionInd": "A", "defRemarks": "Ensure no sharp edges or protruding raised sections. If data plate is not secure, manually re-form the plate and secure the plate using aluminum Speed Tape. If unable to secure the data plate (AOG situations only), the plate may be removed and stowed in the aircraft AOG Pouch.\n\nRecord all legible data (Part Number, Serial Number, etc.) in the applicable Logpage to facilitate restoration/replacement of the data plate.\n\nThis relief is for IN-SERVICE, INSTALLED COMPONENTS ONLY. Do not remove or defer part identification on spare parts.", "efmTab": "E", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-08-31 14:37:26.098253", "faaReviewStartTms": "2025-08-07 14:37:26.098253", "intExt": "EX", "itemDesc": "Component Data Plates", "itemNotes": "This relief applies to Component Data Plates (fixed placards containing part number, serial number, etc.) which are on INSTALLED, ON-WING COMPONENTS only. Data Plates may be missing or degraded.\n\nThis relief DOES NOT APPLY TO DATA TAGS FOR: Aircraft (complete airframe ID), Engine, Propeller, Propeller Blade, or Propeller Hub, or any Life-Limited Part.", "itemNotesInd": "Y", "itemNumber": "11-20-08", "lastUpdate": "2026-02-05

09:51:08.140814", "lastUpdateDisplay": "02/05/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-08-07 12:27:12.746411", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "112008" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "11", "ataDesc": "Interior Placards", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "K", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:55.155454", "faaReviewStartTms": "2011-12-09 12:36:55.155454", "intExt": "IP", "itemDesc": "Cabin Inop Placards Need Replenishing", "itemNotesInd": "N", "itemNumber": "11-30-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "113002" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "11", "ataDesc": "Interior Placards", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Before deferral, you MUST: \r\nContact the MCC for approval\r\nVerify the placard/marking is NOT FAA/AD required. \r\n(Ref TOPP 40-40-05 under Special MCO Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "decisionInd": "A", "defRemarks": "Before deferral, you MUST: \r\nContact the MCC for approval\r\nVerify the placard/marking is NOT FAA/AD required. \r\n(Ref TOPP 40-40-05 under Special MCO Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also

want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "efmTab": "N", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 10/24/13 with description change.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:25:47.497534", "faaReviewStartTms": "2019-02-27 09:25:47.497534", "intExt": "IP", "itemDesc": "Non-Required Interior Placards - Degraded but Legible", "itemNotes": "Discrepant FAA/AD required placards/markings MUST be addressed per TOPP 40-40-05 in conjunction with technical instructions of EA 10-495655-14.", "itemNotesInd": "Y", "itemNumber": "11-30-10", "lastUpdate": "2019-02-27 09:25:51.399996", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "113010" }, { "sequenceNumber": "11", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "11", "ataDesc": "Interior Placards", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Before deferral, you MUST: \r\nContact the MCC for approval\r\nVerify the placard/marking is NOT FAA/AD required. \r\n(Ref TOPP 40-40-05 under Special MCO Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "decisionInd": "A", "defRemarks": "Before deferral, you MUST: \r\nContact the MCC for approval\r\nVerify the placard/marking is NOT FAA/AD required. \r\n(Ref TOPP 40-40-05 under Special MCO Procedures, FAA Required Placards/Markings for step-by-step instructions to determine if the placard/marking is required.)\r\n\r\nIf you identify an error was made and the plane has been dispatched, immediately contact the MCC and your CASS monitor to report the error. (Find your CASS monitor: TechOps Home Page, under SAFETY, SECURITY & COMPLIANCE, Compliance Links on the left, CAS Monitor List bottom right of the page.) You may also want to file an ASAP report under SAFETY, SECURITY & COMPLIANCE, TechOps Maintenance ASAP)", "efmTab": "N", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 10/24/13 with description change.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:27:34.640934", "faaReviewStartTms": "2019-02-27 09:27:34.640934", "intExt": "IP", "itemDesc": "Non-Required Interior Placards - Missing or Illegible", "itemNotes": "Discrepant FAA/AD required placards/markings MUST be

addressed per TOPP 40-40-05 in conjunction with technical instructions of EA 10-495655-14.", "itemNotesInd": "Y", "itemNumber": "11-30-11", "lastUpdate": "2019-02-27 09:27:39.821816", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "113011" }, { "sequenceNumber": "12", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "11", "ataDesc": "Interior Placards", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "I", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:55.880905", "faaReviewStartTms": "2011-12-09 12:36:55.880905", "intExt": "IP", "itemDesc": "Seat Number Placards - Degraded or Missing", "itemNotesInd": "N", "itemNumber": "11-30-12", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "113012" }, { "sequenceNumber": "01", "creationDate": "07/09/2013 08:42:36", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Distribution", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-08-10 08:03:10.946", "faaReviewStartTms": "2013-07-17 08:03:10.947671", "intExt": "EX", "itemDesc": "Flight Deck Air Vent (Non-Gasper) Damaged/Inoperative", "itemNotes": "For flight deck gasper air vent damaged/inoperative reference NEF 21-24-04.", "itemNotesInd": "Y", "itemNumber": "21-20-01", "lastUpdate": "2013-07-17 08:03:16.043175", "lastUpdateDisplay": "07/17/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9776194", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000421388", "rowInsertEmpNoDisplay": "00421388", "rowInsertTms": "2013-07-09 08:41:49.047524", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "212001" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "21", "ataDesc": "Cabin/Crew Rest Area (CRA) Ducting/(Cabin Fresh Air Distr Cont Monit-A350 Only)", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd":

"Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2025-04-17 07:07:38.75561", "faaReviewStartTms": "2025-03-24 07:07:38.75561", "intExt": "IP", "itemDesc": "Cabin Vent Grill Damaged", "itemNotes": "This NEF item may not be used for damaged A330 Ceiling Vent Panels that cannot be secured by normal means. Reference ERA 623957-14TR for authorization to secure vents.", "itemNotesInd": "Y", "itemNumber": "21-21-01", "lastUpdate": "2025-03-24 07:07:55.774466", "lastUpdateDisplay": "03/24/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "212101" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Cargo Ducting/(Cockpit Air Distribution, Control and Monitoring-A350 Only)", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard.", "decisionInd": "A", "defRemarks": "Must not present hazard.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 07:34:50.999", "faaReviewStartTms": "2017-09-25 07:34:51.018706", "intExt": "EX", "itemDesc": "Cargo Compartment Air Outlet Trim Piece Missing", "itemNotesInd": "N", "itemNumber": "21-22-01", "lastUpdate": "2017-09-25 07:36:47.121277", "lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "212201" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Cargo Ducting/(Cockpit Air Distribution, Control and Monitoring-A350 Only)", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard.", "decisionInd": "A", "defRemarks": "Must not present hazard.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 07:36:05.141",

"faaReviewStartTms": "2017-09-25 07:36:05.157222", "intExt": "EX", "itemDesc": "Cargo Compartment Air Outlet Vent Grill Damaged", "itemNotesInd": "N", "itemNumber": "21-22-02", "lastUpdate": "2017-09-25 07:37:27.865734", "lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "212202" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Gasper/Individual Air System", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time reference MEL 25-25-07B for B767-300.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time reference MEL 25-25-07B for B767-300.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2025-08-28 07:14:33.621152", "faaReviewStartTms": "2025-08-04 07:14:33.621152", "intExt": "IP", "itemDesc": "Crew Rest Gasper Air Vent Damaged / Inoperative", "itemNotes": "Bugeye", "itemNotesInd": "Y", "itemNumber": "21-24-01", "lastUpdate": "2025-08-04 07:14:42.74067", "lastUpdateDisplay": "08/04/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "212401" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Gasper/Individual Air System", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 07:40:40.154", "faaReviewStartTms": "2017-09-25 07:40:40.168933", "intExt": "IP", "itemDesc": "Crew Rest Ventilation Grill Damaged", "itemNotesInd": "N", "itemNumber": "21-24-02", "lastUpdate": "2017-09-25 07:46:11.716662", "lastUpdateDisplay": "09/25/2017",

"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "212402" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "21", "ataDesc": "Gasper/Individual Air System", "ataSectCode": "24",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial list", "faaReviewEndTms": "2025-08-28 07:00:17.438686",
"faaReviewStartTms": "2025-08-04 07:00:17.438686", "intExt": "IP", "itemDesc": "Flight
Attendant Seat Gasper Air Vent Damaged / Inoperative", "itemNotesInd": "N",
"itemNumber": "21-24-03", "lastUpdate": "2025-08-04 07:00:27.454114",
"lastUpdateDisplay": "08/04/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "212403" }, { "sequenceNumber": "04",
"creationDate": "07/10/2013 11:45:35", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc":
"Gasper/Individual Air System", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd":
"Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 07:46:03.719",
"faaReviewStartTms": "2017-09-25 07:46:03.731705", "intExt": "EX", "itemDesc": "Flight
Deck Gasper Air Vent Damaged/Inoperative", "itemNotes": "For flight deck air vent (non-
gasper) damaged/inoperative reference NEF 21-20-01.", "itemNotesInd": "Y",
"itemNumber": "21-24-04", "lastUpdate": "2017-09-25 07:47:22.140252",
"lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-07-10
11:43:34.121155", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "212404" },
{ "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "21", "ataDesc": "Gasper/Individual Air System", "ataSectCode": "24",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"C", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2025-08-28
07:02:03.388826", "faaReviewStartTms": "2025-08-04 07:02:03.388826", "intExt": "IP",

"itemDesc": "Passenger Gasper Air Vent Damaged / Inoperative", "itemNotes": "Bugeye",
"itemNotesInd": "Y", "itemNumber": "21-24-05", "lastUpdate": "2025-08-04
07:02:10.653367", "lastUpdateDisplay": "08/04/2025", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "212405" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc":
"Lavatory, Galley Vent System and Fan", "ataSectCode": "26", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 09:55:43.559",
"faaReviewStartTms": "2012-03-06 09:55:42.751976", "intExt": "IG", "itemDesc": "Galley
Gasper Vent Damaged / Inoperative", "itemNotesInd": "N", "itemNumber": "21-26-01",
"lastUpdate": "2012-03-06 09:55:53.84044", "lastUpdateDisplay": "03/06/2012",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "212601" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"21", "ataDesc": "Lavatory, Galley Vent System and Fan", "ataSectCode": "26",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Damage
must not be to an extent that it leaves an opening that items could fall into or that would be
a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent
that it leaves an opening that items could fall into or that would be a security concern.",
"efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30
09:56:04.806", "faaReviewStartTms": "2012-03-06 09:56:04.002648", "intExt": "IG",
"itemDesc": "Galley Ventilation Grill Damaged", "itemNotesInd": "N", "itemNumber": "21-
26-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "212602" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "21", "ataDesc": "Lavatory, Galley Vent System and Fan",
"ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",

"decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list. Reviewed for A350.", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2017-10-19 07:48:21.227", "faaReviewStartTms":
"2017-09-25 07:48:21.239422", "intExt": "IL", "itemDesc": "Lavatory Gasper Vent Damaged
/ Inoperative", "itemNotesInd": "N", "itemNumber": "21-26-03", "lastUpdate": "2017-09-25
07:49:21.925866", "lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "212603" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc":
"Lavatory, Galley Vent System and Fan", "ataSectCode": "26", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an
extent that it leaves an opening that items could fall into or that would be a security
concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it
leaves an opening that items could fall into or that would be a security concern.",
"efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaReviewEndTms": "2012-01-02 12:36:57.261916", "faaReviewStartTms":
"2011-12-09 12:36:57.261916", "intExt": "IL", "itemDesc": "Lavatory Ventilation Grill Cover
Damaged", "itemNotesInd": "N", "itemNumber": "21-26-04", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "212604" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc":
"Lavatory, Galley Vent System and Fan", "ataSectCode": "26", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an
extent that it leaves an opening that items could fall into or that would be a security
concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it
leaves an opening that items could fall into or that would be a security concern.",
"efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial
FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:57.314003",
"faaReviewStartTms": "2011-12-09 12:36:57.314003", "intExt": "IP", "itemDesc": "Video
Control Cabinet Ducting / Grills Damaged", "itemNotesInd": "N", "itemNumber": "21-26-
05", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",

"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "212605" },
{ "sequenceNumber": "01", "creationDate": "04/26/2013 02:39:21", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "21", "ataDesc": "Ground Air Connection", "ataSectCode": "28",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure":
"CONNECTION MAY BE USED IF GROUND AIR HOSE WILL CONNECT", "decisionInd": "A",
"defRemarks": "CONNECTION MAY BE USED IF GROUND AIR HOSE WILL CONNECT",
"efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 07:39:43.469721", "faaReviewStartTms": "2022-03-08
07:39:43.469721", "intExt": "EX", "itemDesc": "Ground Air Connection Flange Damaged",
"itemNotes": "CONNECTION MAY BE USED IF GROUND AIR HOSE WILL CONNECT",
"itemNotesInd": "Y", "itemNumber": "21-28-01", "lastUpdate": "2022-03-08
07:39:52.206856", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9563476", "mplIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "0000426685", "rowInsertEmpNoDisplay": "00426685",
"rowInsertTms": "2013-04-26 02:38:03.78935", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "212801" }, { "sequenceNumber": "01", "creationDate":
"12/03/2019 04:06:06", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Pressurization",
"ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOPProcedure": "MAY BE DEFERRED IF THE TOOL IS NOT REQUIRED FOR ANY
CURRENT MEL ITEMS OR MAINTENANCE TASKS.", "decisionInd": "A", "defRemarks": "MAY
BE DEFERRED IF THE TOOL IS NOT REQUIRED FOR ANY CURRENT MEL ITEMS OR
MAINTENANCE TASKS.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 07:40:33.864115",
"faaReviewStartTms": "2022-03-08 07:40:33.864115", "intExt": "EX", "itemDesc": "Negative
Pressure Relief Door Hold-Open Tool", "itemNotes": "B757 Only - Negative Pressure Relief
Valve Hold-Open Tool, normally stowed in the flight deck gear pouch, and only used for
Pressure Relief Door lock-out during maintenance activities or MEL application, is
occasionally found missing.", "itemNotesInd": "Y", "itemNumber": "21-30-01",
"lastUpdate": "2022-03-08 07:40:41.086344", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "6591316",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000467564",
"rowInsertEmpNoDisplay": "00467564", "rowInsertTms": "2019-12-03 03:55:36.630578",

"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "213001" },
{ "sequenceNumber": "01", "creationDate": "08/16/2012 09:45:12", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "21", "ataDesc": "Crew Rest Area Heating", "ataSectCode": "41",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Crew
rest temperature control works normally. For B747 see the MEL.", "decisionInd": "A",
"defRemarks": "Crew rest temperature control works normally. For B747 see the MEL.",
"efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 07:40:56.312871", "faaReviewStartTms": "2022-03-08
07:40:56.312871", "intExt": "IP", "itemDesc": "Crew Rest Temperature Control Indication
Inop", "itemNotesInd": "N", "itemNumber": "21-41-01", "lastUpdate": "2022-03-08
07:41:04.961941", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "8901348", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000910407", "rowInsertEmpNoDisplay": "00910407",
"rowInsertTms": "2012-08-16 09:40:06.306928", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "214101" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Cooling",
"ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 07:42:39.728467", "faaReviewStartTms": "2022-03-08
07:42:39.728467", "intExt": "EX", "itemDesc": "Ram Air Door Seal Deteriorated",
"itemNotes": "Seal deteriorated but serviceable on ram air inlet door.", "itemNotesInd":
"Y", "itemNumber": "21-50-01", "lastUpdate": "2022-03-08 07:43:02.217324",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "215001" }, { "sequenceNumber": "01",
"creationDate": "06/26/2023 07:56:32", "userId": "0000603060", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc":
"Equipment Cooling Control/Fans/Faults (Use 2533 for A350 Supp Cooling System)",
"ataSectCode": "59", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Not for use for the VCRU Overheat Protection. Utilize A350 MEL 21-
59-01A for VCRU Overheat Protection.\n\n(M)\nOnly 1 VCRU may be deferred. If a VCRU is

inoperative, refer to AMM Task A350-A-21-59-55-00001-560A-A for deactivation procedures.", "decisionInd": "A", "defRemarks": "Not for use for the VCRU Overheat Protection. Utilize A350 MEL 21-59-01A for VCRU Overheat Protection.\n\n(M)\nOnly 1 VCRU may be deferred. If a VCRU is inoperative, refer to AMM Task A350-A-21-59-55-00001-560A-A for deactivation procedures.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2023-08-04 13:58:34.5893", "faaReviewStartTms": "2023-07-11 13:58:34.5893", "intExt": "IG", "itemDesc": "Vapor Cycle Refrigeration Unit (VCRU) Reduced Performance / Inoperative (A350)", "itemNotes": "This item is for A350 aircraft only.", "itemNotesInd": "Y", "itemNumber": "21-59-01", "lastUpdate": "2023-07-11 14:01:30.700643", "lastUpdateDisplay": "07/11/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000603060", "rowInsertEmpNoDisplay": "00603060", "rowInsertTms": "2023-06-26 07:49:36.416642", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00603060", "legacyFrc": "215901" }, { "sequenceNumber": "02", "creationDate": "09/18/2023 08:26:21", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Equipment Cooling Control/Fans/Faults (Use 2533 for A350 Supp Cooling System)", "ataSectCode": "59", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Galley Cooling must be sufficient in all galleys (air temperature at or below 41 degrees F) with the exception of individual position outages due to ACU inop.", "decisionInd": "A", "defRemarks": "Galley Cooling must be sufficient in all galleys (air temperature at or below 41 degrees F) with the exception of individual position outages due to ACU inop.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2023-10-13 12:57:44.19834", "faaReviewStartTms": "2023-09-19 12:57:44.19834", "intExt": "IG", "itemDesc": "SCS (Supplemental Cooling) Reduced Performance (A350 ONLY)", "itemNotesInd": "N", "itemNumber": "21-59-02", "lastUpdate": "2023-10-04 13:15:38.981001", "lastUpdateDisplay": "10/04/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-09-18 08:26:06.015107", "sceptreAutoDefRemarks": "For NEF items \u001A Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557" }, { "sequenceNumber": "03", "creationDate": "09/18/2023 08:37:04", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Equipment Cooling Control/Fans/Faults (Use 2533 for A350 Supp Cooling System)", "ataSectCode": "59",

"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "8", "deactMOProcedure": "Confirm loss of supplemental system cooling capabilities in all galley positions IAW A350 AMM 21-59-XX. To prevent provisioned dry ice dissipation, pull and collar associated circuit breakers for all ACUs on galley breaker panels at galleys locations 402 / 403 / 404 / 409 / 410 referencing applicable CMM for the galleys. Placard subject ACUs at all collared locations.", "decisionInd": "A", "defRemarks": "Confirm loss of supplemental system cooling capabilities in all galley positions IAW A350 AMM 21-59-XX. To prevent provisioned dry ice dissipation, pull and collar associated circuit breakers for all ACUs on galley breaker panels at galleys locations 402 / 403 / 404 / 409 / 410 referencing applicable CMM for the galleys. Placard subject ACUs at all collared locations.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2026-06-14 12:57:55.719461", "faaReviewStartTms": "2026-05-21 12:57:55.719461", "intExt": "IG", "itemDesc": "Inoperative Supplemental Galley Cooling - A350 ONLY - Dry Ice Required All Locations", "itemNotes": "Dry ice provisioning required at all cooled galley cart positions. Contact MCC to apply SPL-item 21-59-00.", "itemNotesInd": "Y", "itemNumber": "21-59-03", "lastUpdate": "2026-05-21 13:00:43.752526", "lastUpdateDisplay": "05/21/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-09-18 08:31:43.321702", "sceptreAutoDefRemarks": "For NEF items \u001A Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00700872" }, { "sequenceNumber": "04", "creationDate": "10/26/2023 12:00:48", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Equipment Cooling Control/Fans/Faults (Use 2533 for A350 Supp Cooling System)", "ataSectCode": "59", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "8", "deactMOProcedure": "Observation of a smoke, wire damage, or overheat event requires additional inspection by maintenance prior to placarding. If the ACU (air cooling unit) is inoperative, pull and secure associated circuit breaker for ACU on galley breaker panel referencing applicable CMM for the galley. Placard subject ACU \"inoperative\".", "decisionInd": "A", "defRemarks": "Observation of a smoke, wire damage, or overheat event requires additional inspection by maintenance prior to placarding. If the ACU (air cooling unit) is inoperative, pull and secure associated circuit breaker for ACU on galley breaker panel referencing applicable CMM for the galley. Placard subject ACU \"inoperative\".", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2026-06-14 12:58:39.305834", "faaReviewStartTms": "2026-05-21 12:58:39.305834", "intExt": "IG", "itemDesc": "Galley Air Cooling Unit Reduced Performance/Inoperative - A350 ONLY - Dry Ice Required Specific

Locations", "itemNotes": "Dry ice provisioning required at any cooled galley cart positions with an inoperative ACU. Contact MCC to apply SPL-item 21-59-00.", "itemNotesInd": "Y", "itemNumber": "21-59-04", "lastUpdate": "2026-05-21 13:02:34.173445", "lastUpdateDisplay": "05/21/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-10-26 11:46:43.845759", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00700872", "legacyFrc": "215904" }, { "sequenceNumber": "01", "creationDate": "07/28/2013 02:39:54", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Zone Temperature Control/(Monitoring-A350 Only)", "ataSectCode": "61", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-08-24 13:02:23.48", "faaReviewStartTms": "2013-07-31 13:02:23.488156", "intExt": "IP", "itemDesc": "Cabin Temp Intake Grill or Retainer Damaged/Missing", "itemNotesInd": "N", "itemNumber": "21-61-01", "lastUpdate": "2013-07-31 14:27:42.74651", "lastUpdateDisplay": "07/31/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9581742", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000548039", "rowInsertEmpNoDisplay": "00548039", "rowInsertTms": "2013-07-28 02:27:10.764701", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "216101" }, { "sequenceNumber": "01", "creationDate": "04/14/2021 13:32:12", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Cabin Air Quality", "ataSectCode": "70", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Reviewed NEF Checklist and Liaison Engineering Support Assistance Request Form for Teledyne Aircraft Cabin Environment Sensor (ACES) System and found acceptable as submitted.", "faaContactName": "Williams", "faaReviewEndTms": "2023-08-21 12:27:29.122133", "faaReviewStartTms": "2023-07-28 12:27:29.122133", "intExt": "IP", "itemDesc": "Teledyne Aircraft Cabin Environment Sensor (ACES) INOP", "itemNotes": "Teledyne Aircraft Cabin Environment Sensor (ACES) System may be inoperative. The ACES System consists of ACES Onboard Devices (AOD) and ACES Sensor Packs (ASP). All or some components may be inoperative.", "itemNotesInd": "Y", "itemNumber": "21-70-01", "lastUpdate": "2023-07-28 12:27:41.855177", "lastUpdateDisplay": "07/28/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",

"rowInsertTms": "2021-04-14 13:27:25.287479", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "217001" }, { "sequenceNumber": "02", "creationDate": "07/28/2023 12:38:41", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Cabin Air Quality", "ataSectCode": "70", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "All associated wiring must be capped and stowed per applicable SWPM/ESPM/ESPP procedures. Must not pose hazards to personnel (e.g. no sharp edges, no arcing, chafing wire damage, etc.).", "defRemarks": "All associated wiring must be capped and stowed per applicable SWPM/ESPM/ESPP procedures. Must not pose hazards to personnel (e.g. no sharp edges, no arcing, chafing wire damage, etc.).", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Split relief from 21-70-01...INOP/MISSING", "faaContactName": "Already approved...see comments", "faaReviewEndTms": "2023-08-21 12:37:03.098503", "faaReviewStartTms": "2023-07-28 12:37:03.098503", "intExt": "IP", "itemDesc": "Teledyne Aircraft Cabin Environment Sensor (ACES) MISSING", "itemNotes": "Teledyne Aircraft Cabin Environment Sensor (ACES) System may be missing. The ACES System consists of ACES Onboard Devices (AOD) and ACES Sensor Packs (ASP). All or some components may be missing.", "itemNotesInd": "Y", "itemNumber": "21-70-02", "lastUpdate": "2023-07-28 12:37:14.575265", "lastUpdateDisplay": "07/28/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-07-28 12:37:03.098503", "sceptreAutoDefRemarks": "For NEF items \u001A Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "217002" }, { "sequenceNumber": "03", "creationDate": "10/03/2024 11:46:14", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "21", "ataDesc": "Cabin Air Quality", "ataSectCode": "70", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-10-27 12:08:11.520771", "faaReviewStartTms": "2024-10-03 12:08:11.520771", "intExt": "IP", "itemDesc": "Sidewall Diffuser Blockers missing - 757-200 ONLY", "itemNotes": "757-200 ONLY, P/N H30567-039 or 25-5830-001 as installed by AA 2161-01021.", "itemNotesInd": "Y", "itemNumber": "21-70-03", "lastUpdate": "2024-10-03 12:34:51.163944", "lastUpdateDisplay": "10/03/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-10-03 11:46:10.004117", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "217003" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "23", "ataDesc": "High Frequency (HF)", "ataSectCode": "11",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"D", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2022-04-01
07:43:42.928282", "faaReviewStartTms": "2022-03-08 07:43:42.928282", "intExt": "EX",
"itemDesc": "HF Sensitivity Knob Damaged / Missing (sensitivity still adjustable)",
"itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y",
"itemNumber": "23-11-01", "lastUpdate": "2022-03-08 07:43:48.617764",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "231101" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Satellite Communications (SATCOM)", "ataSectCode": "25", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Reset Timed Out. Satcom
operational phone numbers will need to be dialed manually.", "decisionInd": "A",
"defRemarks": "Reset Timed Out. Satcom operational phone numbers will need to be
dialed manually.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 07:44:05.595191", "faaReviewStartTms": "2022-03-08
07:44:05.595191", "intExt": "EX", "itemDesc": "Satcom Phone Directory Missing",
"itemNotes": "Reset Timed Out. Satcom operational phone numbers will need to be dialed
manually.", "itemNotesInd": "Y", "itemNumber": "23-25-01", "lastUpdate": "2022-03-08
07:44:30.394905", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "232501" }, { "sequenceNumber": "01",
"creationDate": "06/16/2025 08:54:50", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Passenger Address & Entertainment System Check and Software Loads", "ataSectCode":
"30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A",
"efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as
submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-07-17

13:23:00.272907", "faaReviewStartTms": "2025-06-23 13:23:00.272907", "intExt": "IP",
"itemDesc": "IFE BITE data not offloading over WiFi connection - Except 717", "itemNotes":
"Built In Test Equipment (BITE) data offloading is a capability of Delta Air Lines IFE system
to evaluate IFE equipment performance. No passenger impact for either WiFi or IFE system
as data is used for performance monitoring only.", "itemNotesInd": "Y", "itemNumber":
"23-30-01", "lastUpdate": "2025-06-23 14:42:37.880012", "lastUpdateDisplay":
"06/23/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-06-16 08:53:33.77271",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Passenger Address and Chimes, PAPA (Passenger Address Priority Assy)", "ataSectCode":
"31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A",
"efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaReviewEndTms": "2012-01-02 12:36:57.660694", "faaReviewStartTms":
"2011-12-09 12:36:57.660694", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Cabin Speakers
have static (Still Operational)", "itemNotes": "For inoperative speaker(s) refer to MEL.",
"itemNotesInd": "Y", "itemNumber": "23-31-02", "lastUpdate": "2011-12-09 12:36:53.842",
"lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "LOADJOB", "legacyFrc": "233102" }, { "sequenceNumber": "07",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Passenger Address and Chimes, PAPA (Passenger Address Priority Assy)", "ataSectCode":
"31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure":
"Audio must still be intelligible.", "decisionInd": "A", "defRemarks": "Audio must still be
intelligible.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2022-04-01 07:47:00.57334", "faaReviewStartTms":
"2022-03-08 07:47:00.57334", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "PA System
Loud", "itemNotesInd": "N", "itemNumber": "23-31-07", "lastUpdate": "2022-03-08
07:47:08.952195", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00324557", "legacyFrc": "233107" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 07:47:55.426682", "faaReviewStartTms": "2022-03-08 07:47:55.426682", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Movie Control Panel Inop", "itemNotesInd": "N", "itemNumber": "23-32-04", "lastUpdate": "2022-03-08 07:48:13.862172", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233204" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:58.156701", "faaReviewStartTms": "2011-12-09 12:36:58.156701", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Moving Map Incorrect Data", "itemNotesInd": "N", "itemNumber": "23-32-05", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "233205" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:58.226011", "faaReviewStartTms": "2011-12-09 12:36:58.226011", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Moving Map Interferes With Movie", "itemNotesInd": "N", "itemNumber": "23-32-06", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",

"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "233206" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:58.276796", "faaReviewStartTms": "2011-12-09 12:36:58.276796", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Moving Map Not Communicating", "itemNotesInd": "N", "itemNumber": "23-32-07", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "233207" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:36:58.343216", "faaReviewStartTms": "2011-12-09 12:36:58.343216", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Moving Map Won't Turn On", "itemNotesInd": "N", "itemNumber": "23-32-08", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "233208" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "NOTE: This NEF item does NOT apply to the A220. Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "decisionInd": "A", "defRemarks": "NOTE: This NEF item does NOT apply to the A220. Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2020-12-25 12:31:38.037873", "faaReviewStartTms": "2020-12-01 12:31:38.037873", "ifeltem": "IFE",

"intExt": "IP", "itemDesc": "Overhead/Wall Monitor Inop-F/A Manual Briefing / demo
Required - Video /except A220 fleet/", "itemNotesInd": "N", "itemNumber": "23-32-09",
"lastUpdate": "2020-12-01 12:32:03.388991", "lastUpdateDisplay": "12/01/2020",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233209" },
{ "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Captain
is to brief lead flight attendant to accomplish takeoff briefing/demos.", "decisionInd": "A",
"defRemarks": "Captain is to brief lead flight attendant to accomplish takeoff
briefing/demos.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list. Reviewed for A350.", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2019-03-23 09:33:14.254484", "faaReviewStartTms":
"2019-02-27 09:33:14.254484", "ifelItem": "IFE", "intExt": "IP", "itemDesc": "Video Monitor
Poor Quality -F/A Manual Brief/demo Required - Overhead Monitor", "itemNotesInd": "N",
"itemNumber": "23-32-10", "lastUpdate": "2019-02-27 09:33:17.586939",
"lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "233210" }, { "sequenceNumber": "11",
"creationDate": "11/03/2015 08:36:57", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "23", "ataDesc":
"Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd":
"Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 07:48:43.201788",
"faaReviewStartTms": "2022-03-08 07:48:43.201788", "ifelItem": "IFE", "intExt": "IP",
"itemDesc": "Cell Modem Inoperative (Panasonic IFE System)", "itemNotes": "This deferral
is for the cell modem installed on Panasonic IFE systems. The cell modem transmits and
receives IFE data (BITE, PAXUS, and OneMedia) and is not used for any flight critical
systems. The transfer of data occurs when the aircraft is on the ground. NEF has 365 day
allowable time limit", "itemNotesInd": "Y", "itemNumber": "23-32-11", "lastUpdate": "2022-
03-08 07:48:50.122382", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467",

"rowInsertTms": "2015-11-03 08:35:34.083323", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233211" }, { "sequenceNumber": "12", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "decisionInd": "A", "defRemarks": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:34:42.287644", "faaReviewStartTms": "2019-02-27 09:34:42.287644", "ifeltm": "IFE", "intExt": "IP", "itemDesc": "Video Monitor Will Not Extend -F/A Manual Brief/demo Required- Overhead Monitor", "itemNotesInd": "N", "itemNumber": "23-32-12", "lastUpdate": "2019-02-27 09:34:56.667841", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233212" }, { "sequenceNumber": "14", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "decisionInd": "A", "defRemarks": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2022-04-01 07:49:36.114815", "faaReviewStartTms": "2022-03-08 07:49:36.114815", "ifeltm": "IFE", "intExt": "IP", "itemDesc": "Safety Video Incorrect/Missing -F/A Manual Brief/demo Required", "itemNotesInd": "N", "itemNumber": "23-32-14", "lastUpdate": "2022-03-08 07:49:49.46731", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233214" }, { "sequenceNumber": "15", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Video (Overhead and Airshow)", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd":

"Y", "daysCount": "0", "deactMOProcedure": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "decisionInd": "A", "defRemarks": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2022-04-01 07:50:02.901779", "faaReviewStartTms": "2022-03-08 07:50:02.901779", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Safety Video Poor A/V Quality-F/A Manual Brief/demo Required", "itemNotesInd": "N", "itemNumber": "23-32-15", "lastUpdate": "2022-03-08 07:50:07.060583", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233215" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2026-05-09 09:25:06.202877", "faaReviewStartTms": "2026-04-15 09:25:06.202877", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Audio Inop for Individual Seat - PS, C+, Main Cabin", "itemNotesInd": "N", "itemNumber": "23-33-01", "lastUpdate": "2026-04-16 09:12:47.759058", "lastUpdateDisplay": "04/16/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "233301" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2026-05-14 07:54:37.473104", "faaReviewStartTms": "2026-04-20 07:54:37.473104", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Audio Inop for Individual Seat - Delta One and First Class Only", "itemNotesInd": "N", "itemNumber": "23-33-02", "lastUpdate": "2026-04-20 08:00:21.485296", "lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00700872", "legacyFrc": "233302" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:45:23.238611",
"faaReviewStartTms": "2019-02-27 09:45:23.238611", "ifItem": "IFE", "intExt": "IP",
"itemDesc": "Inseat Audio Jack Audio in One Ear Only", "itemNotesInd": "N",
"itemNumber": "23-33-03", "lastUpdate": "2019-02-27 09:45:29.812403",
"lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "233303" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": ".", "faaReviewEndTms": "2026-05-14 07:54:59.842447",
"faaReviewStartTms": "2026-04-20 07:54:59.842447", "ifItem": "IFE", "intExt": "IP",
"itemDesc": "Inseat Audio Jack Damaged / Obstructed - Delta One and First Class Only",
"itemNotesInd": "N", "itemNumber": "23-33-04", "lastUpdate": "2026-04-20
08:00:43.879103", "lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00700872", "legacyFrc": "233304" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:46:24.436649",
"faaReviewStartTms": "2019-02-27 09:46:24.436649", "ifItem": "IFE", "intExt": "IP",
"itemDesc": "Inseat Music Audio Uncontrollable", "itemNotesInd": "N", "itemNumber":
"23-33-05", "lastUpdate": "2019-02-27 09:46:28.668925", "lastUpdateDisplay":

"02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233305" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:46:50.785946", "faaReviewStartTms": "2019-02-27 09:46:50.785946", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Music Poor Quality / Inoperative", "itemNotesInd": "N", "itemNumber": "23-33-06", "lastUpdate": "2019-02-27 09:46:54.558644", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233306" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:47:18.25073", "faaReviewStartTms": "2019-02-27 09:47:18.25073", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Movie Audio Mixing Channels/Limited", "itemNotesInd": "N", "itemNumber": "23-33-07", "lastUpdate": "2019-02-27 09:47:24.433004", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233307" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:47:48.731132", "faaReviewStartTms": "2019-02-27

09:47:48.731132", "ifItem": "IFE", "intExt": "IP", "itemDesc": "Movie Audio Poor Quality / Static", "itemNotesInd": "N", "itemNumber": "23-33-08", "lastUpdate": "2019-02-27 09:47:52.159268", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233308" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:52:17.307629", "faaReviewStartTms": "2019-02-27 09:52:17.307629", "ifItem": "IFE", "intExt": "IP", "itemDesc": "Movie Audio Volume Too High / Low", "itemNotesInd": "N", "itemNumber": "23-33-09", "lastUpdate": "2019-02-27 09:52:20.319277", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233309" }, { "sequenceNumber": "10", "creationDate": "03/29/2022 12:13:50", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2022-04-28 11:58:47.970284", "faaReviewStartTms": "2022-04-04 11:58:47.970284", "intExt": "IP", "itemDesc": "Passenger Seat Video Monitor Bluetooth Audio Connectivity (IF INSTALLED)", "itemNotes": "Passenger Seat Video Monitor Bluetooth Audio Connection functionality may be inoperative. NEF only applies to aircraft which have Bluetooth functionality installed and activated.", "itemNotesInd": "Y", "itemNumber": "23-33-10", "lastUpdate": "2022-04-04 12:43:31.049234", "lastUpdateDisplay": "04/04/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2022-03-29 12:00:07.823594", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233310" }, { "sequenceNumber": "11", "creationDate": "04/15/2026 10:03:58", "userId":

"0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Passenger Entertainment (Audio)", "ataSectCode":
"33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2026-05-09 09:52:22.696438",
"faaReviewStartTms": "2026-04-15 09:52:22.696438", "ifeltem": "IFE", "intExt": "IP",
"itemDesc": "Inseat Audio Jack Damaged / Obstructed - PS, C+, Main Cabin",
"itemNotesInd": "N", "itemNumber": "23-33-11", "lastUpdate": "2026-04-16
09:16:08.724171", "lastUpdateDisplay": "04/16/2026", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y",
"rowInsertEmpNo": "0000700872", "rowInsertEmpNoDisplay": "00700872",
"rowInsertTms": "2026-04-15 09:52:22.696438", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00700872", "legacyFrc": "233311" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Boarding Music,
Saftey Video and Prerecorded Annoucements", "ataSectCode": "36", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.
Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01
07:52:10.648671", "faaReviewStartTms": "2022-03-08 07:52:10.648671", "ifeltem": "IFE",
"intExt": "IP", "itemDesc": "Boarding Music Incorrect", "itemNotesInd": "N", "itemNumber":
"23-36-01", "lastUpdate": "2022-03-08 07:52:28.17826", "lastUpdateDisplay":
"03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00324557", "legacyFrc": "233601" }, { "sequenceNumber": "02", "creationDate":
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Boarding Music,
Saftey Video and Prerecorded Annoucements", "ataSectCode": "36", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.
Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01
07:52:47.309305", "faaReviewStartTms": "2022-03-08 07:52:47.309305", "ifeltem": "IFE",
"intExt": "IP", "itemDesc": "Boarding Music Poor Quality / Inoperative", "itemNotesInd": "N",
"itemNumber": "23-36-02", "lastUpdate": "2022-03-08 07:52:50.951352",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":

"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233602" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 07:53:11.572912", "faaReviewStartTms": "2022-03-08 07:53:11.572912", "ifeltItem": "IFE", "intExt": "IP", "itemDesc": "Entertainment Audit Tapes or Media Load Out of Date", "itemNotes": "Safety Briefing Video is covered by its own NEF item.", "itemNotesInd": "Y", "itemNumber": "23-37-01", "lastUpdate": "2022-03-08 07:53:21.573548", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233701" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "decisionInd": "A", "defRemarks": "Captain is to brief lead flight attendant to accomplish takeoff briefing/demos.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 09:52:41.421989", "faaReviewStartTms": "2019-02-27 09:52:41.421989", "ifeltItem": "IFE", "intExt": "IP", "itemDesc": "IFE Audio/Video Quality Poor-F/A Manual Brief/demo Required", "itemNotesInd": "N", "itemNumber": "23-37-02", "lastUpdate": "2019-02-27 09:52:45.95037", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233702" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure":

"Must not present hazard to passengers or crew or impede emergency egress.",
"decisionInd": "A", "defRemarks": "Must not present hazard to passengers or crew or impede emergency egress.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list. Reviewed for A350.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 08:02:22.196",
"faaReviewStartTms": "2017-09-25 08:02:22.206947", "ifeltem": "IFE", "intExt": "IP",
"itemDesc": "In-Arm Seat Video Display (ISVD) Hard To Install / Extend", "itemNotesInd": "N", "itemNumber": "23-37-05", "lastUpdate": "2017-09-25 08:03:53.298972",
"lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "233705" }, { "sequenceNumber": "06",
"creationDate": "01/18/2017 09:30:46", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPprocedure": "Disconnect the primary IFE signal line in accordance with the following instructions. After disconnecting the primary line, verify the fault is no longer present and the IFE system is fully operational in the redundant mode.\n1. Disconnect harness connector D95194P at the J8 connection of ADB4.\n2. Cap and stow the D95194P connector IAW BSWPM, CH. 20.\n3. Verify IFE system functionality in backup mode. \n4. Note in a paper log page that connector D95194P at the J8 connection to ADB4 has been disconnected, capped, and stowed.", "decisionInd": "A", "defRemarks": "Disconnect the primary IFE signal line in accordance with the following instructions. After disconnecting the primary line, verify the fault is no longer present and the IFE system is fully operational in the redundant mode.\n1. Disconnect harness connector D95194P at the J8 connection of ADB4.\n2. Cap and stow the D95194P connector IAW BSWPM, CH. 20.\n3. Verify IFE system functionality in backup mode. \n4. Note in a paper log page that connector D95194P at the J8 connection to ADB4 has been disconnected, capped, and stowed.", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Paper Log Page documentation required.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:08:49.512715", "faaReviewStartTms": "2018-01-29 13:08:49.512715", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Redundant IFE Network Operational, Primary IFE Signal Degraded/Inoperative (B767 Only)", "itemNotes": "Video on the B767 IFE system skips in primary mode due to pinched signal wiring. The IFE system must be switched to the redundant mode by disconnecting the primary signal connector. before using this NEF item, confirm the IFE system is fully operational in the redundant mode after the primary

line is disconnected. This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "23-37-06", "lastUpdate": "2018-05-10 07:57:07.19323", "lastUpdateDisplay": "05/10/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2017-01-18 09:16:37.849511", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "233706" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:53:03.678607", "faaReviewStartTms": "2019-02-27 09:53:03.678607", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat On-Demand Movies Unavailable", "itemNotesInd": "N", "itemNumber": "23-37-07", "lastUpdate": "2019-02-27 09:53:06.539928", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233707" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Install placard ON inoperative monitor. For the pre-flight safety brief/demonstration, an adjacent video monitor must be visible to the passenger sitting in the seat with the video inoperative. If video is not visible from an adjacent seat, the flight attendant must perform the safety brief/demonstration for the seat/seats with the inoperative video.", "decisionInd": "A", "defRemarks": "Install placard ON inoperative monitor. For the pre-flight safety brief/demonstration, an adjacent video monitor must be visible to the passenger sitting in the seat with the video inoperative. If video is not visible from an adjacent seat, the flight attendant must perform the safety brief/demonstration for the seat/seats with the inoperative video.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Crew deferral at the request of the MCC permissable.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-09 09:31:58.313681", "faaReviewStartTms": "2026-04-15 09:31:58.313681", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Video

Monitor/Seat Display Unit Inoperative-F/A Manual Brief/demo may be Required - PS, C+, Main Cabin", "itemNotes": "Includes Comfort plus (C+)", "itemNotesInd": "Y", "itemNumber": "23-37-08", "lastUpdate": "2026-04-16 09:16:50.331166", "lastUpdateDisplay": "04/16/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "233708" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Install placard ON inoperative monitor. For the pre-flight safety brief/demonstration, an adjacent video monitor must be visible to the passenger sitting in the seat with the video inoperative. If video is not visible from an adjacent seat, the flight attendant must perform the safety brief/demonstration for the seat/seats with the inoperative video.", "decisionInd": "A", "defRemarks": "Install placard ON inoperative monitor. For the pre-flight safety brief/demonstration, an adjacent video monitor must be visible to the passenger sitting in the seat with the video inoperative. If video is not visible from an adjacent seat, the flight attendant must perform the safety brief/demonstration for the seat/seats with the inoperative video.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Crew deferral at the request of the MCC permissable.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-14 07:55:47.241778", "faaReviewStartTms": "2026-04-20 07:55:47.241778", "ifeltm": "IFE", "intExt": "IP", "itemDesc": "Inseat Video Monitor Inoperative -F/A Manual Brief/demo may be Required - Delta One and First Class Only", "itemNotesInd": "N", "itemNumber": "23-37-09", "lastUpdate": "2026-04-20 08:01:22.0849", "lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "233709" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 08:04:50.43",

"faaReviewStartTms": "2017-09-25 08:04:50.439701", "ifeltem": "IFE", "intExt": "IP",
"itemDesc": "Inseat Video / Music Channels Do Not Match Icons", "itemNotesInd": "N",
"itemNumber": "23-37-10", "lastUpdate": "2017-09-25 08:05:39.880127",
"lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "233710" }, { "sequenceNumber": "14",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode":
"37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure":
"Install placard at seat. If passenger briefing is affected Captain is to brief lead flight
attendant to accomplish takeoff briefing/demos.", "decisionInd": "A", "defRemarks":
"Install placard at seat. If passenger briefing is affected Captain is to brief lead flight
attendant to accomplish takeoff briefing/demos.", "efmTab": "A",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.
Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23
09:56:39.001119", "faaReviewStartTms": "2019-02-27 09:56:39.001119", "ifeltem": "IFE",
"intExt": "IP", "itemDesc": "Inseat Video Poor Video Quality-F/A Manual Brief/demo
Required", "itemNotesInd": "N", "itemNumber": "23-37-14", "lastUpdate": "2019-02-27
09:56:42.365975", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "233714" }, { "sequenceNumber": "15",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode":
"37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A",
"efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list. Reviewed for A350.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2019-03-23 09:57:45.922818", "faaReviewStartTms": "2019-02-27
09:57:45.922818", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Video Screen Wont
Go Into Entertainment", "itemNotesInd": "N", "itemNumber": "23-37-15", "lastUpdate":
"2019-02-27 09:57:50.127191", "lastUpdateDisplay": "02/27/2019",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "233715" }, { "sequenceNumber": "16", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-14 07:56:41.408436", "faaReviewStartTms": "2026-04-20 07:56:41.408436", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Video Touch Screen Unresponsive Delta One and First Class Only", "itemNotes": "Not applicable to inoperative inseat video monitor(s).", "itemNotesInd": "Y", "itemNumber": "23-37-16", "lastUpdate": "2026-04-20 08:01:38.691759", "lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "233716" }, { "sequenceNumber": "17", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-12-24 12:15:06.799209", "faaReviewStartTms": "2022-11-30 12:15:06.799209", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Video Will Not Download Game / Menu", "itemNotes": "Includes in-seat menu application content and Smart IFE functions.", "itemNotesInd": "Y", "itemNumber": "23-37-17", "lastUpdate": "2022-11-30 12:15:14.293375", "lastUpdateDisplay": "11/30/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "233717" }, { "sequenceNumber": "18", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",

"faaComments": "Contained in initial FAA approved list.", "faaContactName": ".",
"faaReviewEndTms": "2019-03-23 10:00:37.442951", "faaReviewStartTms": "2019-02-27
10:00:37.442951", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Satellite TV Inoperative",
"itemNotesInd": "N", "itemNumber": "23-37-18", "lastUpdate": "2019-02-27
10:00:40.190649", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "233718" }, { "sequenceNumber": "19",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode":
"37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A",
"efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaReviewEndTms": "2012-01-02 12:37:01.479904", "faaReviewStartTms":
"2011-12-09 12:37:01.479904", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Universal
Passenger Control Unit (UPCU) Cord Won't Retract / Damaged", "itemNotesInd": "N",
"itemNumber": "23-37-19", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":
"12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"LOADJOB", "legacyFrc": "233719" }, { "sequenceNumber": "21", "creationDate":
"12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video
Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to
an extent that it leaves an opening that items could fall into or that would be a security
concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it
leaves an opening that items could fall into or that would be a security concern.",
"efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaContactName": ".", "faaReviewEndTms": "2026-05-14
07:58:07.908388", "faaReviewStartTms": "2026-04-20 07:58:07.908388", "ifeltem": "IFE",
"intExt": "IP", "itemDesc": "Universal Passenger Control Unit (UPCU) Handset or Cradle
Damaged / Inoperative - Delta One and First Class Only", "itemNotesInd": "N",
"itemNumber": "23-37-21", "lastUpdate": "2026-04-20 08:01:54.094959",
"lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":

"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "233721" }, { "sequenceNumber": "30", "creationDate": "02/12/2018 05:47:08", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified Allowable Time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 07:54:28.602188", "faaReviewStartTms": "2022-03-08 07:54:28.602188", "intExt": "IP", "itemDesc": "Panasonic OML INOP -onboard media loader", "itemNotes": "This item has a allowable limit of 365 days. This NEF is only for the OML being inop NOT the content/entertainment being out of date, if that is the case see NEF 23-37-01. The content should not be out of date because of a INOP OML there are alternate ways for loading the software such as using a PML (portable media loader).", "itemNotesInd": "Y", "itemNumber": "23-37-30", "lastUpdate": "2022-03-08 07:54:34.861423", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2018-02-12 05:39:32.456236", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233730" }, { "sequenceNumber": "31", "creationDate": "11/13/2019 08:03:20", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Ensure that the switch functions properly.", "decisionInd": "R", "defRemarks": "Ensure that the switch functions properly.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2022-04-01 07:54:51.024554", "faaReviewStartTms": "2022-03-08 07:54:51.024554", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "IFE Master Switch Cover", "itemNotes": "A220 Fleet Only", "itemNotesInd": "Y", "itemNumber": "23-37-31", "lastUpdate": "2022-03-08 07:54:56.709927", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000603060", "rowInsertEmpNoDisplay": "00603060", "rowInsertTms": "2019-11-13 07:51:55.685397", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233731" }, { "sequenceNumber": "32", "creationDate": "07/11/2024 09:17:19", "userId":

"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System
Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Acceptable as submitted.", "faaContactName": "Bill L. Williams",
"faaReviewEndTms": "2024-08-04 14:08:16.237496", "faaReviewStartTms": "2024-07-11
14:08:16.237496", "intExt": "IP", "itemDesc": "Inseat Video Screens - Cosmetic Damage",
"itemNotes": "Cosmetic damage may include but is not limited to: significant scratches,
permanent stains, chipped corners, etc.", "itemNotesInd": "Y", "itemNumber": "23-37-32",
"lastUpdate": "2024-07-15 13:33:44.809908", "lastUpdateDisplay": "07/15/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-07-11 09:11:40.339355",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233732" },
{ "sequenceNumber": "33", "creationDate": "09/23/2024 14:30:52", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System
Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams",
"faaReviewEndTms": "2024-10-24 08:47:33.696657", "faaReviewStartTms": "2024-09-30
08:47:33.696657", "intExt": "IP", "itemDesc": "Wireless IFE Secondary File Server
Inoperative (764 and A330-900 ONLY)", "itemNotes": "764 and A330-900 only, P/N E71-
202A01. If Secondary File Server is found inoperative, Wireless In-Flight Entertainment
System remains fully operational through Primary Server.", "itemNotesInd": "Y",
"itemNumber": "23-37-33", "lastUpdate": "2024-09-30 08:47:43.861118",
"lastUpdateDisplay": "09/30/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-09-23
14:19:19.693432", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233733" },
{ "sequenceNumber": "34", "creationDate": "11/17/2025 12:17:50", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System
Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams",

"faaReviewEndTms": "2025-12-11 13:36:51.008882", "faaReviewStartTms": "2025-11-17 13:36:51.008882", "intExt": "IP", "itemDesc": "Redundant IFE Network Inoperative, Seatback Installed Screens (ALL fleets, except 717)", "itemNotesInd": "N", "itemNumber": "23-37-34", "lastUpdate": "2025-11-19 06:29:54.543118", "lastUpdateDisplay": "11/19/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-11-17 12:06:48.662873", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "233734" }, { "sequenceNumber": "35", "creationDate": "04/15/2026 10:19:25", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2026-05-09 10:08:48.996346", "faaReviewStartTms": "2026-04-15 10:08:48.996346", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Inseat Video Touch Screen Unresponsive - PS, C+, Main Cabin", "itemNotes": "Not applicable to inoperative inseat video monitor(s).", "itemNotesInd": "Y", "itemNumber": "23-37-35", "lastUpdate": "2026-04-16 09:18:40.82302", "lastUpdateDisplay": "04/16/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "0000700872", "rowInsertEmpNoDisplay": "00700872", "rowInsertTms": "2026-04-15 10:07:27.718095", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00700872", "legacyFrc": "233735" }, { "sequenceNumber": "36", "creationDate": "04/15/2026 10:26:25", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Personal Video Screen & Inseat Handset, System Faults and Resets", "ataSectCode": "37", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2026-05-09 10:16:23.602532", "faaReviewStartTms": "2026-04-15 10:16:23.602532", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "Universal Passenger Control Unit (UPCU) Handset or Cradle Damaged / Inoperative - PS, C+, Main Cabin", "itemNotesInd": "N", "itemNumber": "23-37-36", "lastUpdate": "2026-04-16 09:19:38.925984", "lastUpdateDisplay": "04/16/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000700872",

"rowInsertEmpNoDisplay": "00700872", "rowInsertTms": "2026-04-15 10:16:23.602532",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00700872", "legacyFrc": "233736" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Maintenance and Ground Interphone, (Remote
Electronics Unit)", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list. Reviewed for A350.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 08:08:22.748",
"faaReviewStartTms": "2017-09-25 08:08:22.756691", "intExt": "EX", "itemDesc": "Service
Interphone Phenolic Block at External Power Damaged", "itemNotes": "The phenolic block
is cracked but the jack can be secured for use. If can not be secured ref MEL. Defer for
block replacement where there is parts and manpower.", "itemNotesInd": "Y",
"itemNumber": "23-41-02", "lastUpdate": "2017-09-25 08:09:26.974194",
"lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "234102" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Cabin Interphone", "ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Handset must be able to be secured in cradle.",
"decisionInd": "A", "defRemarks": "Handset must be able to be secured in cradle.",
"efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Emended Notes.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-01-06 09:08:27.876",
"faaReviewStartTms": "2017-12-13 09:08:27.879636", "intExt": "IP", "itemDesc": "Cabin
Handset Cradle Damaged (Handset operational)", "itemNotes": "See MEL for handset if
cradle is causing the handset not to reset or not operate correctly.", "itemNotesInd": "Y",
"itemNumber": "23-42-01", "lastUpdate": "2017-12-13 12:11:35.88397",
"lastUpdateDisplay": "12/13/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "234201" }, { "sequenceNumber": "01",
"creationDate": "08/15/2017 13:48:13", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":

"Flight Interphone/Medical Communication System", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Troubleshoot system per A330 AWM 23-51-13 and/or 23-51-01, if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with Airbus ESPM Chapter 20-54-50 at the damage location.\n\nOnly on A330 Post AA 2351-01033", "decisionInd": "A", "defRemarks": "Troubleshoot system per A330 AWM 23-51-13 and/or 23-51-01, if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with Airbus ESPM Chapter 20-54-50 at the damage location.\n\nOnly on A330 Post AA 2351-01033", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Removed ER/A reference.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 07:55:47.415787", "faaReviewStartTms": "2022-03-08 07:55:47.415787", "intExt": "IP", "itemDesc": "Cabin medical communication flight deck switch inop(330 only)See notes", "itemNotes": "This NEF allows for the flight deck switch to be rendered inoperative and will render the whole system inoperative.\nTroubleshoot system per A330 AWM 23-51-13 and/or 23-51-01, if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with Airbus ESPM Chapter 20-54-50 at the damage location.\n\nOnly on A330 Post AA 2351-01033", "itemNotesInd": "Y", "itemNumber": "23-51-01", "lastUpdate": "2022-03-08 07:55:57.637921", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2017-08-15 13:39:37.516241", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "235101" }, { "sequenceNumber": "02", "creationDate": "08/15/2017 13:49:12", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Flight Interphone/Medical Communication System", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Troubleshoot system per A330 AWM 23-51-13 and/or 23-51-01, if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with Airbus ESPM Chapter 20-54-50 at the damage location.\n\nOnly on A330 Post AA 2351-01033", "decisionInd": "A", "defRemarks": "Troubleshoot system per A330 AWM 23-51-13 and/or 23-51-01, if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with Airbus ESPM Chapter 20-54-50 at the damage location.\n\nOnly on A330 Post AA 2351-01033", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Removed ER/A reference.", "faaContactName": "Hooogenhout", "faaReviewEndTms": "2022-04-01 07:56:20.309461", "faaReviewStartTms": "2022-03-08 07:56:20.309461", "intExt": "IP", "itemDesc": "Cabin

medical communication jacks inop (330 only) see notes", "itemNotes": "This NEF allows for a cabin medical communication PSU jack to be inoperative.\n\nTroubleshoot system per A330 AWM 23-51-13 and/or 23-51-01, if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with Airbus ESPM Chapter 20-54-50 at the damage location\n\nOnly on A330 Post AA 2351-01033", "itemNotesInd": "Y", "itemNumber": "23-51-02", "lastUpdate": "2022-03-08 07:56:27.646178", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2017-08-15 13:45:46.206645", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "235102" }, { "sequenceNumber": "03", "creationDate": "01/15/2018 08:12:29", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "23", "ataDesc": "Flight Interphone/Medical Communication System", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "(NEF use is for 320 FAM,350/717/737/767/757 only)Troubleshoot system per applicable AWM ,WDM and AMM if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with D6-54446 707, 727 Through 787 SWPM Chapter 20-10-11 OR Airbus ESPM Chapter 20-54-50 at the damage location and record this info in the paper log book .", "decisionInd": "A", "defRemarks": "(NEF use is for 320 FAM,350/717/737/767/757 only)Troubleshoot system per applicable AWM ,WDM and AMM if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with D6-54446 707, 727 Through 787 SWPM Chapter 20-10-11 OR Airbus ESPM Chapter 20-54-50 at the damage location and record this info in the paper log book .", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added C Series.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 07:56:38.875937", "faaReviewStartTms": "2022-03-08 07:56:38.875937", "intExt": "IP", "itemDesc": "Cabin Medical Communication wiring and/or jack(NOT FOR USE ON A330/A220 series)", "itemNotes": "(NEF use is for 320 FAM,350/717/737/767/757/777only)Troubleshoot system per applicable AWM ,WDM and AMM if any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with D6-54446 707, 727 Through 787 SWPM Chapter 20-10-11 OR Airbus ESPM Chapter 20-54-50 at the damage location and record this info in the paper log book . Allowable time on this item is 365 days.", "itemNotesInd": "Y", "itemNumber": "23-51-03", "lastUpdate": "2022-03-08 07:56:42.168032", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2018-01-15 08:02:21.608295",

"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "235103" },
{ "sequenceNumber": "04", "creationDate": "04/16/2020 09:10:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "23", "ataDesc": "Flight Interphone/Medical Communication System",
"ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"William Hoogenhout", "faaReviewEndTms": "2023-12-10 06:43:01.228111",
"faaReviewStartTms": "2023-11-16 06:43:01.228111", "intExt": "IP", "itemDesc": "Capt and
FO's ACP Foam Block (737-800, -900 ONLY)", "itemNotes": "Ensure adjacent compartment
is empty.", "itemNotesInd": "Y", "itemNumber": "23-51-04", "lastUpdate": "2023-11-16
06:43:12.612565", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2020-04-16 09:04:24.389624", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "235104" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Hand
Microphones", "ataSectCode": "54", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":
"0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-12-09 09:15:24.072",
"faaReviewStartTms": "2013-11-15 09:15:24.072287", "intExt": "EX", "itemDesc": "Flight
Deck Microphone Holder Damaged", "itemNotes": "Mike clip/holder. This is in the flight
deck for the crew members. This does not apply to the Emergency PA microphone holder
in the flight deck.", "itemNotesInd": "Y", "itemNumber": "23-54-01", "lastUpdate": "2014-
04-03 10:21:33.267816", "lastUpdateDisplay": "04/03/2014", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "235401" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Cabin and Cockpit Handsets/Cradle", "ataSectCode": "55", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Handset must be able to be
secured in cradle.", "decisionInd": "A", "defRemarks": "Handset must be able to be
secured in cradle.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02

12:37:02.460361", "faaReviewStartTms": "2011-12-09 12:37:02.460361", "intExt": "IP",
"itemDesc": "Crew Rest Handset Holder Damaged (Handset operational)",
"itemNotesInd": "N", "itemNumber": "23-55-01", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "235501" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Cabin and Cockpit Handsets/Cradle", "ataSectCode": "55", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Handset must be able to be
secured in cradle.", "decisionInd": "A", "defRemarks": "Handset must be able to be
secured in cradle.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:02.555472", "faaReviewStartTms": "2011-12-09 12:37:02.555472", "intExt": "EX",
"itemDesc": "Flight Deck Handset Cradle Damaged (Handset operational)",
"itemNotesInd": "N", "itemNumber": "23-55-02", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "235502" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Headsets", "ataSectCode": "56", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":
"0", "decisionInd": "A", "efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms":
"2024-04-04 08:26:20.176142", "faaReviewStartTms": "2024-03-11 08:26:20.176142",
"intExt": "IP", "itemDesc": "Cabin Medical Headset Damaged / Missing", "itemNotes": "this
item is not applicable to the 737 fleet. For Cabin Medical Headset deferral, please see 737
MEL item 23-00-29.", "itemNotesInd": "Y", "itemNumber": "23-56-01", "lastUpdate": "2024-
03-11 08:26:31.585069", "lastUpdateDisplay": "03/11/2024", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "235601" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",

"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Headsets", "ataSectCode": "56", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:02.675544", "faaReviewStartTms": "2011-12-09 12:37:02.675544", "intExt": "EX", "itemDesc": "Excess Flight Deck Headsets (Spares only) Damaged / Missing", "itemNotes": "See applicable fleet MEL for required headsets for required positions.", "itemNotesInd": "Y", "itemNumber": "23-56-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "235602" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Headsets", "ataSectCode": "56", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:02.738965", "faaReviewStartTms": "2011-12-09 12:37:02.738965", "intExt": "EX", "itemDesc": "Flight Deck Headset Cord Holder Damaged / Missing", "itemNotesInd": "N", "itemNumber": "23-56-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "235603" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Headsets", "ataSectCode": "56", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:02.814035", "faaReviewStartTms": "2011-12-09 12:37:02.814035", "intExt": "EX", "itemDesc": "Headset Hangar Damaged / Missing", "itemNotesInd": "N", "itemNumber": "23-56-04", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "235604" },

```
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":  
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "23", "ataDesc": "Wireless Local Area Network", "ataSectCode": "95",  
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":  
"A", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms":  
"2012-06-15 11:47:24.683", "faaReviewStartTms": "2012-05-22 11:47:23.980941",  
"ifeltem": "IFE", "intExt": "IP", "itemDesc": "WIFI Button at L1 Door Does Not Illuminate",  
"itemNotes": "Clarification of WIFI light location.", "itemNotesInd": "Y", "itemNumber": "23-  
95-01", "lastUpdate": "2012-06-01 12:17:29.935409", "lastUpdateDisplay": "06/01/2012",  
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",  
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":  
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto  
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":  
"00637639", "legacyFrc": "239501" }, { "sequenceNumber": "02", "creationDate":  
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":  
"Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Wireless Local Area  
Network", "ataSectCode": "95", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",  
"decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "This  
office has determined it is acceptable to remove the placarding requirements from the  
deferral remarks within NEF 23-95-02, WIFI Inoperative. \r\n\r\nThanks, \r\n\r\nBill L.  
Williams\r\n\r\nAviation Safety Inspector\r\n\r\nDAL CMO-27", "faaContactName": "Bill L.  
Williams", "faaReviewEndTms": "2024-12-19 14:20:20.277897", "faaReviewStartTms":  
"2024-11-25 14:20:20.277897", "ifeltem": "IFE", "intExt": "IP", "itemDesc": "WIFI  
Inoperative", "itemNotesInd": "N", "itemNumber": "23-95-02", "lastUpdate": "2024-11-25  
14:20:25.967544", "lastUpdateDisplay": "11/25/2024", "legacyDeltaAirworthyInd": "N",  
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y",  
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":  
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via  
ACARS", "userIdDisplay": "00324557", "legacyFrc": "239502" }, { "sequenceNumber": "03",  
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",  
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":  
"Wireless Local Area Network", "ataSectCode": "95", "autoDefCde": "NEF", "crewDefInd":  
"Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",  
"faaComments": "Contained in initial FAA approved list. Reviewed for A350.",  
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:03:56.281697",  
"faaReviewStartTms": "2019-02-27 09:03:56.281697", "ifeltem": "IFE", "intExt": "IP",  
"itemDesc": "WIFI Reported Intermittently Inoperative", "itemNotesInd": "N",  
"itemNumber": "23-95-03", "lastUpdate": "2019-02-27 09:04:01.43111",
```

"lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "239503" }, { "sequenceNumber": "04",
"creationDate": "02/19/2013 10:05:50", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc":
"Wireless Local Area Network", "ataSectCode": "95", "autoDefCde": "NEF", "crewDefInd":
"Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Homan", "faaReviewEndTms": "2022-04-01 07:58:07.365099",
"faaReviewStartTms": "2022-03-08 07:58:07.365099", "ifelItem": "IFE", "intExt": "IP",
"itemDesc": "WIFI Handset / WIFI Video Inoperative", "itemNotes": "Includes video content
loader/USB dock located in the handset", "itemNotesInd": "Y", "itemNumber": "23-95-04",
"lastUpdate": "2022-03-08 07:58:17.213839", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9283244",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000939358",
"rowInsertEmpNoDisplay": "00939358", "rowInsertTms": "2013-02-19 09:52:18.812378",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "239504" },
{ "sequenceNumber": "05", "creationDate": "09/09/2016 07:09:49", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "23", "ataDesc": "Wireless Local Area Network", "ataSectCode": "95",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2023-07-29 08:16:06.316995", "faaReviewStartTms": "2023-07-05
08:16:06.316995", "ifelItem": "IFE", "intExt": "IP", "itemDesc": "WIFI system software is not
current", "itemNotes": "The WiFi system must be fully functional. Apply this code only if the
WIFI system requires the latest software version to be installed. It has a Allowable time
limit of 365 days.", "itemNotesInd": "Y", "itemNumber": "23-95-05", "lastUpdate": "2023-
07-05 08:16:12.530578", "lastUpdateDisplay": "07/05/2023", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467",
"rowInsertTms": "2016-09-09 06:55:18.871818", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "239505" }, { "sequenceNumber": "06", "creationDate":
"09/09/2016 07:03:57", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "23", "ataDesc": "Wireless Local Area
Network", "ataSectCode": "95", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",

"decisionInd": "A", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-07-29 08:16:59.125243", "faaReviewStartTms": "2023-07-05 08:16:59.125243", "ifItem": "IFE", "intExt": "IP", "itemDesc": "WIFI system software load failed", "itemNotes": "This code is for a failed software load. The system must be fully functional using the previous software version. If the system is inoperative, use NEF 23-95-02.", "itemNotesInd": "Y", "itemNumber": "23-95-06", "lastUpdate": "2023-07-05 08:17:02.775962", "lastUpdateDisplay": "07/05/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-09-09 06:58:38.319854", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "239506" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "Generator Drive", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:03.498705", "faaReviewStartTms": "2011-12-09 12:37:03.498705", "intExt": "EX", "itemDesc": "IDG Oil Dust Cap Damaged / Missing", "itemNotesInd": "N", "itemNumber": "24-10-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "241001" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "Generator Drive", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:03.552931", "faaReviewStartTms": "2011-12-09 12:37:03.552931", "intExt": "EX", "itemDesc": "IDG Oil Dust Cap Lanyard Damaged / Missing", "itemNotesInd": "N", "itemNumber": "24-10-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "241002" }, { "sequenceNumber": "03", "creationDate": "02/25/2019 06:23:24", "userId": "0000823179", "activeInd": "A",

"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "Generator Drive", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-21 08:03:46.434064", "faaReviewStartTms": "2019-02-25 08:03:46.434064", "intExt": "IP", "itemDesc": "IDG disconnection test harness Missing from Flight Compartment (A330 Only)", "itemNotes": "A330 Fleet Management has decided to incorporate a test harness for assistance in verifying the successful disconnection of an IDG on P&W 4168 powered aircraft. As this harness will be installed on the flight deck for maintenance use to verify no go ODI procedures for the IDG. MPN is 24-0188-501DL STK# 33-2400-3-0607", "itemNotesInd": "Y", "itemNumber": "24-10-03", "lastUpdate": "2019-02-25 08:23:10.286616", "lastUpdateDisplay": "02/25/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2019-02-25 06:17:10.374325", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "241003" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "24", "ataDesc": "APU Generator/(Electric-Ram Air Turbine (RAT)-A350 only)", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Cover must be secure and lugs must not be exposed.", "decisionInd": "A", "defRemarks": "Cover must be secure and lugs must not be exposed.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2022-04-01 08:00:04.261199", "faaReviewStartTms": "2022-03-08 08:00:04.261199", "intExt": "EX", "itemDesc": "APU Generator Terminal Lug Plastic Cover Damaged / Poor Condition", "itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "24-24-01", "lastUpdate": "2022-03-08 08:00:06.900579", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "242401" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "External Power Connector", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Ground power operates normally.", "decisionInd": "A", "defRemarks": "Ground power operates normally.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2022-04-01 08:00:21.930286",

"faaReviewStartTms": "2022-03-08 08:00:21.930286", "intExt": "EX", "itemDesc": "Ground Power Cord Strap Damaged (B757)", "itemNotesInd": "N", "itemNumber": "24-41-01", "lastUpdate": "2022-03-08 08:00:26.954832", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "244101" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "External Power Connector", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Ground power operates normally. Item must be deferred in a condition to prevent electrical shorting. This will require a maintenance check before deferral.", "decisionInd": "A", "defRemarks": "Ground power operates normally. Item must be deferred in a condition to prevent electrical shorting. This will require a maintenance check before deferral.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "biever", "faaReviewEndTms": "2022-04-01 08:00:57.697443", "faaReviewStartTms": "2022-03-08 08:00:57.697443", "intExt": "EX", "itemDesc": "Ground Power Receptacle Guide Cracked", "itemNotesInd": "N", "itemNumber": "24-41-02", "lastUpdate": "2022-03-08 08:01:02.073403", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "244102" }, { "sequenceNumber": "03", "creationDate": "09/18/2024 14:01:28", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "24", "ataDesc": "External Power Connector", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-10-21 07:01:08.865966", "faaReviewStartTms": "2024-09-27 07:01:08.865966", "intExt": "EX", "itemDesc": "Ground Power Unit Guard Cracked or Missing - A320FAM ONLY", "itemNotes": "10-day item\n\nThis deferral applies to A320FAM aircraft ONLY (PN 24-0193-501)", "itemNotesInd": "Y", "itemNumber": "24-41-03", "lastUpdate": "2024-09-27 09:22:37.821074", "lastUpdateDisplay": "09/27/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-09-18 13:54:29.419521", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "244103" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "24", "ataDesc": "AC Power Distribution", "ataSectCode": "51",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "(Not
applicable for Flight Deck EFB Only power outlets, see NEF item notes.) May be
inoperative. Item must be deferred in a condition to prevent electrical shorting. This will
require a maintenance check before deferral.", "decisionInd": "A", "defRemarks": "(Not
applicable for Flight Deck EFB Only power outlets, see NEF item notes.) May be
inoperative. Item must be deferred in a condition to prevent electrical shorting. This will
require a maintenance check before deferral.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": ".", "faaReviewEndTms": "2019-10-14 12:54:53.752126",
"faaReviewStartTms": "2019-09-20 12:54:53.752126", "intExt": "IP", "itemDesc": "Electrical
outlets (AC) or (DC)(NOT for Electronic Flight Bags -EFB power connectors)", "itemNotes":
"This NEF is not for This NEF is not for use for electrical outlets in the Flight Deck labeled
EFB Power Only or EFB Use Only. See fleet specific chapter 46 MEL for Electronic Flight
Bags (EFB) power connector relief....", "itemNotesInd": "Y", "itemNumber": "24-51-01",
"lastUpdate": "2019-09-26 05:13:29.397751", "lastUpdateDisplay": "09/26/2019",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "245101" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"24", "ataDesc": "AC Power Distribution", "ataSectCode": "51", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an
extent that it leaves an opening that items could fall into or that would be a security
concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it
leaves an opening that items could fall into or that would be a security concern.",
"efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial
FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:03.921998",
"faaReviewStartTms": "2011-12-09 12:37:03.921998", "intExt": "IP", "itemDesc": "Ground
Service Electrical Outlet Covers Damaged or Missing", "itemNotesInd": "N",
"itemNumber": "24-51-02", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09

12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00245058", "legacyFrc": "245102" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc":
"PED power / USB seat connectors and Faults", "ataSectCode": "58", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "check if item is contained in
the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF
item.\n\nCheck affected locations/area for acrid/burning smells and face of outlets for
abnormal heat coming from or around the unit. If smell or overheat condition is apparent
contact MCC. \n\nInstall placard at the seat.", "decisionInd": "A", "defRemarks": "check if
item is contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using the NEF item.\n\nCheck affected locations/area for acrid/burning smells and
face of outlets for abnormal heat coming from or around the unit. If smell or overheat
condition is apparent contact MCC. \n\nInstall placard at the seat.", "efmTab": "R",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2019-03-30 11:15:27.163707", "faaReviewStartTms": "2019-03-06
11:15:27.163707", "intExt": "IP", "itemDesc": "Crew Rest PED Power / Empower Inop",
"itemNotes": "Includes PED KID Power system installed on 330-9.", "itemNotesInd": "Y",
"itemNumber": "24-58-01", "lastUpdate": "2019-03-06 11:15:49.152284",
"lastUpdateDisplay": "03/06/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "245801" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId":
"0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "24", "ataDesc": "PED power / USB seat connectors and Faults",
"ataSectCode": "58", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Install placard at the seat.\n\nCheck affected locations/area for
acrid/burning smells and face of outlets for abnormal heat coming from or around the unit.
If smell or overheat condition is apparent contact MCC.", "decisionInd": "A", "defRemarks":
"Install placard at the seat.\n\nCheck affected locations/area for acrid/burning smells and
face of outlets for abnormal heat coming from or around the unit. If smell or overheat
condition is apparent contact MCC.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Amended Deferral Remarks.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2020-01-19 13:06:45.362965", "faaReviewStartTms": "2019-12-26
13:06:45.362965", "intExt": "IP", "itemDesc": "Change to PED Power / Empower Inop at
Individual Seat -Premium Select / Coach Class- CABIN ONLY", "itemNotes": "For Cockpit

power connectors/USB that are not EFB(Electronic Flight Bag) use NEF 24-51-01. If EFB power INOP use the correct fleet specific MEL under ATA chapter 46.", "itemNotesInd": "Y", "itemNumber": "24-58-02", "lastUpdate": "2019-12-26 13:06:51.872712", "lastUpdateDisplay": "12/26/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00406009", "legacyFrc": "245802" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "PED power / USB seat connectors and Faults", "ataSectCode": "58", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Install placard at the seat.\n\nCheck affected locations/area for acrid/burning smells and face of outlets for abnormal heat coming from or around the unit. If smell or overheat condition is apparent contact MCC.", "decisionInd": "A", "defRemarks": "Install placard at the seat.\n\nCheck affected locations/area for acrid/burning smells and face of outlets for abnormal heat coming from or around the unit. If smell or overheat condition is apparent contact MCC.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Amended Deferral Remarks.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2020-01-19 13:07:44.002957", "faaReviewStartTms": "2019-12-26 13:07:44.002957", "intExt": "IP", "itemDesc": "Change to PED Power Inop at Individual Seat- Delta One - CABIN ONLY", "itemNotes": "For Cockpit power connectors/USB that are not EFB(Electronic Flight Bag) use NEF 24-51-01. If EFB power INOP use the correct fleet specific MEL under ATA chapter 46.", "itemNotesInd": "Y", "itemNumber": "24-58-03", "lastUpdate": "2019-12-26 13:07:52.242158", "lastUpdateDisplay": "12/26/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00406009", "legacyFrc": "245803" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc": "PED power / USB seat connectors and Faults", "ataSectCode": "58", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check affected locations/area for acrid/burning smells and face of outlets for abnormal heat coming from or around the unit. If smell or overheat condition is apparent contact MCC.", "decisionInd": "A", "defRemarks": "Check affected locations/area for acrid/burning smells and face of outlets for abnormal heat coming from or around the unit. If smell or overheat condition is apparent contact MCC.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y",

"faaComments": "Contained in initial FAA approved list. Crew Deferral added.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-05-23 13:31:13.297528",
"faaReviewStartTms": "2019-04-29 13:31:13.297528", "intExt": "IP", "itemDesc": "PED
Power / Empower System Zone Inop- CABIN ONLY", "itemNotes": "For Cockpit power
connectors/USB that are not EFB(Electronic Flight Bag) use NEF 24-51-01. If EFB power
INOP use the correct fleet specific MEL under ATA chapter 46.", "itemNotesInd": "Y",
"itemNumber": "24-58-04", "lastUpdate": "2019-04-30 10:16:30.344921",
"lastUpdateDisplay": "04/30/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "245804" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc":
"PED power / USB seat connectors and Faults", "ataSectCode": "58", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Install placard at the seat.",
"decisionInd": "A", "defRemarks": "Install placard at the seat.", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Amended Deferral Remarks.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-05-23 13:31:55.804835",
"faaReviewStartTms": "2019-04-29 13:31:55.804835", "intExt": "IP", "itemDesc": "PED
Power / Empower in Use Light Inop- CABIN ONLY", "itemNotes": "For Cockpit power
connectors/USB that are not EFB(Electronic Flight Bag) use NEF 24-51-01. If EFB power
INOP use the correct fleet specific MEL under ATA chapter 46.", "itemNotesInd": "Y",
"itemNumber": "24-58-05", "lastUpdate": "2019-04-30 10:17:31.915996",
"lastUpdateDisplay": "04/30/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "245805" }, { "sequenceNumber": "06",
"creationDate": "07/11/2024 09:16:17", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "24", "ataDesc":
"PED power / USB seat connectors and Faults", "ataSectCode": "58", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.",
"faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-08-04 14:09:33.260613",
"faaReviewStartTms": "2024-07-11 14:09:33.260613", "intExt": "IP", "itemDesc": "PED
Power Outlets - Cosmetic Damage", "itemNotes": "Cosmetic damage can include but is
not limited to: significant scratches, permanent stains, chipped corners, etc.",

"itemNotesInd": "Y", "itemNumber": "24-58-06", "lastUpdate": "2024-07-15 13:34:06.674058", "lastUpdateDisplay": "07/15/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-07-11 09:05:51.626227", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "245806" }, { "sequenceNumber": "01", "creationDate": "12/27/2019 12:01:42", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Equipment & Furnishings", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2020-01-26 07:11:30.067535", "faaReviewStartTms": "2020-01-02 07:11:30.067535", "intExt": "EX", "itemDesc": "NLG Steering Valve Lock Pin - 757 ONLY", "itemNotesInd": "N", "itemNumber": "25-00-01", "lastUpdate": "2020-01-02 09:03:57.540751", "lastUpdateDisplay": "01/02/2020", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2019-12-27 11:56:33.309264", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "250001" }, { "sequenceNumber": "02", "creationDate": "08/31/2020 09:30:48", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Equipment & Furnishings", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Hand Sanitizer Mount/Bracket may be damaged or missing under the following conditions:\n1) If mount is damaged, no sharp edges or hazards to persons are permitted, remove entire hand sanitizer mount if any sharp edges or hazards exist.\n2) No damage to underlying structure (monument/wall panel) is permitted.\n3) No open holes are permitted. Install attachment hardware to fill holes, or cover open inserts with 3M 425 or 3M 398FRP tape.\n4) If mount is damaged, or security of attachment is suspect, the hand sanitizer dispenser (bottle) must be removed.", "decisionInd": "A", "defRemarks": "Hand Sanitizer Mount/Bracket may be damaged or missing under the following conditions:\n1) If mount is damaged, no sharp edges or hazards to persons are permitted, remove entire hand sanitizer mount if any sharp edges or hazards exist.\n2) No damage to underlying structure (monument/wall panel) is permitted.\n3) No open holes are permitted. Install attachment hardware to fill holes, or cover open inserts with 3M 425 or 3M 398FRP tape.\n4) If mount is damaged, or security of attachment is suspect, the hand sanitizer dispenser (bottle) must be removed.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Bill L.

Williams", "faaReviewEndTms": "2020-09-27 07:34:35.061545", "faaReviewStartTms": "2020-09-03 07:34:35.061545", "intExt": "IP", "itemDesc": "Hand Sanitizer Bracket (post AA #2500-01840)", "itemNotesInd": "N", "itemNumber": "25-00-02", "lastUpdate": "2020-09-03 07:36:04.086544", "lastUpdateDisplay": "09/03/2020", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2020-08-31 09:14:47.961064", "sceptreAutoDefRemarks": "Auto generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "250002" }, { "sequenceNumber": "03", "creationDate": "06/11/2023 03:57:10", "userId": "0000688631", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Equipment & Furnishings", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2023-07-05 03:48:19.531044", "faaReviewStartTms": "2023-06-11 03:48:19.531044", "intExt": "IP", "itemDesc": "NOTAC CLIP IN COCKPIT MISSING", "itemNotes": "NOTAC CLIP DAMAGED/MISSING", "itemNotesInd": "Y", "itemNumber": "25-00-03", "lastUpdate": "2023-06-11 03:48:19.531044", "lastUpdateDisplay": "06/11/2023", "logMultiplicity": "S", "logpageNumber": "4790939", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000688631", "rowInsertEmpNoDisplay": "00688631", "rowInsertTms": "2023-06-11 03:48:19.531044", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00688631", "legacyFrc": "250003" }, { "sequenceNumber": "04", "creationDate": "06/20/2023 12:43:46", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "30", "ataChapterCode": "25", "ataDesc": "Equipment & Furnishings", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-01-07 12:24:41.241029", "faaReviewStartTms": "2023-12-14 12:24:41.241029", "intExt": "IP", "itemDesc": "Landing Gear Pins Tag (Yellow Tag) Missing", "itemNotes": "Subject warning tags are being installed via AA 2510\u001A01333 on all Delta fleets for placement over the throttle levers while the gear down lock pins are installed.", "itemNotesInd": "Y", "itemNumber": "25-00-04", "lastUpdate": "2023-12-14 12:24:59.35157", "lastUpdateDisplay": "12/14/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000603060", "rowInsertEmpNoDisplay": "00603060", "rowInsertTms": "2023-06-20 12:27:53.953549", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "250004" }, { "sequenceNumber": "05", "creationDate": "04/23/2025 09:02:15", "userId":

"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Equipment & Furnishings", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-08-17 11:43:54.233745", "faaReviewStartTms": "2025-07-24 11:43:54.233745", "intExt": "IP", "itemDesc": "Cockpit circuit breaker colored identification cap (Yellow / Red) damaged or missing", "itemNotesInd": "N", "itemNumber": "25-00-05", "lastUpdate": "2025-07-24 11:44:04.121342", "lastUpdateDisplay": "07/24/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-04-23 08:58:45.210296", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "250005" }, { "sequenceNumber": "01", "creationDate": "06/11/2012 16:48:00", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Flight deck ramp vest must be able to remain secure within the designated storage container and be accessible to the flight crew.", "decisionInd": "A", "defRemarks": "Flight deck ramp vest must be able to remain secure within the designated storage container and be accessible to the flight crew.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Williams", "faaReviewEndTms": "2022-04-01 08:01:35.437847", "faaReviewStartTms": "2022-03-08 08:01:35.437847", "intExt": "EX", "itemDesc": "Flight Deck Ramp Inspection Vest Container Damaged", "itemNotesInd": "N", "itemNumber": "25-10-01", "lastUpdate": "2022-03-08 08:01:40.72482", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "0608202", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-06-11 16:42:22.338766", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251001" }, { "sequenceNumber": "02", "creationDate": "10/15/2013 13:08:30", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Cover the damaged area with tape as necessary to prevent any FOD from entering behind the blanking plate.", "decisionInd": "A", "defRemarks": "Cover the damaged area with tape as necessary to prevent any FOD from entering behind the blanking plate.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",

"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:01:58.466308",
"faaReviewStartTms": "2022-03-08 08:01:58.466308", "intExt": "EX", "itemDesc": "Flight
Deck Blanking Plate Broken", "itemNotesInd": "N", "itemNumber": "25-10-02",
"lastUpdate": "2022-03-08 08:02:05.620471", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5143454",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000410844",
"rowInsertEmpNoDisplay": "00410844", "rowInsertTms": "2013-10-15 12:57:15.675548",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251002" },
{ "sequenceNumber": "03", "creationDate": "01/21/2014 13:12:14", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Manuals
must be retained in flight deck flight manual compartment.", "decisionInd": "A",
"defRemarks": "Manuals must be retained in flight deck flight manual compartment.",
"efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 08:02:15.370297", "faaReviewStartTms": "2022-03-08
08:02:15.370297", "intExt": "EX", "itemDesc": "Flight Deck Flight Manual Retaining Bar
Damaged or Missing (B737 Only)", "itemNotesInd": "N", "itemNumber": "25-10-03",
"lastUpdate": "2022-03-08 08:02:20.441915", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5561774",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000925787",
"rowInsertEmpNoDisplay": "00925787", "rowInsertTms": "2014-01-21 13:09:14.180475",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251003" },
{ "sequenceNumber": "04", "creationDate": "02/02/2014 09:42:13", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 08:02:37.322133", "faaReviewStartTms": "2022-03-08
08:02:37.322133", "intExt": "IP", "itemDesc": "Flight Crew Seat Adjust Assist Overhead
Handle Spring Damaged/Missing", "itemNotes": "Handle down does not impeded vision.",
"itemNotesInd": "Y", "itemNumber": "25-10-04", "lastUpdate": "2022-03-08
08:02:42.785442", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9803091", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000877748", "rowInsertEmpNoDisplay": "00877748",
"rowInsertTms": "2014-02-02 09:41:07.066132", "sceptreAutoDefRemarks": "Auto

Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251004" }, { "sequenceNumber": "06", "creationDate": "05/08/2014 10:28:47", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-11-03 14:34:38.448616", "faaReviewStartTms": "2022-10-10 14:34:38.448616", "intExt": "EX", "itemDesc": "Flight Deck Sunvisor or Shade Holder/Pouch Damaged/Missing", "itemNotes": "For the A220\u001As only, if damaged and usable this NEF applies. If inoperative or missing refer to A220 MEL 25-18-05", "itemNotesInd": "Y", "itemNumber": "25-10-06", "lastUpdate": "2022-10-10 14:34:48.692821", "lastUpdateDisplay": "10/10/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5803138", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000705957", "rowInsertEmpNoDisplay": "00705957", "rowInsertTms": "2014-05-08 10:20:59.468926", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251006" }, { "sequenceNumber": "07", "creationDate": "06/30/2015 13:26:33", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Install a placard to restrict items from being stored in the compartment and block off the compartment.\r\n\r\nIf damaged, smooth out all sharp edges.\r\n\r\nData stored in restricted compartment must be available to crew.", "decisionInd": "A", "defRemarks": "Install a placard to restrict items from being stored in the compartment and block off the compartment.\r\n\r\nIf damaged, smooth out all sharp edges.\r\n\r\nData stored in restricted compartment must be available to crew.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Data stored in restricted compartment must be available to crew.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:02:57.122552", "faaReviewStartTms": "2022-03-08 08:02:57.122552", "intExt": "EX", "itemDesc": "Damaged/Missing Cockpit Storage Compartment Door (757 Only, Limited Effectivity)", "itemNotes": "This item is only applicable to the compartment doors listed in the B757 IPC 25-13-52-55 items 250/255(All B757s) and 475/480 (Aircraft 5650-5657 & 5801-5816)//IPC 53-11-51 door assy item 405 for (757-300s).", "itemNotesInd": "Y", "itemNumber": "25-10-07", "lastUpdate": "2022-03-08 08:03:05.229424", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "1826954", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467",

"rowInsertTms": "2015-06-30 13:13:19.794437", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251007" }, { "sequenceNumber": "08", "creationDate": "11/12/2015 07:27:11", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:03:20.86234", "faaReviewStartTms": "2022-03-08 08:03:20.86234", "intExt": "IP", "itemDesc": "Cockpit PED Mount Stowage Bag Missing/Damaged", "itemNotes": "See MEL for missing/damaged PED mounts. This item is for the PED mount stowage bag only. PED mount must be securely stowed in a closet or overhead bin during flight and when not in use.", "itemNotesInd": "Y", "itemNumber": "25-10-08", "lastUpdate": "2022-03-08 08:03:27.247133", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "7936334", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000877748", "rowInsertEmpNoDisplay": "00877748", "rowInsertTms": "2015-11-12 07:25:56.075378", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251008" }, { "sequenceNumber": "09", "creationDate": "12/12/2017 09:05:13", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "1. EFB MUST BE REMOVED FROM DOCKING STATION. Remove EFB from the aircraft and defer per A350 MEL 46-20-07A. No deviations from MEL are permitted.\n\n2. Placard the unlocked docking station DO NOT INSTALL OR STORE EFB IN THIS DOCKING STATION\n\n3. NEF is limited to 10 DAYS, or remainder of MEL 46-20-07A limit, whichever is sooner.", "decisionInd": "A", "defRemarks": "1. EFB MUST BE REMOVED FROM DOCKING STATION. Remove EFB from the aircraft and defer per A350 MEL 46-20-07A. No deviations from MEL are permitted.\n\n2. Placard the unlocked docking station DO NOT INSTALL OR STORE EFB IN THIS DOCKING STATION\n\n3. NEF is limited to 10 DAYS, or remainder of MEL 46-20-07A limit, whichever is sooner.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:03:42.194445", "faaReviewStartTms": "2022-03-08 08:03:42.194445", "intExt": "IP", "itemDesc": "CREW EFB docking compartment padlock missing/damaged- 350 only", "itemNotes": "1. EFB MUST BE REMOVED FROM DOCKING STATION. Remove EFB from the aircraft and defer per A350 MEL 46-20-07A. No deviations from MEL are permitted.\n\n2. Placard the unlocked docking station DO NOT INSTALL OR STORE EFB IN THIS DOCKING STATION\n\n3. NEF is

limited to 10 DAYS, or remainder of MEL 46-20-07A limit, whichever is sooner.",
"itemNotesInd": "Y", "itemNumber": "25-10-09", "lastUpdate": "2022-03-08
08:03:47.823858", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179",
"rowInsertTms": "2017-12-12 09:05:13.928", "sceptreAutoDefRemarks": "Auto Generated
Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557",
"legacyFrc": "251009" }, { "sequenceNumber": "38", "creationDate": "12/09/2011 12:36:53",
"userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime":
"120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:04:13.647059",
"faaReviewStartTms": "2022-03-08 08:04:13.647059", "intExt": "EX", "itemDesc": "A/C Out
of Service Tag Damaged", "itemNotesInd": "N", "itemNumber": "25-10-38", "lastUpdate":
"2022-03-08 08:04:19.091572", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251038" },
{ "sequenceNumber": "39", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:04:50.523476",
"faaReviewStartTms": "2022-03-08 08:04:50.523476", "intExt": "EX", "itemDesc": "Boom
MIC Holders (Clips)", "itemNotesInd": "N", "itemNumber": "25-10-39", "lastUpdate":
"2022-03-08 08:04:55.488082", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251039" },
{ "sequenceNumber": "40", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "There is
no requirement to safety wire switch guards per Boeing. Safety wire may be installed after

delivery by the customer, or by Boeing at customer request. email on file.", "decisionInd": "A", "defRemarks": "There is no requirement to safety wire switch guards per Boeing. Safety wire may be installed after delivery by the customer, or by Boeing at customer request. email on file.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:05:16.570608", "faaReviewStartTms": "2022-03-08 08:05:16.570608", "intExt": "EX", "itemDesc": "Broken Copper Safety Wire for EEC Switch (B757 Only)", "itemNotes": "EEC alt/norm switch cover has broken safety wire. Must be safetied at next station where copper wire is available. There is no requirement to safety wire switch guards per Boeing.", "itemNotesInd": "Y", "itemNumber": "25-10-40", "lastUpdate": "2022-03-08 08:05:23.825844", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251040"}, {"sequenceNumber": "41", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:06:36.051237", "faaReviewStartTms": "2022-03-08 08:06:36.051237", "intExt": "EX", "itemDesc": "Center Pedestal Clear Plastic Paperwork Holder Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-41", "lastUpdate": "2022-03-08 08:06:41.896458", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251041"}, {"sequenceNumber": "43", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:06:55.54134", "faaReviewStartTms": "2022-03-08 08:06:55.54134", "intExt": "EX", "itemDesc": "Document Holders Damaged", "itemNotesInd": "N", "itemNumber": "25-10-43", "lastUpdate": "2022-03-08 08:07:02.085374", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",

"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251043" }, { "sequenceNumber": "44", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:07:49.884534", "faaReviewStartTms": "2022-03-08 08:07:49.884534", "intExt": "EX", "itemDesc": "Eyebrow Window Visors Damaged", "itemNotesInd": "N", "itemNumber": "25-10-44", "lastUpdate": "2022-03-08 08:07:57.069592", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251044" }, { "sequenceNumber": "45", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "If compartment door does not stay closed then remove items from compartment and secure door closed. If removing items and compartment contains emergency equipment then see MEL.", "decisionInd": "A", "defRemarks": "If compartment door does not stay closed then remove items from compartment and secure door closed. If removing items and compartment contains emergency equipment then see MEL.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:08:28.169457", "faaReviewStartTms": "2022-03-08 08:08:28.169457", "intExt": "EX", "itemDesc": "Flight Deck Access Compartment Latches Damaged / Hard to Operate", "itemNotesInd": "N", "itemNumber": "25-10-45", "lastUpdate": "2022-03-08 08:08:33.924573", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251045" }, { "sequenceNumber": "46", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",

"daysCount": "0", "deactMOProcedure": "If ashtray is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "decisionInd": "A", "defRemarks": "If ashtray is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:04.990114", "faaReviewStartTms": "2011-12-09 12:37:04.990114", "intExt": "EX", "itemDesc": "Flight Deck Ashtrays Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-46", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "251046" }, { "sequenceNumber": "47", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:05.068981", "faaReviewStartTms": "2011-12-09 12:37:05.068981", "intExt": "EX", "itemDesc": "Flight Deck Coat or Hat Hooks / Hangers Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-10-47", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "251047" }, { "sequenceNumber": "48", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "For tie downs that are not in usable condition, alternate storage areas (coat closets or overhead storage bins) must be available for use by crewmembers. If Crew stowage tie-down unusable, alternate stowage area must be made available.", "decisionInd": "A", "defRemarks": "For tie downs that are not in usable condition, alternate storage areas (coat closets or overhead storage bins) must be available for use by crewmembers. If Crew stowage tie-down unusable, alternate stowage area must be made available.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",

"faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:09:21.197854", "faaReviewStartTms": "2022-03-08 08:09:21.197854", "intExt": "EX", "itemDesc": "Flight Deck Crew Stowage Tie Downs or Belts Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-48", "lastUpdate": "2022-03-08 08:09:26.838371", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251048" }, { "sequenceNumber": "49", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:09:43.400171", "faaReviewStartTms": "2022-03-08 08:09:43.400171", "intExt": "EX", "itemDesc": "Flight Deck CRT Cleaning Kit Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-49", "lastUpdate": "2022-03-08 08:09:47.549054", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251049" }, { "sequenceNumber": "50", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "If cup holder is missing and leaves an opening, cover with tape.", "decisionInd": "A", "defRemarks": "If cup holder is missing and leaves an opening, cover with tape.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:05.278487", "faaReviewStartTms": "2011-12-09 12:37:05.278487", "intExt": "EX", "itemDesc": "Flight Deck Cup Holder or Insert Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-10-50", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "251050" }, { "sequenceNumber": "51", "creationDate": "12/09/2011 12:36:53", "userId":

"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to crew.", "decisionInd": "A", "defRemarks": "Must not present hazard to crew.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:10:03.96258", "faaReviewStartTms": "2022-03-08 08:10:03.96258", "intExt": "EX", "itemDesc": "Flight Deck Door Closing Strap Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-51", "lastUpdate": "2022-03-08 08:10:09.252982", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251051" }, { "sequenceNumber": "52", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "decisionInd": "A", "defRemarks": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2022-04-01 08:10:40.465863", "faaReviewStartTms": "2022-03-08 08:10:40.465863", "intExt": "EX", "itemDesc": "Flight Deck Floor Coverings Worn / Damaged / Missing", "itemNotes": "Covers floor covering and carpet", "itemNotesInd": "Y", "itemNumber": "25-10-52", "lastUpdate": "2022-03-08 08:10:46.282253", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251052" }, { "sequenceNumber": "53", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be inoperative in the stowed position or missing.", "decisionInd": "A", "defRemarks": "May be inoperative in the stowed position or missing.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-07-02

13:00:42.428", "faaReviewStartTms": "2017-06-08 13:01:30.845781", "intExt": "EX",
"itemDesc": "Flight Deck Food Sliding Table / Food Trays Damaged / Missing", "itemNotes":
"For A319/320/321 and A330, 350 pilot sliding tables see MEL.", "itemNotesInd": "Y",
"itemNumber": "25-10-53", "lastUpdate": "2017-06-30 08:27:14.758189",
"lastUpdateDisplay": "06/30/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "251053" }, { "sequenceNumber": "54",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "F", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-
02 12:37:05.605608", "faaReviewStartTms": "2011-12-09 12:37:05.605608", "intExt": "EX",
"itemDesc": "Flight Deck Forms or Consumables Need Replenishing", "itemNotes": "These
are items normally used up. Any forms required for flight must be replaced. See FOM for
required forms", "itemNotesInd": "Y", "itemNumber": "25-10-54", "lastUpdate": "2011-12-
09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "251054" }, { "sequenceNumber": "55",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": ".",
"faaReviewEndTms": "2022-08-27 13:21:16.853507", "faaReviewStartTms": "2022-08-03
13:21:16.853507", "intExt": "EX", "itemDesc": "Flight Deck Ramp Inspection Vests
damaged or missing", "itemNotes": "Any standard Reflective Safety Vest can replace a
missing flight deck safety vest if a Flight Ops Branded Vest is not available. The Flight Ops
Safety Vests, P/N P600FOXl and P/N P600FO2X , can be obtained by ordering in Ariba.",
"itemNotesInd": "Y", "itemNumber": "25-10-55", "lastUpdate": "2022-08-03
13:21:24.63084", "lastUpdateDisplay": "08/03/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00324557", "legacyFrc": "251055" }, { "sequenceNumber": "56", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "F", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:12:20.322127", "faaReviewStartTms": "2022-03-08 08:12:20.322127", "intExt": "EX", "itemDesc": "Flight Deck Software Binder or Disks Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-56", "lastUpdate": "2022-03-08 08:12:31.932723", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251056" }, { "sequenceNumber": "57", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not pose any safety hazard. Cracked Mirror may require taping.", "decisionInd": "A", "defRemarks": "Damage must not pose any safety hazard. Cracked Mirror may require taping.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:12:58.765621", "faaReviewStartTms": "2022-03-08 08:12:58.765621", "intExt": "EX", "itemDesc": "Flight Deck Vanity Mirror Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-57", "lastUpdate": "2022-03-08 08:13:03.903657", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251057" }, { "sequenceNumber": "58", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If container is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "decisionInd": "A", "defRemarks": "If container is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "efmTab": "D",

"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:05.87465", "faaReviewStartTms": "2011-12-09 12:37:05.87465", "intExt": "EX", "itemDesc": "Flight Deck Waste Containers Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-58", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "251058" }, { "sequenceNumber": "59", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "This is subject to conditions not requiring it's use.", "decisionInd": "A", "defRemarks": "This is subject to conditions not requiring it's use.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial approval", "faaReviewEndTms": "2022-11-03 14:37:01.43999", "faaReviewStartTms": "2022-10-10 14:37:01.43999", "intExt": "EX", "itemDesc": "Flight Deck Window Shades (retractable) Damaged", "itemNotes": "For the A220\u0021As only, if damaged and usable this NEF applies. If inoperative or missing refer to A220 MEL 25-18-05", "itemNotesInd": "Y", "itemNumber": "25-10-59", "lastUpdate": "2022-10-10 14:37:10.697188", "lastUpdateDisplay": "10/10/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251059" }, { "sequenceNumber": "60", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:13:28.959529", "faaReviewStartTms": "2022-03-08 08:13:28.959529", "intExt": "EX", "itemDesc": "HGS / HUD Quilted Cover Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-10-60", "lastUpdate": "2022-03-08 08:13:34.617529", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00324557", "legacyFrc": "251060" }, { "sequenceNumber": "61", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-07-02 13:09:28.112", "faaReviewStartTms": "2017-06-08 13:10:16.538663", "intExt": "EX", "itemDesc": "Instrument Panel Foot Rest Damaged", "itemNotes": "For A319/320/321 ,330 and A350 pilot retractable footrest see MEL.", "itemNotesInd": "Y", "itemNumber": "25-10-61", "lastUpdate": "2017-06-30 08:27:31.296887", "lastUpdateDisplay": "06/30/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "251061" }, { "sequenceNumber": "62", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 08:25:16.597", "faaReviewStartTms": "2017-09-25 08:25:16.602811", "intExt": "EX", "itemDesc": "Instrument Panel Foot Tread Trim Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-62", "lastUpdate": "2017-09-25 08:26:34.909003", "lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "251062" }, { "sequenceNumber": "63", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:13:59.916207", "faaReviewStartTms": "2022-03-08 08:13:59.916207", "intExt": "EX", "itemDesc": "Logbook Holder Damaged", "itemNotesInd": "N", "itemNumber": "25-10-63", "lastUpdate": "2022-03-08 08:14:03.31508", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",

"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251063" }, { "sequenceNumber": "64", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Item may not be missing if wires normally attach to it or if it presents an electrical hazard.", "decisionInd": "A", "defRemarks": "Item may not be missing if wires normally attach to it or if it presents an electrical hazard.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 08:30:29.986", "faaReviewStartTms": "2017-09-25 08:30:29.989956", "intExt": "EX", "itemDesc": "Map / Chart Holders Damaged / Missing", "itemNotes": "For Airbus food sliding table map holders see NEF 25-16-04.", "itemNotesInd": "Y", "itemNumber": "25-10-64", "lastUpdate": "2017-09-25 08:31:34.338416", "lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "251064" }, { "sequenceNumber": "65", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to crew or impede emergency egress. Do not use on B757 aircraft, use MEL 25-11-02A per the FAA.", "decisionInd": "A", "defRemarks": "Must not present hazard to crew or impede emergency egress. Do not use on B757 aircraft, use MEL 25-11-02A per the FAA.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:44:19.275113", "faaReviewStartTms": "2023-11-16 06:44:19.275113", "intExt": "EX", "itemDesc": "Observer's Foot Rest Assemblies Damaged", "itemNotes": "MELs are available for the observer seat including associated equipment if the seat is acceptable to the FAA inspector for performance of official duties.", "itemNotesInd": "Y", "itemNumber": "25-10-65", "lastUpdate": "2023-11-16 06:44:23.884961", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251065" }, { "sequenceNumber": "66",

"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list. Reviewed for A350.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:15:03.953817",
"faaReviewStartTms": "2022-03-08 08:15:03.953817", "intExt": "EX", "itemDesc":
"Observer's Seat Latch Knob Damaged(see notes)", "itemNotes": "Only for a damaged
knob, Latch must still operate and not prevent egress or pose a hazard to crew.",
"itemNotesInd": "Y", "itemNumber": "25-10-66", "lastUpdate": "2022-03-08
08:15:10.249135", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251066" }, { "sequenceNumber": "67",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an
opening that items could fall into.", "decisionInd": "A", "defRemarks": "Damage must not
be to an extent that it leaves an opening that items could fall into.", "efmTab": "D",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "a", "faaReviewEndTms": "2022-04-01 08:15:59.313919",
"faaReviewStartTms": "2022-03-08 08:15:59.313919", "intExt": "EX", "itemDesc": "Side
Stick Bellows / Boot Worn / Damaged", "itemNotesInd": "N", "itemNumber": "25-10-67",
"lastUpdate": "2022-03-08 08:16:19.61323", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251067" },
{ "sequenceNumber": "68", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:16:42.325291",
"faaReviewStartTms": "2022-03-08 08:16:42.325291", "intExt": "EX", "itemDesc": "Spare
Bulb Kit Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-10-68",

"lastUpdate": "2022-03-08 08:16:48.772607", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251068" },
{ "sequenceNumber": "69", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:17:11.100977",
"faaReviewStartTms": "2022-03-08 08:17:11.100977", "intExt": "EX", "itemDesc": "Spare
Bulb Kit Needs Replenishing", "itemNotesInd": "N", "itemNumber": "25-10-69",
"lastUpdate": "2022-03-08 08:17:29.261013", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251069" },
{ "sequenceNumber": "70", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Compartment", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "This is
subject to conditions not requiring it's use.", "decisionInd": "A", "defRemarks": "This is
subject to conditions not requiring it's use.", "efmTab": "D", "faaAcceptanceRequiredInd":
"Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial",
"faaReviewEndTms": "2022-11-03 14:38:40.24952", "faaReviewStartTms": "2022-10-10
14:38:40.24952", "intExt": "EX", "itemDesc": "Sunshade or Clips Damaged / Missing",
"itemNotes": "This NEF item is not applicable to the A220 fleet. Reference A220 MEL 25-18-
05.", "itemNotesInd": "Y", "itemNumber": "25-10-70", "lastUpdate": "2022-10-10
14:38:48.319891", "lastUpdateDisplay": "10/10/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251070" }, { "sequenceNumber": "71",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",

"faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial",
"faaReviewEndTms": "2022-04-01 08:18:41.402686", "faaReviewStartTms": "2022-03-08
08:18:41.402686", "intExt": "EX", "itemDesc": "Yoke Thumb Wheel Reminder Inoperative",
"itemNotesInd": "N", "itemNumber": "25-10-71", "lastUpdate": "2022-03-08
08:18:46.396839", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251071" }, { "sequenceNumber": "72",
"creationDate": "07/19/2023 13:05:41", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms":
"2023-08-12 13:40:21.013204", "faaReviewStartTms": "2023-07-19 13:40:21.013204",
"intExt": "IP", "itemDesc": "AIRCRAFT OUT OF SERVICE TAG MISSING", "itemNotes":
"AIRCRAFT OUT OF SERVICE TAG MISSING", "itemNotesInd": "Y", "itemNumber": "25-10-
72", "lastUpdate": "2023-07-19 13:40:31.321746", "lastUpdateDisplay": "07/19/2023",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "4948900",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000980054",
"rowInsertEmpNoDisplay": "00980054", "rowInsertTms": "2023-07-19 12:53:08.753683",
"sceptreAutoDefRemarks": "For NEF items \u001A Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251072" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:06.706385", "faaReviewStartTms": "2011-
12-09 12:37:06.706385", "intExt": "EX", "itemDesc": "Flight Deck Armrest Covers Damaged
/ Missing", "itemNotes": "For inoperative flight crew armrest see MEL.", "itemNotesInd":
"Y", "itemNumber": "25-11-01", "lastUpdate": "2011-12-09 12:36:53.842",
"lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "LOADJOB", "legacyFrc": "251101" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":

"Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:06.809631", "faaReviewStartTms": "2011-12-09 12:37:06.809631", "intExt": "EX", "itemDesc": "Flight Deck Seat Belt Tidy Clips Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-11-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "251102" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be lightly worn in a cosmetic fashion, but seat still serviceable and cushion is not torn or otherwise has hole in fabric.", "decisionInd": "A", "defRemarks": "May be lightly worn in a cosmetic fashion, but seat still serviceable and cushion is not torn or otherwise has hole in fabric.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2018-10-19 05:58:50.077427", "faaReviewStartTms": "2018-09-25 05:58:50.077427", "intExt": "EX", "itemDesc": "Flight Deck Seat Covers Worn", "itemNotes": "For this item if it is lightly worn, or wrong color replace at next overnight where parts are available.", "itemNotesInd": "Y", "itemNumber": "25-11-03", "lastUpdate": "2018-09-25 09:13:38.894212", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "251103" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Cushion and fabric may not be torn or have holes in fabric. The cushion seat must be secured.", "decisionInd": "A", "defRemarks": "Cushion and fabric may not be torn or have holes in fabric. The cushion seat must be secured.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:06.942022", "faaReviewStartTms": "2011-12-09 12:37:06.942022", "intExt": "EX", "itemDesc": "Flight Deck Seat Cushions Flat or

Damaged", "itemNotes": "Cushion flat or damaged (i.e.; velcro missing).", "itemNotesInd": "Y", "itemNumber": "25-11-04", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "251104" }, { "sequenceNumber": "05", "creationDate": "10/13/2012 12:39:44", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Seat functions normal and trim is secure. Must not present hazard to crew or impede emergency egress.", "decisionInd": "A", "defRemarks": "Seat functions normal and trim is secure. Must not present hazard to crew or impede emergency egress.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:19:46.771302", "faaReviewStartTms": "2022-03-08 08:19:46.771302", "intExt": "EX", "itemDesc": "Flight Deck Seat Trim Damaged", "itemNotesInd": "N", "itemNumber": "25-11-05", "lastUpdate": "2022-03-08 08:20:02.602401", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9083307", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000827032", "rowInsertEmpNoDisplay": "00827032", "rowInsertTms": "2012-10-13 12:32:20.444552", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251105" }, { "sequenceNumber": "06", "creationDate": "06/25/2014 16:28:43", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Only one of two straps may be damaged or broken. Verify condition of the remaining strap.", "decisionInd": "A", "defRemarks": "Only one of two straps may be damaged or broken. Verify condition of the remaining strap.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:25:52.141559", "faaReviewStartTms": "2022-03-08 08:25:52.141559", "intExt": "IP", "itemDesc": "Observers Seat - Seat Bottom Stowage Strap Damaged/Broken", "itemNotes": "Only to be used with observers jump seat that has two straps used to secure the seat in the up position.", "itemNotesInd": "Y", "itemNumber": "25-11-06", "lastUpdate": "2022-03-08 08:26:03.892056", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5711663", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000972506", "rowInsertEmpNoDisplay": "00972506",

"rowInsertTms": "2014-06-25 16:17:20.683483", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251106" }, { "sequenceNumber": "07", "creationDate": "08/25/2014 18:21:45", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The pad may be damaged or missing provided the rotary lap buckle operates normally.", "decisionInd": "A", "defRemarks": "The pad may be damaged or missing provided the rotary lap buckle operates normally.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-09-21 05:14:57.276", "faaReviewStartTms": "2014-08-28 05:14:57.281252", "intExt": "IP", "itemDesc": "Flight Deck Seat Comfort Pad Damaged/Missing", "itemNotes": "The pad, if installed, is located on the back of the rotary lap buckle. Not all aircraft have a pad installed on the rotary lap buckle.", "itemNotesInd": "Y", "itemNumber": "25-11-07", "lastUpdate": "2014-08-28 07:45:42.957724", "lastUpdateDisplay": "08/28/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "6349180", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000331991", "rowInsertEmpNoDisplay": "00331991", "rowInsertTms": "2014-08-25 18:11:36.609583", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "251107" }, { "sequenceNumber": "08", "creationDate": "07/15/2015 18:10:15", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Flight Deck Seats/Belts", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Single point rotary release must be fully operational; if any section of the release tab is bent it must not impede the action of the rotary release mechanism. Broken or missing release tab must not have any exposed sharp edges.", "decisionInd": "A", "defRemarks": "Single point rotary release must be fully operational; if any section of the release tab is bent it must not impede the action of the rotary release mechanism. Broken or missing release tab must not have any exposed sharp edges.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time to 10.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:26:20.280492", "faaReviewStartTms": "2022-03-08 08:26:20.280492", "intExt": "IP", "itemDesc": "Shoulder Harness Quick Release Tab Broken/Bent (B767 Only)", "itemNotes": "The single point rotary release system is fully operational. This tab releases the shoulder restraints only. B767 only. This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-11-08", "lastUpdate": "2022-03-08 08:26:25.793947", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",

"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000966492", "rowInsertEmpNoDisplay": "00966492", "rowInsertTms": "2015-07-15 17:54:33.942956", "sceptreAutoDefRemarks": "None", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251108" }, { "sequenceNumber": "01", "creationDate": "06/30/2012 10:44:54", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Ceiling & Sidewall Lining", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Pouch or container must securely hold and allow access to the contents.", "decisionInd": "A", "defRemarks": "Pouch or container must securely hold and allow access to the contents.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:27:52.392162", "faaReviewStartTms": "2022-03-08 08:27:52.392162", "intExt": "EX", "itemDesc": "Gear Pin Pouch/Container Damaged / Poor Condition", "itemNotesInd": "N", "itemNumber": "25-12-01", "lastUpdate": "2022-03-08 08:27:56.134054", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "8541432", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000417171", "rowInsertEmpNoDisplay": "00417171", "rowInsertTms": "2012-06-30 10:29:46.908331", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251201" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cockpit Floor Covering", "ataSectCode": "13", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Compartment needs to be secured", "decisionInd": "A", "defRemarks": "Compartment needs to be secured", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:28:24.497373", "faaReviewStartTms": "2022-03-08 08:28:24.497373", "intExt": "EX", "itemDesc": "Flight Deck Stowage Compartment Door Lock Damaged", "itemNotesInd": "N", "itemNumber": "25-13-01", "lastUpdate": "2022-03-08 08:28:29.930241", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251301" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cockpit Trim/Panels", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":

"0", "deactMOProcedure": "If items can not be secured with remaining closet restraints, closet must not be used for storage.", "decisionInd": "A", "defRemarks": "If items can not be secured with remaining closet restraints, closet must not be used for storage.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2022-04-01 08:28:55.426951", "faaReviewStartTms": "2022-03-08 08:28:55.426951", "intExt": "EX", "itemDesc": "Flight Deck Closet Restraints Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-14-01", "lastUpdate": "2022-03-08 08:29:00.391866", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251401" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Cockpit Trim/Panels", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Appearance items, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "decisionInd": "A", "defRemarks": "Appearance items, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:31:09.496108", "faaReviewStartTms": "2022-03-08 08:31:09.496108", "intExt": "EX", "itemDesc": "Flight Deck Interior Trim Damaged/Missing (Including Glareshield & Condensation Drain Tube)", "itemNotes": "Includes condensation drain tubes.This NEF item has a 365 day allowable time limit. Panels that cover live electrical terminals cannot be deferred per this NEF.", "itemNotesInd": "Y", "itemNumber": "25-14-02", "lastUpdate": "2022-03-08 08:31:16.296176", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251402" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cockpit Trim/Panels", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Verify that no electrical wiring is exposed.", "decisionInd": "A", "defRemarks": "Verify that no electrical wiring is exposed.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:07.197212",

"faaReviewStartTms": "2011-12-09 12:37:07.197212", "intExt": "EX", "itemDesc": "Flight Deck Outlet Covers Damaged", "itemNotesInd": "N", "itemNumber": "25-14-03", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "251403" }, { "sequenceNumber": "04", "creationDate": "06/30/2014 08:05:04", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cockpit Trim/Panels", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "No sharp edges may be present and must not present hazard to the crew. \r\n\r\nEnsure circuit breaker is identified with a temporary identification label.", "decisionInd": "A", "defRemarks": "No sharp edges may be present and must not present hazard to the crew. \r\n\r\nEnsure circuit breaker is identified with a temporary identification label.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:31:35.734523", "faaReviewStartTms": "2022-03-08 08:31:35.734523", "intExt": "EX", "itemDesc": "Flight Compartment C/B Panel Identification Label Support Damaged/Missing", "itemNotes": "Circuit breaker identification label support may be removed as long as a circuit breaker identification label is installed per 14 CFR 25.1357(d).", "itemNotesInd": "Y", "itemNumber": "25-14-04", "lastUpdate": "2022-03-08 08:31:41.569304", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5847201", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000925787", "rowInsertEmpNoDisplay": "00925787", "rowInsertTms": "2014-06-30 07:49:30.934717", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251404" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Forward Equipment Center", "ataSectCode": "15", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:33:06.92306", "faaReviewStartTms": "2022-03-08 08:33:06.92306", "intExt": "EX", "itemDesc": "Fuel Valve Deactivation Tool (A330 Only) Damaged / Missing", "itemNotes": "Replace at next RON station where parts are available. NW Stock# 33-2500-3-0828", "itemNotesInd": "Y", "itemNumber": "25-15-01", "lastUpdate": "2022-03-08 08:33:19.30109", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",

"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251501" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Forward Equipment Center", "ataSectCode": "15", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:33:55.843404", "faaReviewStartTms": "2022-03-08 08:33:55.843404", "intExt": "EX", "itemDesc": "Printer Cover Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-15-02", "lastUpdate": "2022-03-08 08:34:05.494861", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251502" }, { "sequenceNumber": "01", "creationDate": "10/08/2014 12:01:55", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Cockpit Equipment", "ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. \n\nContact the MCC to ensure that Flight Control applies S item 25-16-01 prior to dispatch to ensure the aircraft is restricted from polar routes.\n\nWhen removing the NEF, contact the MCC to ensure that S item 25-16-01 is removed.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. \n\nContact the MCC to ensure that Flight Control applies S item 25-16-01 prior to dispatch to ensure the aircraft is restricted from polar routes.\n\nWhen removing the NEF, contact the MCC to ensure that S item 25-16-01 is removed.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:34:32.358332", "faaReviewStartTms": "2022-03-08 08:34:32.358332", "intExt": "EX", "itemDesc": "Polar Suits", "itemNotes": "May be inoperative or missing provided flight is not conducted on polar routes.", "itemNotesInd": "Y", "itemNumber": "25-16-01", "lastUpdate": "2022-03-08 08:34:36.363404", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "6215425", "mpIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000378935", "rowInsertEmpNoDisplay": "00378935", "rowInsertTms": "2014-10-08 11:50:52.663256", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251601" },

```
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId":  
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "25", "ataDesc": "Misc. Cockpit Equipment", "ataSectCode": "16",  
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":  
"D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved  
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:35:04.41495",  
"faaReviewStartTms": "2022-03-08 08:35:04.41495", "intExt": "EX", "itemDesc": "Flight  
Deck Pencil / Pen Holder Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-  
16-02", "lastUpdate": "2022-03-08 08:35:12.552163", "lastUpdateDisplay": "03/08/2022",  
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",  
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":  
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto  
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251602" },  
{ "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId":  
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "25", "ataDesc": "Misc. Cockpit Equipment", "ataSectCode": "16",  
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":  
"D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved  
list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-  
04-01 08:35:50.064539", "faaReviewStartTms": "2022-03-08 08:35:50.064539", "intExt":  
"EX", "itemDesc": "Yoke / Table Chart Clips Damaged Missing", "itemNotesInd": "N",  
"itemNumber": "25-16-04", "lastUpdate": "2022-03-08 08:35:55.387864",  
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",  
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":  
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09  
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",  
"userIdDisplay": "00324557", "legacyFrc": "251604" }, { "sequenceNumber": "05",  
"creationDate": "10/02/2019 13:11:12", "userId": "0000324557", "activeInd": "A",  
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":  
"Misc. Cockpit Equipment", "ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "Y",  
"daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",  
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:36:05.867284",  
"faaReviewStartTms": "2022-03-08 08:36:05.867284", "intExt": "IP", "itemDesc": "Fly-Away  
Kit (A220 only)", "itemNotesInd": "N", "itemNumber": "25-16-05", "lastUpdate": "2022-03-  
08 08:36:21.125091", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",  
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",  
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",  
"rowInsertTms": "2019-10-02 13:04:42.390395", "sceptreAutoDefRemarks": "Auto
```

Generated NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557",
"legacyFrc": "251605" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53",
"userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime":
"120", "ataChapterCode": "25", "ataDesc": "All A/C Documents/Forms/Charts",
"ataSectCode": "17", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "F", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms":
"2022-04-01 08:36:44.824346", "faaReviewStartTms": "2022-03-08 08:36:44.824346",
"intExt": "EX", "itemDesc": "Abnormal Checklist Damaged or Worn but Legible",
"itemNotesInd": "N", "itemNumber": "25-17-01", "lastUpdate": "2022-03-08
08:36:50.879176", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251701" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"All A/C Documents/Forms/Charts", "ataSectCode": "17", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "F",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:37:12.101699",
"faaReviewStartTms": "2022-03-08 08:37:12.101699", "intExt": "EX", "itemDesc":
"Contaminated Runway Hard Cards Damaged or Worn but Legible", "itemNotesInd": "N",
"itemNumber": "25-17-02", "lastUpdate": "2022-03-08 08:37:19.670809",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "251702" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"All A/C Documents/Forms/Charts", "ataSectCode": "17", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "F",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:37:48.036777",
"faaReviewStartTms": "2022-03-08 08:37:48.036777", "intExt": "EX", "itemDesc": "Speed
Book Damaged or Worn but Legible", "itemNotesInd": "N", "itemNumber": "25-17-03",
"lastUpdate": "2022-03-08 08:37:53.293982", "lastUpdateDisplay": "03/08/2022",

"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251703" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "ACARS Printer Paper", "ataSectCode": "18",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"F", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:39:13.152784",
"faaReviewStartTms": "2022-03-08 08:39:13.152784", "intExt": "EX", "itemDesc": "Printer
Paper Needs Replenishing", "itemNotesInd": "N", "itemNumber": "25-18-01", "lastUpdate":
"2022-03-08 08:39:18.419152", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251801" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must
still be functional and secure.", "decisionInd": "A", "defRemarks": "Must still be functional
and secure.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "A", "faaReviewEndTms":
"2024-12-12 11:55:06.986634", "faaReviewStartTms": "2024-11-18 11:55:06.986634",
"intExt": "IP", "itemDesc": "Pilot Crew Rest Area Assist handles Poor Condition",
"itemNotesInd": "N", "itemNumber": "25-19-01", "lastUpdate": "2024-11-19
09:57:26.862397", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251901" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then
complete the MEL deferral process, otherwise defer using the NEF item.", "decisionInd":
"A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL

deferral process, otherwise defer using the NEF item.", "efmTab": "R",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2024-12-12 11:53:35.460995",
"faaReviewStartTms": "2024-11-18 11:53:35.460995", "intExt": "IP", "itemDesc": "Pilot
Crew Rest Area Bunk Door (Check MEL)", "itemNotesInd": "N", "itemNumber": "25-19-02",
"lastUpdate": "2024-11-19 09:57:38.24259", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251902" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2024-12-12 11:54:02.729896",
"faaReviewStartTms": "2024-11-18 11:54:02.729896", "intExt": "IP", "itemDesc": "Pilot
Crew Rest Area Grills / Vents Damaged", "itemNotesInd": "N", "itemNumber": "25-19-03",
"lastUpdate": "2024-11-19 09:57:48.837769", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251903" },
{ "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list. Clarified allowable time to 365.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2024-12-12 11:55:51.252973", "faaReviewStartTms": "2024-11-18
11:55:51.252973", "intExt": "IP", "itemDesc": "Pilot Crew Rest Area Interior Trim or Wall
Covering Damaged / Missing", "itemNotes": "This NEF item has a 365 day allowable time
limit.", "itemNotesInd": "Y", "itemNumber": "25-19-04", "lastUpdate": "2024-11-19
09:57:59.577455", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251904" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",

"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 25-25-07F for B767-300, MEL 25-25-07F for B767-400 and MEL 25-29-04F for B777 aircraft.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 25-25-07F for B767-300, MEL 25-25-07F for B767-400 and MEL 25-29-04F for B777 aircraft.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Approved during list integration and initial approval.", "faaContactName": "Initial list", "faaReviewEndTms": "2024-12-12 11:56:25.78575", "faaReviewStartTms": "2024-11-18 11:56:25.78575", "intExt": "IP", "itemDesc": "Pilot Crew Rest Area Pillows, Blankets, Mattress Pads, Sheets damaged/ Missing", "itemNotesInd": "N", "itemNumber": "25-19-05", "lastUpdate": "2024-11-19 09:58:19.628583", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251905" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "U", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time to 365.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:24:46.387788", "faaReviewStartTms": "2018-01-29 13:24:46.387788", "intExt": "IP", "itemDesc": "Crew Rest Area Carpet or Floor Coverings Worn / Damage / Missing", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-19-06", "lastUpdate": "2018-02-26 09:37:48.204527", "lastUpdateDisplay": "02/26/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "251906" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Any exposed wiring must be protected.", "decisionInd": "A", "defRemarks": "Any exposed wiring

must be protected.", "efmTab": "U", "faaAcceptanceRequiredInd": "Y",
"faaReviewEndTms": "2015-04-17 16:04:12.361", "faaReviewStartTms": "2015-03-24
16:04:12.360916", "intExt": "IP", "itemDesc": "Crew Rest Area Floor Track Covers Damaged
/ Loose / Missing", "itemNotesInd": "N", "itemNumber": "25-19-07", "lastUpdate": "2015-
03-24 16:04:15.318467", "lastUpdateDisplay": "03/24/2015", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "251907" }, { "sequenceNumber": "08",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOPprocedure": "If ashtray is missing and leaves hole exposed,
inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin
tape, nylon or fiberglass reinforced tape, not masking tape).", "decisionInd": "A",
"defRemarks": "If ashtray is missing and leaves hole exposed, inspect for foreign objects
then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass
reinforced tape, not masking tape).", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": "spelling
edit", "faaReviewEndTms": "2024-12-12 11:57:45.080133", "faaReviewStartTms": "2024-
11-18 11:57:45.080133", "intExt": "IP", "itemDesc": "Pilot Crew Rest Ashtray Damaged /
Missing", "itemNotesInd": "N", "itemNumber": "25-19-08", "lastUpdate": "2024-11-19
09:58:27.821186", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251908" }, { "sequenceNumber": "09",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial",
"faaReviewEndTms": "2024-12-12 11:58:25.001864", "faaReviewStartTms": "2024-11-18
11:58:25.001864", "intExt": "IP", "itemDesc": "Pilot Crew Rest Coat / Hat Hangar or Clip
Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-19-09", "lastUpdate": "2024-
11-19 09:58:36.220304", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":

"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251909" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2024-12-12 11:59:13.110529", "faaReviewStartTms": "2024-11-18 11:59:13.110529", "intExt": "IP", "itemDesc": "Pilot Crew Rest Foot Rest Restraining Straps Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-19-10", "lastUpdate": "2024-11-19 09:58:44.535211", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251910" }, { "sequenceNumber": "11", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2024-12-12 12:00:05.005299", "faaReviewStartTms": "2024-11-18 12:00:05.005299", "intExt": "IP", "itemDesc": "Pilot Crew Rest Headrest Cover Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-19-11", "lastUpdate": "2024-11-19 09:58:52.871112", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251911" }, { "sequenceNumber": "13", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "If cover is missing Place masking tape over the peep hole to insure security.", "decisionInd": "A", "defRemarks": "If cover is missing Place masking tape over the peep hole to insure security.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2024-12-12 12:01:30.397836", "faaReviewStartTms": "2024-11-18 12:01:30.397836", "intExt": "IP", "itemDesc": "Pilot Crew Rest Peep Hole Blocked / Damaged", "itemNotes": "Crew rest door peep hole in a330.", "itemNotesInd": "Y", "itemNumber": "25-19-13", "lastUpdate": "2024-

11-19 09:59:20.708606", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251913" }, { "sequenceNumber": "14", "creationDate": "02/19/2014 01:34:21", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-12-12 12:02:17.179462", "faaReviewStartTms": "2024-11-18 12:02:17.179462", "intExt": "IP", "itemDesc": "Pilot Crew Rest Seat Cushions and Coverings Damaged/Torn", "itemNotesInd": "N", "itemNumber": "25-19-14", "lastUpdate": "2024-11-19 09:59:29.250784", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5993966", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000352228", "rowInsertEmpNoDisplay": "00352228", "rowInsertTms": "2014-02-19 01:18:59.922095", "sceptreAutoDefRemarks": "Auto generated log Nef via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251914" }, { "sequenceNumber": "15", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "If tie-back is missing secure curtain with ties or string.", "decisionInd": "A", "defRemarks": "If tie-back is missing secure curtain with ties or string.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2024-12-12 12:03:12.199069", "faaReviewStartTms": "2024-11-18 12:03:12.199069", "intExt": "IP", "itemDesc": "Pilot Crew Rest Seat Curtain Tie-back Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-19-15", "lastUpdate": "2024-11-19 09:59:36.398914", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251915" }, { "sequenceNumber": "16", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",

"faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial",
"faaReviewEndTms": "2024-12-12 12:03:41.830854", "faaReviewStartTms": "2024-11-18
12:03:41.830854", "intExt": "IP", "itemDesc": "Pilot Crew Rest Stowage Compartment or
Bag Damaged", "itemNotesInd": "N", "itemNumber": "25-19-16", "lastUpdate": "2024-11-
19 09:59:56.184921", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251916" }, { "sequenceNumber": "17",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial",
"faaReviewEndTms": "2024-12-12 12:04:33.099844", "faaReviewStartTms": "2024-11-18
12:04:33.099844", "intExt": "IP", "itemDesc": "Pilot Crew Rest Tray Table Damaged /
Missing", "itemNotesInd": "N", "itemNumber": "25-19-17", "lastUpdate": "2024-11-19
10:00:07.309572", "lastUpdateDisplay": "11/19/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "251917" }, { "sequenceNumber": "18",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc":
"Pilots Crew Rest Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list. Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-12-12 12:05:39.288317",
"faaReviewStartTms": "2024-11-18 12:05:39.288317", "intExt": "IP", "itemDesc": "Pilot
Crew Rest Vanity Mirrors Damaged / Missing", "itemNotes": "This NEF item has a 365 day
allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-19-18", "lastUpdate":
"2024-11-19 10:00:20.737751", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "251918" },
{ "sequenceNumber": "19", "creationDate": "12/29/2011 15:42:54", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",

"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if
item is contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using the NEF item. At this time, reference MEL 25-25-08C/D/E for B767-300 and MEL
25-25-08C/D/E for B767-400 and MEL 25-75-03C/D/E for A330 aircraft", "decisionInd": "A",
"defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL
deferral process, otherwise defer using the NEF item. At this time, reference MEL 25-25-
08C/D/E for B767-300 and MEL 25-25-08C/D/E for B767-400 and MEL 25-75-03C/D/E for
A330 aircraft", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"BIEVER", "faaReviewEndTms": "2019-03-23 10:20:38.441087", "faaReviewStartTms":
"2019-02-27 10:20:38.441087", "intExt": "IP", "itemDesc": "Pilot Crew Rest Seat Curtain
Missing", "itemNotes": "This is the curtain used for the crew rest seats located in Business
Class. The curtain is required for flights scheduled over 8 hrs by Pilot Working Agreement. If
curtain is required schedule maintenance at next station.", "itemNotesInd": "Y",
"itemNumber": "25-19-19", "lastUpdate": "2019-02-27 10:20:41.184028",
"lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2011-12-29
15:30:36.738368", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "251919" },
{ "sequenceNumber": "20", "creationDate": "12/29/2011 15:38:37", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if
item is contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using the NEF item. At this time, reference MEL 25-25-08C/D/E for B767-300 and MEL
25-25-08C/D/E for B767-400 and MEL 25-75-03C/D/E for A330 aircraft \n\n\nSecure
curtain if applicable.", "decisionInd": "A", "defRemarks": "Check if item is contained in the
MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At
this time, reference MEL 25-25-08C/D/E for B767-300 and MEL 25-25-08C/D/E for B767-
400 and MEL 25-75-03C/D/E for A330 aircraft \n\n\nSecure curtain if applicable.",
"efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaContactName": "BIEVER",
"faaReviewEndTms": "2019-03-23 10:20:24.462421", "faaReviewStartTms": "2019-02-27
10:20:24.462421", "intExt": "IP", "itemDesc": "Pilot Crew Rest Seat Curtain Damaged",
"itemNotes": "This is the curtain used for the crew rest seats located in Business Class.
The curtain is required for flights scheduled over 8 hrs by Pilot Working Agreement. If
curtain is required schedule maintenance at next station.", "itemNotesInd": "Y",
"itemNumber": "25-19-20", "lastUpdate": "2019-02-27 10:20:28.081198",

"lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2011-12-29
15:38:02.035599", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "251920" },
{ "sequenceNumber": "23", "creationDate": "03/05/2014 19:12:13", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must
not present hazard to passengers or crew. Flapper door and access door must be secured
closed and placarded: \"Do not use\".", "decisionInd": "A", "defRemarks": "Must not present
hazard to passengers or crew. Flapper door and access door must be secured closed and
placarded: \"Do not use\".", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-12-12 12:06:48.178323",
"faaReviewStartTms": "2024-11-18 12:06:48.178323", "intExt": "IP", "itemDesc": "Pilot
Crew Rest Trash Liner Damaged/Missing", "itemNotesInd": "N", "itemNumber": "25-19-23",
"lastUpdate": "2024-11-19 10:00:35.143906", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "6017736",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000703356",
"rowInsertEmpNoDisplay": "00703356", "rowInsertTms": "2014-03-05 19:00:49.684568",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251923" },
{ "sequenceNumber": "24", "creationDate": "02/01/2012 15:05:55", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must
not present hazard to crew or impede emergency egress and the seat must be usable.",
"decisionInd": "A", "defRemarks": "Must not present hazard to crew or impede emergency
egress and the seat must be usable.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaComments": "ok", "faaContactName": "Biever", "faaReviewEndTms": "2024-12-12
12:07:17.752995", "faaReviewStartTms": "2024-11-18 12:07:17.752995", "intExt": "IP",
"itemDesc": "Pilot Crew Rest Seat Will Not Adjust", "itemNotes": "The seat must be usable,
if not defer per appropriate the MEL.", "itemNotesInd": "Y", "itemNumber": "25-19-24",
"lastUpdate": "2024-11-19 10:00:47.9854", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000526090",
"rowInsertEmpNoDisplay": "00526090", "rowInsertTms": "2012-02-01 15:00:48.307103",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251924" },
{ "sequenceNumber": "25", "creationDate": "11/06/2014 14:47:27", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Secure
loose or remove any loose or damaged seal. Tape any opening to prevent debris from
entering beneath the lower lobe crew rest as needed.", "defRemarks": "Secure loose or
remove any loose or damaged seal. Tape any opening to prevent debris from entering
beneath the lower lobe crew rest as needed.", "efmTab": "X", "faaAcceptanceRequiredInd":
"Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01
08:41:21.349353", "faaReviewStartTms": "2022-03-08 08:41:21.349353", "intExt": "IP",
"itemDesc": "Aft Lower Lobe Crew Rest Dust Seal Damaged or Missing (767 only)",
"itemNotes": "Aft Lower Lobe Crew Rest Dust seal may be missing or damaged. \r\n\r\nThis
FRC to replace 25-74-01 when EFM rev 2 is published and boarded on all fleets.",
"itemNotesInd": "Y", "itemNumber": "25-19-25", "lastUpdate": "2022-03-08
08:41:30.302936", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "5342422", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2014-11-06 14:44:41.166298", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "251925" }, { "sequenceNumber": "26", "creationDate":
"03/01/2016 13:20:48", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Pilots Crew Rest
Area", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL
deferral process, otherwise defer using the NEF item.", "decisionInd": "A", "defRemarks":
"Check if item is contained in the MEL; if yes then complete the MEL deferral process,
otherwise defer using the NEF item.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-12-12 12:08:31.465944",
"faaReviewStartTms": "2024-11-18 12:08:31.465944", "intExt": "IP", "itemDesc": "Pilot
Crew Rest Area Bunk Curtain (Check MEL)", "itemNotesInd": "N", "itemNumber": "25-19-
26", "lastUpdate": "2024-11-19 10:00:57.360803", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467",
"rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-03-01 13:06:30.858784",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251926" },
{ "sequenceNumber": "27", "creationDate": "03/01/2016 13:11:12", "userId":

"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Check if
item is contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using the NEF item.", "decisionInd": "A", "defRemarks": "Check if item is contained in
the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF
item.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2024-12-12 12:10:04.374416", "faaReviewStartTms":
"2024-11-18 12:10:04.374416", "intExt": "IP", "itemDesc": "Pilot Crew Rest Area Bunk
Curtain Tie-Back (Check MEL)", "itemNotesInd": "N", "itemNumber": "25-19-27",
"lastUpdate": "2024-11-19 10:01:15.387812", "lastUpdateDisplay": "11/19/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467",
"rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-03-01 13:08:23.169319",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251927" },
{ "sequenceNumber": "30", "creationDate": "06/22/2018 07:52:44", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Pilots Crew Rest Area", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"R", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 08:42:42.655579", "faaReviewStartTms": "2022-03-08
08:42:42.655579", "intExt": "IP", "itemDesc": "767(only) crew rest secondary door hold
open magnet and magnet catch inop or missing", "itemNotes": "This NEF is only for the
magnet or the magnet catch on the secondary door(small drop down door not the main
entry door) on the crew rest on 767 A/C only.", "itemNotesInd": "Y", "itemNumber": "25-19-
30", "lastUpdate": "2022-03-08 08:42:56.134434", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179",
"rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2018-06-22 07:51:22.082413",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "251930" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "For the
onboard wheelchair strap, remove the onboard wheelchair. Flight Crew must notify gate
agent that no wheelchair is available. If wheelchair is required by passenger then contact

MCC for guidance.", "decisionInd": "A", "defRemarks": "For the onboard wheelchair strap, remove the onboard wheelchair. Flight Crew must notify gate agent that no wheelchair is available. If wheelchair is required by passenger then contact MCC for guidance.", "efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:44:04.755879", "faaReviewStartTms": "2022-03-08 08:44:04.755879", "intExt": "IP", "itemDesc": "Wheelchair strap Missing- Pilot notify gate agent each flight that no wheelchair is available--Missing or Damaged", "itemNotes": "This NEF item has a 10 day allowable time limit. MCC: A wheelchair must be provided for any passenger that requires it on an aircraft with a wheelchair accessible lavatory. For aircraft without a wheelchair accessible lavatory the passenger may be required to provide 48hrs notice and check-in one hour before the check-in time for the general public to be guaranteed an onboard wheelchair.", "itemNotesInd": "Y", "itemNumber": "25-20-01", "lastUpdate": "2022-03-08 08:44:13.343109", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252001" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "K", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:09.258577", "faaReviewStartTms": "2011-12-09 12:37:09.258577", "intExt": "IP", "itemDesc": "Braille Book Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-20-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252003" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "If cracked it may require taping. Must not present damage to passengers or crew.", "decisionInd": "A", "defRemarks": "If cracked it may require taping. Must not present damage to passengers or crew.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:09.307117", "faaReviewStartTms": "2011-

12-09 12:37:09.307117", "intExt": "IP", "itemDesc": "Cabin Mirrors Damaged / Missing",
"itemNotesInd": "N", "itemNumber": "25-20-04", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "252004" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc":
"Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Must not present hazard to passengers or crew or
impede emergency egress. Damage must not be to an extent that it leaves an opening that
items could fall into or that would be a security concern.", "decisionInd": "A",
"defRemarks": "Must not present hazard to passengers or crew or impede emergency
egress. Damage must not be to an extent that it leaves an opening that items could fall into
or that would be a security concern.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list. Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:27:31.665208",
"faaReviewStartTms": "2018-01-29 13:27:31.665208", "intExt": "IP", "itemDesc": "Cabin
Trim Torn / Damaged / Missing", "itemNotes": "This NEF item has a 365 day allowable time
limit.", "itemNotesInd": "Y", "itemNumber": "25-20-05", "lastUpdate": "2018-02-22
05:46:44.579064", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "252005" }, { "sequenceNumber": "06",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "K", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial",
"faaReviewEndTms": "2022-04-01 08:44:33.125632", "faaReviewStartTms": "2022-03-08
08:44:33.125632", "intExt": "IP", "itemDesc": "Equipment and Furnishings Manual Cover
Damaged / Poor Condition", "itemNotesInd": "N", "itemNumber": "25-20-06", "lastUpdate":
"2022-03-08 08:44:37.041209", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto

Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252006" },
{ "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"K", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:45:01.51291",
"faaReviewStartTms": "2022-03-08 08:45:01.51291", "intExt": "IP", "itemDesc": "Equipment
and Furnishings Manual Needs Worksheets", "itemNotesInd": "N", "itemNumber": "25-20-
07", "lastUpdate": "2022-03-08 08:45:04.632695", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252007" },
{ "sequenceNumber": "12", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:09.88829", "faaReviewStartTms": "2011-12-
09 12:37:09.88829", "intExt": "IP", "itemDesc": "Seat Tray Containers or Tray Liners
Damaged", "itemNotes": "This can include Flight Deck and crew rest area tray
Containers/liners", "itemNotesInd": "Y", "itemNumber": "25-20-12", "lastUpdate": "2011-
12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252012" }, { "sequenceNumber": "13",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "M", "faaAcceptanceRequiredInd": "Y",
"faaReviewEndTms": "2019-07-04 01:16:17.41353", "faaReviewStartTms": "2019-06-10
01:16:17.41353", "intExt": "IP", "itemDesc": "Universal Precaution Kit (UPK) Used /
Missing", "itemNotes": "upk opened", "itemNotesInd": "Y", "itemNumber": "25-20-13",
"lastUpdate": "2019-06-11 14:46:13.7252", "lastUpdateDisplay": "06/11/2019",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252013" }, { "sequenceNumber": "14", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If wheelchair is not usable attach placard or tag to chair. Flight Crew must notify gate agent that no wheelchair is available. If wheelchair is required by passenger then contact MCC for guidance.", "decisionInd": "A", "defRemarks": "If wheelchair is not usable attach placard or tag to chair. Flight Crew must notify gate agent that no wheelchair is available. If wheelchair is required by passenger then contact MCC for guidance.", "efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:45:18.252475", "faaReviewStartTms": "2022-03-08 08:45:18.252475", "intExt": "IP", "itemDesc": "Wheelchair Damaged/Missing-Pilot notify gate agent each flight that no wheelchair is available", "itemNotes": "This NEF item has a 10 day allowable time limit. MCC: An on-board wheelchair must be provided for any passenger that requires it provided the passenger provides 48 hours' notice and checks-in one hour before the check-in time for the general public to be guaranteed an onboard wheelchair. If a passenger does not meet advance notice or check-in requirements, a wheelchair must still be provided if you can do so by making reasonable efforts, without delaying the flight.", "itemNotesInd": "Y", "itemNumber": "25-20-14", "lastUpdate": "2022-03-08 08:45:21.993113", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252014" }, { "sequenceNumber": "16", "creationDate": "05/15/2013 15:07:11", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Per TOPP 50-10-10: Contact the MCC to have the missing item replaced at the next Delta Maintenance Station where time and required parts are available. If EFM is missing, install a placard in aircraft logbook including instruction for flight crew to enter all discrepancies in the aircraft logbook and report them to the MCC or local maintenance.", "decisionInd": "A", "defRemarks": "Per TOPP 50-10-10: Contact the MCC to have the missing item replaced at the next Delta Maintenance Station where time and required parts are available. If EFM is missing, install a placard in aircraft logbook including instruction for flight crew to enter all discrepancies in the aircraft logbook and report them to the MCC or local maintenance.", "efmTab": "K",

"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 08:45:47.753976", "faaReviewStartTms": "2022-03-08
08:45:47.753976", "intExt": "IP", "itemDesc": "Equipment and Furnishings Manual or
Individual Components Missing", "itemNotes": "For EFM needs worksheets reference NEF
25-20-07. For EFM cover damaged/poor condition reference NEF 25-20-06.",
"itemNotesInd": "Y", "itemNumber": "25-20-16", "lastUpdate": "2022-03-08
08:45:52.948075", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "0155300", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2013-05-15 14:55:15.716132", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "252016" }, { "sequenceNumber": "18", "creationDate":
"01/26/2014 10:41:34", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger
Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Seat belt extension pouch must be capable of
holding the extensions securely.", "decisionInd": "A", "defRemarks": "Seat belt extension
pouch must be capable of holding the extensions securely.", "efmTab": "M",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Repair pouch as needed to allow for
normal storage.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-12-05
14:44:28.61", "faaReviewStartTms": "2014-11-11 14:44:28.610395", "intExt": "IP",
"itemDesc": "Seat Belt Extension Pouch Damaged/Poor Condition", "itemNotesInd": "N",
"itemNumber": "25-20-18", "lastUpdate": "2014-11-11 14:44:31.372039",
"lastUpdateDisplay": "11/11/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "5648452", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000869844", "rowInsertEmpNoDisplay": "00869844", "rowInsertTms": "2014-01-26
10:25:49.945381", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "252018" },
{ "sequenceNumber": "21", "creationDate": "06/26/2014 19:23:56", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "No
sharp edges may be present and must not present hazard to passengers or crew.\n\n(M)
Procedure (If the handrail is to be removed):\n1. Remove the handrail.\n2. (PRE AA 3320-
01184 ONLY) Obtain an ER/A to deactivate the handrail light and apply MEL 33-20-01B.\n3.
Create a log and defer all removed seat row placards to NEF code 11-30-12.",
"decisionInd": "A", "defRemarks": "No sharp edges may be present and must not present
hazard to passengers or crew.\n\n(M) Procedure (If the handrail is to be removed):\n1.

Remove the handrail.\n2. (PRE AA 3320-01184 ONLY) Obtain an ER/A to deactivate the handrail light and apply MEL 33-20-01B.\n3. Create a log and defer all removed seat row placards to NEF code 11-30-12.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:47:04.423019", "faaReviewStartTms": "2022-03-08 08:47:04.423019", "intExt": "IP", "itemDesc": "Cabin Handrail Damaged/Missing- B717 Only", "itemNotesInd": "N", "itemNumber": "25-20-21", "lastUpdate": "2022-03-08 08:47:12.089481", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5323957", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000421388", "rowInsertEmpNoDisplay": "00421388", "rowInsertTms": "2014-06-26 19:21:46.130723", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252021" }, { "sequenceNumber": "22", "creationDate": "11/06/2014 14:13:16", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Approved during list integration and initial approval.", "faaContactName": "Initial list", "faaReviewEndTms": "2015-08-16 13:43:50.618", "faaReviewStartTms": "2015-07-23 13:43:50.619986", "intExt": "IP", "itemDesc": "Coat Hangers Damaged/Missing", "itemNotes": "This FRC replaced 25-25-02.", "itemNotesInd": "Y", "itemNumber": "25-20-22", "lastUpdate": "2015-08-12 12:24:01.662153", "lastUpdateDisplay": "08/12/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-06 14:11:33.103449", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00517467", "legacyFrc": "252022" }, { "sequenceNumber": "23", "creationDate": "11/06/2014 14:39:29", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-08-22 09:05:32.556", "faaReviewStartTms": "2015-07-29 09:05:32.557963", "intExt": "IP", "itemDesc": "Trash Trap Netting Damaged/Missing", "itemNotes": "Trash Trap netting is being installed during High Seat density mod. Netting runs between the seatbacks of the last row in F/C and the bulkhead. In place to prevent trash from falling between the seatback and the bulkhead. \r\n\r\nThis FRC replaced 25-73-09.", "itemNotesInd": "Y", "itemNumber": "25-20-23", "lastUpdate": "2015-08-26 13:19:56.114413", "lastUpdateDisplay": "08/26/2015", "legacyDeltaAirworthyInd": "N",

"logMultiplicity": "S", "logpageNumber": "5498138", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2014-11-06 14:37:52.97287", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00517467", "legacyFrc": "252023" }, { "sequenceNumber": "58", "creationDate":
"11/15/2022 08:00:15", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger
Compartment", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "For configurations which use the seat-strapping
method of stowage for passenger wheelchairs, two wheelchair strapping kits are required.
If more than two strapping kits are provisioned, supernumerary kits may be missing or
damaged, if minimum two serviceable strapping kits remain.\n\nThis NEF does not apply
to closet stowage of wheelchairs, or for onboard aisle chair. For onboard wheelchair (aisle
chair) stowage, see NEF 25-20-01.", "decisionInd": "A", "defRemarks": "For configurations
which use the seat-strapping method of stowage for passenger wheelchairs, two
wheelchair strapping kits are required. If more than two strapping kits are provisioned,
supernumerary kits may be missing or damaged, if minimum two serviceable strapping kits
remain.\n\nThis NEF does not apply to closet stowage of wheelchairs, or for onboard aisle
chair. For onboard wheelchair (aisle chair) stowage, see NEF 25-20-01.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable. as submitted.",
"faaContactName": "Bill L. Williams", "faaReviewEndTms": "2022-12-15 07:38:19.938367",
"faaReviewStartTms": "2022-11-21 07:38:19.938367", "intExt": "IP", "itemDesc":
"Passenger Wheelchair Seat Strapping Kits (Supernumerary Kits Only)", "itemNotesInd":
"N", "itemNumber": "25-20-58", "lastUpdate": "2022-11-21 10:06:26.687739",
"lastUpdateDisplay": "11/21/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2022-11-15
07:57:39.156712", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252058" },
{ "sequenceNumber": "05", "creationDate": "12/14/2015 12:18:09", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "For missing pocket one passenger information card is required per
seat assembly.", "decisionInd": "A", "defRemarks": "For missing pocket one passenger
information card is required per seat assembly.", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Clarification.", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2018-11-30 08:59:51.136415", "faaReviewStartTms":

"2018-11-06 08:59:51.136415", "intExt": "IP", "itemDesc": "Passenger Seat PLASTIC Literature Pocket Damaged/Missing", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats that have PLASTIC literature seat pockets; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-05", "lastUpdate": "2018-11-06 08:59:58.117777", "lastUpdateDisplay": "11/06/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2015-12-14 12:10:39.450601", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252105" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "For missing pocket one passenger information card is required per seat assembly.", "decisionInd": "A", "defRemarks": "For missing pocket one passenger information card is required per seat assembly.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2016-01-07 12:05:30.113", "faaReviewStartTms": "2015-12-14 12:05:30.115645", "intExt": "IP", "itemDesc": "Passenger Seat LEATHER Literature Pocket Missing", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats that have leather literature seat pockets; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-06", "lastUpdate": "2015-12-14 12:05:45.864505", "lastUpdateDisplay": "12/14/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "252106" }, { "sequenceNumber": "08", "creationDate": "12/14/2015 12:32:40", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarification.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2016-02-26 12:15:09.97", "faaReviewStartTms": "2016-02-02 12:15:09.974924", "intExt": "IP", "itemDesc": "Passenger Seat PLASTIC Literature Pocket Damaged/Torn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats that have PLASTIC literature seat pockets; First Class, Business Elite, World Business Class or

Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-08", "lastUpdate": "2016-02-04 07:18:35.076989", "lastUpdateDisplay": "02/04/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2015-12-14 12:17:25.915477", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00517467", "legacyFrc": "252108" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "At least one required per each occupied seat assembly.", "decisionInd": "A", "defRemarks": "At least one required per each occupied seat assembly.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:16:06.816", "faaReviewStartTms": "2012-03-06 10:16:06.084797", "intExt": "IP", "itemDesc": "Passenger Seat Information Cards Damaged or Missing", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-09", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "252109" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If ashtray cover is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "decisionInd": "A", "defRemarks": "If ashtray cover is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:16:38.144", "faaReviewStartTms": "2012-03-06 10:16:37.337444", "intExt": "IP", "itemDesc": "Passenger Seat Ashtray Cover Damaged / Missing", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y",

"itemNumber": "25-21-10", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00245058", "legacyFrc": "252110" }, { "sequenceNumber": "12",
"creationDate": "12/14/2015 12:33:02", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Clarification.", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2018-10-19 06:13:51.794281", "faaReviewStartTms":
"2018-09-25 06:13:51.794281", "intExt": "IP", "itemDesc": "Passenger Seat PLASTIC
Literature Pocket Worn", "itemNotes": "Disregard the ATA description code. This NEF code
applies to all passenger seats that have PLASTIC literature pockets; First Class, Business
Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd":
"Y", "itemNumber": "25-21-12", "lastUpdate": "2018-09-25 09:22:54.329945",
"lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2015-12-14
12:23:11.591041", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252112" },
{ "sequenceNumber": "13", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Must not present hazard to passengers or crew or impede
emergency egress.", "decisionInd": "A", "defRemarks": "Must not present hazard to
passengers or crew or impede emergency egress.", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:31:19.654194",
"faaReviewStartTms": "2018-01-29 13:31:19.654194", "intExt": "IP", "itemDesc":
"Passenger Seat Assembly Aisle Trim Damaged / Missing", "itemNotes": "Disregard the ATA
description code. This NEF code applies to all passenger seats; First Class, Business Elite,
World Business Class or Premium Economy or Coach Class seats. This NEF item has a 365
day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-21-13", "lastUpdate":
"2018-02-22 05:47:31.363862", "lastUpdateDisplay": "02/22/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",

"mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252113" }, { "sequenceNumber": "16", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:18:16.238", "faaReviewStartTms": "2012-03-06 10:18:15.469529", "intExt": "IP", "itemDesc": "Passenger Seat Belt Extension Incorrect Type", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-16", "lastUpdate": "2012-03-06 10:18:20.763461", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "252116" }, { "sequenceNumber": "17", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-06-01 13:26:12.51", "faaReviewStartTms": "2015-05-08 13:26:12.512316", "intExt": "IP", "itemDesc": "Passenger Seat Belt Extension Missing", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-17", "lastUpdate": "2015-05-12 11:35:27.803533", "lastUpdateDisplay": "05/12/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "252117" }, { "sequenceNumber": "24", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:18:57.992",

"faaReviewStartTms": "2012-03-06 10:18:57.189432", "intExt": "IP", "itemDesc":
 "Passenger Seat Tray Table Needs Adjustment", "itemNotes": "Disregard the ATA
 description code. This NEF code applies to all passenger seats; First Class, Business Elite,
 World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y",
 "itemNumber": "25-21-24", "lastUpdate": "2012-03-06 10:19:02.905797",
 "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
 "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
 "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
 "userIdDisplay": "00637639", "legacyFrc": "252124" }, { "sequenceNumber": "25",
 "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
 "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
 "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde":
 "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Tray table latch must
 be operational if not operational use NEF 25-21-26. Must not present hazard to passengers
 or crew or impede emergency egress.", "decisionInd": "A", "defRemarks": "Tray table latch
 must be operational if not operational use NEF 25-21-26. Must not present hazard to
 passengers or crew or impede emergency egress.", "efmTab": "S",
 "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2019-04-05 05:44:58.661211",
 "faaReviewStartTms": "2019-03-12 05:44:58.661211", "intExt": "IP", "itemDesc":
 "Passenger Seat Tray Table or Latch Damaged", "itemNotes": "Disregard the ATA
 description code. This NEF code applies to all passenger seats; Delta one ,First Class,
 Business Elite, World Business Class or Premium Economy or Coach Class seats.",
 "itemNotesInd": "Y", "itemNumber": "25-21-25", "lastUpdate": "2019-03-12
 05:45:03.876723", "lastUpdateDisplay": "03/12/2019", "legacyDeltaAirworthyInd": "N",
 "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
 "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
 "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
 ACARS", "userIdDisplay": "00823179", "legacyFrc": "252125" }, { "sequenceNumber": "26",
 "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A",
 "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
 "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde":
 "NEF", "crewDefInd": "N", "daysCount": "8", "deactMOProcedure": "Critical
 notes\n\nAccomplish ER/A 525535-14MA Rev C to install an INOP cover to secure the tray
 table and arms. INOP cover MPN 34000019// 56-2500-3-1248 . Cover must keep the Tray
 table completely closed. Must not present a hazard to passengers or crew or impede
 emergency egress.\n\nIf INOP cover is not available, tray table and arms MUST be
 removed. Must not present a hazard to passengers or crew or impede emergency egress.",

"decisionInd": "A", "defRemarks": "Critical notes\n\nAccomplish ER/A 525535-14MA Rev C to install an INOP cover to secure the tray table and arms. INOP cover MPN 34000019// 56-2500-3-1248 . Cover must keep the Tray table completely closed. Must not present a hazard to passengers or crew or impede emergency egress.\n\nIf INOP cover is not available, tray table and arms MUST be removed. Must not present a hazard to passengers or crew or impede emergency egress.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Republish with effectivity. No change to relief.", "faaContactName": ".", "faaReviewEndTms": "2026-06-14 12:18:14.678573", "faaReviewStartTms": "2026-05-21 12:18:14.678573", "intExt": "IP", "itemDesc": "Coach Class Passenger Seat Tray Table Inop", "itemNotes": "Disregard the ATA description code. This NEF code applies to Coach Class passenger seats only.\n\nWhen a meal tray table must be removed: 1. Part must be tagged with the MPN, AC #, and removal location 2. Part must be secured in the MCO pouch and documented in the log deferral 3. Email must be sent to Cabin Maintenance (cabin.mtc@delta.com) notifying of the meal tray removal and include the log page as reference This will help ensure parts are recovered and held until a permanent repair can be accomplished.", "itemNotesInd": "Y", "itemNumber": "25-21-26", "lastUpdate": "2026-05-21 12:33:51.748183", "lastUpdateDisplay": "05/21/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "252126" }, { "sequenceNumber": "27", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "PMI Frable accepted.", "faaContactName": "Biever", "faaReviewEndTms": "2018-10-19 06:20:47.319114", "faaReviewStartTms": "2018-09-25 06:20:47.319114", "intExt": "IP", "itemDesc": "Passenger Seat Tray Table Cosmetic Damage", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-27", "lastUpdate": "2018-09-25 09:22:57.488834", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252127" }, { "sequenceNumber": "28", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",

"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Wires must be secured and cover/wires must not present hazard to passenger. Component covers must be present.", "decisionInd": "A", "defRemarks": "Wires must be secured and cover/wires must not present hazard to passenger. Component covers must be present.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2019-10-25 12:49:31.752529", "faaReviewStartTms": "2019-10-01 12:49:31.752529", "intExt": "IP", "itemDesc": "Passenger Seat Under Seat Component Covers Damaged / Loose", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-28", "lastUpdate": "2019-10-01 12:49:57.561963", "lastUpdateDisplay": "10/01/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252128" }, { "sequenceNumber": "30", "creationDate": "11/15/2013 10:42:59", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to passengers or crew.", "decisionInd": "A", "defRemarks": "Must not present hazard to passengers or crew.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-08-22 08:19:00.241", "faaReviewStartTms": "2015-07-29 08:19:00.243028", "intExt": "IP", "itemDesc": "Passenger Seat Armrest Cover Damaged or Missing - Coach Only", "itemNotes": "For Damaged / Inop Armrest See MEL. For B/E & F/C seats see NEF 25-28-10 -\r\n\r\nPassenger Seat Armrest Cover / Trim Damaged or Missing - B/E & F/C only.\r\n\r\nThis FRC replaced 25-21-08.", "itemNotesInd": "Y", "itemNumber": "25-21-30", "lastUpdate": "2015-07-29 08:20:15.373908", "lastUpdateDisplay": "07/29/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-11-15 10:27:25.934812", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "000517467", "legacyFrc": "252130" }, { "sequenceNumber": "31", "creationDate": "02/14/2012 11:36:08", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF",

"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to passengers or crew or impede emergency egress.", "defRemarks": "Must not present hazard to passengers or crew or impede emergency egress.", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2018-04-15 11:12:44.182564",
"faaReviewStartTms": "2018-03-22 11:12:44.182564", "intExt": "IP", "itemDesc": "Inseat Video Monitor Trim Damaged / Missing", "itemNotes": "This item has a allowable limit of 365 days", "itemNotesInd": "Y", "itemNumber": "25-21-31", "lastUpdate": "2018-03-22 11:13:06.724034", "lastUpdateDisplay": "03/22/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000884040", "rowInsertEmpNoDisplay": "00884040",
"rowInsertTms": "2012-02-14 11:22:50.798609", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252131" }, { "sequenceNumber": "32", "creationDate": "09/11/2012 15:28:28", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Headrest assembly must be secure and follow the contour of the seat back. Must not present hazard to crew or impede emergency egress and the seat must be usable.", "decisionInd": "A", "defRemarks": "Headrest assembly must be secure and follow the contour of the seat back. Must not present hazard to crew or impede emergency egress and the seat must be usable.", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "May be inoperativable providing headrest is secured to follow the contour of the seat back.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2012-11-24 05:19:39.075", "faaReviewStartTms": "2012-10-31 05:19:39.078795", "intExt": "IP", "itemDesc": "Passenger Seat Headrest Broken", "itemNotesInd": "N", "itemNumber": "25-21-32", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "0920223", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2012-09-11 15:20:23.485599", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "252132" }, { "sequenceNumber": "33", "creationDate": "01/24/2014 09:44:01", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The literature pocket must be able to hold the required passenger safety material for the seat.", "decisionInd": "A", "defRemarks": "The literature pocket must be able to hold the required passenger safety

material for the seat.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-04-10 14:41:28.432",
"faaReviewStartTms": "2014-03-17 14:41:28.431203", "intExt": "IP", "itemDesc":
"Passenger Seat Literature Pocket Spring Damaged/Missing", "itemNotes": "Disregard the
ATA description code. This NEF code applies to all passenger seats; First Class, Business
Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd":
"Y", "itemNumber": "25-21-33", "lastUpdate": "2014-03-18 07:44:23.026313",
"lastUpdateDisplay": "03/18/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-01-24
09:38:44.317154", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "252133" },
{ "sequenceNumber": "34", "creationDate": "01/24/2014 10:25:27", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2018-12-14 07:20:41.00207", "faaReviewStartTms":
"2018-11-20 07:20:41.00207", "intExt": "IP", "itemDesc": "Passenger Seat Armrest
Cover/Trim Worn/Cosmetic Damage/Incorrect Color", "itemNotes": "Disregard the ATA
description code. This NEF code applies to all passenger seats; First Class, Business Elite,
World Business Class or Premium Economy or Coach Class seats. Allowable time limit for
this NEF is 365 days . \n\nThis FRC replaced 25-21-08.", "itemNotesInd": "Y",
"itemNumber": "25-21-34", "lastUpdate": "2018-11-20 07:20:44.923532",
"lastUpdateDisplay": "11/20/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-01-24
10:13:12.735517", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252134" },
{ "sequenceNumber": "35", "creationDate": "05/13/2014 16:34:17", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "(M) Procedure Required:\n\n1. Disconnect, cap and stow monitor
harness at Seat Electronics Box for affected monitor per AMM.\n\nThe flight crew can
reference this deactivation procedure in the EFM procedures section.", "defRemarks": "(M)
Procedure Required:\n\n1. Disconnect, cap and stow monitor harness at Seat Electronics
Box for affected monitor per AMM.\n\nThe flight crew can reference this deactivation

procedure in the EFM procedures section.", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaContactName": ".", "faaReviewEndTms": "2019-03-23 10:31:43.411717", "faaReviewStartTms": "2019-02-27 10:31:43.411717", "ifeltItem": "IFE", "intExt": "IP", "itemDesc": "Inseat Video Arms Damaged / Inoperative", "itemNotesInd": "N", "itemNumber": "25-21-35", "lastUpdate": "2019-02-27 10:31:46.267266", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-05-13 16:26:15.482287", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252135" }, { "sequenceNumber": "36", "creationDate": "11/06/2014 13:39:03", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-04-17 14:54:08.206", "faaReviewStartTms": "2015-03-24 14:54:08.209614", "intExt": "IP", "itemDesc": "Passenger Seat Headrest Cover Missing/Torn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-36", "lastUpdate": "2015-03-24 14:54:12.765062", "lastUpdateDisplay": "03/24/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-06 13:31:47.436291", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "252136" }, { "sequenceNumber": "37", "creationDate": "11/06/2014 13:52:36", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-04-17 14:57:31.551", "faaReviewStartTms": "2015-03-24 14:57:31.556752", "intExt": "IP", "itemDesc": "Passenger Seat Headrest Damaged/Torn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-37", "lastUpdate": "2015-03-24 14:57:34.916981", "lastUpdateDisplay": "03/24/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",

"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-06 13:38:25.851463",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "252137" },
{ "sequenceNumber": "38", "creationDate": "11/06/2014 14:01:29", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Damage must not be to an extent that it leaves an opening that
items could fall into or that would be a security concern.", "defRemarks": "Damage must
not be to an extent that it leaves an opening that items could fall into or that would be a
security concern.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms":
"2015-04-17 15:23:27.598", "faaReviewStartTms": "2015-03-24 15:23:27.602641", "intExt":
"IP", "itemDesc": "Passenger Seat Tray Book Holder Damaged", "itemNotes": "Some
aircraft configurations now have a book holder built into the tray table, with a flip up
holder.", "itemNotesInd": "Y", "itemNumber": "25-21-38", "lastUpdate": "2015-03-24
15:23:30.976636", "lastUpdateDisplay": "03/24/2015", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2014-11-06 13:46:05.924705", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00637639", "legacyFrc": "252138" }, { "sequenceNumber": "39", "creationDate":
"11/06/2014 13:57:20", "userId": "0000517467", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class
Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to
passengers or crew or impede emergency egress.", "decisionInd": "A", "defRemarks":
"Must not present hazard to passengers or crew or impede emergency egress.", "efmTab":
"S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Approved during list integration
and initial approval.", "faaContactName": "Initial list", "faaReviewEndTms": "2015-08-23
07:59:22.026", "faaReviewStartTms": "2015-07-30 07:59:22.028708", "intExt": "IP",
"itemDesc": "Passenger Seat Trim Damaged/Missing", "itemNotes": "This FRC replaced 25-
20-11.", "itemNotesInd": "Y", "itemNumber": "25-21-39", "lastUpdate": "2015-08-12
12:22:58.708795", "lastUpdateDisplay": "08/12/2015", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2014-11-06 13:51:56.324072", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":

"00517467", "legacyFrc": "252139" }, { "sequenceNumber": "40", "creationDate": "11/06/2014 14:00:40", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-04-17 15:36:34.939", "faaReviewStartTms": "2015-03-24 15:36:34.941317", "intExt": "IP", "itemDesc": "Passenger Seat Foot Rest Cover Damaged/Torn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-40", "lastUpdate": "2015-03-24 15:36:38.43228", "lastUpdateDisplay": "03/24/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-06 13:59:13.087372", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "252140" }, { "sequenceNumber": "41", "creationDate": "11/12/2014 15:47:45", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-19 07:11:05.512965", "faaReviewStartTms": "2018-09-25 07:11:05.512965", "intExt": "IP", "itemDesc": "Passenger Seat Headrest Cover Worn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-41", "lastUpdate": "2018-09-25 09:23:06.42553", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 15:32:10.935126", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252141" }, { "sequenceNumber": "42", "creationDate": "11/12/2014 15:51:44", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName":

"Hoogenhout", "faaReviewEndTms": "2018-10-19 07:16:03.14642", "faaReviewStartTms": "2018-09-25 07:16:03.14642", "intExt": "IP", "itemDesc": "Passenger Seat Foot Rest Cover Worn", "itemNotesInd": "N", "itemNumber": "25-21-42", "lastUpdate": "2018-09-25 09:23:10.366119", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 15:38:18.806542", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252142" }, { "sequenceNumber": "44", "creationDate": "11/12/2014 15:57:03", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:33:10.019948", "faaReviewStartTms": "2018-01-29 13:33:10.019948", "intExt": "IP", "itemDesc": "Passenger Seat LEATHER Literature Pocket Damaged/Torn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats that have LEATHER literature seat pockets; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-21-44", "lastUpdate": "2018-02-22 05:47:53.495392", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 15:43:50.793461", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252144" }, { "sequenceNumber": "45", "creationDate": "11/12/2014 16:02:50", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-19 07:21:43.958338", "faaReviewStartTms": "2018-09-25 07:21:43.958338", "intExt": "IP", "itemDesc": "Passenger Seat LEATHER Literature Pocket Worn", "itemNotes": "Disregard the ATA description code. This NEF code applies to all passenger seats that have LEATHER literature pockets; First Class, Business Elite, World Business Class or Premium Economy or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-21-45", "lastUpdate": "2018-09-25 09:23:14.528519",

"lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12
15:49:15.815419", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252145" },
{ "sequenceNumber": "46", "creationDate": "11/12/2014 15:58:32", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2026-01-02 08:25:17.562793", "faaReviewStartTms":
"2025-12-09 08:25:17.562793", "intExt": "IP", "itemDesc": "Passenger Seat
Cushions/Covers Damaged/Torn", "itemNotes": "If torn, may need to apply MEL for
inoperative seat. For this item if it is or torn, replace at next available overnight. Disregard
the ATA description code. This NEF code applies to all passenger seats; First Class,
Business Elite, World Business Class or Premium Economy or Coach Class seats. \n\nThis
FRC replaced 25-21-12.", "itemNotesInd": "Y", "itemNumber": "25-21-46", "lastUpdate":
"2025-12-09 08:25:27.125452", "lastUpdateDisplay": "12/09/2025",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 15:52:03.389768",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252146" },
{ "sequenceNumber": "48", "creationDate": "01/31/2016 09:27:32", "userId":
"0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Ensure that the seat belt extensions can be stowed securely in the
same compartment that the seat belt extension storage pouch is/should be located in.",
"decisionInd": "A", "defRemarks": "Ensure that the seat belt extensions can be stowed
securely in the same compartment that the seat belt extension storage pouch is/should be
located in.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2017-02-26 07:46:03.075", "faaReviewStartTms":
"2017-02-02 07:46:05.446113", "intExt": "IP", "itemDesc": "Seat Belt Extension Storage
Pouch Missing/Damaged.", "itemNotes": "This item is for the seat belt extension storage
pouch. Use item 25-21-17 for missing seat belt extensions.", "itemNotesInd": "Y",
"itemNumber": "25-21-48", "lastUpdate": "2017-02-02 07:46:12.784275",
"lastUpdateDisplay": "02/02/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",

"logpageNumber": "2333346", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000342071", "rowInsertEmpNoDisplay": "00342071", "rowInsertTms": "2016-01-31 09:26:43.49128", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00517467", "legacyFrc": "252148" }, { "sequenceNumber": "58", "creationDate": "10/17/2011 14:15:36", "userId": "0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "All other seat controls must work normally except for the \"Sleep\" control.", "decisionInd": "A", "defRemarks": "All other seat controls must work normally except for the \"Sleep\" control.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Biever", "faaReviewEndTms": "2020-01-19 13:09:44.394093", "faaReviewStartTms": "2019-12-26 13:09:44.394093", "intExt": "IP", "itemDesc": "Delta One Seat Land Control Inoperative", "itemNotes": "The \"Land\" control allows the seat to fully retract to the full upright position with one control. Other seat controls can be used to perform the same function as the land control. Disregard the ATA description code, this NEF code applies to Delta One seats.", "itemNotesInd": "Y", "itemNumber": "25-21-58", "lastUpdate": "2019-12-26 13:09:49.858098", "lastUpdateDisplay": "12/26/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-10-17 14:15:36.363", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00406009", "legacyFrc": "252158" }, { "sequenceNumber": "60", "creationDate": "10/17/2011 14:15:36", "userId": "0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "All other seat controls must work normally except for the \"Land\" control.", "decisionInd": "A", "defRemarks": "All other seat controls must work normally except for the \"Land\" control.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Biever", "faaReviewEndTms": "2020-01-19 13:10:38.765897", "faaReviewStartTms": "2019-12-26 13:10:38.765897", "intExt": "IP", "itemDesc": "Delta One Sleep Control Inoperative", "itemNotes": "The \"Sleep\" control allows the seat to fully recline with one control. Other seat controls can be used to perform the same function as the sleep control. Disregard the ATA description code, this NEF code applies to Delta One seats.", "itemNotesInd": "Y", "itemNumber": "25-21-60", "lastUpdate": "2019-12-26 13:10:47.28215", "lastUpdateDisplay": "12/26/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-10-17 14:15:36.363", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00406009", "legacyFrc": "252160" }, { "sequenceNumber": "67", "creationDate": "05/18/2020 11:34:50", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Delta One Suite SECONDARY PCU may be inoperative provided:\n- Primary PCU is operative,\n- All recline/lumbar/foot rest/lighting features are operative or deferred via the applicable MEL/NEF,\n- No damaged wires or exposed EWIS, and\n- No sharp edges or hazards to personnel.", "decisionInd": "A", "defRemarks": "Delta One Suite SECONDARY PCU may be inoperative provided:\n- Primary PCU is operative,\n- All recline/lumbar/foot rest/lighting features are operative or deferred via the applicable MEL/NEF,\n- No damaged wires or exposed EWIS, and\n- No sharp edges or hazards to personnel.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2020-06-12 05:50:10.343661", "faaReviewStartTms": "2020-05-19 05:50:10.343661", "intExt": "IP", "itemDesc": "Delta One Suite - SECONDARY PCU Inoperative - Recline/Foot Rest Controls (A350/B777/B764)", "itemNotes": "Secondary Passenger Control Unit (PCU) is the small lower PCU.", "itemNotesInd": "Y", "itemNumber": "25-21-67", "lastUpdate": "2020-05-19 08:07:41.078768", "lastUpdateDisplay": "05/19/2020", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2020-05-18 11:28:58.352978", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252167" }, { "sequenceNumber": "70", "creationDate": "04/13/2026 14:03:06", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Tourist Class Passenger Seats/Belts/Traytables", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "For seat belt TSO tag only. Do not use for any other discrepancies on the seat belt. The deferred seatbelt may remain installed, but once the seatbelt is removed, the seatbelt is not authorized for re-installation without a TSO tag. This NEF is only authorized for seatbelts currently installed on-wing.", "defRemarks": "For seat belt TSO tag only. Do not use for any other discrepancies on the seat belt. The deferred seatbelt may remain installed, but once the seatbelt is removed, the seatbelt is not authorized for re-installation without a TSO tag. This NEF is only authorized for seatbelts currently installed on-wing.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Dan Ratcliff", "faaReviewEndTms": "2026-05-10 10:01:30.735198", "faaReviewStartTms": "2026-04-16 10:01:30.735198",

"intExt": "IP", "itemDesc": "Seatbelt TSO Tags Worn or Missing", "itemNotesInd": "N",
"itemNumber": "25-21-70", "lastUpdate": "2026-04-16 10:02:12.805039",
"lastUpdateDisplay": "04/16/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000700872", "rowInsertEmpNoDisplay": "00700872", "rowInsertTms": "2026-04-13
13:59:37.209376", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00700872", "legacyFrc": "252170" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window",
"ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "DO NOT USE ON OVERWING EXIT SHADES- SEE BELOW. CAUTION
WHEN USING NEF ON CREW REST RESTS- SEE BELOW\n\n**Over wing exit shades are to
be deferred under NEF 25-22-11. Due to 14 CFR 25.809(Emergency exit arrangement) the
over wing exit shade must not be stuck closed. If these shades are stuck in the closed
position, the shade must be removed.\n\n"IF SHADE IS REMOVED OR MISSING AT A
CREW REST SEAT, FWD THE SEAT TO MEL" CONTACT MCC FOR CREW REST SEAT
LOCATIONS ", "decisionInd": "A", "defRemarks": "DO NOT USE ON OVERWING EXIT
SHADES- SEE BELOW. CAUTION WHEN USING NEF ON CREW REST RESTS- SEE
BELOW\n\nOver wing exit shades are to be deferred under NEF 25-22-11. Due to 14 CFR
25.809(Emergency exit arrangement) the over wing exit shade must not be stuck closed. If
these shades are stuck in the closed position, the shade must be removed.*\n\n**IF
SHADE IS REMOVED OR MISSING AT A CREW REST SEAT, FWD THE SEAT TO MEL"
CONTACT MCC FOR CREW REST SEAT LOCATIONS ", "efmTab": "W",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Amended to address VDRP.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-12-03 06:16:51.682608",
"faaReviewStartTms": "2018-11-09 06:16:51.682608", "intExt": "IP", "itemDesc": "Cabin
Window Shade Stuck / Damaged / Missing (NOT FOR OVER WING EXIT SHADE)",
"itemNotes": "DO NOT USE ON OVERWING EXIT SHADES- SEE BELOW. CAUTION WHEN
USING NEF ON CREW REST RESTS- SEE BELOW\n\nOver wing exit shades are to be
deferred under NEF 25-22-11. Due to 14 CFR 25.809(Emergency exit arrangement) the
over wing exit shade must not be stuck closed. If these shades are stuck in the closed
position, the shade must be removed.*\n\n"IF SHADE IS REMOVED OR MISSING AT A
CREW REST SEAT, FWD THE SEAT TO MEL" CONTACT MCC FOR CREW REST SEAT
LOCATIONS ", "itemNotesInd": "Y", "itemNumber": "25-22-01", "lastUpdate": "2018-12-04
12:29:23.574956", "lastUpdateDisplay": "12/04/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":

"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252201" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-28 09:13:50.636862", "faaReviewStartTms": "2026-05-04 09:13:50.636862", "intExt": "IP", "itemDesc": "Sidewall Panel Damaged", "itemNotes": "This NEF item has a 365 day allowable time limit.\n\nThis NEF does not include the cabin decompression flaps on 330 Dado panels. The center decompression flaps must be closed with no gaps. If panel has been actuated, it can be reset per A330 AMM.", "itemNotesInd": "Y", "itemNumber": "25-22-03", "lastUpdate": "2026-05-04 09:16:34.94189", "lastUpdateDisplay": "05/04/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "252203" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-28 09:11:38.428261", "faaReviewStartTms": "2026-05-04 09:11:38.428261", "intExt": "IP", "itemDesc": "Wall Covering Torn, Damaged or Missing", "itemNotes": "This NEF item does not include return air grills.\n\nThis NEF does not include the cabin decompression flaps on 330 Dado panels. The center decompression flaps must be closed with no gaps. If panel has been actuated, it can be reset per A330 AMM.\n\nThis NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-22-05", "lastUpdate": "2026-05-04

09:17:15.150376", "lastUpdateDisplay": "05/04/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "252205" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "W", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:12.405534", "faaReviewStartTms": "2011-12-09 12:37:12.405534", "intExt": "IP", "itemDesc": "Window Cover Trim Damaged", "itemNotesInd": "N", "itemNumber": "25-22-06", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "252206" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "If window trim cover is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "decisionInd": "A", "defRemarks": "If window trim cover is missing and leaves hole exposed, inspect for foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not masking tape).", "efmTab": "W", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-09-06 09:51:39.92", "faaReviewStartTms": "2012-08-13 09:51:39.230883", "intExt": "IP", "itemDesc": "Window Cover Trim Missing", "itemNotes": "This NEF item has a 10 day allowable time limit. If the window shade is missing use NEF 25-22-01 - Cabin Window Shade Stuck / Damaged / Missing.", "itemNotesInd": "Y", "itemNumber": "25-22-07", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "252207" }, { "sequenceNumber": "08", "creationDate": "02/14/2012 11:21:42", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:57:44.353356", "faaReviewStartTms": "2018-01-29 13:57:44.353356", "ifeltItem": "IFE", "intExt": "IP", "itemDesc": "Overhead / Wall Mounted Video Monitor Trim Damaged", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-22-08", "lastUpdate": "2018-02-22 05:48:37.419403", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000884040", "rowInsertEmpNoDisplay": "00884040", "rowInsertTms": "2012-02-14 11:12:19.563376", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252208" }, { "sequenceNumber": "10", "creationDate": "02/21/2013 20:04:57", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The cabin lower sidewall panels must be secure and there must be no gaps between the panels.", "decisionInd": "A", "defRemarks": "The cabin lower sidewall panels must be secure and there must be no gaps between the panels.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2015-08-16 13:48:07.668", "faaReviewStartTms": "2015-07-23 13:48:07.66931", "intExt": "IP", "itemDesc": "Cabin Lower Sidewall Panel Connecting Strip Damaged/Missing", "itemNotes": "The connector is the vertical plastic trim that goes between the cabin lower sidewall panels. Cabin lower sidewall panels are also called carpet risers.", "itemNotesInd": "Y", "itemNumber": "25-22-10", "lastUpdate": "2015-07-23 13:48:24.447695", "lastUpdateDisplay": "07/23/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "2213022", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-02-21 19:55:09.588185", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00517467", "legacyFrc": "252210" }, { "sequenceNumber": "11", "creationDate": "11/09/2018 06:21:02", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Ceiling/Wall

Lining/Window Shade/Inner Window", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "For 767-300 only a placard MPN 11-1158-501 (stk # 00-0812-3-4910) must be installed on each location that this NEF is used. If placard is not in stock in station please reference ERA 573465-14MA for placard replication. Location of placard can be placed any where on the exit door that is not on an existing placard and not on the clear plastic/ shade itself. The placard location must be noticeable for the passenger, crew, and maintenance for easy identification when the item is on deferral and when cleared.", "decisionInd": "A", "defRemarks": "For 767-300 only a placard MPN 11-1158-501 (stk # 00-0812-3-4910) must be installed on each location that this NEF is used. If placard is not in stock in station please reference ERA 573465-14MA for placard replication. Location of placard can be placed any where on the exit door that is not on an existing placard and not on the clear plastic/ shade itself. The placard location must be noticeable for the passenger, crew, and maintenance for easy identification when the item is on deferral and when cleared.", "efmTab": "W", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added to address VDRP.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-08-04 11:54:18.348358", "faaReviewStartTms": "2019-07-11 11:54:18.348358", "intExt": "IP", "itemDesc": "Overwing EXIT WINDOW(ONLY) Shade Stuck OPEN / Damaged / Missing(Placard needed for 767-300 only see deferral remarks)", "itemNotes": "NEF USE IS FOR OVERWING EXIT ONLY. SHADE MUST NOT BE STUCK CLOSED -SEE BELOW. DO NOT USE NEF FOR ANY OTHER CABIN SHADE. All other cabin locations are to be deferred under NEF 25-22-01.\n\nREGULATORY REQUIREMENT\n14 CFR 25.809 states \u001Aeach emergency exit must have means to permit viewing of the conditions outside the exit when the exit is closed\u001A. To comply with this regulation, this NEF prohibits the deferral of an overwing exit shade stuck in the closed position. If overwing exit window shades are stuck in the closed position, the shade must be removed prior to using this NEF deferral.", "itemNotesInd": "Y", "itemNumber": "25-22-11", "lastUpdate": "2019-07-11 11:54:30.661802", "lastUpdateDisplay": "07/11/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2018-11-09 06:16:39.263509", "sceptreAutoDefRemarks": "AUTO GENERATED LOG CTL VIA ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252211" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Any Exposed Wiring Must Be Protected. Must not present hazard to passengers or crew or impede emergency egress.", "decisionInd": "A", "defRemarks": "Any Exposed Wiring Must

Be Protected. Must not present hazard to passengers or crew or impede emergency egress.", "efmTab": "U", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2015-04-17 16:08:05.719", "faaReviewStartTms": "2015-03-24 16:08:05.718274", "intExt": "IP", "itemDesc": "Seat Track Covers Damaged, Loose or Missing", "itemNotesInd": "N", "itemNumber": "25-23-04", "lastUpdate": "2015-03-24 16:08:10.489549", "lastUpdateDisplay": "03/24/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "252304" }, { "sequenceNumber": "05", "creationDate": "08/02/2013 14:10:32", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If the trim is in poor condition, secure the trim and defer for later replacement. If the trim is damaged and cannot be reinstalled or is missing, apply tamper-evident security seal to prevent unauthorized access between one side of the E/E compartment door and the floor.", "decisionInd": "A", "defRemarks": "If the trim is in poor condition, secure the trim and defer for later replacement. If the trim is damaged and cannot be reinstalled or is missing, apply tamper-evident security seal to prevent unauthorized access between one side of the E/E compartment door and the floor.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:47:46.673563", "faaReviewStartTms": "2022-03-08 08:47:46.673563", "intExt": "IP", "itemDesc": "Cabin E/E Hatch Cover Trim Poor Condition/Damaged/Missing", "itemNotes": "This NEF item has a 10 day allowable time limit. Blue and white security tamper-evident security seal part number 0412-20248 may be used.", "itemNotesInd": "Y", "itemNumber": "25-23-05", "lastUpdate": "2022-03-08 08:47:52.456125", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5075539", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000910407", "rowInsertEmpNoDisplay": "00910407", "rowInsertTms": "2013-08-02 14:00:50.582223", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252305" }, { "sequenceNumber": "07", "creationDate": "11/17/2014 09:36:21", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "decisionInd": "A", "defRemarks": "May be worn, frayed, torn, damaged, loose, missing (must not present

hazard to pax/crew or impede emergency egress).", "efmTab": "U",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-01-06 06:08:48.123394",
"faaReviewStartTms": "2018-12-13 06:08:48.123394", "intExt": "IP", "itemDesc": "Cabin
Carpet (Other than Aisle and Cross-Aisle) Worn/Torn/Frayed/Missing(For gum or soiled use
CTL 25-23-06)", "itemNotes": "For aisle and cross-aisle carpet use NEF code 25-23-10. This
code is for all cabin carpet except aisle and cross-aisle carpet.\n\nFor flight deck flooring
reference NEF 25-10-53 - Deck Floor Coverings Worn / Damaged / Missing.\n\nFor any dirty
Carpet (soiled/Gum) use CTL 25-23-06.\n\nThis FRC replaced 25-23-01.This NEF item has
a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-23-07",
"lastUpdate": "2018-12-13 06:08:51.988308", "lastUpdateDisplay": "12/13/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-17 09:35:29.52736",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252307" },
{ "sequenceNumber": "08", "creationDate": "11/17/2014 09:48:36", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be
worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or
impede emergency egress).", "decisionInd": "A", "defRemarks": "May be worn, frayed, torn,
damaged, loose, missing (must not present hazard to pax/crew or impede emergency
egress).", "efmTab": "U", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2018-02-22 13:58:58.539549", "faaReviewStartTms":
"2018-01-29 13:58:58.539549", "intExt": "IP", "itemDesc": "Lavatory Flooring
Damaged/Worn", "itemNotes": "For flight deck flooring reference NEF 25-10-53 - Deck
Floor Coverings Worn / Damaged / Missing.\n\nThis FRC replaced 25-23-01.This NEF item
has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-23-08",
"lastUpdate": "2018-09-25 09:23:24.609769", "lastUpdateDisplay": "09/25/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-17 09:39:15.561194",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252308" },
{ "sequenceNumber": "09", "creationDate": "11/17/2014 09:51:38", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23",

"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "decisionInd": "A", "defRemarks": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "efmTab": "U", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:59:23.311282", "faaReviewStartTms": "2018-01-29 13:59:23.311282", "intExt": "IP", "itemDesc": "Vinyl Flooring Damaged/Worn/Missing", "itemNotes": "Vinyl flooring is used in the galley and entry ways. Also known as NTF.\n\nFor flight deck flooring reference NEF 25-10-53 - Deck Floor Coverings Worn / Damaged / Missing.\n\nThis FRC replaced 25-23-01.This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-23-09", "lastUpdate": "2018-09-25 09:23:27.528407", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-17 09:41:58.580099", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252309" }, { "sequenceNumber": "10", "creationDate": "01/13/2016 12:01:26", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "decisionInd": "A", "defRemarks": "May be worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or impede emergency egress).", "efmTab": "U", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-01-06 06:10:04.133133", "faaReviewStartTms": "2018-12-13 06:10:04.133133", "intExt": "IP", "itemDesc": "Cabin Carpet (Aisle and Cross-Aisle) Worn/Torn/Frayed/Missing(For gum or soiled use CTL 25-23-06)", "itemNotes": "This code is for the cabin aisle and cross-aisle carpet only. For all other cabin carpet use NEF code 25-23-07.\n\nFor flight deck flooring reference NEF 25-10-53 - Deck Floor Coverings Worn / Damaged / Missing.\n\nFor any dirty Carpet (soiled/Gum) use CTL 25-23-06.\n\nThis FRC and 25-23-07 replaced 25-23-01.This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-23-10", "lastUpdate": "2018-12-13 06:10:09.514385", "lastUpdateDisplay": "12/13/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-01-13 11:59:45.101791", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252310" },
{ "sequenceNumber": "13", "creationDate": "12/24/2019 10:37:57", "userId":
"0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Cabin Floor coverings", "ataSectCode": "23",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure":
"Applicable only for P/N 17230AA Trim Assy (post-ER/A 523335-14MA)\n\u001A Verify no
tape, carpet, or other obstructions are installed across gap between the LLCR Secondary
Escape Hatch and Floor Structure\n\u001A Verify edges of carpet are secure and not a trip
hazard\n\u001A Accomplish an Operational Check of the LLCR Hatch per AMM 25-29 prior
to deferral", "decisionInd": "A", "defRemarks": "Applicable only for P/N 17230AA Trim Assy
(post-ER/A 523335-14MA)\n\u001A Verify no tape, carpet, or other obstructions are
installed across gap between the LLCR Secondary Escape Hatch and Floor
Structure\n\u001A Verify edges of carpet are secure and not a trip hazard\n\u001A
Accomplish an Operational Check of the LLCR Hatch per AMM 25-29 prior to deferral",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2020-02-14 08:35:56.097237", "faaReviewStartTms": "2020-01-21
08:35:56.097237", "intExt": "IP", "itemDesc": "B767 Secondary Escape Hatch Edge Trim
Damaged/Missing", "itemNotes": "This applies only to the B767-300/400. Lower Lobe Crew
Rest (LLCR) Secondary Escape Hatch plastic carpet-edge trim pieces (P/N 17230AA,
installed by ER/A 523335-14MA) may be degraded or missing, so long as there is no
interference with hatch operation, and the broken edges do not pose a hazard to
passengers or crew.", "itemNotesInd": "Y", "itemNumber": "25-23-13", "lastUpdate":
"2020-01-21 08:36:02.701669", "lastUpdateDisplay": "01/21/2020",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oi": "N", "rowInsertEmpNo": "0000694555",
"rowInsertEmpNoDisplay": "00694555", "rowInsertTms": "2019-12-24 10:29:01.536506",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00406009", "legacyFrc": "252313" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Partitions/Curtains", "ataSectCode": "24",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be
worn, frayed, torn, damaged, loose, missing (must not present hazard to pax/crew or
impede emergency egress). If tieback is missing secure curtains open or remove and store
in closet.", "decisionInd": "A", "defRemarks": "May be worn, frayed, torn, damaged, loose,
missing (must not present hazard to pax/crew or impede emergency egress). If tieback is
missing secure curtains open or remove and store in closet.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved

list.", "faaContactName": ".", "faaReviewEndTms": "2018-10-19 08:17:58.907901",
"faaReviewStartTms": "2018-09-25 08:17:58.907901", "intExt": "IP", "itemDesc": "Cabin
Curtain Tiebacks Damaged or Missing", "itemNotesInd": "N", "itemNumber": "25-24-01",
"lastUpdate": "2018-09-25 09:23:30.815749", "lastUpdateDisplay": "09/25/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252401" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Partitions/Curtains", "ataSectCode": "24",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "May be
inoperative in open position or with window removed. To remove window:\n\n1. Remove 4
mounting screws from window frame and remove frame.\n2. Remove window from the
divider.\n3. Re-install frame and mounting screws into divider.\n4. Placard window \"MUST
REMAIN WITH AIRPLANE\" and stow in available closet.", "decisionInd": "A", "defRemarks":
"May be inoperative in open position or with window removed. To remove window:\n\n1.
Remove 4 mounting screws from window frame and remove frame.\n2. Remove window
from the divider.\n3. Re-install frame and mounting screws into divider.\n4. Placard
window \"MUST REMAIN WITH AIRPLANE\" and stow in available closet.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Moved from A319 to 757.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:47:49.452291",
"faaReviewStartTms": "2023-11-16 06:47:49.452291", "intExt": "IP", "itemDesc": "Direct
View bulkhead Window - 757 NBA Config/330 only", "itemNotes": "This NEF item applies
only to the 757 NBA/330 only configured aircraft that have Direct View bulkhead Window.",
"itemNotesInd": "Y", "itemNumber": "25-24-03", "lastUpdate": "2023-11-16
06:47:59.874865", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "252403" }, { "sequenceNumber": "04",
"creationDate": "03/10/2015 14:30:55", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Partitions/Curtains", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Must not present hazard to pax/crew or impede
emergency egress.\n\nAny emergency exit markings, instructions and/or signs must be
present and legible on cabin dividers or curtains. If emergency exit markings, instructions
and/or signs are missing, do not defer to NEF, contact the MCC.", "decisionInd": "A",

"defRemarks": "Must not present hazard to pax/crew or impede emergency egress.\n\nAny emergency exit markings, instructions and/or signs must be present and legible on cabin dividers or curtains. If emergency exit markings, instructions and/or signs are missing, do not defer to NEF, contact the MCC.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Remarks amended.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:48:54.036821", "faaReviewStartTms": "2023-11-16 06:48:54.036821", "intExt": "IP", "itemDesc": "Cabin Dividers/Curtains Frayed/Worn", "itemNotes": "This FRC replaces 25-24-02.", "itemNotesInd": "Y", "itemNumber": "25-24-04", "lastUpdate": "2023-11-16 06:49:09.002605", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2015-03-10 14:21:48.547823", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252404" }, { "sequenceNumber": "05", "creationDate": "03/10/2015 14:41:10", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Partitions/Curtains", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "DO NOT REMOVE CABIN DIVIDERS FROM B717 AIRCRAFT. CONTACT MCC IF MISSING AND DO NOT DEFER USING THIS NEF **** \nFor Crew Rest Curtains, check the applicable MEL for relief**\nMust not present hazard to pax/crew or impede emergency egress.\nAny emergency exit markings,instructions and/or signs must be present and legible on cabin dividers or curtains. Pay particular attention to B717.\nMarkings/placards are to be verified prior to removal of any part. If emergency exit markings, instructions and/or signs are missing, DO NOT DEFFER to NEF contact the MCC. \nIf divider to be removed contains non-FAA required placards a second NEF(11-30-11) must be made.", "decisionInd": "A", "defRemarks": "DO NOT REMOVE CABIN DIVIDERS FROM B717 AIRCRAFT. CONTACT MCC IF MISSING AND DO NOT DEFER USING THIS NEF **** \nFor Crew Rest Curtains, check the applicable MEL for relief*\nMust not present hazard to pax/crew or impede emergency egress.\nAny emergency exit markings,instructions and/or signs must be present and legible on cabin dividers or curtains. Pay particular attention to B717.\nMarkings/placards are to be verified prior to removal of any part. If emergency exit markings, instructions and/or signs are missing, DO NOT DEFFER to NEF contact the MCC. \nIf divider to be removed contains non-FAA required placards a second NEF(11-30-11) must be made.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Remarks amended.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-02-14 14:17:07.987221", "faaReviewStartTms": "2021-01-21 14:17:07.987221", "intExt": "IP", "itemDesc": "Cabin Dividers/Curtains Damaged/Loose/Torn/Missing (Missing Dividers N/A to B717)",

"itemNotes": "This FRC replaces 25-24-02.", "itemNotesInd": "Y", "itemNumber": "25-24-05", "lastUpdate": "2021-01-21 14:17:25.234361", "lastUpdateDisplay": "01/21/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2015-03-10 14:25:19.951871", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252405" }, { "sequenceNumber": "08", "creationDate": "06/05/2025 12:29:04", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Partitions/Curtains", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Ensure locking mechanism for securing the privacy partitions are functional.", "decisionInd": "A", "defRemarks": "Ensure locking mechanism for securing the privacy partitions are functional.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-06-29 14:50:59.789341", "faaReviewStartTms": "2025-06-05 14:50:59.789341", "intExt": "IL", "itemDesc": "L4 Lavatory Privacy Partition Retention Straps (764 ONLY)", "itemNotesInd": "N", "itemNumber": "25-24-08", "lastUpdate": "2025-06-09 13:49:49.512922", "lastUpdateDisplay": "06/09/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-06-05 12:12:51.973451", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252408" }, { "sequenceNumber": "02", "creationDate": "05/11/2016 08:30:17", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Attendant Seats/Belts", "ataSectCode": "25", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Verify the seat pan can still be deployed with a reasonable amount of force without the secondary seat deployment handle.", "decisionInd": "A", "defRemarks": "Verify the seat pan can still be deployed with a reasonable amount of force without the secondary seat deployment handle.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2016-06-10 13:15:45.09", "faaReviewStartTms": "2016-05-17 13:15:45.089087", "intExt": "IP", "itemDesc": "Aft Flight Attendant Seat Deployment Assist Handle Damaged / Missing (B717 Only)", "itemNotes": "Applicable to the convenience handles installed on the seat pan per AA 2520-01906 which helps the flight attendant deploy the seat.", "itemNotesInd": "Y", "itemNumber": "25-25-02", "lastUpdate": "2016-05-18 08:02:35.53498", "lastUpdateDisplay": "05/18/2016", "legacyDeltaAirworthyInd": "N",

"logMultiplicity": "M", "logpageNumber": "8531938", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000877748", "rowInsertEmpNoDisplay": "00877748",
"rowInsertTms": "2016-05-11 08:23:07.430733", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00517467", "legacyFrc": "252502" }, { "sequenceNumber": "04", "creationDate":
"12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Attendant
Seats/Belts", "ataSectCode": "25", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":
"0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-04-28 13:46:54.629429",
"faaReviewStartTms": "2018-04-04 13:46:54.629429", "intExt": "IP", "itemDesc": "Flight
Attendant Seat Trim/Covering Damaged/Torn/Missing", "itemNotes": "This FRC to be
replaced by 25-25-09, 25-25-10, 25-25-12 and 25-25-13 when EFM rev 2 is published and
boarded on all fleets.", "itemNotesInd": "Y", "itemNumber": "25-25-04", "lastUpdate":
"2018-04-04 13:47:12.109745", "lastUpdateDisplay": "04/04/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252504" },
{ "sequenceNumber": "10", "creationDate": "11/15/2013 09:49:10", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Attendant Seats/Belts", "ataSectCode": "25",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Must
not present hazard to passengers or crew or impede emergency egress.", "decisionInd":
"A", "defRemarks": "Must not present hazard to passengers or crew or impede emergency
egress.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted
11/13/14, Description change.", "faaContactName": "Hoogenhout", "faaReviewEndTms":
"2014-11-27 15:05:30.828", "faaReviewStartTms": "2014-11-03 15:05:30.82843", "intExt":
"IP", "itemDesc": "Flight Attendant Jumpseat Trim Damaged/Torn/Missing", "itemNotes":
"Reference NEF 25-25-09 for Flight Attendant seat cushions and coverings.",
"itemNotesInd": "Y", "itemNumber": "25-25-10", "lastUpdate": "2014-11-13
08:06:06.344681", "lastUpdateDisplay": "11/13/2014", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2013-11-15 09:35:27.823128", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00637639", "legacyFrc": "252510" }, { "sequenceNumber": "12", "creationDate":
"11/12/2014 15:58:44", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":

"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Attendant Seats/Belts", "ataSectCode": "25", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-12-07 10:28:19.563", "faaReviewStartTms": "2014-11-13 10:28:19.563551", "intExt": "IP", "itemDesc": "Flight Attendant Jumpseat Cushions and Coverings Damaged/Torn", "itemNotes": "Includes Flight Attendant headrest cover and cushion. Reference NEF 25-25-10 for Flight Attendant Seat Trim Damaged/Torn/Missing.\r\n\r\nThis FRC to replace 25-25-09 when EFM rev 2 is published and boarded on all fleets.", "itemNotesInd": "Y", "itemNumber": "25-25-12", "lastUpdate": "2014-11-13 10:32:29.219508", "lastUpdateDisplay": "11/13/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 15:57:53.51056", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "252512" }, { "sequenceNumber": "13", "creationDate": "11/12/2014 16:13:37", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Attendant Seats/Belts", "ataSectCode": "25", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2025-08-10 12:09:51.458457", "faaReviewStartTms": "2025-07-17 12:09:51.458457", "intExt": "IP", "itemDesc": "Flight Attendant Jumpseat Cushions and Coverings Worn", "itemNotes": "Includes Flight Attendant headrest cover/cushion (ALL FLEETS), and cushion inserts (A350). \r\n\r\nReference NEF 25-25-10 for Flight Attendant Seat Trim Damaged/Torn/Missing.", "itemNotesInd": "Y", "itemNumber": "25-25-13", "lastUpdate": "2025-07-17 12:10:36.652637", "lastUpdateDisplay": "07/17/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 16:01:23.734528", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252513" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:13.366063", "faaReviewStartTms": "2011-12-09 12:37:13.366063", "intExt": "IP", "itemDesc": "Attendant Storage Box Cosmetic

Damage", "itemNotes": "More than cosmetic damaged covered by MEL.", "itemNotesInd": "Y", "itemNumber": "25-26-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252601" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:13.415507", "faaReviewStartTms": "2011-12-09 12:37:13.415507", "intExt": "IP", "itemDesc": "Closet Door Assist Spring Broken - Door still usable", "itemNotesInd": "N", "itemNumber": "25-26-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252602" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:13.486691", "faaReviewStartTms": "2011-12-09 12:37:13.486691", "intExt": "IP", "itemDesc": "Closet Door Handle Hard to Turn - Still Operational", "itemNotesInd": "N", "itemNumber": "25-26-04", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252604" }, { "sequenceNumber": "11", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Damaged trim/decorative laminate must not pose a hazard to passengers or crew. Acceptable to cut/remove loose

sections. Smooth any sharp edges. Application of 3M 398FRP fiberglass tape is acceptable to smooth edges (tape must not interfere with bin operation; do not exceed 1 sq ft of tape at any location).", "decisionInd": "A", "defRemarks": "Damaged trim/decorative laminate must not pose a hazard to passengers or crew. Acceptable to cut/remove loose sections. Smooth any sharp edges. Application of 3M 398FRP fiberglass tape is acceptable to smooth edges (tape must not interfere with bin operation; do not exceed 1 sq ft of tape at any location).", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Amended Allowable Time to 365 days to facilitate corrective action.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-24 12:20:26.036894", "faaReviewStartTms": "2026-04-30 12:20:26.036894", "intExt": "IP", "itemDesc": "Stowage Bin / Trim / Decorative Laminate / Cosmetic Damage", "itemNotes": "Cosmetic damage to bonded trim details and decorative laminate ONLY, otherwise see MEL. Damaged trim/decorative laminate must not pose a hazard to passengers or crew. Acceptable to cut/remove loose sections. Smooth any sharp edges. Application of 3M 398FRP fiberglass tape is acceptable to smooth edges (tape must not interfere with bin operation; do not exceed 1 sq ft of tape at any location).", "itemNotesInd": "Y", "itemNumber": "25-26-11", "lastUpdate": "2026-04-30 12:21:00.529071", "lastUpdateDisplay": "04/30/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252611" }, { "sequenceNumber": "12", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Latch must still operate. For inop latch or quarter turn lug see MEL.", "decisionInd": "A", "defRemarks": "Latch must still operate. For inop latch or quarter turn lug see MEL.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "a", "faaReviewEndTms": "2016-06-16 07:44:42.37", "faaReviewStartTms": "2016-05-23 07:44:42.373034", "intExt": "IP", "itemDesc": "Stowage Bin Latching Mechanism Out of Adjustment - Still Operational", "itemNotesInd": "N", "itemNumber": "25-26-12", "lastUpdate": "2016-05-23 14:51:52.530874", "lastUpdateDisplay": "05/23/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "252612" }, { "sequenceNumber": "13", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",

"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2024-09-27 09:14:56.194579", "faaReviewStartTms": "2024-09-03 09:14:56.194579", "intExt": "IP", "itemDesc": "Stowage Bin Snubber Damaged or Missing(not for 319/320/321)", "itemNotes": "Can not use NEF on 319/320/321 over head bin doors due to free falling doors and injuries.\n\nAffected overhead bin should be considered operational and may be used. For overhead bins that are inoperative, refer to the applicable MEL.", "itemNotesInd": "Y", "itemNumber": "25-26-13", "lastUpdate": "2024-09-03 09:15:06.953577", "lastUpdateDisplay": "09/03/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252613" }, { "sequenceNumber": "14", "creationDate": "05/24/2014 06:23:50", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Must not present hazard to passengers or crew or impede emergency egress. Door must stow properly", "decisionInd": "A", "defRemarks": "Must not present hazard to passengers or crew or impede emergency egress. Door must stow properly", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-08-22 13:21:07.622", "faaReviewStartTms": "2015-07-29 13:21:07.623993", "intExt": "IP", "itemDesc": "Closet Door Hold Open Latch/Catch Damaged/Inoperative", "itemNotesInd": "N", "itemNumber": "25-26-14", "lastUpdate": "2015-07-29 13:21:11.772713", "lastUpdateDisplay": "07/29/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "1454697", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000786030", "rowInsertEmpNoDisplay": "00786030", "rowInsertTms": "2014-05-24 06:07:11.999566", "sceptreAutoDefRemarks": "Auto generated log NEF via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00517467", "legacyFrc": "252614" }, { "sequenceNumber": "15", "creationDate": "11/12/2014 11:21:41", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:49:39.849225", "faaReviewStartTms": "2022-03-08 08:49:39.849225", "intExt": "IP", "itemDesc": "Video

Control Unit Door Damaged/Missing", "itemNotesInd": "N", "itemNumber": "25-26-15",
"lastUpdate": "2022-03-08 08:49:43.188348", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-12 11:10:05.696113",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252615" },
{ "sequenceNumber": "17", "creationDate": "06/12/2016 09:35:14", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode":
"26", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPprocedure": "1.
If a section of the bin stop is remaining, trim loose sections as required to remove any
sharp edges. If the entire section is missing, no maintenance action is required.\r\n2.
Clean surface per P.S. 900-1, No. 07 using isopropyl alcohol. Wipe dry before it
evaporates. Do not use MEK or MPK.\r\n3. Apply 3M 398 FR tape over any loose sections
that were trimmed in step 1. Ensure tape overlaps at least 1 onto the bin stop and at least 1
onto the bin. Due to flammability requirements, only 3M 398 FR tape is allowed for use.",
"decisionInd": "A", "defRemarks": "1. If a section of the bin stop is remaining, trim loose
sections as required to remove any sharp edges. If the entire section is missing, no
maintenance action is required.\r\n2. Clean surface per P.S. 900-1, No. 07 using isopropyl
alcohol. Wipe dry before it evaporates. Do not use MEK or MPK.\r\n3. Apply 3M 398 FR tape
over any loose sections that were trimmed in step 1. Ensure tape overlaps at least 1 onto
the bin stop and at least 1 onto the bin. Due to flammability requirements, only 3M 398 FR
tape is allowed for use.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2018-02-22 14:00:06.569796", "faaReviewStartTms": "2018-01-29
14:00:06.569796", "intExt": "IP", "itemDesc": "Overhead Bin Auxiliary Bin Stop (A319, A320
Only)", "itemNotes": "Applicable to A319 and A320 post AA 2500-01771 and AA 2500-
01772 only.This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y",
"itemNumber": "25-26-17", "lastUpdate": "2018-02-22 13:29:01.402373",
"lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "2354075", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-06-12
09:28:24.410956", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252617" },
{ "sequenceNumber": "19", "creationDate": "07/29/2019 15:09:58", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode":

"26", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure":
"Wire Damage\n1. Troubleshoot system per 16D12W32000 B767-400 WDM Supplement
Section 25-25-05, if any wire damage (chafed, exposed or otherwise damage) is identified,
coil and stow wire in accordance with D6-54446 707, 727 Through 787 SWPM Chapter 20-
10-11 Paragraph 17 and 18 at the damage location.\n2. Ensure the remainder of the
system is operating normally.\n\nElec. Component Damage\n1 Troubleshoot system per
16D12W32000 B767-400 WDM Supplement 25-25-05, until a component is identified as
the root cause.\n2. For the Bin Assist System: Pull and Collar C/B C9879, on the P34 Aux
Power Panel, reference 16D12W32000 B767-400 WDM Supplement 25-25-05 and D6-
54446 707, 727 Through 787 SWPM 20-00-10.\n3. Note the component damaged,
including EIN and location in the NEF log page.\n\nMech. Component Damage\nVerify no
sharp edges or hazards. Verify no binding or interference with bin operation and no damage
to aircraft or bin structure. Contact engineering if disconnection or removal instructions
are req'd", "decisionInd": "A", "defRemarks": "Wire Damage\n1. Troubleshoot system per
16D12W32000 B767-400 WDM Supplement Section 25-25-05, if any wire damage (chafed,
exposed or otherwise damage) is identified, coil and stow wire in accordance with D6-
54446 707, 727 Through 787 SWPM Chapter 20-10-11 Paragraph 17 and 18 at the damage
location.\n2. Ensure the remainder of the system is operating normally.\n\nElec.
Component Damage\n1 Troubleshoot system per 16D12W32000 B767-400 WDM
Supplement 25-25-05, until a component is identified as the root cause.\n2. For the Bin
Assist System: Pull and Collar C/B C9879, on the P34 Aux Power Panel, reference
16D12W32000 B767-400 WDM Supplement 25-25-05 and D6-54446 707, 727 Through 787
SWPM 20-00-10.\n3. Note the component damaged, including EIN and location in the NEF
log page.\n\nMech. Component Damage\nVerify no sharp edges or hazards. Verify no
binding or interference with bin operation and no damage to aircraft or bin structure.
Contact engineering if disconnection or removal instructions are req'd", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2024-12-07 07:10:17.784905", "faaReviewStartTms": "2024-11-13
07:10:17.784905", "intExt": "IP", "itemDesc": "Overhead Bin Lift Assist system components
(767-400 POST MOD only)", "itemNotesInd": "N", "itemNumber": "25-26-19", "lastUpdate":
"2024-11-13 07:10:29.630843", "lastUpdateDisplay": "11/13/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179",
"rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2019-07-29 14:58:22.696213",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252619" },
{ "sequenceNumber": "20", "creationDate": "06/03/2021 10:01:38", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",

"ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPProcedure": "Wire Damage\n1. Troubleshoot per 18D07R009WDM, B767-300 WDM Supplement Sect. 25-28-07, if any wire damage (chafed, exposed or otherwise damage) is identified, cut out damage and coil and stow wire IAW D6-54446 707, 727 - 787 SWPM Chapter 20-10-11 Para 18 and 19 at the damage location.\n2. Ensure the remainder of the system is operating normally.\nElec. Component Damage\n1. Troubleshoot per 18D07R009WDM, B767-300 WDM Supplement Sect. 25-28-07, until a component is identified as the root cause.\n2. For the Bin Assist System: Pull and Collar C/B C9910, on the P87 FWD LEFT MISC EQUIP PNL, reference 18D07R009WDM, B767-300 WDM Supplement Sect. 25-28-07 and D6-54446 707, 727 - 787 SWPM 20-00-10.\n3. Note the component damaged, including EIN and location in the NEF log page.\nMech. Component Damage\n1. Verify no sharp edges or hazards. Verify no binding or interference with bin operation. Verify no damage to aircraft or bin structure. If disconnection or removal is req'd, contact Dept 555.", "defRemarks": "Wire Damage\n1. Troubleshoot per 18D07R009WDM, B767-300 WDM Supplement Sect. 25-28-07, if any wire damage (chafed, exposed or otherwise damage) is identified, cut out damage and coil and stow wire IAW D6-54446 707, 727 - 787 SWPM Chapter 20-10-11 Para 18 and 19 at the damage location.\n2. Ensure the remainder of the system is operating normally.\nElec. Component Damage\n1. Troubleshoot per 18D07R009WDM, B767-300 WDM Supplement Sect. 25-28-07, until a component is identified as the root cause.\n2. For the Bin Assist System: Pull and Collar C/B C9910, on the P87 FWD LEFT MISC EQUIP PNL, reference 18D07R009WDM, B767-300 WDM Supplement Sect. 25-28-07 and D6-54446 707, 727 - 787 SWPM 20-00-10.\n3. Note the component damaged, including EIN and location in the NEF log page.\nMech. Component Damage\n1. Verify no sharp edges or hazards. Verify no binding or interference with bin operation. Verify no damage to aircraft or bin structure. If disconnection or removal is req'd, contact Dept 555.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2021-07-05 10:44:09.705856", "faaReviewStartTms": "2021-06-11 10:44:09.705856", "intExt": "IP", "itemDesc": "Overhead Bin Lift Assist System Components (767-300 POST MOD only)", "itemNotes": "The Bin Lift Assist system installed via AA 2526-01293 / 2500-01823 for B767-300 A/C 180-199, 1200-1201, 1601-1606, 1701-1708 in the passenger cabin may be missing/inoperative.\n\nNOTE: The 22\u001A center OVHD bins have not been modified to install lift assist.", "itemNotesInd": "Y", "itemNumber": "25-26-20", "lastUpdate": "2021-06-16 13:06:13.440872", "lastUpdateDisplay": "06/16/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2021-06-03 09:56:27.311826", "sceptreAutoDefRemarks": "Auto

Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252620" }, { "sequenceNumber": "21", "creationDate": "09/26/2021 01:06:40", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Associated bin must close and latch manually. Verify no sharp edges or hazards. Verify no binding or interference with bin operation. Verify no damage to a/c or bin structure.", "defRemarks": "Associated bin must close and latch manually. Verify no sharp edges or hazards. Verify no binding or interference with bin operation. Verify no damage to a/c or bin structure.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-09-27 09:15:38.290576", "faaReviewStartTms": "2024-09-03 09:15:38.290576", "intExt": "IP", "itemDesc": "Overhead Bin Lift Assist System (737-900 ONLY)", "itemNotes": "Overhead bin lift assist system installed in the passenger cabin may be missing or inoperative (737-900 ONLY).\n\nAffected overhead bin should be considered operational and may be used. For overhead bins that are inoperative, refer to the applicable MEL.", "itemNotesInd": "Y", "itemNumber": "25-26-21", "lastUpdate": "2024-09-03 09:15:44.119957", "lastUpdateDisplay": "09/03/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "7819714", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000977522", "rowInsertEmpNoDisplay": "00977522", "rowInsertTms": "2021-09-26 01:05:06.094115", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252621" }, { "sequenceNumber": "22", "creationDate": "01/04/2023 00:17:58", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2023-02-03 13:19:24.375227", "faaReviewStartTms": "2023-01-10 13:19:24.375227", "intExt": "IP", "itemDesc": "A321NEO Bin Closing Tool Missing/Damaged", "itemNotesInd": "N", "itemNumber": "25-26-22", "lastUpdate": "2023-02-10 06:41:51.631284", "lastUpdateDisplay": "02/10/2023", "logMultiplicity": "S", "logpageNumber": "7818031", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000977522", "rowInsertEmpNoDisplay": "00977522", "rowInsertTms": "2023-01-04 00:14:27.211774", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252622" }, { "sequenceNumber": "23", "creationDate": "04/22/2024 08:36:07", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":

"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Stowage Compartments/Closets", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Verify no sharp edges or hazards. Verify no binding or interference with bin operation. Verify no damage to aircraft or bin structure. Contact Liaison Engineering if disconnection or removal instructions are required.", "decisionInd": "A", "defRemarks": "Verify no sharp edges or hazards. Verify no binding or interference with bin operation. Verify no damage to aircraft or bin structure. Contact Liaison Engineering if disconnection or removal instructions are required.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.\n\nUpdated NEF item notes for clarity. Intent unchanged. TJM", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2026-02-22 13:25:01.968556", "faaReviewStartTms": "2026-01-29 13:25:01.968556", "intExt": "IP", "itemDesc": "Overhead Bin Lift Assist System - A350 A/C", "itemNotes": "May be missing or inoperative. This NEF is NOT applicable to electrical aspects of the bin lift assist system. This NEF should not be used to defer damage to the bin structure (i.e. strongback, bucket). If the bin structure is damaged, reference the MEL.", "itemNotesInd": "Y", "itemNumber": "25-26-23", "lastUpdate": "2026-01-29 13:25:15.281951", "lastUpdateDisplay": "01/29/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-04-22 08:29:18.409659", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252623" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Service units", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-06-29 12:35:15.74", "faaReviewStartTms": "2012-06-05 12:35:15.0912", "intExt": "IP", "itemDesc": "Cabin Flight Attendant Panel Door Magnet Weak", "itemNotesInd": "N", "itemNumber": "25-27-01", "lastUpdate": "2012-06-05 12:35:19.482723", "lastUpdateDisplay": "06/05/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "252701" }, { "sequenceNumber": "03", "creationDate": "02/07/2012 08:26:05", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Passenger Service units", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The lens

cover must be intact and not cracked or damaged. This NEF is only for the marking on the lens. The associated passenger seat or lavatory must have a legible NO SMOKING / FASTEN SEAT BELT / RETURN TO CABIN sign that is readily available.", "decisionInd": "A", "defRemarks": "The lens cover must be intact and not cracked or damaged. This NEF is only for the marking on the lens. The associated passenger seat or lavatory must have a legible NO SMOKING / FASTEN SEAT BELT / RETURN TO CABIN sign that is readily available.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 14:00:33.04196", "faaReviewStartTms": "2018-01-29 14:00:33.04196", "intExt": "IP", "itemDesc": "Passenger Notice System Sign in Poor Condition", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-27-03", "lastUpdate": "2018-02-22 13:29:12.725126", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-02-07 08:21:39.266489", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "252703" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Passenger Service units", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:51:00.099709", "faaReviewStartTms": "2023-11-16 06:51:00.099709", "intExt": "IP", "itemDesc": "Passenger to Flight Attendant Call Light Inop", "itemNotes": "This NEF does not cover the Lavatory Call Light Smoke Detected Function on 767-300/400 aircraft. see the MEL to defer this function. \n\nThis NEF item cannot be applied on the A350. Please refer to the A350 MEL for relief related to Passenger Call Lights. \n\nThe FAA has rescinded policy letter MMEL PL-128, Wheelchair Accessible Lavatories. Any and all restrictions which identified as more restrictive then the MMEL relief requirements have in regards to wheelchairs accessible lavatories have been removed.", "itemNotesInd": "Y", "itemNumber": "25-27-04", "lastUpdate": "2023-11-16 06:51:07.412526", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252704" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc":

"Passenger Service units", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-19 08:36:48.600924", "faaReviewStartTms": "2018-09-25 08:36:48.600924", "intExt": "IP", "itemDesc": "PSU Panel Minor Damaged but Functions Properly", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-27-05", "lastUpdate": "2018-09-25 09:23:42.274149", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252705" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "H", "faaReviewEndTms": "2020-01-19 13:12:44.758075", "faaReviewStartTms": "2019-12-26 13:12:44.758075", "intExt": "IP", "itemDesc": "Delta One Seat Lumbar Support Inop", "itemNotesInd": "N", "itemNumber": "25-28-03", "lastUpdate": "2019-12-26 13:12:52.305175", "lastUpdateDisplay": "12/26/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00406009", "legacyFrc": "252803" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:14.427255", "faaReviewStartTms": "2011-12-09 12:37:14.427255", "intExt": "IP", "itemDesc": "Cocktail Tray Table Damaged", "itemNotesInd": "N", "itemNumber": "25-28-04", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"userIdDisplay": "LOADJOB", "legacyFrc": "252804" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": ".", "faaReviewEndTms": "2023-12-10 06:51:40.963855",
"faaReviewStartTms": "2023-11-16 06:51:40.963855", "intExt": "IP", "itemDesc": "First /
Business Class Seat Lumbar Function Inop (A330)", "itemNotesInd": "N", "itemNumber":
"25-28-05", "lastUpdate": "2023-11-16 06:51:48.295832", "lastUpdateDisplay":
"11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00324557", "legacyFrc": "252805" }, { "sequenceNumber": "07", "creationDate":
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger
Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOPprocedure": "Not to be used on electrically operated seats.
Footrest must stow in the upright position or must be secured in the upright condition for
egress.", "decisionInd": "A", "defRemarks": "Not to be used on electrically operated seats.
Footrest must stow in the upright position or must be secured in the upright condition for
egress.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in
initial FAA approved list.", "faaContactName": "updated", "faaReviewEndTms": "2020-07-
06 05:29:19.607632", "faaReviewStartTms": "2020-06-12 05:29:19.607632", "intExt": "IP",
"itemDesc": "Fold Down Footrest Inoperative / Damaged / Missing", "itemNotes": "This may
be the footrest attached to the back of the seat in front of the passenger or the footrest
attached to the affected seat.", "itemNotesInd": "Y", "itemNumber": "25-28-07",
"lastUpdate": "2020-06-12 05:30:02.305768", "lastUpdateDisplay": "06/12/2020",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "252807" },
{ "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved

list.", "faaReviewEndTms": "2012-01-02 12:37:14.578766", "faaReviewStartTms": "2011-12-09 12:37:14.578766", "intExt": "IP", "itemDesc": "Portable Footrest Damaged", "itemNotesInd": "N", "itemNumber": "25-28-08", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252808" }, { "sequenceNumber": "09", "creationDate": "09/24/2013 16:23:03", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The following criteria MUST be met:\r\n1. No airbag material can protrude past the end of the cover.\r\n2. No stitching may be broken.\r\n3. The cover cannot be torn or have any holes.\r\n\r\nIf the seat belt or seat belt cover is torn or damaged reference the appropriate manuals for serviceable limits and reference the MEL or manual to defer.", "decisionInd": "A", "defRemarks": "The following criteria MUST be met:\r\n1. No airbag material can protrude past the end of the cover.\r\n2. No stitching may be broken.\r\n3. The cover cannot be torn or have any holes.\r\n\r\nIf the seat belt or seat belt cover is torn or damaged reference the appropriate manuals for serviceable limits and reference the MEL or manual to defer.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-10-21 10:51:18.273", "faaReviewStartTms": "2013-09-27 10:51:18.272244", "intExt": "IP", "itemDesc": "Airbag Seat Belt Leather Cover Worn", "itemNotes": "This NEF is only for cosmetic issues only. Disregard the ATA description code. This NEF code applies to all passenger seats; First Class, Business Elite, World Business Class or Economy Comfort or Coach Class seats.", "itemNotesInd": "Y", "itemNumber": "25-28-09", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "8539418", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000953697", "rowInsertEmpNoDisplay": "00953697", "rowInsertTms": "2013-09-24 16:11:18.705132", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "252809" }, { "sequenceNumber": "10", "creationDate": "11/15/2013 10:46:48", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to passengers or crew.", "decisionInd": "A", "defRemarks": "Must not present hazard to passengers or crew.", "efmTab": "S",

"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2025-06-12 08:09:15.039651", "faaReviewStartTms": "2025-05-19
08:09:15.039651", "intExt": "IP", "itemDesc": "Passenger Seat Armrest Cover Damaged or
Missing - Delta One / Prem Select", "itemNotes": "For Damaged / Inop Armrest See MEL.
For coach seats see NEF 25-21-30 - Passenger Seat Armrest Cover / Trim Damaged or
Missing\n\nThis FRC replaced 25-21-08.", "itemNotesInd": "Y", "itemNumber": "25-28-10",
"lastUpdate": "2025-05-19 08:09:32.785525", "lastUpdateDisplay": "05/19/2025",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-11-15 10:30:48.960239",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252810" },
{ "sequenceNumber": "11", "creationDate": "12/08/2017 08:02:10", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables",
"ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Ensure the partition assembly common to the discrepant gas strut
remains free from other signs of damage. For the 350 Ensure the partition can be locked in
the open & closed positions and that the partition can be opened and closed properly. For
the 330 NEO this NEF can be used for any portion of the Delta one privacy divider system
as long as it can be locked in fully down or is all the way open.", "decisionInd": "A",
"defRemarks": "Ensure the partition assembly common to the discrepant gas strut remains
free from other signs of damage. For the 350 Ensure the partition can be locked in the open
& closed positions and that the partition can be opened and closed properly. For the 330
NEO this NEF can be used for any portion of the Delta one privacy divider system as long as
it can be locked in fully down or is all the way open.", "efmTab": "S",
"faaAcceptanceRequiredInd": "Y", "faaComments": "ADDED 330-NEO",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:53:03.018949",
"faaReviewStartTms": "2023-11-16 06:53:03.018949", "intExt": "IP", "itemDesc": "Delta
One suite privacy divider gas strut inop (A350/330-NEO/764 POST SUITE MOD only)",
"itemNotes": "Ensure the partition assembly common to the discrepant gas strut remains
free from other signs of damage. For the 767-400/350 Ensure the partition can be locked in
the open & closed positions and that the partition can be opened and closed properly. For
the 767-400/330 NEO this NEF can be used for any portion of the Delta one privacy divider
system as long as it can be locked in fully down or is all the way open.", "itemNotesInd":
"Y", "itemNumber": "25-28-11", "lastUpdate": "2023-11-16 06:53:16.435231",
"lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":

"0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2017-12-08 07:59:20.170192", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252811" }, { "sequenceNumber": "12", "creationDate": "01/04/2024 09:24:57", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Verify that the symbol on the button that returns the seat to the upright condition is legible.", "decisionInd": "A", "defRemarks": "Verify that the symbol on the button that returns the seat to the upright condition is legible.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-02-01 09:04:55.115806", "faaReviewStartTms": "2024-01-08 09:04:55.115806", "intExt": "IP", "itemDesc": "Delta One PCU Cosmetic Damage (A350 3568-3576, JSP001 Seats ONLY)", "itemNotes": "Only applicable to cosmetic damage to the PCU on A350 ships 3568-3576, JSP001 seats.", "itemNotesInd": "Y", "itemNumber": "25-28-12", "lastUpdate": "2024-01-08 09:07:19.697397", "lastUpdateDisplay": "01/08/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-01-04 09:21:10.227141", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252812" }, { "sequenceNumber": "13", "creationDate": "02/01/2024 09:14:35", "userId": "0000603060", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Revision Acceptable, as submitted", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2024-07-20 09:22:26.74073", "faaReviewStartTms": "2024-06-26 09:22:26.74073", "intExt": "IP", "itemDesc": "Delta One Seat Suite Door, Lower Magnet, A350 and A330-900 Thompson Delta One suites ONLY", "itemNotesInd": "N", "itemNumber": "25-28-13", "lastUpdate": "2024-06-27 12:37:58.815765", "lastUpdateDisplay": "06/27/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-02-01 09:03:44.651163", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00603060", "legacyFrc": "252813" }, { "sequenceNumber": "14", "creationDate": "06/05/2024 11:57:14", "userId": "0000603060", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",

"ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables",
"ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms":
"2024-07-21 12:34:34.026003", "faaReviewStartTms": "2024-06-27 12:34:34.026003",
"intExt": "IP", "itemDesc": "Wireless Charging Module INOP (Delta One (BC) Vantage XL
seats on AC 3520 and sub)", "itemNotesInd": "N", "itemNumber": "25-28-14", "lastUpdate":
"2024-06-27 12:42:05.204813", "lastUpdateDisplay": "06/27/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-06-05 11:50:05.429782",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00603060", "legacyFrc": "252814" },
{ "sequenceNumber": "16", "creationDate": "02/12/2025 15:23:17", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables",
"ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Must not present hazard to passengers or crew or impede
emergency egress.", "defRemarks": "Must not present hazard to passengers or crew or
impede emergency egress.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Item a duplicate of item 25-21-39...received email approval from Bill
Williams, FAA-CMO.", "faaContactName": "See below", "faaReviewEndTms": "2025-03-08
15:20:57.140469", "faaReviewStartTms": "2025-02-12 15:20:57.140469", "intExt": "IP",
"itemDesc": "Passenger Seat Trim Damaged/Missing - Delta One/Prem Select",
"itemNotesInd": "N", "itemNumber": "25-28-16", "lastUpdate": "2025-02-12
15:21:10.631334", "lastUpdateDisplay": "02/12/2025", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2025-02-12 15:20:57.140469", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "252816" }, { "sequenceNumber": "18", "creationDate":
"11/17/2025 12:39:10", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger
Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "S", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams",
"faaReviewEndTms": "2025-12-11 13:38:17.240528", "faaReviewStartTms": "2025-11-17
13:38:17.240528", "intExt": "IP", "itemDesc": "PCU backlighting (A330-200/-300 fleets)",

"itemNotes": "Applicable to Cirrus and Thompson seat PCU's on the A330 -200/-300 fleets ONLY", "itemNotesInd": "Y", "itemNumber": "25-28-18", "lastUpdate": "2025-11-19 06:29:33.026961", "lastUpdateDisplay": "11/19/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-11-17 12:26:00.790127", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "252818" }, { "sequenceNumber": "19", "creationDate": "05/21/2026 12:30:21", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "FC/WBC Passenger Seats/Belts/Traytables", "ataSectCode": "28", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "8", "deactMOProcedure": "Critical notes*\n\nAccomplish ER/A 525535-14MA Rev C to install an INOP cover to secure the tray table and arms. INOP cover MPN 34000019// 56-2500-3-1248 . Cover must keep the Tray table completely closed. Must not present a hazard to passengers or crew or impede emergency egress.\n\nIf INOP cover is not available, tray table and arms MUST be removed. Must not present a hazard to passengers or crew or impede emergency egress.", "defRemarks": "*Critical notes\n\nAccomplish ER/A 525535-14MA Rev C to install an INOP cover to secure the tray table and arms. INOP cover MPN 34000019// 56-2500-3-1248 . Cover must keep the Tray table completely closed. Must not present a hazard to passengers or crew or impede emergency egress.\n\nIf INOP cover is not available, tray table and arms MUST be removed. Must not present a hazard to passengers or crew or impede emergency egress.", "efmTab": "S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Republish with effectivity. No change to relief.", "faaContactName": ".", "faaReviewEndTms": "2026-06-14 12:29:44.37858", "faaReviewStartTms": "2026-05-21 12:29:44.37858", "intExt": "IP", "itemDesc": "D1/ Prem/ FC Passenger Tray Table Inop", "itemNotes": "Disregard the ATA description code. This NEF code applies to Delta One, Premium Economy, or First Class passenger seats.\n\nWhen a meal tray table must be removed: 1. Part must be tagged with the MPN, AC #, and removal location 2. Part must be secured in the MCO pouch and documented in the log deferral 3. Email must be sent to Cabin Maintenance (cabin.mtc@delta.com) notifying of the meal tray removal and include the log page as reference This will help ensure parts are recovered and held until a permanent repair can be accomplished.", "itemNotesInd": "Y", "itemNumber": "25-28-19", "lastUpdate": "2026-05-21 12:34:13.051412", "lastUpdateDisplay": "05/21/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000700872", "rowInsertEmpNoDisplay": "00700872", "rowInsertTms": "2026-05-21 12:29:44.37858", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":

"00700872", "legacyFrc": "252819" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Premium Select Seats", "ataSectCode": "29", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:14.63309", "faaReviewStartTms": "2011-12-09 12:37:14.63309", "intExt": "IP", "itemDesc": "Bassinet Damaged", "itemNotesInd": "N", "itemNumber": "25-29-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252901" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Premium Select Seats", "ataSectCode": "29", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:14.676576", "faaReviewStartTms": "2011-12-09 12:37:14.676576", "intExt": "IP", "itemDesc": "Bassinet Missing", "itemNotesInd": "N", "itemNumber": "25-29-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "252902" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Premium Select Seats", "ataSectCode": "29", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "(M) Procedure Required: Close table leafs and secure closed with leaf latches if available. If leaf latches are not available, secure table leafs closed with onboard strap. If unable to secure with onboard strap, defer the affected seats per MEL. Placard inoperative table \"Unserviceable - Do Not Use\". The flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required: Close table leafs and secure closed with leaf latches if available. If leaf latches are not available, secure table leafs closed with onboard strap. If unable to secure with onboard strap, defer the affected seats per MEL. Placard inoperative table \"Unserviceable - Do Not Use\". The flight crew can reference this

deactivation procedure in the EFM procedures section.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Changed from A319 to 757.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 10:32:53.195537",
"faaReviewStartTms": "2019-02-27 10:32:53.195537", "intExt": "IP", "itemDesc": "Pedestal
Table All Failure Modes Except Vertical Adjustment -757 NBA Config", "itemNotes": "This
NEF item applies only to the 757 NBA configured aircraft.", "itemNotesInd": "Y",
"itemNumber": "25-29-04", "lastUpdate": "2019-02-27 10:32:55.871543",
"lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00823179", "legacyFrc": "252904" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Premium Select Seats", "ataSectCode": "29", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOProcedure": "(M) Procedure Required Install placard in
logbook. Close table leafs and secure closed with leaf latches. Install table top pad and
verify it is secure. Placard inoperative table "Unserviceable - Do Not Use". The flight crew
can reference this deactivation procedure in the EFM procedures section.", "decisionInd":
"A", "defRemarks": "(M) Procedure Required Install placard in logbook. Close table leafs
and secure closed with leaf latches. Install table top pad and verify it is secure. Placard
inoperative table "Unserviceable - Do Not Use". The flight crew can reference this
deactivation procedure in the EFM procedures section.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Changed from A319 to 757.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 10:33:29.998104",
"faaReviewStartTms": "2019-02-27 10:33:29.998104", "intExt": "IP", "itemDesc": "Pedestal
Table Vertical Adjustment - 757 NBA Config", "itemNotes": "This NEF item applies only to
the 757 NBA configured aircraft.", "itemNotesInd": "Y", "itemNumber": "25-29-05",
"lastUpdate": "2019-02-27 10:33:33.003537", "lastUpdateDisplay": "02/27/2019",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "252905" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "Buffet/Galley", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd":
"Y", "daysCount": "0", "deactMOProcedure": "Must stow properly or must be secured or
removed so as not to impede egress.", "decisionInd": "A", "defRemarks": "Must stow

properly or must be secured or removed so as not to impede egress.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Changed to correct for spelling, grammar or capitalization only to standardize format.", "faaContactName": "Biever", "faaReviewEndTms": "2012-02-24 10:55:23.921", "faaReviewStartTms": "2012-01-31 10:55:23.157794", "intExt": "IG", "itemDesc": "Attendant Work Tables in Galley Damaged/Missing", "itemNotesInd": "N", "itemNumber": "25-30-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "253001" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Buffet/Galley", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:55:20.852223", "faaReviewStartTms": "2018-01-29 13:55:20.852223", "intExt": "IG", "itemDesc": "Cork Screws Damaged / Missing", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-30-02", "lastUpdate": "2018-02-22 13:29:33.966099", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253002" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Buffet/Galley", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:54:40.959522", "faaReviewStartTms": "2018-01-29 13:54:40.959522", "intExt": "IG", "itemDesc": "Galley Cosmetic Trim / Wall coverings / Bumpers Damaged / Missing", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-30-03", "lastUpdate": "2018-02-22 13:30:28.769826", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N",

"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "253003" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Buffet/Galley", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y",
"faaReviewEndTms": "2012-03-30 10:21:54.06", "faaReviewStartTms": "2012-03-06
10:21:53.262165", "intExt": "IG", "itemDesc": "Galley Drain Screen or Cover Damaged /
Missing", "itemNotesInd": "N", "itemNumber": "25-30-04", "lastUpdate": "2012-03-06
10:21:58.128374", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "253004" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc":
"Buffet/Galley", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOPProcedure": "Must not present hazard to passengers or crew.",
"decisionInd": "A", "defRemarks": "Must not present hazard to passengers or crew.",
"efmTab": "U", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable
time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-05-18
08:58:36.522793", "faaReviewStartTms": "2019-04-24 08:58:36.522793", "intExt": "IG",
"itemDesc": "Galley Floor Covering Torn/Damaged/Missing", "itemNotes": "This NEF item
has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-30-05",
"lastUpdate": "2019-04-24 08:58:39.500615", "lastUpdateDisplay": "04/24/2019",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253005" },
{ "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Buffet/Galley", "ataSectCode": "30", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:22:26.175",
"faaReviewStartTms": "2012-03-06 10:22:25.384696", "intExt": "IG", "itemDesc": "Galley
Utensils Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-30-06",

"lastUpdate": "2012-03-06 10:22:30.447194", "lastUpdateDisplay": "03/06/2012",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "253006" },
{ "sequenceNumber": "08", "creationDate": "06/30/2013 03:24:38", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "Buffet/Galley", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd":
"Y", "daysCount": "0", "deactMOProcedure": "Must not present hazard to passengers or
crew or impede emergency egress. Door must stow properly", "decisionInd": "A",
"defRemarks": "Must not present hazard to passengers or crew or impede emergency
egress. Door must stow properly", "efmTab": "G", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-08-17 15:36:20.949",
"faaReviewStartTms": "2013-07-24 15:36:20.957752", "intExt": "IG", "itemDesc": "Galley
Door Hold Open Latch Damaged/Inoperative", "itemNotes": "For A330 reference IPC 25-
31-52-75 item 140 - chiller door holder assembly.", "itemNotesInd": "Y", "itemNumber":
"25-30-08", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay":
"12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber":
"0956966", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000229053",
"rowInsertEmpNoDisplay": "00229053", "rowInsertTms": "2013-06-30 03:16:57.461465",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "253008" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Galley Structure, Doors and Latches/Cart Restraint
Latches", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Must stow properly or must be secured so as not to impede egress.
Damage must not affect the integrity of the structure and does not create any hazards to
personnel (e.g. sharp edges)", "decisionInd": "A", "defRemarks": "Must stow properly or
must be secured so as not to impede egress. Damage must not affect the integrity of the
structure and does not create any hazards to personnel (e.g. sharp edges)", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.
Clarify description on 5/19/25", "faaContactName": ".", "faaReviewEndTms": "2025-06-12
08:20:34.674637", "faaReviewStartTms": "2025-05-19 08:20:34.674637", "intExt": "IG",
"itemDesc": "GalleyGalley Counter / Counter Shelf Damaged (including dents)",
"itemNotesInd": "N", "itemNumber": "25-31-01", "lastUpdate": "2025-05-19
08:20:56.329884", "lastUpdateDisplay": "05/19/2025", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",

"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "253101" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Galley Structure, Doors and Latches/Cart Restraint Latches", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must stow properly or must be secured so as not to impede egress.", "decisionInd": "A", "defRemarks": "Must stow properly or must be secured so as not to impede egress.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:15.418819", "faaReviewStartTms": "2011-12-09 12:37:15.418819", "intExt": "IG", "itemDesc": "Counter Shelf Stuck", "itemNotesInd": "N", "itemNumber": "25-31-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "253102" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Galley Structure, Doors and Latches/Cart Restraint Latches", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:23:16.384", "faaReviewStartTms": "2012-03-06 10:23:15.588125", "intExt": "IG", "itemDesc": "Galley Drawer Will Not Open / Hard to Open or Close", "itemNotes": "Quarter Turn Latches are covered in MEL.", "itemNotesInd": "Y", "itemNumber": "25-31-04", "lastUpdate": "2012-03-06 10:23:22.724198", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "253104" }, { "sequenceNumber": "09", "creationDate": "08/20/2013 00:55:25", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Galley Structure, Doors and Latches/Cart Restraint Latches", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Secure the counter top with tape and ensure that no sharp edges exist. Ensure that the bun warmer door does not bind.", "decisionInd": "A", "defRemarks": "Secure the counter top with tape and ensure that no sharp edges exist. Ensure that the bun warmer door does not

bind.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2022-04-01 08:51:44.325967", "faaReviewStartTms":
"2022-03-08 08:51:44.325967", "intExt": "IG", "itemDesc": "G2 Galley Countertop
Disbonded (B737 only)", "itemNotes": "This NEF is for the B737 G2 galley only (the forward
galley area, aft module). The disbonding of the countertop may cause the bun warmer door
to bind.", "itemNotesInd": "Y", "itemNumber": "25-31-09", "lastUpdate": "2022-03-08
08:51:49.818466", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "5141890", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000958043", "rowInsertEmpNoDisplay": "00958043",
"rowInsertTms": "2013-08-20 00:52:50.155396", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "253109" }, { "sequenceNumber": "10", "creationDate":
"09/02/2013 20:48:52", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Galley Structure,
Doors and Latches/Cart Restraint Latches", "ataSectCode": "31", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Ensure primary (large latches)
are operational. Install a placard at the cart bay that only full length carts may be used in
that location.", "decisionInd": "A", "defRemarks": "Ensure primary (large latches) are
operational. Install a placard at the cart bay that only full length carts may be used in that
location.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2014-08-01 11:40:17.296", "faaReviewStartTms":
"2014-07-08 11:40:17.300801", "intExt": "IG", "itemDesc": "Galley Cart Bay Side Latch
Inop/Missing", "itemNotes": "For 737-900 aircraft reference CMM 25-31-81 Fig 11 item 165,
remote retainer assembly.", "itemNotesInd": "Y", "itemNumber": "25-31-10", "lastUpdate":
"2015-02-26 13:10:27.771056", "lastUpdateDisplay": "02/26/2015",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "5028328",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000378852",
"rowInsertEmpNoDisplay": "00378852", "rowInsertTms": "2013-09-02 20:40:15.517209",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "253110" },
{ "sequenceNumber": "11", "creationDate": "07/06/2014 05:18:07", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "25", "ataDesc": "Galley Structure, Doors and Latches/Cart Restraint
Latches", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "The most aft container or cart must remain empty with a placard
that states EMPTY, DO NOT REMOVE on the container/cart in addition to a DO NOT USE
placard around the extractor for that bay.", "decisionInd": "A", "defRemarks": "The most aft
container or cart must remain empty with a placard that states EMPTY, DO NOT REMOVE

on the container/cart in addition to a DO NOT USE placard around the extractor for that bay.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added CART extractor and expanded fleet relief. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-14 09:08:00.496963", "faaReviewStartTms": "2026-04-20 09:08:00.496963", "intExt": "IP", "itemDesc": "Galley/Closet Container/Cart Extractor Damaged/Inoperative", "itemNotes": "The galley container/cart extractor consists of a handle with cable or strap in a track with a bracket to pull out a container or cart in the aft portion of the storage bay. This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-31-11", "lastUpdate": "2026-04-20 09:08:05.765065", "lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "5662987", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000229053", "rowInsertEmpNoDisplay": "00229053", "rowInsertTms": "2014-07-06 05:17:39.028874", "sceptreAutoDefRemarks": "Auto generated log NEF via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "253111"}, {"sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:52:11.421997", "faaReviewStartTms": "2022-03-08 08:52:11.421997", "intExt": "IG", "itemDesc": "Cabin Step Stool Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-32-01", "lastUpdate": "2022-03-08 08:52:16.670823", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "253201"}, {"sequenceNumber": "02", "creationDate": "03/10/2014 17:24:12", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "1. Ensure that the waste receptacle is empty and void of any waste material. \r\n2. Must not present hazard to passengers or crew.\r\n3. Flapper door and/or access door must be secured closed and placarded: Do not use. 3M 398FR tape can be used to secure the door closed.", "decisionInd": "A", "defRemarks": "1. Ensure that the waste receptacle is empty and void of any waste material. \r\n2. Must not present hazard to passengers or crew.\r\n3. Flapper door and/or access door must be secured closed and

placarded: Do not use. 3M 398FR tape can be used to secure the door closed.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Reviewed data.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-11-23 08:34:48.45397", "faaReviewStartTms": "2024-10-30 08:34:48.45397", "intExt": "IG", "itemDesc": "Galley Waste Compartment/Container Liner Missing/Damaged (NOT to be used for waste carts)", "itemNotes": "Only one trash compartment liner is permitted to be missing from fixed locations. Item is NOT to be used for missing wheeled carts or liners as they are catering equipment.", "itemNotesInd": "Y", "itemNumber": "25-32-02", "lastUpdate": "2024-10-30 08:35:01.9849", "lastUpdateDisplay": "10/30/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "5612029", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000437100", "rowInsertEmpNoDisplay": "00437100", "rowInsertTms": "2014-03-10 17:16:48.444227", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "253202" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:24:34.259", "faaReviewStartTms": "2012-03-06 10:24:33.46519", "intExt": "IG", "itemDesc": "Galley Cup Holders Damaged", "itemNotesInd": "N", "itemNumber": "25-32-03", "lastUpdate": "2012-03-06 10:24:37.567049", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "253203" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:24:45.616", "faaReviewStartTms": "2012-03-06 10:24:44.821414", "intExt": "IG", "itemDesc": "Galley Document Clips Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-32-04", "lastUpdate": "2012-03-06 10:24:48.925807", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"userIdDisplay": "00637639", "legacyFrc": "253204" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:24:57.887",
"faaReviewStartTms": "2012-03-06 10:24:57.092977", "intExt": "IG", "itemDesc": "Galley
Drawers Damaged / Corroded", "itemNotesInd": "N", "itemNumber": "25-32-05",
"lastUpdate": "2012-03-06 10:25:00.908002", "lastUpdateDisplay": "03/06/2012",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "253205" },
{ "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device",
"ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms":
"2012-03-30 10:25:10.043", "faaReviewStartTms": "2012-03-06 10:25:09.249186", "intExt":
"IG", "itemDesc": "Galley Drawers Missing", "itemNotesInd": "N", "itemNumber": "25-32-
06", "lastUpdate": "2012-03-06 10:25:14.664593", "lastUpdateDisplay": "03/06/2012",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "253206" },
{ "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device",
"ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms":
"2018-03-22 08:17:33.287092", "faaReviewStartTms": "2018-02-26 08:17:33.287092",
"intExt": "IG", "itemDesc": "Galley Storage Compartment Minor Damage", "itemNotes":
"For INOP storage compartment see MEL.This NEF item has a 365 day allowable time
limit.", "itemNotesInd": "Y", "itemNumber": "25-32-07", "lastUpdate": "2018-02-26
08:18:04.003474", "lastUpdateDisplay": "02/26/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":

"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253207" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.\n2. Placard Hot Plate Inoperative". \n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.\n2. Placard Hot Plate Inoperative". \n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:52:30.360083", "faaReviewStartTms": "2022-03-08 08:52:30.360083", "intExt": "IG", "itemDesc": "Hot Plate Inoperative", "itemNotesInd": "N", "itemNumber": "25-32-08", "lastUpdate": "2022-03-08 08:52:33.514999", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "253208" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:16.553922", "faaReviewStartTms": "2011-12-09 12:37:16.553922", "intExt": "IL", "itemDesc": "Lavatory Paper Towel Holders Damaged", "itemNotesInd": "N", "itemNumber": "25-32-09", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "253209" }, { "sequenceNumber": "10",

"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an
extent that it leaves an opening that items could fall into or that would be a security
concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it
leaves an opening that items could fall into or that would be a security concern.",
"efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaReviewEndTms": "2012-01-02 12:37:16.784172", "faaReviewStartTms":
"2011-12-09 12:37:16.784172", "intExt": "IL", "itemDesc": "Lavatory Sanitizer Dispensers
Damaged", "itemNotesInd": "N", "itemNumber": "25-32-10", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "253210" }, { "sequenceNumber": "11",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Misc. Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "K",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-07 14:05:35.049",
"faaReviewStartTms": "2014-11-13 14:05:35.049199", "intExt": "IP", "itemDesc":
"Miscellaneous Cabin Forms Need Replenishing", "itemNotesInd": "N", "itemNumber":
"25-32-11", "lastUpdate": "2014-11-13 14:05:38.698083", "lastUpdateDisplay":
"11/13/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00637639", "legacyFrc": "253211" }, { "sequenceNumber": "12", "creationDate":
"12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Misc.
Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:33:15.004",
"faaReviewStartTms": "2012-03-06 10:33:14.220014", "intExt": "IG", "itemDesc":
"Miscellaneous Galley Supplies Need Replenishing", "itemNotesInd": "N", "itemNumber":
"25-32-12", "lastUpdate": "2012-03-06 10:33:18.168648", "lastUpdateDisplay":
"03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":

"9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00637639", "legacyFrc": "253212" }, { "sequenceNumber": "13", "creationDate":
"10/07/2016 10:55:52", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Misc.
Equipment/Work tables/M2 Device", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "A319/320/321/330/350 fire
containment gloves are located in the MEL. This NEF is still active for the fire containment
bags on all fleets. If containment bag seal has failed but the kit has not been opened,
perform weight check per AMM 25-60-06. If the weight check passes, the bag is within
AMM limits and deferral to NEF is not permitted.", "decisionInd": "A", "defRemarks":
"A319/320/321/330/350 fire containment gloves are located in the MEL. This NEF is still
active for the fire containment bags on all fleets. If containment bag seal has failed but the
kit has not been opened, perform weight check per AMM 25-60-06. If the weight check
passes, the bag is within AMM limits and deferral to NEF is not permitted.", "efmTab": "M",
"faaAcceptanceRequiredInd": "Y", "faaComments": "A350 verbiage added. Clarified
allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-08-18
09:59:05.659924", "faaReviewStartTms": "2023-07-25 09:59:05.659924", "intExt": "IP",
"itemDesc": "Fire Containment Bag/Gloves Missing/Damaged(NOT FOR GLOVES ON
AIRBUS PLANES)", "itemNotes": "A319/320/321/330/350 fire containment gloves are
located in the MEL. This NEF is still active for the fire containment bags on all fleets.This
item is applicable to post AA 2560-01539 aircraft which installs fire containment bags and
fire gloves on the aircraft. This item can be used for any number of bags or gloves in any
combination.This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y",
"itemNumber": "25-32-13", "lastUpdate": "2023-07-25 09:59:15.262246",
"lastUpdateDisplay": "07/25/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-10-07
10:51:37.255224", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "253213" },
{ "sequenceNumber": "14", "creationDate": "05/29/2025 06:54:07", "userId":
"0000324557", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Misc. Equipment/Work tables/M2 Device",
"ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab":
"G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2025-06-22
06:50:38.209545", "faaReviewStartTms": "2025-05-29 06:50:38.209545", "intExt": "IG",
"itemDesc": "Galley Soap Dispenser", "itemNotesInd": "N", "itemNumber": "25-32-14",

"lastUpdate": "2025-05-29 06:50:38.209545", "lastUpdateDisplay": "05/29/2025",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-05-29 06:50:38.209545",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "253214" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "Chillers/A350 Supplemental Cooling System", "ataSectCode": "33",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:17.103183", "faaReviewStartTms": "2011-
12-09 12:37:17.103183", "intExt": "IG", "itemDesc": "Chilled Air Temperature Gauges
Inoperative", "itemNotesInd": "N", "itemNumber": "25-33-01", "lastUpdate": "2011-12-09
12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "253301" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "0000700872", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Chillers/A350 Supplemental Cooling System", "ataSectCode": "33", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "8", "deactMOProcedure": "(M) Procedure Required:\n1.
Pull and secure associated circuit breaker. Observation of a smoke or overheat event
requires additional inspection by Maintenance prior to placarding.\n2. Placard Chiller
"Inoperative". \n\nThe flight crew can reference this deactivation procedure in the EFM
procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required:\n1. Pull
and secure associated circuit breaker. Observation of a smoke or overheat event requires
additional inspection by Maintenance prior to placarding.\n2. Placard Chiller "Inoperative".
\n\nThe flight crew can reference this deactivation procedure in the EFM procedures
section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2026-06-14 13:00:06.922833", "faaReviewStartTms":
"2026-05-21 13:00:06.922833", "intExt": "IG", "itemDesc": "Chiller Inoperative / Damaged -
EXCEPT A350", "itemNotes": "Reference NEF 21-59-xx for the A350. Contact MCC to apply
SPL-item 21-59-00.", "itemNotesInd": "Y", "itemNumber": "25-33-02", "lastUpdate": "2026-
05-21 13:04:37.089275", "lastUpdateDisplay": "05/21/2026", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":

"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "253302" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Chillers/A350 Supplemental Cooling System", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:17.246283", "faaReviewStartTms": "2011-12-09 12:37:17.246283", "intExt": "IG", "itemDesc": "Chiller Shelf Clip Missing", "itemNotesInd": "N", "itemNumber": "25-33-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "253303" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Chillers/A350 Supplemental Cooling System", "ataSectCode": "33", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.\n2. Placard Freezer Inoperative". \n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.\n2. Placard Freezer Inoperative". \n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 10:36:52.467201", "faaReviewStartTms": "2019-02-27 10:36:52.467201", "intExt": "IG", "itemDesc": "Galley Freezer Inoperative", "itemNotesInd": "N", "itemNumber": "25-33-05", "lastUpdate": "2019-02-27 10:36:55.697975", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253305" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Chillers/A350 Supplemental Cooling System", "ataSectCode": "33", "autoDefCde": "NEF",

"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:17.512688", "faaReviewStartTms": "2011-
12-09 12:37:17.512688", "intExt": "IG", "itemDesc": "Thermos Units Damaged / Missing",
"itemNotesInd": "N", "itemNumber": "25-33-06", "lastUpdate": "2011-12-09 12:36:53.842",
"lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "LOADJOB", "legacyFrc": "253306" }, { "sequenceNumber": "07",
"creationDate": "09/06/2012 14:00:04", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Chillers/A350 Supplemental Cooling System", "ataSectCode": "33", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "For a damaged or inoperative
chiller cart air flap assembly, secure the flap assembly of loose parts and tape opening to
prevent loss of chiller air into galley as needed. Placard Chilling Compartment
'Inoperative'.", "decisionInd": "A", "defRemarks": "For a damaged or inoperative chiller cart
air flap assembly, secure the flap assembly of loose parts and tape opening to prevent loss
of chiller air into galley as needed. Placard Chilling Compartment 'Inoperative'.", "efmTab":
"G", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 09/18/2013 with
Description change.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-07-
04 12:41:58.636627", "faaReviewStartTms": "2024-06-10 12:41:58.636627", "intExt": "IG",
"itemDesc": "Galley Chiller Air Distribution System - Cart Air Flaps and Chilled
Compartments Damaged", "itemNotes": "If a chiller cart air flap is missing, damaged,
broken or stuck open, air will continue to flow and may degrade chiller ability to chill food if
cart is not present.", "itemNotesInd": "Y", "itemNumber": "25-33-07", "lastUpdate": "2024-
06-10 12:42:10.824439", "lastUpdateDisplay": "06/10/2024", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "8917988", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000910407", "rowInsertEmpNoDisplay": "00910407",
"rowInsertTms": "2012-09-06 13:51:28.516597", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "253307" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Ovens",
"ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Door knob must latch securely. This NEF cannot be used if the door
will not latch securely closed.", "decisionInd": "A", "defRemarks": "Door knob must latch
securely. This NEF cannot be used if the door will not latch securely closed.", "efmTab":

"G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified Deferral Remarks", "faaContactName": "DAL edit", "faaReviewEndTms": "2025-06-22 06:59:53.597455", "faaReviewStartTms": "2025-05-29 06:59:53.597455", "intExt": "IG", "itemDesc": "Oven Door / Secondary Latch Damaged", "itemNotesInd": "N", "itemNumber": "25-34-01", "lastUpdate": "2025-05-29 07:00:09.776509", "lastUpdateDisplay": "05/29/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "253401" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Ovens", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "M) Procedure Required:\n\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.(For C series NEF Deactivate an inoperative Oven as follows: On the CB electronic synoptic page, set the following applicable circuit breaker to OUT and LOCK (refer to AMP TASK BD500?-A?-J24?00-?00-?06AAA-?398D-?A):\n2. Placard Oven \"Inoperative\".\n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "M) Procedure Required:\n\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.(For C series NEF Deactivate an inoperative Oven as follows: On the CB electronic synoptic page, set the following applicable circuit breaker to OUT and LOCK (refer to AMP TASK BD500?-A?-J24?00-?00-?06AAA-?398D-?A):\n2. Placard Oven \"Inoperative\".\n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added C Series.", "faaContactName": "Hoogerhout", "faaReviewEndTms": "2019-03-23 10:39:03.272626", "faaReviewStartTms": "2019-02-27 10:39:03.272626", "intExt": "IG", "itemDesc": "Oven -includes oven timers Damaged / Inoperative", "itemNotes": "C series Oven circuit breakers are electronic. Improper lockout can cause possible ODI's due to reactivation at next electrical power reset. That's why it is imperative to confirm the CB's are LOCKED AND NOT JUST OUT.\n\nG1 Galley Oven -GLY 1 EQPT 1- Virtual Electronic C/B # CDC4-13-1", "itemNotesInd": "Y", "itemNumber": "25-34-02", "lastUpdate": "2019-02-27 10:42:18.04572", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"userIdDisplay": "00823179", "legacyFrc": "253402" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Bun Warmers", "ataSectCode": "35", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "(M) Procedure Required:\n\n1. Pull and secure
associated circuit breaker. Observation of a smoke or overheat event requires additional
inspection by Maintenance prior to placarding.\n2. Placard Bun Warmer
"Inoperative".\n\nThe flight crew can reference this deactivation procedure in the EFM
procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required:\n\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event
requires additional inspection by Maintenance prior to placarding.\n2. Placard Bun
Warmer "Inoperative".\n\nThe flight crew can reference this deactivation procedure in the
EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-05-25 08:27:38.959865",
"faaReviewStartTms": "2024-05-01 08:27:38.959865", "intExt": "IG", "itemDesc": "Bun
Warmer / Warming Compartment Damaged / Inoperative", "itemNotesInd": "N",
"itemNumber": "25-35-01", "lastUpdate": "2024-05-01 08:27:49.713175",
"lastUpdateDisplay": "05/01/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "253501" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Coffee Makers", "ataSectCode": "36", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-
02 12:37:17.826191", "faaReviewStartTms": "2011-12-09 12:37:17.826191", "intExt": "IG",
"itemDesc": "Brewing Pot Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-
36-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "253601" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Coffee Makers", "ataSectCode": "36", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "(M) Procedure

Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.(For C series NEF Deactivate an inoperative Coffee maker as follows : On the CB electronic synoptic page, set the following applicable circuit breaker to OUT and LOCK (refer to AMP TASK BD500?-A?-J24?00-?00-?06AAA-?398D-?A):\n2. If leaking, shut off associated water supply.\n3. Placard Coffee Maker "Inoperative". \nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.(For C series NEF Deactivate an inoperative Coffee maker as follows : On the CB electronic synoptic page, set the following applicable circuit breaker to OUT and LOCK (refer to AMP TASK BD500?-A?-J24?00-?00-?06AAA-?398D-?A):\n2. If leaking, shut off associated water supply.\n3. Placard Coffee Maker "Inoperative". \nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-05-24 05:36:41.878452", "faaReviewStartTms": "2019-04-30 05:36:41.878452", "intExt": "IG", "itemDesc": "Coffee Maker Damaged / Inoperative", "itemNotes": "EXPRESSO MAKERS ARE ALSO VALID UNDER THIS NEF. \nC series Coffee maker circuit breakers are electronic. Improper lockout can cause possible ODI's due to reactivation at next electrical power reset. That's why it is imperative to confirm the CB's are LOCKED AND NOT JUST OUT. \nG1 Galley Coffee maker-GLY 1 EQPT 2 - Virtual Electronic C/B # CDC4-11-1\nG4 Galley Coffee maker-GLY 4 EQPT 5 - Virtual Electronic C/B # CDC5-16-1 :Compartment A403 (Inboard)\nG4 Galley Coffee maker-GLY 4 EQPT 6 - Virtual Electronic C/B # CDC5-6-1 : Compartment A402 (outboard)", "itemNotesInd": "Y", "itemNumber": "25-36-02", "lastUpdate": "2019-04-30 05:36:56.999974", "lastUpdateDisplay": "04/30/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253602" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Coffee Makers", "ataSectCode": "36", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:17.903042", "faaReviewStartTms": "2011-12-09 12:37:17.903042", "intExt": "IG", "itemDesc": "Coffee Maker Hot Water Spigot Inoperative", "itemNotesInd": "N", "itemNumber": "25-36-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":

"12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "253603" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Coffee Makers", "ataSectCode": "36", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.(For C series NEF Deactivate an inoperative Coffee maker as follows : On the CB electronic synoptic page, set the following applicable circuit breaker to OUT and LOCK (refer to AMP TASK BD500?-A?-J24?00-?00-?06AAA-?398D-?A):\n2. Shut off associated water supply.\n3. Placard Coffee Maker \"Inoperative\".\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "(M) Procedure Required:\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.(For C series NEF Deactivate an inoperative Coffee maker as follows : On the CB electronic synoptic page, set the following applicable circuit breaker to OUT and LOCK (refer to AMP TASK BD500?-A?-J24?00-?00-?06AAA-?398D-?A):\n2. Shut off associated water supply.\n3. Placard Coffee Maker \"Inoperative\".\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added C Series.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 09:12:05.946893", "faaReviewStartTms": "2019-02-27 09:12:05.946893", "intExt": "IG", "itemDesc": "Coffee Maker Leaking", "itemNotes": "C series Coffee maker circuit breakers are electronic. Improper lockout can cause possible ODI's due to reactivation at next electrical power reset. That's why it is imperative to confirm the CB's are LOCKED AND NOT JUST OUT. \n\nG1 Galley Coffee maker-GLY 1 EQPT 2 - Virtual Electronic C/B # CDC4-11-1\nG4 Galley Coffee maker-GLY 4 EQPT 5 - Virtual Electronic C/B # CDC5-16-1 :Compartment A403 (Inboard)\nG4 Galley Coffee maker-GLY 4 EQPT 6 - Virtual Electronic C/B # CDC5-6-1 : Compartment A402 (outboard)", "itemNotesInd": "Y", "itemNumber": "25-36-04", "lastUpdate": "2019-02-27 09:12:09.89759", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253604" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",

"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Coffee Makers", "ataSectCode": "36", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:18.126241", "faaReviewStartTms": "2011-12-09 12:37:18.126241", "intExt": "IG", "itemDesc": "Coffee Maker Light Inoperative", "itemNotesInd": "N", "itemNumber": "25-36-05", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "253605" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Coffee Makers", "ataSectCode": "36", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:18.18299", "faaReviewStartTms": "2011-12-09 12:37:18.18299", "intExt": "IG", "itemDesc": "Coffee Maker Tray Missing", "itemNotesInd": "N", "itemNumber": "25-36-06", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "253606" }, { "sequenceNumber": "08", "creationDate": "01/08/2014 09:03:27", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Coffee Makers", "ataSectCode": "36", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "M) Procedure Required:\n\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.\n2. If leaking, shut off associated water supply.\n3. Placard Water Boiler \"Inoperative\".\n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "decisionInd": "A", "defRemarks": "M) Procedure Required:\n\n1. Pull and secure associated circuit breaker. Observation of a smoke or overheat event requires additional inspection by Maintenance prior to placarding.\n2. If leaking, shut off associated water supply.\n3. Placard Water Boiler \"Inoperative\".\n\nThe flight crew can reference this deactivation procedure in the EFM procedures section.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 10:44:19.34823",

"faaReviewStartTms": "2019-02-27 10:44:19.34823", "intExt": "IG", "itemDesc": "Water Boiler Inoperative", "itemNotesInd": "N", "itemNumber": "25-36-08", "lastUpdate": "2019-02-27 10:44:26.36641", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9528396", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000684559", "rowInsertEmpNoDisplay": "00684559", "rowInsertTms": "2014-01-08 09:02:42.045221", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "253608" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "All Beverage, Meal, Trash and Service Carts.", "ataSectCode": "38", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must be secured.", "decisionInd": "A", "defRemarks": "Must be secured.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-04-16 09:57:50.644", "faaReviewStartTms": "2012-03-23 09:57:49.879155", "intExt": "IG", "itemDesc": "Cabin Cart Tie Down Damaged / Inoperative", "itemNotesInd": "N", "itemNumber": "25-38-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "253801" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "All Beverage, Meal, Trash and Service Carts.", "ataSectCode": "38", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2019-06-13 08:33:59.580367", "faaReviewStartTms": "2019-05-20 08:33:59.580367", "intExt": "IG", "itemDesc": "3 tier Collapsible Trolley Damaged", "itemNotesInd": "N", "itemNumber": "25-38-02", "lastUpdate": "2019-05-20 08:34:02.794255", "lastUpdateDisplay": "05/20/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "253802" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Verify that table still stows properly or secure

table in stowed position.", "decisionInd": "A", "defRemarks": "Verify that table still stows properly or secure table in stowed position.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:19.131305", "faaReviewStartTms": "2011-12-09 12:37:19.131305", "intExt": "IL", "itemDesc": "Diaper Changing Table Damaged", "itemNotesInd": "N", "itemNumber": "25-40-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "254001" }, { "sequenceNumber": "03", "creationDate": "07/06/2017 10:06:10", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Inspect lavatory trash access door for proper operation and fire seal integrity. If any discrepancies are found with the lavatory trash access door, use MEL 25-00-22B.\n\nRemove lower vanity door/shroud or secure closed with pressure sensitive tape.\nIf door/shroud is removed, send to Atlanta Midfield / Department 206.", "decisionInd": "A", "defRemarks": "Inspect lavatory trash access door for proper operation and fire seal integrity. If any discrepancies are found with the lavatory trash access door, use MEL 25-00-22B.\n\nRemove lower vanity door/shroud or secure closed with pressure sensitive tape.\nIf door/shroud is removed, send to Atlanta Midfield / Department 206.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-07 11:59:29.287442", "faaReviewStartTms": "2026-04-13 11:59:29.287442", "intExt": "IL", "itemDesc": "Lower Vanity Access Door/Shroud Damaged/Missing (B737-900 Only, See notes)", "itemNotes": "Applicable only to B737-900 Delta ship numbers listed below:\n\n3801-3848 when modified by AA 2540-01324, Lower Vanity Door/Shroud Retrofit.\n3849 and subsequent - These ships were modified during production.\n3931-3963 POST AA 2500-01847 \n\nThis deferral is only applicable to the lower vanity outer cosmetic door/shroud. If the lavatory trash access door is damaged or the fire seal of the lavatory trash compartment is compromised, use MEL 25-00-22B.", "itemNotesInd": "Y", "itemNumber": "25-40-03", "lastUpdate": "2026-04-13 11:59:48.783903", "lastUpdateDisplay": "04/13/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2017-07-06 09:51:06.904433", "sceptreAutoDefRemarks": "Lower Vanity Access Door /Shroud Damaged/Missing (B737-900 Only, See notes)", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "254003" },

```
{ "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",  
  "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":  
  "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd":  
  "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y",  
  "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-  
02 12:37:19.319945", "faaReviewStartTms": "2011-12-09 12:37:19.319945", "intExt": "IL",  
  "itemDesc": "Lavatory Coat Hook Damaged / Missing", "itemNotesInd": "N",  
  "itemNumber": "25-40-05", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":  
  "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":  
  "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",  
  "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",  
  "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":  
  "LOADJOB", "legacyFrc": "254005" }, { "sequenceNumber": "06", "creationDate":  
  "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active",  
  "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode":  
  "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A",  
  "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA  
approved list.", "faaReviewEndTms": "2012-01-02 12:37:19.427817", "faaReviewStartTms":  
  "2011-12-09 12:37:19.427817", "intExt": "IL", "itemDesc": "Lavatory Cup Holder Damaged /  
Missing", "itemNotesInd": "N", "itemNumber": "25-40-06", "lastUpdate": "2011-12-09  
12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",  
  "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",  
  "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":  
  "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via  
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254006" }, { "sequenceNumber": "07",  
  "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",  
  "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":  
  "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":  
  "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments":  
  "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02  
12:37:19.483351", "faaReviewStartTms": "2011-12-09 12:37:19.483351", "intExt": "IL",  
  "itemDesc": "Lavatory Deodorizer Holder Damaged or Missing", "itemNotesInd": "N",  
  "itemNumber": "25-40-07", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":  
  "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":  
  "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",  
  "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",  
  "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":  
  "LOADJOB", "legacyFrc": "254007" }, { "sequenceNumber": "08", "creationDate":
```

"12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:19.568029", "faaReviewStartTms": "2011-12-09 12:37:19.568029", "intExt": "IL", "itemDesc": "Lavatory Door Snubber / Ejector Support Damaged Missing", "itemNotesInd": "N", "itemNumber": "25-40-08", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254008" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Door remains in track and door closes normally.", "decisionInd": "A", "defRemarks": "Door remains in track and door closes normally.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:19.628719", "faaReviewStartTms": "2011-12-09 12:37:19.628719", "intExt": "IL", "itemDesc": "Lavatory Entry Door Track roller missing - Door closes Normally", "itemNotesInd": "N", "itemNumber": "25-40-09", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "254009" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:19.704446", "faaReviewStartTms": "2011-12-09 12:37:19.704446", "intExt": "IL", "itemDesc": "Lavatory Inside Door Ash Trays Damaged / Missing", "itemNotes": "For external door ashtrays - see MEL", "itemNotesInd": "Y", "itemNumber": "25-40-10", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254010" }, { "sequenceNumber": "11", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Mirror can only be scratched or damaged in such a fashion not to pose a hazard to occupants. Cracked/damaged mirror may require taping. Graffiti must be covered up.", "decisionInd": "A", "defRemarks": "Mirror can only be scratched or damaged in such a fashion not to pose a hazard to occupants. Cracked/damaged mirror may require taping. Graffiti must be covered up.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "I", "faaReviewEndTms": "2016-01-07 12:36:27.038", "faaReviewStartTms": "2015-12-14 12:36:27.037997", "intExt": "IL", "itemDesc": "Lavatory Mirror Cracked / Damaged", "itemNotesInd": "N", "itemNumber": "25-40-11", "lastUpdate": "2015-12-14 12:37:56.075618", "lastUpdateDisplay": "12/14/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "254011" }, { "sequenceNumber": "12", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:19.787729", "faaReviewStartTms": "2011-12-09 12:37:19.787729", "intExt": "IL", "itemDesc": "Lavatory Paper or Supplies Need Replenishing", "itemNotesInd": "N", "itemNumber": "25-40-12", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254012" }, { "sequenceNumber": "15", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName":

"Hoogenhout", "faaReviewEndTms": "2026-05-14 09:03:01.117605", "faaReviewStartTms": "2026-04-20 09:03:01.117605", "intExt": "IL", "itemDesc": "Lavatory Trim / Wall Coverings / Damaged or Missing(see comments)", "itemNotes": "This NEF item has a 365 day allowable time limit. This NEF cannot be used for the bi-fold door hinge seal.\n\nCan NOT be used for A321NEO door privacy/profile seal, see MEL 38-30-01A.", "itemNotesInd": "Y", "itemNumber": "25-40-15", "lastUpdate": "2026-04-20 09:03:10.485017", "lastUpdateDisplay": "04/20/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "254015" }, { "sequenceNumber": "17", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Access door must fully shut closed and seal for fire containment. If needed see applicable MEL if door stays open. NEF item is for snubber only.", "decisionInd": "A", "defRemarks": "Access door must fully shut closed and seal for fire containment. If needed see applicable MEL if door stays open. NEF item is for snubber only.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-11-10 10:58:50.015", "faaReviewStartTms": "2014-10-17 10:58:50.019416", "intExt": "IL", "itemDesc": "Lavatory Waste Flapper Door Snubber Damaged/Missing", "itemNotes": "NEF item is for snubber only that may not be installed. Maintenance may need to adjust the snubber or remove snubber to allow the door to close flush.", "itemNotesInd": "Y", "itemNumber": "25-40-17", "lastUpdate": "2014-10-21 14:44:01.341244", "lastUpdateDisplay": "10/21/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "254017" }, { "sequenceNumber": "18", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-03-03 09:57:22.768", "faaReviewStartTms": "2014-02-07 09:57:22.764427", "intExt": "IL", "itemDesc": "Soap Dispenser Damaged / Missing", "itemNotes": "The FAA has rescinded policy letter MMEL PL-128, Wheelchair Accessible Lavatories. Any and all restrictions which identified as more restrictive then the MMEL

relief requirements have in regards to wheelchairs accessible lavatories have been removed.", "itemNotesInd": "Y", "itemNumber": "25-40-18", "lastUpdate": "2014-02-20 07:48:49.032378", "lastUpdateDisplay": "02/20/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "254018" }, { "sequenceNumber": "20", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:20.258579", "faaReviewStartTms": "2011-12-09 12:37:20.258579", "intExt": "IL", "itemDesc": "Toilet Paper Roll Holder Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-40-20", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254020" }, { "sequenceNumber": "21", "creationDate": "08/09/2013 17:02:25", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The waste bin door opens and closes normally. Waste door must shut closed for fire containment. If needed see applicable MEL if door stays open.", "decisionInd": "A", "defRemarks": "The waste bin door opens and closes normally. Waste door must shut closed for fire containment. If needed see applicable MEL if door stays open.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-10-21 11:02:39.964", "faaReviewStartTms": "2013-09-27 11:02:39.963359", "intExt": "IL", "itemDesc": "Lavatory Waste Flapper Door Foot Step Inoperative", "itemNotes": "767-300ER - Reference CMM/IPC 25-48-65 page 213", "itemNotesInd": "Y", "itemNumber": "25-40-21", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5097839", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000910407", "rowInsertEmpNoDisplay": "00910407", "rowInsertTms": "2013-08-09 16:58:28.237977", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "254021" }, { "sequenceNumber": "22", "creationDate":

"01/22/2015 09:16:42", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage is limited to areas directly under where the seat interfaces on the shroud assembly (completely covered when the seat is lowered). Damage cannot yield in a hole that penetrates all the way through the shroud in a way that creates a cavity that would be subject to TSA security procedures.", "decisionInd": "A", "defRemarks": "Damage is limited to areas directly under where the seat interfaces on the shroud assembly (completely covered when the seat is lowered). Damage cannot yield in a hole that penetrates all the way through the shroud in a way that creates a cavity that would be subject to TSA security procedures.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-19 08:42:40.400339", "faaReviewStartTms": "2018-09-25 08:42:40.400339", "intExt": "IL", "itemDesc": "Lavatory Shroud Cosmetic Damage", "itemNotesInd": "N", "itemNumber": "25-40-22", "lastUpdate": "2018-09-25 09:23:46.472371", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "6718352", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000914954", "rowInsertEmpNoDisplay": "00914954", "rowInsertTms": "2015-01-22 09:15:02.100643", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "254022" }, { "sequenceNumber": "23", "creationDate": "11/13/2024 12:18:04", "userId": "0000324557", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatories", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Ensure waste flap operates manually to fully close. If any EWIS damage is found (wire damage, arcing, electrical smoking), contact engineering for repair.", "defRemarks": "Ensure waste flap operates manually to fully close. If any EWIS damage is found (wire damage, arcing, electrical smoking), contact engineering for repair.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2024-12-07 12:02:23.941003", "faaReviewStartTms": "2024-11-13 12:02:23.941003", "intExt": "IP", "itemDesc": "Inoperative Sensor, Automatic Touchless Waste Flap (infrared or capacitive)", "itemNotesInd": "N", "itemNumber": "25-40-23", "lastUpdate": "2024-11-13 12:02:23.941003", "lastUpdateDisplay": "11/13/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-13 12:02:23.941003", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "000324557", "legacyFrc": "254023" }, { "sequenceNumber": "01", "creationDate":

"12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatory Modules (Includes Floors)", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 2/20/14. MMEL PL-128 letter rescinded.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-03-03 09:59:06.406", "faaReviewStartTms": "2014-02-07 09:59:06.402554", "intExt": "IL", "itemDesc": "Lavatory Assist Handles Damaged / Missing", "itemNotes": "The FAA has rescinded policy letter MMEL PL-128, Wheelchair Accessible Lavatories. Any and all restrictions which identified as more restrictive than the MMEL relief requirements have in regards to wheelchairs accessible lavatories have been removed.", "itemNotesInd": "Y", "itemNumber": "25-41-01", "lastUpdate": "2014-02-20 08:53:07.49935", "lastUpdateDisplay": "02/20/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "254101" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Lavatory Modules (Includes Floors)", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:20.551109", "faaReviewStartTms": "2011-12-09 12:37:20.551109", "intExt": "IL", "itemDesc": "Lavatory Occupied Sign Inop or Missing", "itemNotesInd": "N", "itemNumber": "25-41-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254103" }, { "sequenceNumber": "01", "creationDate": "11/08/2012 01:37:40", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Lavatory Counter/Basin/Sink Stoppers", "ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Maybe damaged, cracked or dented as long as water cannot leak in the sink cabinet and the integrity of the lavatory waste container is not compromised for fire containment. No sharp edges may be present

and must not present hazard to passengers or crew.", "decisionInd": "A", "defRemarks": "Maybe damaged, cracked or dented as long as water cannot leak in the sink cabinet and the integrity of the lavatory waste container is not compromised for fire containment. No sharp edges may be present and must not present hazard to passengers or crew.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:51:15.136775", "faaReviewStartTms": "2018-01-29 13:51:15.136775", "intExt": "IL", "itemDesc": "Lavatory Countertop Damaged", "itemNotes": "Water basin must be serviceable. This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-42-01", "lastUpdate": "2018-02-22 14:01:25.855389", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "8873356", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000970071", "rowInsertEmpNoDisplay": "00970071", "rowInsertTms": "2012-11-08 01:37:29.11196", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "254201" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cabinets/Soap and Towel Dispensers/Mirror", "ataSectCode": "43", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:20.617776", "faaReviewStartTms": "2011-12-09 12:37:20.617776", "intExt": "IL", "itemDesc": "Amenity Holder Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-43-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "254301" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cabinets/Soap and Towel Dispensers/Mirror", "ataSectCode": "43", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.",

"efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:20.74464", "faaReviewStartTms": "2011-12-09 12:37:20.74464", "intExt": "IL", "itemDesc": "Feminine Napkin Storage Cabinet Damaged", "itemNotesInd": "N", "itemNumber": "25-43-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "254302" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cabinets/Soap and Towel Dispensers/Mirror", "ataSectCode": "43", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:20.786774", "faaReviewStartTms": "2011-12-09 12:37:20.786774", "intExt": "IL", "itemDesc": "Kleenex Holder Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-43-03", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "254303" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Toilets (Seat, Trim and Shrouds)", "ataSectCode": "44", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:20.841058", "faaReviewStartTms": "2011-12-09 12:37:20.841058", "intExt": "IL", "itemDesc": "Lavatory Seat Cover Holder Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-44-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "254401" }, { "sequenceNumber": "02",

"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Toilets (Seat, Trim and Shrouds)", "ataSectCode": "44", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2014-07-03 08:41:19.859", "faaReviewStartTms": "2014-06-09
08:41:19.86276", "intExt": "IL", "itemDesc": "Toilet Seat Lids or Dampers Damaged /
Missing", "itemNotes": "This NEF does include the hold open and slow close function of the
toilet seat/lid damper.", "itemNotesInd": "Y", "itemNumber": "25-44-02", "lastUpdate":
"2014-06-12 12:03:33.644014", "lastUpdateDisplay": "06/12/2014",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "254402" },
{ "sequenceNumber": "01", "creationDate": "09/11/2014 10:02:49", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Expanded relief to the A321/A321
NEO", "faaContactName": "Williams", "faaReviewEndTms": "2023-06-29
13:02:07.239855", "faaReviewStartTms": "2023-06-05 13:02:07.239855", "intExt": "EX",
"itemDesc": "A319/320/321 Cargo Cargo Compartment Bulb Seal Damaged/Missing",
"itemNotes": "Cargo compartment bulb seals (ABS0398, ABS0305, ABS0399 profiles)
between the slanted sidewall panels and the adjacent vertical sidewall and horizontal floor
panels are not required on A319, A320, A321, and A321NEO. Reference IPC 53-22-02-20F
items 50 and 60 and IPC 53-22-02-20J items 180 and 190 for examples of typical
locations.", "itemNotesInd": "Y", "itemNumber": "25-50-01", "lastUpdate": "2023-06-05
13:02:20.297632", "lastUpdateDisplay": "06/05/2023", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000410844", "rowInsertEmpNoDisplay": "00410844",
"rowInsertTms": "2014-09-11 09:58:29.260339", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "255001" }, { "sequenceNumber": "02", "creationDate":
"12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo
Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": ".",

"faaReviewEndTms": "2018-10-19 08:43:41.760018", "faaReviewStartTms": "2018-09-25 08:43:41.760018", "intExt": "EX", "itemDesc": "Cargo Compartment Anti Skid tape Worn / Missing", "itemNotesInd": "N", "itemNumber": "25-50-02", "lastUpdate": "2018-09-25 08:43:47.596211", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "255002" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "For A319, A320, A321, A330, A350, B737, B757, B767 aircraft see the MEL for relief. Required nets must be serviceable. For missing required nets refer to MEL for deferral procedures.", "decisionInd": "A", "defRemarks": "For A319, A320, A321, A330, A350, B737, B757, B767 aircraft see the MEL for relief. Required nets must be serviceable. For missing required nets refer to MEL for deferral procedures.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "A350 added in the Deferral Remarks.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:54:41.176025", "faaReviewStartTms": "2023-11-16 06:54:41.176025", "intExt": "EX", "itemDesc": "Cargo Compartment Barrier Net Damaged/Missing (B717only)(737 cosmetic damage only for inop use MEL see notes) (A220 see MEL 50-22-01)", "itemNotes": "NEF relief for 737 is limited to cosmetic damage for inop and missing please reference MEL 25-00-05A and 25-00-05B. For B717 net can be missing or operationally damaged since there is no MEL relief.", "itemNotesInd": "Y", "itemNumber": "25-50-03", "lastUpdate": "2023-11-16 06:55:26.274278", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "255003" }, { "sequenceNumber": "04", "creationDate": "11/06/2014 14:20:57", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "PDU wheels worn but still operational. If inop see MEL.", "defRemarks": "PDU wheels worn but still operational. If inop see MEL.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2023-03-19 09:40:55.313651", "faaReviewStartTms": "2023-02-23 09:40:55.313651", "intExt": "EX", "itemDesc": "Cargo Moveable PDU Wheels Worn (EXCEPT A330)", "itemNotes": "This FRC to replace 25-52-01 when EFM rev 2 is published and boarded on all fleets. \n\nOn A330s,

defer per MEL item 25-51-01C or 25-51-01D.", "itemNotesInd": "Y", "itemNumber": "25-50-04", "lastUpdate": "2023-02-23 09:41:14.336681", "lastUpdateDisplay": "02/23/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-06 14:18:20.157871", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "255004" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.112821", "faaReviewStartTms": "2011-12-09 12:37:21.112821", "intExt": "EX", "itemDesc": "Cargo Compartment Has Fish Smell", "itemNotesInd": "N", "itemNumber": "25-50-05", "lastUpdate": "2012-06-25 14:51:17.214934", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "255005" }, { "sequenceNumber": "06", "creationDate": "11/06/2014 14:31:50", "userId": "0000406009", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2020-01-16 08:07:47.542903", "faaReviewStartTms": "2019-12-23 08:07:47.542903", "intExt": "EX", "itemDesc": "Cargo Net Hooks Damaged/Missing", "itemNotes": "Hooks used to keep cargo nets out of the way during loading.\r\n\r\nThis FRC to replace 25-56-01 when EFM rev 2 is published and boarded on all fleets.", "itemNotesInd": "Y", "itemNumber": "25-50-06", "lastUpdate": "2019-12-23 08:07:54.922359", "lastUpdateDisplay": "12/23/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2014-11-06 14:24:45.425272", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00406009", "legacyFrc": "255006" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "O",

"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.188153", "faaReviewStartTms": "2011-12-09 12:37:21.188153", "intExt": "EX", "itemDesc": "Cargo Compartment has Graffiti", "itemNotesInd": "N", "itemNumber": "25-50-08", "lastUpdate": "2012-06-25 14:51:17.233258", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "255008" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:50:45.169487", "faaReviewStartTms": "2018-01-29 13:50:45.169487", "intExt": "EX", "itemDesc": "Cargo Compartment Non-Slip Tape Worn / Missing", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-50-09", "lastUpdate": "2018-02-22 14:01:36.509882", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "255009" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.290609", "faaReviewStartTms": "2011-12-09 12:37:21.290609", "intExt": "EX", "itemDesc": "Cargo Compartment Profile Bar Damaged", "itemNotesInd": "N", "itemNumber": "25-50-10", "lastUpdate": "2012-06-25 14:51:17.271922", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "255010" }, { "sequenceNumber": "11", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":

"Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.336891", "faaReviewStartTms": "2011-12-09 12:37:21.336891", "intExt": "EX",
"itemDesc": "Cargo Compartment Sidewall Trim Damaged / Missing", "itemNotesInd": "N",
"itemNumber": "25-50-11", "lastUpdate": "2012-06-25 14:51:17.290037",
"lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "LOADJOB", "legacyFrc": "255011" }, { "sequenceNumber": "12",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.442816", "faaReviewStartTms": "2011-12-09 12:37:21.442816", "intExt": "EX",
"itemDesc": "Cargo Control Pendant Rubber Cover Damaged or Poor Condition",
"itemNotesInd": "N", "itemNumber": "25-50-12", "lastUpdate": "2012-06-25
14:51:17.314723", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "255012" }, { "sequenceNumber": "13",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.565736", "faaReviewStartTms": "2011-12-09 12:37:21.565736", "intExt": "EX",
"itemDesc": "Cargo Door Draft Seal Worn", "itemNotesInd": "N", "itemNumber": "25-50-
13", "lastUpdate": "2012-06-25 14:51:17.336074", "lastUpdateDisplay": "06/25/2012",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "255013" },
{ "sequenceNumber": "14", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":

"25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:21.724398", "faaReviewStartTms": "2011-12-09 12:37:21.724398", "intExt": "EX", "itemDesc": "Cargo Pendant Holder Damaged", "itemNotesInd": "N", "itemNumber": "25-50-14", "lastUpdate": "2012-06-25 14:51:17.350814", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "255014", { "sequenceNumber": "15", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-09-21 16:19:47.587", "faaReviewStartTms": "2014-08-28 16:19:47.588956", "intExt": "EX", "itemDesc": "Cargo Repair Kit Expired/Damaged/Missing", "itemNotesInd": "N", "itemNumber": "25-50-15", "lastUpdate": "2014-10-22 16:47:05.43868", "lastUpdateDisplay": "10/22/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "255015", { "sequenceNumber": "16", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-26 16:00:26.41", "faaReviewStartTms": "2014-12-02 16:00:26.4091", "intExt": "EX", "itemDesc": "Master Cargo Control Indication Lights/Switch Covers (Panel/Pendant Still Operative)", "itemNotes": "This item is for the lights or switch covers on the cargo loading control panel or pendant. The panel / pendant still controls the loading system properly. For inoperative panel / pendant, see MEL.", "itemNotesInd": "Y", "itemNumber": "25-50-16", "lastUpdate": "2014-12-02 16:00:30.134702", "lastUpdateDisplay": "12/02/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"userIdDisplay": "00637639", "legacyFrc": "255016" }, { "sequenceNumber": "17",
"creationDate": "05/23/2022 12:48:45", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Cargo Compartments", "ataSectCode": "50", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOProcedure": "B767-300 (POST AA 2553-01018) Cargo Pendant
Plastic Cover (3D Printed Plastic Protective Cover - P/N 25-5790-001) may be damaged or
missing. No sharp edges or hazards to personnel are permitted. Round sharp edges or
remove damaged cover. No damage to underlying pendant or wiring is permitted.",
"decisionInd": "A", "defRemarks": "B767-300 (POST AA 2553-01018) Cargo Pendant Plastic
Cover (3D Printed Plastic Protective Cover - P/N 25-5790-001) may be damaged or missing.
No sharp edges or hazards to personnel are permitted. Round sharp edges or remove
damaged cover. No damage to underlying pendant or wiring is permitted.", "efmTab": "O",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted",
"faaContactName": "Bill L. Williams", "faaReviewEndTms": "2022-06-18 13:44:54.333933",
"faaReviewStartTms": "2022-05-25 13:44:54.333933", "intExt": "IP", "itemDesc": "B767-300
Cargo Pendant Plastic Cover (POST AA 2553-01018)", "itemNotes": "3D Printed Plastic
Protective Cover (P/N 25-5790-001)", "itemNotesInd": "Y", "itemNumber": "25-50-17",
"lastUpdate": "2022-06-02 09:59:16.441903", "lastUpdateDisplay": "06/02/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2022-05-23 12:41:42.423973",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "255017" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"25", "ataDesc": "Emergency Equipment", "ataSectCode": "60", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Redundant equipment may be
missing provided a safety belt, life vest and O2 mask remain to provide for demo briefing
aids.", "decisionInd": "A", "defRemarks": "Redundant equipment may be missing provided
a safety belt, life vest and O2 mask remain to provide for demo briefing aids.", "efmTab":
"M", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-04-16 09:53:59.407",
"faaReviewStartTms": "2012-03-23 09:53:58.642782", "intExt": "IP", "itemDesc": "Demo
Equipment (Safety Belt, Life Vest, O2 Mask) Excess Equipment", "itemNotesInd": "N",
"itemNumber": "25-60-03", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"userIdDisplay": "00245058", "legacyFrc": "256003" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Emergency Equipment", "ataSectCode": "60", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "M", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-12-21 12:23:13.954526",
"faaReviewStartTms": "2018-11-27 12:23:13.954526", "intExt": "IP", "itemDesc": "Security
Kit Inoperative, Missing or Missing Equipment", "itemNotes": "Includes Handcuffs",
"itemNotesInd": "Y", "itemNumber": "25-60-04", "lastUpdate": "2018-11-27
12:23:17.715677", "lastUpdateDisplay": "11/27/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "256004" }, { "sequenceNumber": "06",
"creationDate": "02/24/2012 12:41:42", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Emergency Equipment", "ataSectCode": "60", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "M", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "biever", "faaReviewEndTms": "2014-12-05 14:41:08.211",
"faaReviewStartTms": "2014-11-11 14:41:08.211773", "intExt": "IP", "itemDesc": "Demo
Equipment Pouch/Container Broken or Missing", "itemNotesInd": "N", "itemNumber": "25-
60-06", "lastUpdate": "2014-11-11 14:41:13.533278", "lastUpdateDisplay": "11/11/2014",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "2220212",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-02-24 12:26:16.926599",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "256006" },
{ "sequenceNumber": "07", "creationDate": "03/23/2012 08:44:15", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "25", "ataDesc": "Emergency Equipment", "ataSectCode": "60",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"M", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:49:33.730579",
"faaReviewStartTms": "2018-01-29 13:49:33.730579", "intExt": "IP", "itemDesc": "Demo O2
Mask Damaged/Missing", "itemNotes": "This is for the spare mask only.This NEF item has a
365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-60-07",
"lastUpdate": "2018-02-22 14:01:45.94195", "lastUpdateDisplay": "02/22/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",

"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000458787",
"rowInsertEmpNoDisplay": "00458787", "rowInsertTms": "2012-03-23 08:41:30.165989",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "256007" },
{ "sequenceNumber": "08", "creationDate": "06/25/2013 10:19:33", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "25", "ataDesc": "Emergency Equipment", "ataSectCode": "60",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"K", "faaAcceptanceRequiredInd": "Y", "faaComments": "Allowable Time 10 days.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-08-02 15:54:40.664",
"faaReviewStartTms": "2013-07-09 15:54:40.700647", "intExt": "IP", "itemDesc":
"Evacuation Preparation Checklist and/or Holder Damaged or Missing", "itemNotes": "This
NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-60-
08", "lastUpdate": "2013-07-17 07:43:31.754673", "lastUpdateDisplay": "07/17/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9775663",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-06-25 10:18:26.067879",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "256008" },
{ "sequenceNumber": "09", "creationDate": "11/14/2018 07:52:18", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Emergency Equipment", "ataSectCode": "60",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"S", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added additional fleet types.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2020-06-21 11:47:58.695632",
"faaReviewStartTms": "2020-05-28 11:47:58.695632", "intExt": "IP", "itemDesc": ""CREW
ONLY" labeled HEADREST COVERS/ BAG MISSING OR DAMAGED", "itemNotes": "CREW
ONLY\u001A labeled removable headrest covers on the aft RH seats of the cabin. These
seats will be \u001Asoft blocked\u001A, which means Revenue Management can still sell
the aft RH seats to revenue passengers, however, they will not be assigned to any non-
revs. If revenue passengers are in the seat, then F/A\u001As can move them to a location
forward in the cabin to free up the seats to be available during turbulence. The headrest
covers (Qty: 2) will be stored in the storage bag during Taxi/Takeoff/Landing and stowed in
the emergency equipment overhead bin. They are not permanently installed on the seat.",
"itemNotesInd": "Y", "itemNumber": "25-60-09", "lastUpdate": "2020-05-29
17:50:13.634213", "lastUpdateDisplay": "05/29/2020", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179",

"rowInsertTms": "2018-11-14 07:36:12.966978", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "256009" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "25", "ataDesc": "Escape Slides/Rafts", "ataSectCode": "61", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Cover port with clear tape to prevent rain water ingress.", "decisionInd": "A", "defRemarks": "Cover port with clear tape to prevent rain water ingress.", "efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-19 15:26:07.543", "faaReviewStartTms": "2014-11-25 15:26:07.539336", "intExt": "IP", "itemDesc": "Evacuation Slide Bottle View Port Lens Damaged / Missing", "itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-61-01", "lastUpdate": "2014-11-25 15:26:10.765103", "lastUpdateDisplay": "11/25/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "256101" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Escape Slides/Rafts", "ataSectCode": "61", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": ".", "faaReviewEndTms": "2018-10-19 08:44:57.340692", "faaReviewStartTms": "2018-09-25 08:44:57.340692", "intExt": "IP", "itemDesc": "Slide Bustle Scuffed", "itemNotesInd": "N", "itemNumber": "25-61-07", "lastUpdate": "2018-09-25 09:23:51.346058", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "256107" }, { "sequenceNumber": "09", "creationDate": "04/21/2026 08:21:31", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Escape Slides/Rafts", "ataSectCode": "61", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "The red pull tab must be present and in serviceable condition. Only the clear plastic cover can be missing or damaged. If damaged, remove plastic cover from the aircraft to ensure pull tab is accessible and visible.", "decisionInd": "A", "defRemarks": "The red pull tab must be present and in serviceable condition. Only the clear plastic cover can be missing or damaged. If

damaged, remove plastic cover from the aircraft to ensure pull tab is accessible and visible.", "efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2026-05-17 09:57:43.993202", "faaReviewStartTms": "2026-04-23 09:57:43.993202", "intExt": "IP", "itemDesc": "Slide Manual Inflation Pull-Tab/Handle Clear Cover", "itemNotesInd": "N", "itemNumber": "25-61-09", "lastUpdate": "2026-04-23 11:57:52.903368", "lastUpdateDisplay": "04/23/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2026-04-21 08:10:59.632785", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "256109" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Life Vests and Containers", "ataSectCode": "62", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Crew Life Vest must be able to remain secure within the designated storage pocket and not be vulnerable to falling out.", "decisionInd": "A", "defRemarks": "Crew Life Vest must be able to remain secure within the designated storage pocket and not be vulnerable to falling out.", "efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-05 14:46:41.786", "faaReviewStartTms": "2014-11-11 14:46:41.785834", "intExt": "IP", "itemDesc": "Crew Life Vest Cover Missing or Weak Velcro", "itemNotesInd": "N", "itemNumber": "25-62-01", "lastUpdate": "2014-11-11 14:46:46.200251", "lastUpdateDisplay": "11/11/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "256201" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Life Vests and Containers", "ataSectCode": "62", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If end cap is missing, perform visual inspection to ensure life vest pouch has not been compromised. Make sure life vest placard is facing the floor.\r\n\r\nIf the life vest container cover is damaged, ensure there are no sharp edges that could present a safety hazard.", "decisionInd": "A", "defRemarks": "If end cap is missing, perform visual inspection to ensure life vest pouch has not been compromised. Make sure life vest placard is facing the floor.\r\n\r\nIf the life vest container cover is damaged, ensure there are no sharp edges that could present a safety hazard.", "efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaComments": "Updated NEF Item Notes.",

"faaContactName": "Hoogenhout", "faaReviewEndTms": "2016-05-26 15:45:57.226",
"faaReviewStartTms": "2016-05-02 15:45:57.230534", "intExt": "IP", "itemDesc": "Life Vest
Container End Cap Damaged / Missing", "itemNotes": "If the life vest container cap seal is
missing/broken, check the MEL for applicability. If the seal is missing/broken and not listed
in the MEL, use NEF code 25-62-07.", "itemNotesInd": "Y", "itemNumber": "25-62-03",
"lastUpdate": "2016-05-23 07:30:49.083494", "lastUpdateDisplay": "05/23/2016",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "256203" },
{ "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Life Vests and Containers", "ataSectCode": "62",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "For
those associated with crew or passenger seats, refer to associated MEL.\n\nIf red life vest
seal security seal is missing, perform visual inspection to ensure life vest pouch has not
been compromised. Make sure life vest placard is facing the floor.", "decisionInd": "A",
"defRemarks": "For those associated with crew or passenger seats, refer to associated
MEL.\n\nIf red life vest seal security seal is missing, perform visual inspection to ensure life
vest pouch has not been compromised. Make sure life vest placard is facing the floor.",
"efmTab": "M", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A321.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-14 08:19:46.701536",
"faaReviewStartTms": "2018-09-20 08:19:46.701536", "intExt": "IP", "itemDesc": "Life Vest
Seals Broken/Missing", "itemNotesInd": "N", "itemNumber": "25-62-07", "lastUpdate":
"2018-09-20 08:19:57.556406", "lastUpdateDisplay": "09/20/2018",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "256207" },
{ "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId":
"0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Life Vests and Containers", "ataSectCode": "62",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if
item is still contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using this NEF Item. For those associated with crew or passenger seats, refer to
associated MEL.", "decisionInd": "A", "defRemarks": "Check if item is still contained in the
MEL; if yes then complete the MEL deferral process, otherwise defer using this NEF Item.
For those associated with crew or passenger seats, refer to associated MEL.", "efmTab":

"M", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A321.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2016-05-16 14:43:34.183",
"faaReviewStartTms": "2016-04-22 14:43:34.187943", "intExt": "IP", "itemDesc": "Spare Life
Vest Bag Damaged", "itemNotes": "As of 06/18/2014 all MELs contain spare vests
inop/missing except for the A319/320/321 MEL.", "itemNotesInd": "Y", "itemNumber": "25-
62-08", "lastUpdate": "2016-04-26 10:09:19.614833", "lastUpdateDisplay": "04/26/2016",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "256208" },
{ "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId":
"0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Life Vests and Containers", "ataSectCode": "62",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if
item is still contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using this NEF Item. For those associated with crew or passenger seats, refer to
associated MEL.", "decisionInd": "A", "defRemarks": "Check if item is still contained in the
MEL; if yes then complete the MEL deferral process, otherwise defer using this NEF Item.
For those associated with crew or passenger seats, refer to associated MEL.", "efmTab":
"M", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A321.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2016-05-16 14:44:17.782",
"faaReviewStartTms": "2016-04-22 14:44:17.782654", "intExt": "IP", "itemDesc": "Spare Life
Vests Missing", "itemNotes": "As of 06/18/2014 all MELs contain spare vests inop/missing
except for the A319/320/321 MEL.", "itemNotesInd": "Y", "itemNumber": "25-62-09",
"lastUpdate": "2016-04-26 10:09:31.732131", "lastUpdateDisplay": "04/26/2016",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "256209" },
{ "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Life Vests and Containers", "ataSectCode": "62",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab":
"M", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2014-11-27 14:57:34.285", "faaReviewStartTms": "2014-11-03
14:57:34.285", "intExt": "IP", "itemDesc": "Survival Kit Container Strap Damaged",
"itemNotesInd": "N", "itemNumber": "25-62-10", "lastUpdate": "2014-11-13
07:38:47.766598", "lastUpdateDisplay": "11/13/2014", "legacyDeltaAirworthyInd": "N",

"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "256210" }, { "sequenceNumber": "11",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"First Aid/Medical Kits/UPK/ Security Kit", "ataSectCode": "63", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "May require Temporary
Strap.", "decisionInd": "A", "defRemarks": "May require Temporary Strap.", "efmTab": "M",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:24.331872", "faaReviewStartTms": "2011-
12-09 12:37:24.331872", "intExt": "IP", "itemDesc": "First-Aid Kit Strap Damaged /
Inoperative", "itemNotes": "This item is only for the strap that holds the kit. If kit is
unserviceable or if security seal is broken see MEL.", "itemNotesInd": "Y", "itemNumber":
"25-63-11", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay":
"12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00245058", "legacyFrc": "256311" }, { "sequenceNumber": "04", "creationDate":
"12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Emergency
Equipment (Flashlights, Axes, Megaphones, Survival Kits)", "ataSectCode": "65",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"M", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2014-11-27 14:51:25.436", "faaReviewStartTms": "2014-11-03
14:51:25.435488", "intExt": "IP", "itemDesc": "Flash Light Holder Seals Broken/Missing",
"itemNotesInd": "N", "itemNumber": "25-65-04", "lastUpdate": "2014-11-13
07:39:42.481266", "lastUpdateDisplay": "11/13/2014", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "256504" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Emergency Equipment (Flashlights, Axes, Megaphones, Survival Kits)", "ataSectCode":
"65", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure":
"Crash Axe must still be secured.", "decisionInd": "A", "defRemarks": "Crash Axe must still

be secured.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:24.995472", "faaReviewStartTms": "2011-12-09 12:37:24.995472", "intExt": "EX",
"itemDesc": "Flight Deck Crash Axe Cover Damaged / Missing", "itemNotesInd": "N",
"itemNumber": "25-65-05", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00245058", "legacyFrc": "256505" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Main Equipment Center", "ataSectCode": "71", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-
02 12:37:25.289095", "faaReviewStartTms": "2011-12-09 12:37:25.289095", "intExt": "EX",
"itemDesc": "Electrostatic Wrist Strap Damaged / Missing", "itemNotesInd": "N",
"itemNumber": "25-71-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":
"12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"LOADJOB", "legacyFrc": "257101" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Miscellaneous/Cabin
Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns", "ataSectCode": "73",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:25.329148", "faaReviewStartTms": "2011-
12-09 12:37:25.329148", "intExt": "EX", "itemDesc": "A/C Aft Service Bay Indication Light
Lenses Cracked", "itemNotesInd": "N", "itemNumber": "25-73-01", "lastUpdate": "2011-12-
09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "257301" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":

"Miscellaneous/Cabin Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns",
"ataSectCode": "73", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:25.379194", "faaReviewStartTms": "2011-12-09 12:37:25.379194", "intExt": "EX",
"itemDesc": "A/C Service Bay Compartment Light Lenses Cracked", "itemNotesInd": "N",
"itemNumber": "25-73-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":
"12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"LOADJOB", "legacyFrc": "257302" }, { "sequenceNumber": "03", "creationDate":
"12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Miscellaneous/Cabin
Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns", "ataSectCode": "73",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:25.419722", "faaReviewStartTms": "2011-
12-09 12:37:25.419722", "intExt": "EX", "itemDesc": "Aft Service Bay Insulation Blanket
Worn / Damaged", "itemNotesInd": "N", "itemNumber": "25-73-03", "lastUpdate": "2011-
12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "257303" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Miscellaneous/Cabin Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns",
"ataSectCode": "73", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:25.460545", "faaReviewStartTms": "2011-12-09 12:37:25.460545", "intExt": "EX",
"itemDesc": "E & E Service Bay Floor Panel Damaged", "itemNotesInd": "N", "itemNumber":
"25-73-04", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "257304" },

{ "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Miscellaneous/Cabin Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns", "ataSectCode": "73", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Does not apply to tape over MD90 nitrogen discharge port. Not for engine and T/R hoist point see MEL or specific NEF.", "decisionInd": "A", "defRemarks": "Does not apply to tape over MD90 nitrogen discharge port. Not for engine and T/R hoist point see MEL or specific NEF.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-07-02 13:34:09.777", "faaReviewStartTms": "2017-06-08 13:35:05.167705", "intExt": "EX", "itemDesc": "Hoist Point Plug / Cover Missing (NON ENGINE OR T/R)", "itemNotes": "All Aircraft passenger door, cargo doors slat, flap, vertical stabilizer, horizontal stabilizer, rudder, elevator hoist point plugs and hoist point covers. Not for engine and T/R hoist point see MEL or specific NEF.", "itemNotesInd": "Y", "itemNumber": "25-73-06", "lastUpdate": "2017-07-05 10:19:17.772378", "lastUpdateDisplay": "07/05/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "257306" }, { "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Miscellaneous/Cabin Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns", "ataSectCode": "73", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:53:15.50253", "faaReviewStartTms": "2022-03-08 08:53:15.50253", "intExt": "IP", "itemDesc": "IFE Cabinet Trim and Cosmetic Items Damaged / Missing", "itemNotes": "MISC Items Having Only Cosmetic Function.This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-73-07", "lastUpdate": "2022-03-08 08:53:21.571201", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00324557", "legacyFrc": "257307" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Miscellaneous/Cabin Accommodations/Wheelchair/Demo EQ/Bassinet/Seat Belt Extns", "ataSectCode": "73", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Captain is to brief lead flight attendant to use alternate method per On-Board Manual.", "decisionInd": "A", "defRemarks": "Captain is to brief lead flight attendant to use alternate method per On-Board Manual.", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2019-03-23 09:16:47.86921", "faaReviewStartTms": "2019-02-27 09:16:47.86921", "intExt": "EX", "itemDesc": "PSU Tool Missing- Must Brief F/A to use alt method per OBM", "itemNotesInd": "N", "itemNumber": "25-73-08", "lastUpdate": "2019-02-27 09:16:51.747283", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "257308" }, { "sequenceNumber": "01", "creationDate": "11/18/2024 09:17:32", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must still be functional and secure.", "defRemarks": "Must still be functional and secure.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to duplicate/split pilot and FA NEF/CTL/OPN items.", "faaContactName": "See below", "faaReviewEndTms": "2024-12-12 09:05:07.986826", "faaReviewStartTms": "2024-11-18 09:05:07.986826", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area Assist handles Poor Condition", "itemNotesInd": "N", "itemNumber": "25-74-01", "lastUpdate": "2024-11-18 12:17:53.582809", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:04:39.773341", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257401" }, { "sequenceNumber": "02", "creationDate": "11/18/2024 09:21:40", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. \n\nRemoval of the bunk door is

acceptable for repair development.", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item.

\n\nRemoval of the bunk door is acceptable for repair development.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms": "2025-01-17 09:48:12.264938", "faaReviewStartTms": "2024-12-24 09:48:12.264938", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area Bunk Door (Check MEL) A330-200 ONLY", "itemNotes": "This NEF is for the pilot to FA pass through door on A330-200 aircraft ONLY", "itemNotesInd": "Y", "itemNumber": "25-74-02", "lastUpdate": "2024-12-24 09:50:20.991766", "lastUpdateDisplay": "12/24/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:08:15.805533", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257402" }, { "sequenceNumber": "03", "creationDate": "11/18/2024 09:16:32", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms": "2024-12-12 09:11:43.289098", "faaReviewStartTms": "2024-11-18 09:11:43.289098", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area Grills / Vents Damaged", "itemNotesInd": "N", "itemNumber": "25-74-03", "lastUpdate": "2024-11-18 12:18:37.053608", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:11:43.289098", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257403" }, { "sequenceNumber": "04", "creationDate": "11/18/2024 09:15:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms": "2024-12-12 09:15:47.06619", "faaReviewStartTms": "2024-11-18 09:15:47.06619", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area Interior Trim or Wall Covering Damaged / Missing", "itemNotes": "This NEF item has a 365-day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "25-74-04", "lastUpdate": "2024-11-18

12:18:48.839332", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2024-11-18 09:15:47.06619", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "257404" }, { "sequenceNumber": "05", "creationDate":
"11/18/2024 09:26:38", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant
Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":
"0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the
MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 25-
25-07F for B767-300, MEL 25-25-07F for B767-400.", "defRemarks": "Check if item is
contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using
the NEF item. At this time, reference MEL 25-25-07F for B767-300, MEL 25-25-07F for
B767-400.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/
FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below",
"faaReviewEndTms": "2024-12-12 09:20:10.388578", "faaReviewStartTms": "2024-11-18
09:20:10.388578", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area Pillows,
Blankets, Mattress Pads, Sheets damaged/ Missing", "itemNotesInd": "N", "itemNumber":
"25-74-05", "lastUpdate": "2024-11-18 12:19:05.73619", "lastUpdateDisplay":
"11/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:20:10.388578",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257405" },
{ "sequenceNumber": "06", "creationDate": "11/18/2024 09:36:26", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If
ashtray is missing and leaves hole exposed, inspect for foreign objects then cover with
suitable pressure sensitive tape (i.e. bag bin tape, nylon or fiberglass reinforced tape, not
masking tape).", "defRemarks": "If ashtray is missing and leaves hole exposed, inspect for
foreign objects then cover with suitable pressure sensitive tape (i.e. bag bin tape, nylon or
fiberglass reinforced tape, not masking tape).", "efmTab": "R",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot
and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms":
"2024-12-12 09:23:57.749952", "faaReviewStartTms": "2024-11-18 09:23:57.749952",
"intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Ashtray Damaged / Missing",

"itemNotesInd": "N", "itemNumber": "25-74-06", "lastUpdate": "2024-11-18 12:19:34.701555", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:23:57.749952", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257406" }, { "sequenceNumber": "07", "creationDate": "11/18/2024 09:37:01", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms": "2024-12-12 09:27:15.586467", "faaReviewStartTms": "2024-11-18 09:27:15.586467", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Coat / Hat Hangar or Clip Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-74-07", "lastUpdate": "2024-11-18 12:19:48.663957", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:27:15.586467", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257407" }, { "sequenceNumber": "09", "creationDate": "11/18/2024 09:40:31", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "If cover is missing, place masking tape over the peep hole to ensure security.", "defRemarks": "If cover is missing, place masking tape over the peep hole to ensure security.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms": "2024-12-12 09:39:21.70228", "faaReviewStartTms": "2024-11-18 09:39:21.70228", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Peep Hole Blocked / Damaged", "itemNotes": "Crew rest door peep hole in A330", "itemNotesInd": "Y", "itemNumber": "25-74-09", "lastUpdate": "2024-11-18 12:20:24.554206", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 09:39:21.70228", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257409" },

```
{ "sequenceNumber": "10", "creationDate": "11/18/2024 09:52:34", "userId":  
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74",  
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "R",  
"faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot  
and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms":  
"2024-12-12 09:43:21.553843", "faaReviewStartTms": "2024-11-18 09:43:21.553843",  
"intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Stowage Compartment or Bag  
Damaged", "itemNotesInd": "N", "itemNumber": "25-74-10", "lastUpdate": "2024-11-18  
12:20:35.219172", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N",  
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",  
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",  
"rowInsertTms": "2024-11-18 09:43:21.553843", "sceptreAutoDefRemarks": "Auto  
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":  
"00324557", "legacyFrc": "257410" }, { "sequenceNumber": "11", "creationDate":  
"11/18/2024 09:54:54", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":  
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant  
Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":  
"0", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA  
approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below",  
"faaReviewEndTms": "2024-12-12 09:47:30.444618", "faaReviewStartTms": "2024-11-18  
09:47:30.444618", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Tray Table  
Damaged / Missing", "itemNotesInd": "N", "itemNumber": "25-74-11", "lastUpdate": "2024-  
11-18 12:20:52.053123", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd":  
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",  
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",  
"rowInsertTms": "2024-11-18 09:47:30.444618", "sceptreAutoDefRemarks": "Auto  
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":  
"00324557", "legacyFrc": "257411" }, { "sequenceNumber": "12", "creationDate":  
"11/18/2024 09:52:47", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":  
"Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Flight Attendant  
Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":  
"0", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA  
approval to split pilot and FA NEF/CTL/OPN items", "faaContactName": "See below",  
"faaReviewEndTms": "2024-12-12 09:52:16.031043", "faaReviewStartTms": "2024-11-18  
09:52:16.031043", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Vanity Mirrors  
Damaged / Missing", "itemNotes": "This NEF item has a 365-day allowable time limit.",  
"itemNotesInd": "Y", "itemNumber": "25-74-12", "lastUpdate": "2024-11-18
```

12:21:10.2848", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2024-11-18 09:52:16.031043", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "257412" }, { "sequenceNumber": "13", "creationDate":
"11/18/2024 10:02:41", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant
Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":
"0", "deactMOProcedure": "Must not present hazard to passengers or crew. Flapper door
and access door must be secured closed and placarded: \"DO NOT USE\"", "defRemarks":
"Must not present hazard to passengers or crew. Flapper door and access door must be
secured closed and placarded: \"DO NOT USE\"", "efmTab": "R",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split pilot
and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms":
"2024-12-12 09:55:17.444736", "faaReviewStartTms": "2024-11-18 09:55:17.444736",
"intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Trash Liner Damaged/Missing",
"itemNotesInd": "N", "itemNumber": "25-74-13", "lastUpdate": "2024-11-18
12:21:28.763049", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2024-11-18 09:55:17.444736", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "257413" }, { "sequenceNumber": "14", "creationDate":
"11/18/2024 10:42:26", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc": "Flight Attendant
Crew Rest", "ataSectCode": "74", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":
"0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the
MEL deferral process, otherwise defer using the NEF item.", "defRemarks": "Check if item
is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer
using the NEF item.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Added w/ FAA approval to split pilot and FA NEF/CTL/OPN items", "faaContactName":
"See below", "faaReviewEndTms": "2024-12-12 10:40:41.105109", "faaReviewStartTms":
"2024-11-18 10:40:41.105109", "intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area
Bunk Curtain (Check MEL)", "itemNotesInd": "N", "itemNumber": "25-74-14", "lastUpdate":
"2024-11-18 12:21:46.108354", "lastUpdateDisplay": "11/18/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557",

"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-11-18 10:40:41.105109",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "257414" },
{ "sequenceNumber": "15", "creationDate": "11/18/2024 10:58:22", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "25", "ataDesc": "Flight Attendant Crew Rest", "ataSectCode": "74",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if
item is contained in the MEL; if yes then complete the MEL deferral process, otherwise
defer using the NEF item.", "defRemarks": "Check if item is contained in the MEL; if yes
then complete the MEL deferral process, otherwise defer using the NEF item.", "efmTab":
"R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added w/ FAA approval to split
pilot and FA NEF/CTL/OPN items", "faaContactName": "See below", "faaReviewEndTms":
"2024-12-12 10:43:54.868363", "faaReviewStartTms": "2024-11-18 10:43:54.868363",
"intExt": "IP", "itemDesc": "Flight Attendant Crew Rest Area Bunk Curtain Tie-Back (Check
MEL)", "itemNotesInd": "N", "itemNumber": "25-74-15", "lastUpdate": "2024-11-18
12:22:08.422814", "lastUpdateDisplay": "11/18/2024", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2024-11-18 10:43:54.868363", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "257415" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "365", "ataChapterCode": "25", "ataDesc": "Interior Stairways",
"ataSectCode": "75", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list. Clarified allowable time.", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2018-02-22 13:47:38.576581", "faaReviewStartTms":
"2018-01-29 13:47:38.576581", "intExt": "EX", "itemDesc": "Aft Stairway Ceiling or Sidewall
Panel Damaged / Poor Condition", "itemNotes": "This NEF item has a 365 day allowable
time limit.", "itemNotesInd": "Y", "itemNumber": "25-75-01", "lastUpdate": "2018-02-22
14:02:07.355941", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "257501" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "25", "ataDesc":
"Interior Stairways", "ataSectCode": "75", "autoDefCde": "NEF", "crewDefInd": "Y",

"daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:25.796345", "faaReviewStartTms": "2011-12-09 12:37:25.796345", "intExt": "EX",
"itemDesc": "Airstair Control Handle Knob Damaged / Missing", "itemNotes": "Airstair handle must still be operational.", "itemNotesInd": "Y", "itemNumber": "25-75-02",
"lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "257502" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "26", "ataDesc": "Cargo Smoke/(Avionics Compartment Fire and Smoke Detection-A350 only)", "ataSectCode": "15", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Detector must operate normally and grill must still protect detector. Must not present hazard.", "decisionInd": "A", "defRemarks": "Detector must operate normally and grill must still protect detector. Must not present hazard.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:26.043745", "faaReviewStartTms": "2011-12-09 12:37:26.043745", "intExt": "EX", "itemDesc": "Cargo Smoke Detector Grill Damaged", "itemNotesInd": "N", "itemNumber": "26-15-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "261501" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "26", "ataDesc": "Lavatory Smoke", "ataSectCode": "17", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOProcedure": "Detector Must Operate Normally and grill must still protect detector. Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "decisionInd": "A", "defRemarks": "Detector Must Operate Normally and grill must still protect detector. Damage must not be to an extent that it leaves an opening that items could fall into or that would be a security concern.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:26.183678",
"faaReviewStartTms": "2011-12-09 12:37:26.183678", "intExt": "IL", "itemDesc": "Lavatory Smoke Detector Grill Damaged", "itemNotesInd": "N", "itemNumber": "26-17-03",

"lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "261703" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"26", "ataDesc": "Cabin, Galley, Crew Rest Smoke/ Overheat, SDCU", "ataSectCode": "19",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure":
"Detector Must Operate Normally and grill must still protect detector.", "decisionInd": "A",
"defRemarks": "Detector Must Operate Normally and grill must still protect detector.",
"efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaReviewEndTms": "2012-01-02 12:37:26.375396", "faaReviewStartTms":
"2011-12-09 12:37:26.375396", "intExt": "IP", "itemDesc": "Crew Rest Smoke Detector Grill
Damaged", "itemNotesInd": "N", "itemNumber": "26-19-01", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "261901" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "26", "ataDesc":
"Crew Rest", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "deactMOProcedure": "May be inoperative provided door(s) is closed.", "decisionInd":
"A", "defRemarks": "May be inoperative provided door(s) is closed.", "efmTab": "R",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-26 15:55:59.945",
"faaReviewStartTms": "2014-12-02 15:55:59.944199", "intExt": "IP", "itemDesc": "Crew
Rest Area Smoke Detector Cover Latch Damaged", "itemNotes": "For Smoke detector
faults see MEL", "itemNotesInd": "Y", "itemNumber": "26-27-01", "lastUpdate": "2014-12-
02 15:56:03.17907", "lastUpdateDisplay": "12/02/2014", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "262701" }, { "sequenceNumber": "01",
"creationDate": "12/18/2014 14:17:54", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "27", "ataDesc":
"Horizontal Stabilizer", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "No sharp edges may be present and must not

present hazard to the crew.", "decisionInd": "A", "defRemarks": "No sharp edges may be present and must not present hazard to the crew.", "efmTab": "D",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-03-23 10:45:25.323204",
"faaReviewStartTms": "2019-02-27 10:45:25.323204", "intExt": "EX", "itemDesc": "Stab Trim Cutout Switch Guard or Spring Damaged/Broken/Missing -B717 Only", "itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "27-40-01", "lastUpdate": "2019-02-27 10:45:28.118844", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "6297748", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000311927", "rowInsertEmpNoDisplay": "00311927", "rowInsertTms": "2014-12-18 14:17:20.034796", "sceptreAutoDefRemarks": "Auto Generated Log NEF via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "274001" }, { "sequenceNumber": "01", "creationDate": "05/23/2022 12:32:09", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "27", "ataDesc": "Spoiler Rigging", "ataSectCode": "66", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2022-10-14 09:48:29.383001", "faaReviewStartTms": "2022-09-20 09:48:29.383001", "intExt": "IP", "itemDesc": "Spoiler Maintenance Key", "itemNotes": "May be missing or damaged.", "itemNotesInd": "Y", "itemNumber": "27-66-01", "lastUpdate": "2022-09-20 09:48:41.642817", "lastUpdateDisplay": "09/20/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2022-05-23 12:31:51.18825", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "276601" }, { "sequenceNumber": "01", "creationDate": "05/10/2016 11:11:03", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "28", "ataDesc": "Fuel", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "The primary safety gate/stop on the fuel shutoff switch must be in good condition and prevent the fuel shutoff switch from slipping over the gate into the off position without positively pulling the switch knob out. If the fuel shutoff switch gate is worn to the point of causing the switch to slip into the off position, this deferral can't be used.\r\n\r\nIf the switch guard plate is damaged, make sure no sharp edges are present and any deformation of the plate does not interfere with any switches/controls. If any safety hazard or interference is present, remove the plate.", "decisionInd": "A", "defRemarks": "The primary safety gate/stop on the fuel shutoff switch must be in good

condition and prevent the fuel shutoff switch from slipping over the gate into the off position without positively pulling the switch knob out. If the fuel shutoff switch gate is worn to the point of causing the switch to slip into the off position, this deferral can't be used.

If the switch guard plate is damaged, make sure no sharp edges are present and any deformation of the plate does not interfere with any switches/controls. If any safety hazard or interference is present, remove the plate.

"efmTab": "D",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2024-03-28 12:15:18.364504", "faaReviewStartTms": "2024-03-04 12:15:18.364504",
"intExt": "IP", "itemDesc": "Engine Fuel Cut-off Switch Guard plate Damaged / Missing (B717 Only)", "itemNotes": "Applicable to the Engine Fuel Cut-off Switch Guard plate installed on the B717 throttle control module under AA 7612-01011.", "itemNotesInd": "Y",
"itemNumber": "28-00-01", "lastUpdate": "2024-03-04 12:15:44.664207",
"lastUpdateDisplay": "03/04/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-05-10 10:57:01.842175", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "280001" },
{ "sequenceNumber": "01", "creationDate": "10/17/2014 08:07:52", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "28", "ataDesc": "Distribution", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Fueling panel spray pan may be missing; however fueling is not allowed. Install placard at the fueling panel. State on placard: Fueling Panel Spray Pan Missing - Do Not Fuel.", "decisionInd": "A",
"defRemarks": "Fueling panel spray pan may be missing; however fueling is not allowed. Install placard at the fueling panel. State on placard: Fueling Panel Spray Pan Missing - Do Not Fuel.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:54:16.881749", "faaReviewStartTms": "2022-03-08 08:54:16.881749", "intExt": "IP",
"itemDesc": "Fueling Panel Spray Pan", "itemNotes": "The spray pan is required to be installed during fueling of the aircraft. This NEF item has a 10 day allowable time limit.",
"itemNotesInd": "Y", "itemNumber": "28-20-01", "lastUpdate": "2022-03-08 08:54:24.529609", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "6160344", "mplIndicator": "Y", "oii": "Y",
"rowInsertEmpNo": "0000387457", "rowInsertEmpNoDisplay": "00387457",
"rowInsertTms": "2014-10-17 07:54:58.774089", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "282001" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":

"Active", "allowableTime": "120", "ataChapterCode": "28", "ataDesc": "Refuel/De-Fuel/Servicing/Valves, Fuel Caps/(Engine Feed Fuel Pump Sys-A350 Only)",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms":
"2022-04-01 08:54:52.495473", "faaReviewStartTms": "2022-03-08 08:54:52.495473",
"intExt": "EX", "itemDesc": "Defuel Valve Lens Cap Damaged / Missing", "itemNotes": "Lens
cap for defuel valve in fueling panel", "itemNotesInd": "Y", "itemNumber": "28-21-01",
"lastUpdate": "2022-03-08 08:54:58.24202", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "282101" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"28", "ataDesc": "Refuel/De-Fuel/Servicing/Valves, Fuel Caps/(Engine Feed Fuel Pump
Sys-A350 Only)", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOProcedure": "Plate can have minor damage but must still
perform its intended function to close the switch guard.", "decisionInd": "A", "defRemarks":
"Plate can have minor damage but must still perform its intended function to close the
switch guard.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:26.765654", "faaReviewStartTms": "2011-12-09 12:37:26.765654", "intExt": "EX",
"itemDesc": "Fueling Door Striker Plate for Red Switch Cap Damaged", "itemNotes":
"Striker plate for fuel fill valve red switch cap.", "itemNotesInd": "Y", "itemNumber": "28-21-
02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "282102" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "28", "ataDesc": "Refuel/De-Fuel/Servicing/Valves, Fuel Caps/(Engine
Feed Fuel Pump Sys-A350 Only)", "ataSectCode": "21", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:55:10.730562",
"faaReviewStartTms": "2022-03-08 08:55:10.730562", "intExt": "EX", "itemDesc": "Fueling

Panel "Set" Button Damaged / Inoperative", "itemNotes": "Does not affect fueling of a/c",
"itemNotesInd": "Y", "itemNumber": "28-21-03", "lastUpdate": "2022-03-08
08:55:15.135142", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "282103" }, { "sequenceNumber": "04",
"creationDate": "02/19/2025 09:06:05", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "45", "ataChapterCode": "28", "ataDesc":
"Refuel/De-Fuel/Servicing/Valves, Fuel Caps/(Engine Feed Fuel Pump Sys-A350 Only)",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "All parts of the broken lanyard or chain must be entirely detached
from the cap and the coupling and discarded.", "decisionInd": "A", "defRemarks": "All parts
of the broken lanyard or chain must be entirely detached from the cap and the coupling
and discarded.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms":
"2025-08-23 14:29:57.041146", "faaReviewStartTms": "2025-07-30 14:29:57.041146",
"intExt": "EX", "itemDesc": "Refuel Coupling Cap Lanyard or Chain - Broken or Missing
LIMITED FLEET APPLICABILITY", "itemNotes": "Lanyard or Chain on the Refuel Coupling
Cap may be missing or removed for the following fleets: B763, B764, A221, A223,
A319/320/321/321N, A330. For A350, use relief in the CDL. For B717, B737, B757, no
published relief available (or this configuration is not installed).\n\nNo damage permitted
to the cap or to the refuel coupling. If the cap is missing or damaged, do not use this NEF:
Use relief in MEL or CDL.", "itemNotesInd": "Y", "itemNumber": "28-21-04", "lastUpdate":
"2025-07-30 14:30:55.477587", "lastUpdateDisplay": "07/30/2025",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-02-19 08:58:09.476458",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "282104" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "29", "ataDesc": "Ground Servicing Components/ Hand Pumps",
"ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Use ECAM to fill.", "decisionInd": "A", "defRemarks": "Use ECAM to
fill.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in
initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2025-09-19
11:59:15.895775", "faaReviewStartTms": "2025-08-26 11:59:15.895775", "intExt": "EX",

"itemDesc": "Hydraulic Quantity Gauge at Service Panel Inop (A330 Only)",
"itemNotesInd": "N", "itemNumber": "29-16-01", "lastUpdate": "2025-08-26
11:59:24.451509", "lastUpdateDisplay": "08/26/2025", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "291601" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "29", "ataDesc":
"Ground Servicing Components/ Hand Pumps", "ataSectCode": "16", "autoDefCde":
"NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "No leaks permitted.
Reservoir Pressure Feed must be operative.", "decisionInd": "A", "defRemarks": "No leaks
permitted. Reservoir Pressure Feed must be operative.", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "Williams", "faaReviewEndTms": "2022-04-01 08:57:10.872",
"faaReviewStartTms": "2022-03-08 08:57:10.872", "intExt": "EX", "itemDesc": "Hydraulic
Reservoir Fill Hand Pump Inop (A32x. A330, A350)", "itemNotes": "Hydraulic Reservoir
Filling Hand Pump (FIN: 1009GM for A319/320/321, FIN: 5204JM for A330, FIN: 5001JE for
A350) may be inoperative. Reservoir servicing must be accomplished by pressure feed.
This NEF applies ONLY to the Reservoir Filling Pump (located on the Green System Ground
Service Panel). This NEF does NOT apply to the Yellow System Auxiliary Pump.",
"itemNotesInd": "Y", "itemNumber": "29-16-02", "lastUpdate": "2022-03-08
08:57:16.479489", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "291602" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "29", "ataDesc":
"Ground Servicing Components/ Hand Pumps", "ataSectCode": "16", "autoDefCde":
"NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:26.925483", "faaReviewStartTms": "2011-
12-09 12:37:26.925483", "intExt": "EX", "itemDesc": "Hydraulic Reservoir Hose or Bottle
Damaged / Poor Condition", "itemNotesInd": "N", "itemNumber": "29-16-03", "lastUpdate":
"2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "291603" },
{ "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"29", "ataDesc": "Ground Servicing Components/ Hand Pumps", "ataSectCode": "16",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:26.968575", "faaReviewStartTms": "2011-
12-09 12:37:26.968575", "intExt": "EX", "itemDesc": "Hydraulic Service Bay Chains,
Lanyards, Clips Damaged / Missing", "itemNotesInd": "N", "itemNumber": "29-16-04",
"lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "291604" },
{ "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"29", "ataDesc": "Ground Servicing Components/ Hand Pumps", "ataSectCode": "16",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:27.056049", "faaReviewStartTms": "2011-
12-09 12:37:27.056049", "intExt": "EX", "itemDesc": "Hydraulic Service Bay Dust Cover
Caps Damaged / Missing", "itemNotesInd": "N", "itemNumber": "29-16-05", "lastUpdate":
"2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "291605" },
{ "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "29", "ataDesc": "Ground Servicing Components/ Hand Pumps",
"ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Missing hose not allowed for A321 and B717 fleets. Damaged hose
is approved for all other fleets.", "decisionInd": "A", "defRemarks": "Missing hose not
allowed for A321 and B717 fleets. Damaged hose is approved for all other fleets.",
"efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A350.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-02-16 08:00:34.073509",
"faaReviewStartTms": "2023-01-23 08:00:34.073509", "intExt": "EX", "itemDesc":

"Hydraulic Service Bay Manual Service Hoses Damaged/Missing", "itemNotes": "Missing hose allowed for A319, A320, A330, A350, 737, 757, 767 fleets only.", "itemNotesInd": "Y", "itemNumber": "29-16-06", "lastUpdate": "2023-01-23 08:00:42.389311", "lastUpdateDisplay": "01/23/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "291606" }, { "sequenceNumber": "07", "creationDate": "11/05/2012 13:09:54", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "29", "ataDesc": "Ground Servicing Components/ Hand Pumps", "ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:57:31.699853", "faaReviewStartTms": "2022-03-08 08:57:31.699853", "intExt": "EX", "itemDesc": "Hydraulic Reservoir Fill Pump Handle Missing", "itemNotes": "This is the hand pump used for ground service of hydraulic system. System can still be serviced by pressure feed.", "itemNotesInd": "Y", "itemNumber": "29-16-07", "lastUpdate": "2022-03-08 08:57:37.489619", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "8889246", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000634257", "rowInsertEmpNoDisplay": "00634257", "rowInsertTms": "2012-11-05 13:05:14.280491", "sceptreAutoDefRemarks": "Auto Generated Log NEF via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "291607" }, { "sequenceNumber": "08", "creationDate": "09/05/2012 03:02:32", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "29", "ataDesc": "Ground Servicing Components/ Hand Pumps", "ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Pressure fill operates normally.", "decisionInd": "A", "defRemarks": "Pressure fill operates normally.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:57:55.374027", "faaReviewStartTms": "2022-03-08 08:57:55.374027", "intExt": "EX", "itemDesc": "Hydraulic Manual Servicing Port Threads Damaged (A319/320)", "itemNotes": "Can use ECAM or servicing panel gage for filling.", "itemNotesInd": "Y", "itemNumber": "29-16-08", "lastUpdate": "2022-03-08 08:58:06.55445", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "8954522", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000410844", "rowInsertEmpNoDisplay": "00410844", "rowInsertTms": "2012-09-05 02:51:52.640576", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":

"00324557", "legacyFrc": "291608" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "31", "ataDesc": "Panels", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Knob must be secure.", "decisionInd": "A", "defRemarks": "Knob must be secure.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 08:59:10.080361", "faaReviewStartTms": "2022-03-08 08:59:10.080361", "intExt": "EX", "itemDesc": "Flight Deck Control Knob Set Screw Head Worn", "itemNotes": "This NEF item has a 10 day allowable time limit. Relief is for the screw head used for tightening being worn.", "itemNotesInd": "Y", "itemNumber": "31-10-01", "lastUpdate": "2022-03-08 08:59:16.072288", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "311001" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "31", "ataDesc": "Overhead", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Can be loose but must still be attached in a way that C/B's are clearly identified. Must not interfere with operation of Circuit Breakers.", "decisionInd": "A", "defRemarks": "Can be loose but must still be attached in a way that C/B's are clearly identified. Must not interfere with operation of Circuit Breakers.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-10-19 09:02:07.568", "faaReviewStartTms": "2017-09-25 09:02:07.569698", "intExt": "EX", "itemDesc": "Circuit Breaker Bar Loose / Damaged(see notes)", "itemNotes": "Please follow guidance of CFR 25-1357(D)- If the ability to reset a circuit breaker or replace a fuse is essential to safety in flight, that circuit breaker or fuse must be located and identified so that it can be readily reset or replaced in flight.", "itemNotesInd": "Y", "itemNumber": "31-14-01", "lastUpdate": "2017-09-25 09:03:11.35944", "lastUpdateDisplay": "09/25/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "311401" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "31", "ataDesc": "Overhead", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount":

"0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:27.247697", "faaReviewStartTms": "2011-12-09 12:37:27.247697", "intExt": "EX",
"itemDesc": "Overhead Switch Rubber Tip Damaged / Missing", "itemNotesInd": "N",
"itemNumber": "31-14-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":
"12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"LOADJOB", "legacyFrc": "311402" }, { "sequenceNumber": "01", "creationDate":
"06/16/2014 06:40:33", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "31", "ataDesc": "Flight Data
Recorder System", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 08:59:39.07503",
"faaReviewStartTms": "2022-03-08 08:59:39.07503", "intExt": "EX", "itemDesc": "Flight &
Voice Recorder Driver/Extractor Missing", "itemNotes": "Driver/Extractor tool ref MPN
ABN7066-1 ref IPC 31-31-00-10 item 275.", "itemNotesInd": "Y", "itemNumber": "31-31-
01", "lastUpdate": "2022-03-08 08:59:44.288348", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5700135",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000877748",
"rowInsertEmpNoDisplay": "00877748", "rowInsertTms": "2014-06-16 06:32:57.456231",
"sceptreAutoDefRemarks": "Auto generated log NEF via Acars", "suggestedManDefCde":
"NEF", "userIdDisplay": "00324557", "legacyFrc": "313101" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "31", "ataDesc":
"EngineIndicatingCrewAlertSyst(EICAS),ElectronicCentralizedAircraftMonitor(ECAM)",
"ataSectCode": "63", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms":
"2022-04-01 09:00:15.722716", "faaReviewStartTms": "2022-03-08 09:00:15.722716",
"intExt": "EX", "itemDesc": "EICAS Maintenance Switch(es) inoperative", "itemNotes": "Set
up for next possible repair opportunity since switch may be needed during maintenance
checks.", "itemNotesInd": "Y", "itemNumber": "31-63-01", "lastUpdate": "2022-03-08
09:00:21.031422", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00324557", "legacyFrc": "316301" }, { "sequenceNumber": "01", "creationDate": "06/05/2014 12:37:26", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "32", "ataDesc": "Links/Braces/Conduits", "ataSectCode": "25", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "1. Accomplish a detailed visual inspection of:\r\nA) The subject area and adjacent structure to ensure no additional damage is present\r\nB) The inside the upper link hinge pin to ensure no evidence of damage to the hinge pin or retention pin. \r\n2. Ensure that the remaining shaft section of the support pin within the upper torsion link pin is not loose.\r\n3. Contact the MCC and Liaison Engineering with any discrepancies.", "decisionInd": "A", "defRemarks": "1. Accomplish a detailed visual inspection of:\r\nA) The subject area and adjacent structure to ensure no additional damage is present\r\nB) The inside the upper link hinge pin to ensure no evidence of damage to the hinge pin or retention pin. \r\n2. Ensure that the remaining shaft section of the support pin within the upper torsion link pin is not loose.\r\n3. Contact the MCC and Liaison Engineering with any discrepancies.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:00:49.948846", "faaReviewStartTms": "2022-03-08 09:00:49.948846", "intExt": "EX", "itemDesc": "Nose Gear Torque Link Hold Open Bracket Damaged (767 only)", "itemNotes": "This NEF item has a 10 day allowable time limit. Bracket MPN 162T1618-1 is only used for MTC functions and is a non essential equipment.", "itemNotesInd": "Y", "itemNumber": "32-25-01", "lastUpdate": "2022-03-08 09:00:55.82643", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5859476", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000814849", "rowInsertEmpNoDisplay": "00814849", "rowInsertTms": "2014-06-05 12:36:55.31495", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "322501" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "32", "ataDesc": "Extension & Retraction", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:01:26.083353", "faaReviewStartTms": "2022-03-08 09:01:26.083353", "intExt": "EX", "itemDesc": "Landing Gear Pins Missing", "itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "32-30-01", "lastUpdate": "2022-03-08 09:01:32.01755", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto

Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "323001" },
{ "sequenceNumber": "02", "creationDate": "11/27/2015 11:13:29", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "32", "ataDesc": "Extension & Retraction", "ataSectCode": "30",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time to 10.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:01:42.525918",
"faaReviewStartTms": "2022-03-08 09:01:42.525918", "intExt": "IP", "itemDesc": "Landing
Gear Pin Pouch Damaged/Missing", "itemNotes": "Use this item for the landing gear pin
pouch damaged/missing. When this item is used then the gear pins must be removed or
stowed in a secure location and NEF code 32-30-01 must also be applied for the gear pins
missing. This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y",
"itemNumber": "32-30-02", "lastUpdate": "2022-03-08 09:01:48.148369",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "7788689", "mpIndicator": "N", "oii": "Y", "rowInsertEmpNo":
"0000426685", "rowInsertEmpNoDisplay": "00426685", "rowInsertTms": "2015-11-27
11:09:40.229124", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "323002" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "32", "ataDesc":
"Wheels & Brakes", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName": ".",
"faaReviewEndTms": "2022-04-01 09:02:13.139788", "faaReviewStartTms": "2022-03-08
09:02:13.139788", "intExt": "EX", "itemDesc": "Brake Deactivation Tool - Missing",
"itemNotesInd": "N", "itemNumber": "32-40-01", "lastUpdate": "2022-03-08
09:02:17.975364", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "324001" }, { "sequenceNumber": "01",
"creationDate": "10/09/2012 16:39:29", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "32", "ataDesc":
"Supplementary Gear", "ataSectCode": "70", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "May be missing provided the downlock pin is not
required for MEL tail skid deactivation.", "decisionInd": "A", "defRemarks": "May be missing
provided the downlock pin is not required for MEL tail skid deactivation.", "efmTab": "X",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",

"faaReviewEndTms": "2022-04-01 09:02:36.808361", "faaReviewStartTms": "2022-03-08 09:02:36.808361", "intExt": "EX", "itemDesc": "Tail Skid Lockout Tool Missing", "itemNotesInd": "N", "itemNumber": "32-70-01", "lastUpdate": "2022-03-08 09:02:43.287967", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "8839340", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000467564", "rowInsertEmpNoDisplay": "00467564", "rowInsertTms": "2012-10-09 16:28:06.683934", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "327001" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2022-04-01 09:03:09.866923", "faaReviewStartTms": "2022-03-08 09:03:09.866923", "intExt": "EX", "itemDesc": "Flight Deck Video In Use Light Inop", "itemNotesInd": "N", "itemNumber": "33-10-02", "lastUpdate": "2022-03-08 09:03:13.557269", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "331002" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPProcedure": "The illumination function may be inoperative provide the switch still operates properly.", "decisionInd": "A", "defRemarks": "The illumination function may be inoperative provide the switch still operates properly.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:03:30.248144", "faaReviewStartTms": "2022-03-08 09:03:30.248144", "intExt": "EX", "itemDesc": "Service Interphone Illuminated Override Switch Inoperative", "itemNotes": "This pushbutton used for maintenance. 50vu panel.", "itemNotesInd": "Y", "itemNumber": "33-10-03", "lastUpdate": "2022-03-08 09:03:36.107479", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "331003" }, { "sequenceNumber": "04", "creationDate": "06/21/2025 18:54:04", "userId": "0000854041", "activeInd": "N",

"activeIndDisplay": "New", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Flight Compartment", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "NO REMARKS", "defRemarks": "NO REMARKS", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2025-07-15 18:48:25.339299", "faaReviewStartTms": "2025-06-21 18:48:25.339299", "intExt": "IP", "itemDesc": "OVHD ANNUN LT PULL TO DIM SWITCH KNOB MISSING", "itemNotes": "LIGHT SWITCH MUST RETAIN DIMMING FUNCTIONALITY.", "itemNotesInd": "Y", "itemNumber": "33-10-04", "lastUpdate": "2025-06-21 18:48:25.339299", "lastUpdateDisplay": "06/21/2025", "logMultiplicity": "M", "logpageNumber": "7396697", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000854041", "rowInsertEmpNoDisplay": "00854041", "rowInsertTms": "2025-06-21 18:48:25.339299", "sceptreAutoDefRemarks": "OVHD ANNUN LT PULL TO DIM SWITCH KNOB MISSING.", "suggestedManDefCde": "NEF", "userIdDisplay": "00854041", "legacyFrc": "331004" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Crew Rest Lighting", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-20-02D for B767-300 and MEL 33-21-01E for A330 aircraft.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-20-02D for B767-300 and MEL 33-21-01E for A330 aircraft.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2019-03-23 10:48:16.637366", "faaReviewStartTms": "2019-02-27 10:48:16.637366", "intExt": "IP", "itemDesc": "Crew Rest Area Stair Tread Lighting Inoperative", "itemNotesInd": "N", "itemNumber": "33-12-01", "lastUpdate": "2019-02-27 10:48:20.148944", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "331201" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Crew Rest Lighting", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-21-01 for A330 aircraft.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then

complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-21-01 for A330 aircraft.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2019-03-23 10:49:17.312241", "faaReviewStartTms": "2019-02-27 10:49:17.312241", "intExt": "IP", "itemDesc": "Crew Rest Area Stowage Compartment / Bin Lighting Inoperative", "itemNotesInd": "N", "itemNumber": "33-12-02", "lastUpdate": "2019-02-27 10:49:19.866618", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "331202" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Crew Rest Lighting", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-20-02F for B767-300 and MEL 33-20-02C for B767-400 and MEL 33-21-01 for A330 aircraft.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-20-02F for B767-300 and MEL 33-20-02C for B767-400 and MEL 33-21-01 for A330 aircraft.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "biever", "faaReviewEndTms": "2019-03-23 10:49:29.574539", "faaReviewStartTms": "2019-02-27 10:49:29.574539", "intExt": "IP", "itemDesc": "Crew Rest Reading Lights Inop", "itemNotesInd": "N", "itemNumber": "33-12-03", "lastUpdate": "2019-02-27 10:49:32.506185", "lastUpdateDisplay": "02/27/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "331203" }, { "sequenceNumber": "04", "creationDate": "06/19/2013 04:25:31", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Crew Rest Lighting", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-21-01 for A330 aircraft.", "decisionInd": "A", "defRemarks": "Check if item is contained in the MEL; if yes then complete the MEL deferral process, otherwise defer using the NEF item. At this time, reference MEL 33-21-01 for A330 aircraft.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",

"faaReviewEndTms": "2022-04-01 09:03:54.711323", "faaReviewStartTms": "2022-03-08 09:03:54.711323", "intExt": "IP", "itemDesc": "Crew Rest Sink Overhead Light Inoperative", "itemNotesInd": "N", "itemNumber": "33-12-04", "lastUpdate": "2022-03-08 09:04:00.480372", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "0940141", "mplIndicator": "Y", "oii": "Y", "rowInsertEmpNo": "0000667694", "rowInsertEmpNoDisplay": "00667694", "rowInsertTms": "2013-06-19 04:17:26.485451", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "331204" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Flood/Map/Overhead/Grimes Lights", "ataSectCode": "18", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-18 13:01:18.843", "faaReviewStartTms": "2014-11-24 13:01:18.844365", "intExt": "EX", "itemDesc": "Grimes Light Lens Damaged / Missing", "itemNotesInd": "N", "itemNumber": "33-18-01", "lastUpdate": "2014-11-24 13:01:23.2321", "lastUpdateDisplay": "11/24/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "331801" }, { "sequenceNumber": "01", "creationDate": "08/15/2014 22:23:03", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Lighting Control / Dimming / Rheostats", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "No sharp edges may be present and must not present hazard to the crew.", "decisionInd": "A", "defRemarks": "No sharp edges may be present and must not present hazard to the crew.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2022-04-01 09:05:14.541983", "faaReviewStartTms": "2022-03-08 09:05:14.541983", "intExt": "EX", "itemDesc": "Landing Light Gang Bar Assembly Damaged/Missing", "itemNotesInd": "N", "itemNumber": "33-19-01", "lastUpdate": "2022-03-08 09:05:29.045042", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "6269854", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000705569", "rowInsertEmpNoDisplay": "00705569", "rowInsertTms": "2014-08-15 22:22:02.61692", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "331901" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058",

"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Bulb may be discolored but still operational. For emergency lighting or inoperative cabin lighting see MEL.", "decisionInd": "A", "defRemarks": "Bulb may be discolored but still operational. For emergency lighting or inoperative cabin lighting see MEL.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:27.693287", "faaReviewStartTms": "2011-12-09 12:37:27.693287", "intExt": "IP", "itemDesc": "Cabin Light Bulb Discolored But Still Operational", "itemNotesInd": "N", "itemNumber": "33-21-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "332101"}, {"sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Lights are fully operational. Len is cracked or has temp repair but must be secure. For inoperative cabin lens see MEL.", "decisionInd": "A", "defRemarks": "Lights are fully operational. Len is cracked or has temp repair but must be secure. For inoperative cabin lens see MEL.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Update by NEF Admin", "faaReviewEndTms": "2025-02-20 09:31:42.167264", "faaReviewStartTms": "2025-01-27 09:31:42.167264", "intExt": "IP", "itemDesc": "Cabin Light Lens Cracked or Damaged", "itemNotes": "DO NOT USE for MISSING lenses unless specifically referenced in other NEF items. MISSING sidewall or ceiling light lenses normally require engineering documentation for dispatch.", "itemNotesInd": "Y", "itemNumber": "33-21-02", "lastUpdate": "2025-01-27 09:31:51.398183", "lastUpdateDisplay": "01/27/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "332102"}, {"sequenceNumber": "09", "creationDate": "05/24/2016 12:09:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y",

"faaContactName": "Homan", "faaReviewEndTms": "2016-06-24 14:48:14.327",
"faaReviewStartTms": "2016-05-31 14:48:14.332438", "intExt": "IP", "itemDesc": "Cabin
PSU Pod Halo Accent Lighting Inoperative (A319/320 Only)", "itemNotes": "Applicable to
the modified A319/320 PSU pod blue halo accent light function. If the amber call light
function of the PSU pod is also inoperative, create an additional deferral using NEF 25-27-
04. Press and reset the attendant call button to verify which functions are inoperative.",
"itemNotesInd": "Y", "itemNumber": "33-21-09", "lastUpdate": "2016-05-31
14:49:39.742533", "lastUpdateDisplay": "05/31/2016", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467",
"rowInsertTms": "2016-05-24 11:58:18.695647", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00517467", "legacyFrc": "332109" }, { "sequenceNumber": "10", "creationDate":
"01/04/2018 05:44:01", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "For in suite reading light please see NEF 33-23-01.", "decisionInd":
"A", "defRemarks": "For in suite reading light please see NEF 33-23-01.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaComments": "ADDED 330-NEO",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:42:03.863631",
"faaReviewStartTms": "2023-11-16 06:42:03.863631", "intExt": "IP", "itemDesc": "Delta one
suite mood lighting(A350/A330-NEO)", "itemNotes": "This NEF is for use INOP mood
lighting on the Delta one Suite installed currently on the A350/ 777 POST MOD/ 330-NEO
only.", "itemNotesInd": "Y", "itemNumber": "33-21-10", "lastUpdate": "2023-11-16
06:42:16.622198", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179",
"rowInsertTms": "2018-01-04 05:34:33.568777", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "332110" }, { "sequenceNumber": "11", "creationDate":
"08/27/2019 13:40:12", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination",
"ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "1. Troubleshoot system per A330 AWM 33-21-90, and ASM 33-21-
26.\n2. Pull and collar CBs FIN 328LG RH (location B08) and/or 329 LG LH (location B07)
on the 5001VE per TOPP 40-40-05 Section VII Para. F and ESPM 20-46-10, depending on
damage.\n3. If any wire damage (chafed, exposed or otherwise damage) is identified, coil
and stow wire in accordance with the Airbus ESPM Chapter 20-54-50 at the damage

location, reference AWM 33-21-90, and ASM 33-21-26.", "decisionInd": "A", "defRemarks": "1. Troubleshoot system per A330 AWM 33-21-90, and ASM 33-21-26.\n2. Pull and collar CBs FIN 328LG RH (location B08) and/or 329 LG LH (location B07) on the 5001VE per TOPP 40-40-05 Section VII Para. F and ESPM 20-46-10, depending on damage.\n3. If any wire damage (chafed, exposed or otherwise damage) is identified, coil and stow wire in accordance with the Airbus ESPM Chapter 20-54-50 at the damage location, reference AWM 33-21-90, and ASM 33-21-26.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-09-22 05:37:39.11252", "faaReviewStartTms": "2019-08-29 05:37:39.11252", "intExt": "IP", "itemDesc": "330NEO Handrail lighting INOP", "itemNotesInd": "N", "itemNumber": "33-21-11", "lastUpdate": "2019-08-30 09:58:26.191974", "lastUpdateDisplay": "08/30/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2019-08-27 13:23:40.992895", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "332111" }, { "sequenceNumber": "12", "creationDate": "04/05/2022 13:27:29", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The Aft Cabin Lighting \u001ACabin Touch Screen\u001A (CTS) control panel may be inoperative, provided the FWD panel remains operative and all cabin illumination functions remain operative (or otherwise deferred per other approved MEL/NEF).", "defRemarks": "The Aft Cabin Lighting \u001ACabin Touch Screen\u001A (CTS) control panel may be inoperative, provided the FWD panel remains operative and all cabin illumination functions remain operative (or otherwise deferred per other approved MEL/NEF).", "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2022-05-20 10:24:13.728165", "faaReviewStartTms": "2022-04-26 10:24:13.728165", "intExt": "IP", "itemDesc": "76K Cabin Lighting \u001A AFT CTS Control Panel", "itemNotes": "This NEF applies only to \u001A76K\u001A configuration, 767-300 post-AA 2500-01823. Only applies to the secondary (aft) CTS panel.", "itemNotesInd": "Y", "itemNumber": "33-21-12", "lastUpdate": "2022-04-26 12:04:14.422786", "lastUpdateDisplay": "04/26/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2022-04-05 13:19:25.484494", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "332112" },

```
{ "sequenceNumber": "13", "creationDate": "02/10/2023 06:46:03", "userId":  
"0000365377", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120",  
"ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21",  
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":  
"H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.",  
"faaContactName": "Bill L. Williams", "faaReviewEndTms": "2023-04-06 13:22:24.202594",  
"faaReviewStartTms": "2023-03-13 13:22:24.202594", "intExt": "IP", "itemDesc": "Underbin  
(Handrail) Flexible Strip Lights (A321NEO ONLY)", "itemNotesInd": "N", "itemNumber": "33-  
21-13", "lastUpdate": "2023-03-13 13:22:24.202594", "lastUpdateDisplay": "03/13/2023",  
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",  
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",  
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-02-10 06:41:25.278449",  
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",  
"suggestedManDefCde": "NEF", "userIdDisplay": "00365377", "legacyFrc": "332113" },  
{ "sequenceNumber": "14", "creationDate": "03/13/2023 10:27:34", "userId":  
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21",  
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":  
"H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.",  
"faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-02-02 11:44:45.21448",  
"faaReviewStartTms": "2025-01-09 11:44:45.21448", "intExt": "IP", "itemDesc":  
"Ceiling/Sidewall HERO Lights (A321NEO)", "itemNotes": "Not to be used for normal ceiling  
or sidewall lighting. See MEL", "itemNotesInd": "Y", "itemNumber": "33-21-14",  
"lastUpdate": "2025-01-09 11:44:51.388083", "lastUpdateDisplay": "01/09/2025",  
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",  
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",  
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-03-13 10:26:33.061713",  
"sceptreAutoDefRemarks": "For NEF items \u001A Auto Generated Log NEF Via ACARS",  
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "332114" },  
{ "sequenceNumber": "15", "creationDate": "04/14/2023 06:11:11", "userId":  
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21",  
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "To use  
this NEF, the branding light must be LED style illumination. A glass light bulb would present  
a possible debris hazard and require the lens. Verify the Branding Light is LED style and the  
lens may be missing.", "decisionInd": "A", "defRemarks": "To use this NEF, the branding  
light must be LED style illumination. A glass light bulb would present a possible debris  
hazard and require the lens. Verify the Branding Light is LED style and the lens may be
```

missing.", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2023-05-15 07:40:27.183549", "faaReviewStartTms": "2023-04-21 07:40:27.183549", "intExt": "IP", "itemDesc": "Branding Light Lens Missing", "itemNotes": "Cabin LED style Branding Light lens is missing.", "itemNotesInd": "Y", "itemNumber": "33-21-15", "lastUpdate": "2025-06-23 14:44:55.314178", "lastUpdateDisplay": "06/23/2025", "logMultiplicity": "M", "logpageNumber": "1000000", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000391283", "rowInsertEmpNoDisplay": "00391283", "rowInsertTms": "2023-04-14 06:01:02.609352", "sceptreAutoDefRemarks": "Branding Light Lens Missing", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "332115" }, { "sequenceNumber": "16", "creationDate": "08/09/2024 11:21:50", "userId": "0000475905", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2024-09-02 11:20:14.096837", "faaReviewStartTms": "2024-08-09 11:20:14.096837", "intExt": "IP", "itemDesc": "UNDER SEAT ACCENT LIGHTS INOP.B757C A/C ONLY", "itemNotesInd": "N", "itemNumber": "33-21-16", "lastUpdate": "2024-08-09 11:20:14.096837", "lastUpdateDisplay": "08/09/2024", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000475905", "rowInsertEmpNoDisplay": "00475905", "rowInsertTms": "2024-08-09 11:20:14.096837", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00475905", "legacyFrc": "332116" }, { "sequenceNumber": "17", "creationDate": "08/19/2025 13:31:55", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Cabin Illumination", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-09-12 14:37:37.418635", "faaReviewStartTms": "2025-08-19 14:37:37.418635", "intExt": "IP", "itemDesc": "3D Lit Widget - D1 cabins", "itemNotesInd": "N", "itemNumber": "33-21-17", "lastUpdate": "2025-08-20 10:12:45.526582", "lastUpdateDisplay": "08/20/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2025-08-19 13:22:40.555783", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "332117" }, { "sequenceNumber": "04", "creationDate": "05/22/2012 11:33:27", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Passenger Signs",

"ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Per
email dated 12/10/2014 - I have no issue with this. It remains Accepted.",
"faaContactName": "Homan", "faaReviewEndTms": "2014-12-06 13:31:48.283",
"faaReviewStartTms": "2014-11-12 13:31:48.286685", "intExt": "IP", "itemDesc":
"Passenger Service Unit WIFI Light Inoperative", "itemNotes": "For No Smoking and Fasten
Seatbelt lights see MEL.", "itemNotesInd": "Y", "itemNumber": "33-22-04", "lastUpdate":
"2014-12-10 07:56:12.435586", "lastUpdateDisplay": "12/10/2014",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-05-22 11:18:36.891427",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "332204" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "33", "ataDesc": "Passenger Reading Lights", "ataSectCode": "23",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"H", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2013-04-22 04:27:23.061",
"faaReviewStartTms": "2013-03-29 04:27:23.05941", "intExt": "IP", "itemDesc": "Passenger
Reading Light Inoperative", "itemNotesInd": "N", "itemNumber": "33-23-01", "lastUpdate":
"2013-03-31 00:40:21.064068", "lastUpdateDisplay": "03/31/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "332301" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"33", "ataDesc": "Passenger Reading Lights", "ataSectCode": "23", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "No exposed lamps or wiring
can exist, causing a hazard to passengers.", "decisionInd": "A", "defRemarks": "No exposed
lamps or wiring can exist, causing a hazard to passengers.", "efmTab": "H",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:28.152429", "faaReviewStartTms": "2011-
12-09 12:37:28.152429", "intExt": "IP", "itemDesc": "Passenger Reading Light Lens /
Diffuser Damaged or Missing", "itemNotesInd": "N", "itemNumber": "33-23-02",
"lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":

"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "332302" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Passenger Reading Lights", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:28.230457", "faaReviewStartTms": "2011-12-09 12:37:28.230457", "intExt": "IP", "itemDesc": "Passenger Reading Light Needs Adjustment", "itemNotesInd": "N", "itemNumber": "33-23-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "332303" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Passenger Reading Lights", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:28.264566", "faaReviewStartTms": "2011-12-09 12:37:28.264566", "intExt": "IP", "itemDesc": "Passenger Reading Light Won't Turn Off", "itemNotesInd": "N", "itemNumber": "33-23-04", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "332304" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Passenger Reading Lights", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:28.32343", "faaReviewStartTms": "2011-12-09 12:37:28.32343", "intExt": "IP", "itemDesc": "Passenger Reading Lights Inop Multiple Locations", "itemNotesInd": "N", "itemNumber": "33-23-05", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",

"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"LOADJOB", "legacyFrc": "332305" }, { "sequenceNumber": "06", "creationDate":
"03/14/2023 08:54:18", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Passenger Reading
Lights", "ataSectCode": "23", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Acceptable, as submitted.", "faaContactName": "Bill L. William", "faaReviewEndTms":
"2023-04-14 13:36:59.568438", "faaReviewStartTms": "2023-03-21 13:36:59.568438",
"intExt": "IP", "itemDesc": "Forward Entry Mood Lights - Bezel (B717 ONLY)", "itemNotes":
"This NEF applies only to the B717 LED Mood Light configuration post-AA 3323-
01027.\n\nThe decorative plastic diffuser/bezel (MPN 0203063-001EA or equivalent) may
be missing from the B717 Forward Cabin drop ceiling mood light(s).", "itemNotesInd": "Y",
"itemNumber": "33-23-06", "lastUpdate": "2023-03-21 14:54:42.718755",
"lastUpdateDisplay": "03/21/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2023-03-14
08:48:19.359525", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "332306" },
{ "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "33", "ataDesc": "Attendant Call/Annunciator", "ataSectCode": "24",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"T", "faaAcceptanceRequiredInd": "Y", "faaComments": "The addition of NEF Item Notes is
accepted. Added A321.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-
07-02 14:27:46.93", "faaReviewStartTms": "2017-06-08 14:27:47.363178", "intExt": "IP",
"itemDesc": "Attendant Panel Switch Light Inop - Switch Still Operates", "itemNotes":
"Check MEL for specific switch light prior to deferral. This NEF is for the light inside of the
switch light. Items associated with the forward attendant panel on the A319/320/321 are
located in the MEL.", "itemNotesInd": "Y", "itemNumber": "33-24-04", "lastUpdate": "2017-
07-05 10:22:55.419028", "lastUpdateDisplay": "07/05/2017", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc":
"332404" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId":
"LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "33", "ataDesc": "Attendant Call/Annunciator", "ataSectCode": "24",

"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:28.669033", "faaReviewStartTms": "2011-12-09 12:37:28.669033", "intExt": "IP", "itemDesc": "Attendant Panel Switch Light Lens Damaged", "itemNotesInd": "N", "itemNumber": "33-24-05", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "332405" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Attendant Call/Annunciator", "ataSectCode": "24", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-22 09:02:59.23173", "faaReviewStartTms": "2022-03-29 09:02:59.23173", "intExt": "IP", "itemDesc": "Passenger to Flight Attendant Call System(not for A350)", "itemNotes": "This NEF is NOT applicable to A350 aircraft (refer to A350 MEL 44-13-02A). \n\nOn B757, B763, and B764 aircraft, this NEF may NOT be used to defer amber, pink or red Flight Attendant Visual Alert Lights (reference B757, B763, or B764 MEL)\n\nThe FAA has rescinded policy letter MMEL PL-128, Wheelchair Accessible Lavatories. Any and all restrictions which identified as more restrictive than the MMEL relief requirements, in regard to wheelchairs accessible lavatories, have been removed.", "itemNotesInd": "Y", "itemNumber": "33-24-09", "lastUpdate": "2022-03-29 09:03:10.760604", "lastUpdateDisplay": "03/29/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "332409" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Entry Door Area/Flight Attendant Lights", "ataSectCode": "25", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Does not apply to emergency lights. Lens must be secure.", "decisionInd": "A", "defRemarks": "Does not apply to emergency lights. Lens must be secure.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-18 12:59:32.259", "faaReviewStartTms": "2014-11-24 12:59:32.260879", "intExt": "EX", "itemDesc": "Aft Air Stair Light Lens / Cover Damaged", "itemNotesInd": "N", "itemNumber": "33-25-01", "lastUpdate": "2014-11-24 12:59:35.620721",

"lastUpdateDisplay": "11/24/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00637639", "legacyFrc": "332501" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"Entry Door Area/Flight Attendant Lights", "ataSectCode": "25", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "There must be acceptable
lighting to allow reading of check list. This may require overhead lighting switch to be
accessible from the seated position.", "decisionInd": "A", "defRemarks": "There must be
acceptable lighting to allow reading of check list. This may require overhead lighting switch
to be accessible from the seated position.", "efmTab": "H", "faaAcceptanceRequiredInd":
"Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-
01-02 12:37:29.141434", "faaReviewStartTms": "2011-12-09 12:37:29.141434", "intExt":
"IP", "itemDesc": "Flight Attendant Reading Light Inoperative", "itemNotesInd": "N",
"itemNumber": "33-25-02", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00245058", "legacyFrc": "332502" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"Entry Door Area/Flight Attendant Lights", "ataSectCode": "25", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:29.255556", "faaReviewStartTms": "2011-
12-09 12:37:29.255556", "intExt": "IP", "itemDesc": "Threshold Light Inop", "itemNotes":
"For flight deck door viewing port lights see MEL.", "itemNotesInd": "Y", "itemNumber": "33-
25-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "332503" },
{ "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"33", "ataDesc": "Entry Door Area/Flight Attendant Lights", "ataSectCode": "25",

"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Lens must be secure.", "decisionInd": "A", "defRemarks": "Lens must be secure.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:29.327926", "faaReviewStartTms": "2011-12-09 12:37:29.327926", "intExt": "IP", "itemDesc": "Threshold Light Lens / Cover Damaged", "itemNotesInd": "N", "itemNumber": "33-25-04", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "332504" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Lavatory Lights", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "May be inoperative (partially) provided sufficient lighting exists (For Return To Seat sign lighting or emergency lights, refer to MEL).This NEF is not applicable to A350 please see MEL 33-21-02.", "decisionInd": "A", "defRemarks": "May be inoperative (partially) provided sufficient lighting exists (For Return To Seat sign lighting or emergency lights, refer to MEL).This NEF is not applicable to A350 please see MEL 33-21-02.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "A350 Exclusion added.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-07-02 14:54:27.96", "faaReviewStartTms": "2017-06-08 14:54:38.123429", "intExt": "IP", "itemDesc": "Lavatory Light Inoperative (not for A350)", "itemNotes": "This NEF is not applicable to A350 please see MEL 33-21-02.", "itemNotesInd": "Y", "itemNumber": "33-26-01", "lastUpdate": "2017-07-05 10:24:10.216706", "lastUpdateDisplay": "07/05/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "332601" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Lavatory Lights", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Lens must be secure.", "decisionInd": "A", "defRemarks": "Lens must be secure.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:29.470993", "faaReviewStartTms": "2011-12-09 12:37:29.470993", "intExt": "IP", "itemDesc": "Lavatory Light Lens Damaged", "itemNotesInd": "N", "itemNumber": "33-26-02", "lastUpdate": "2013-12-04

14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00245058", "legacyFrc": "332602" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"All Lavatory Lights", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-03-13 07:10:54.251644",
"faaReviewStartTms": "2021-02-17 07:10:54.251644", "intExt": "IP", "itemDesc": "Lavatory
Occupied Light Inop (Restricted application on the A350)", "itemNotes": "On the A350, this
NEF applies to the lights in the Passenger Cabin ONLY. For the A350 Flight Deck Lav
OCCPD Light, use MEL 44-01-02A.", "itemNotesInd": "Y", "itemNumber": "33-26-03",
"lastUpdate": "2021-02-17 07:11:04.076299", "lastUpdateDisplay": "02/17/2021",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "332603" },
{ "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"33", "ataDesc": "All Lavatory Lights", "ataSectCode": "26", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:29.604049", "faaReviewStartTms": "2011-
12-09 12:37:29.604049", "intExt": "IP", "itemDesc": "Lavatory Please Lock Door Light Inop",
"itemNotesInd": "N", "itemNumber": "33-26-04", "lastUpdate": "2011-12-09 12:36:53.842",
"lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "LOADJOB", "legacyFrc": "332604" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"All Lavatory Lights", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOPprocedure": "No electrical wiring can be exposed. Lens or
cover must still be secure.", "decisionInd": "A", "defRemarks": "No electrical wiring can be
exposed. Lens or cover must still be secure.", "efmTab": "H", "faaAcceptanceRequiredInd":

"Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:29.701109", "faaReviewStartTms": "2011-12-09 12:37:29.701109", "intExt": "IP", "itemDesc": "Lavatory Sign Lens / Cover Damaged", "itemNotesInd": "N", "itemNumber": "33-26-05", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "332605" }, { "sequenceNumber": "06", "creationDate": "01/06/2013 09:24:15", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "All Lavatory Lights", "ataSectCode": "26", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2013-02-10 08:06:48.996", "faaReviewStartTms": "2013-01-17 08:06:48.999244", "intExt": "IP", "itemDesc": "Lavatory Lock Door Light Inop", "itemNotes": "Light is located in the lavatory and may state \"Please Lock Door\" or \"Lock Door\".", "itemNotesInd": "Y", "itemNumber": "33-26-06", "lastUpdate": "2013-01-19 09:09:09.600666", "lastUpdateDisplay": "01/19/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "0695545", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-01-06 09:22:16.119267", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "332606" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Galley/Closet", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:29.775588", "faaReviewStartTms": "2011-12-09 12:37:29.775588", "intExt": "IP", "itemDesc": "Closet Light Inop", "itemNotesInd": "N", "itemNumber": "33-27-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "332701" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Galley/Closet", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd":

"Y", "daysCount": "0", "deactMOProcedure": "Lens must be secure. If lens is missing then bulb is removed.", "decisionInd": "A", "defRemarks": "Lens must be secure. If lens is missing then bulb is removed.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:29.85745", "faaReviewStartTms": "2011-12-09 12:37:29.85745", "intExt": "IP", "itemDesc": "Closet Light Lens Damaged / Missing", "itemNotesInd": "N", "itemNumber": "33-27-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "332702" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Galley/Closet", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Galley Power Operates Normally.", "decisionInd": "A", "defRemarks": "Galley Power Operates Normally.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:28:30.269", "faaReviewStartTms": "2012-03-06 10:28:29.486235", "intExt": "IG", "itemDesc": "Galley Power Indicator Light Inop in Galley", "itemNotesInd": "N", "itemNumber": "33-27-04", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "332704" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Galley/Closet", "ataSectCode": "27", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:28:41.242", "faaReviewStartTms": "2012-03-06 10:28:40.451559", "intExt": "IG", "itemDesc": "Galley Power Indicator Light Lens Damaged", "itemNotesInd": "N", "itemNumber": "33-27-05", "lastUpdate": "2012-03-06 10:28:44.111625", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "332705" }, { "sequenceNumber": "06", "creationDate": "01/26/2012 14:02:29", "userId":

"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "33", "ataDesc": "Galley/Closet", "ataSectCode": "27", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "H",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Biever", "faaReviewEndTms":
"2012-06-25 07:59:03.493", "faaReviewStartTms": "2012-06-01 07:59:02.842008", "intExt":
"IG", "itemDesc": "Galley Work Light", "itemNotesInd": "N", "itemNumber": "33-27-06",
"lastUpdate": "2012-06-01 07:59:12.02112", "lastUpdateDisplay": "06/01/2012",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "100001",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000723936",
"rowInsertEmpNoDisplay": "00723936", "rowInsertTms": "2012-01-26 14:00:25.124948",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "332706" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "33", "ataDesc": "Internal Cargo Compartment Lights", "ataSectCode":
"31", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A",
"efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2013-06-06
17:30:41.096", "faaReviewStartTms": "2013-05-13 17:30:41.098076", "intExt": "EX",
"itemDesc": "Cargo Compartment Door Light Housing Damaged", "itemNotesInd": "N",
"itemNumber": "33-31-01", "lastUpdate": "2013-05-13 17:30:48.215738",
"lastUpdateDisplay": "05/13/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00637639", "legacyFrc": "333101" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"Wheel Well/External Loading Lights", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms":
"2022-04-01 09:06:50.198304", "faaReviewStartTms": "2022-03-08 09:06:50.198304",
"intExt": "EX", "itemDesc": "External Power Connection Compartment Light Lens
Damaged/Missing", "itemNotesInd": "N", "itemNumber": "33-32-01", "lastUpdate": "2022-
03-08 09:06:56.148921", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "333201" }, { "sequenceNumber": "02",

"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"Wheel Well/External Loading Lights", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms":
"2022-04-01 09:07:14.215606", "faaReviewStartTms": "2022-03-08 09:07:14.215606",
"intExt": "EX", "itemDesc": "External Power Connection Indication Light Lens
Damaged/Missing", "itemNotesInd": "N", "itemNumber": "33-32-02", "lastUpdate": "2022-
03-08 09:07:22.243221", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "333202" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"Wheel Well/External Loading Lights", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms":
"2022-04-01 09:07:41.323753", "faaReviewStartTms": "2022-03-08 09:07:41.323753",
"intExt": "EX", "itemDesc": "Fuel Service Bay Indication Light Lens Damaged",
"itemNotesInd": "N", "itemNumber": "33-32-03", "lastUpdate": "2022-03-08
09:07:50.086925", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00324557", "legacyFrc": "333203" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc":
"Wheel Well/External Loading Lights", "ataSectCode": "32", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2022-04-01 09:08:15.77951",
"faaReviewStartTms": "2022-03-08 09:08:15.77951", "intExt": "EX", "itemDesc": "Potable
Water Service Bay Indication Light Lens Damaged", "itemNotesInd": "N", "itemNumber":
"33-32-04", "lastUpdate": "2022-03-08 09:08:21.349559", "lastUpdateDisplay":
"03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":

"00324557", "legacyFrc": "333204" }, { "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Wheel Well/External Loading Lights", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-18 15:52:14.05", "faaReviewStartTms": "2014-11-24 15:52:14.050483", "intExt": "EX", "itemDesc": "Service Bay Compartment Light Lens Damaged/Missing", "itemNotesInd": "N", "itemNumber": "33-32-05", "lastUpdate": "2014-11-24 15:52:17.022353", "lastUpdateDisplay": "11/24/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "333205" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Wheel Well/External Loading Lights", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:09:03.571381", "faaReviewStartTms": "2022-03-08 09:09:03.571381", "intExt": "EX", "itemDesc": "Toilet Service Indication Light Lens Damaged/Missing", "itemNotesInd": "N", "itemNumber": "33-32-06", "lastUpdate": "2022-03-08 09:09:09.128718", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "333206" }, { "sequenceNumber": "02", "creationDate": "02/26/2013 15:02:05", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "33", "ataDesc": "Interior Lights & Signs", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The exit cover must be present. Emergency exit light(s) illumination operation is normal.", "decisionInd": "A", "defRemarks": "The exit cover must be present. Emergency exit light(s) illumination operation is normal.", "efmTab": "H", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2013-04-14 12:28:44.562", "faaReviewStartTms": "2013-03-21 12:28:44.565991", "intExt": "IP", "itemDesc": "Emergency Exit Cover Diffuser Lens Damaged or Missing", "itemNotes": "The exit cover must be present. This NEF is for the diffuser lens only. The diffuser lens is the clear lens on the bottom of the cover.", "itemNotesInd": "Y", "itemNumber": "33-51-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",

"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9502824",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000648198",
"rowInsertEmpNoDisplay": "00648198", "rowInsertTms": "2013-02-26 14:59:07.178203",
"sceptreAutoDefRemarks": "Auto generated log NEF via ACARS", "suggestedManDefCde":
"NEF", "userIdDisplay": "00245058", "legacyFrc": "335102" }, { "sequenceNumber": "01",
"creationDate": "05/25/2017 12:49:39", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "34", "ataDesc":
"Weather Radar", "ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:09:50.87211",
"faaReviewStartTms": "2022-03-08 09:09:50.87211", "intExt": "IP", "itemDesc": "Vibration
Monitor Unit for the WX radar antenna drive 757-200 only", "itemNotes": "AA 3442-01139
installs a (VMU) Vibration Monitor Unit that monitors the vibration of the Wx Radar Antenna
Drive Motor and alerts to pre-failure conditions. It is installed in the in the Forward EE bay
of B757-200 A/C. This NEF has a 365 day allowable time limit..", "itemNotesInd": "Y",
"itemNumber": "34-42-01", "lastUpdate": "2022-03-08 09:09:56.952172",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2017-05-25
12:39:24.615235", "sceptreAutoDefRemarks": "Vibration Monitor Unit for the WX radar
antenna drive (757-200 only)", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "344201" }, { "sequenceNumber": "02", "creationDate":
"05/18/2020 10:57:08", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "34", "ataDesc": "Weather Radar",
"ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2022-04-01 09:10:13.226298", "faaReviewStartTms":
"2022-03-08 09:10:13.226298", "intExt": "IP", "itemDesc": "Weather Radar XCVR Mounting
Base (MBA-4 Series) - Extractor Assembly", "itemNotesInd": "N", "itemNumber": "34-42-
02", "lastUpdate": "2022-03-08 09:10:18.41337", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2020-05-18 10:52:01.307957",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "344202" },
{ "sequenceNumber": "01", "creationDate": "12/02/2013 05:28:13", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "34", "ataDesc": "VHF Omni Range (VOR)", "ataSectCode": "55",

"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Nav system operation is normal and the nav frequency can be viewed in an alternate display (PFD, ND, DU, ect). Must not obstruct the view of the display and must not present hazard to the crew, no sharp edges.", "decisionInd": "A", "defRemarks": "Nav system operation is normal and the nav frequency can be viewed in an alternate display (PFD, ND, DU, ect). Must not obstruct the view of the display and must not present hazard to the crew, no sharp edges.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2022-04-01 09:10:45.14038", "faaReviewStartTms": "2022-03-08 09:10:45.14038", "intExt": "EX", "itemDesc": "Nav Radio Control Panel Frequency Display Window Damaged", "itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "34-55-01", "lastUpdate": "2022-03-08 09:10:48.948938", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5016562", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000342592", "rowInsertEmpNoDisplay": "00342592", "rowInsertTms": "2013-12-02 05:13:29.884088", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "345501" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "34", "ataDesc": "FMS/Nav Data Loading", "ataSectCode": "64", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:11:06.886592", "faaReviewStartTms": "2022-03-08 09:11:06.886592", "intExt": "EX", "itemDesc": "Data Loader Inop / Fail Light Illuminated", "itemNotesInd": "N", "itemNumber": "34-64-01", "lastUpdate": "2022-03-08 09:11:10.192913", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "346401" }, { "sequenceNumber": "01", "creationDate": "09/20/2019 13:57:16", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "35", "ataDesc": "Crew Oxygen Bottle", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:12:37.65688", "faaReviewStartTms": "2022-03-08 09:12:37.65688", "intExt": "IP", "itemDesc": "CREW OXYGEN CYLINDER COMPARTMENT WINDOW", "itemNotes": "MAY BE WORN, DIRTY OR DAMAGED NO (M) OR (O) PROCEDURES", "itemNotesInd": "Y", "itemNumber": "35-11-01", "lastUpdate": "2022-03-

08 09:12:53.198175", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000244143", "rowInsertEmpNoDisplay": "00244143",
"rowInsertTms": "2019-09-20 13:46:37.639084", "sceptreAutoDefRemarks": "XX",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "351101" },
{ "sequenceNumber": "01", "creationDate": "10/24/2013 01:12:25", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"35", "ataDesc": "Oxygen Storage/Oxygen Generators", "ataSectCode": "21",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Oxygen
door must be operational and must not be obstructed. Secure opening with tape as
required.", "decisionInd": "A", "defRemarks": "Oxygen door must be operational and must
not be obstructed. Secure opening with tape as required.", "efmTab": "C",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2013-11-22 05:19:37.706", "faaReviewStartTms": "2013-10-29
05:19:37.708625", "intExt": "IP", "itemDesc": "PSU Oxygen Door Test Stop Assembly
Broken", "itemNotes": "On Airbus fleets this is called a \"test button\". The stop
assembly/test button is used for operational testing of the oxygen door on PSUs.",
"itemNotesInd": "Y", "itemNumber": "35-21-01", "lastUpdate": "2013-12-04
14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9752490", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000308928", "rowInsertEmpNoDisplay": "00308928",
"rowInsertTms": "2013-10-24 01:09:28.177645", "sceptreAutoDefRemarks": "Auto
Generated Log OPN Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00245058", "legacyFrc": "352101" }, { "sequenceNumber": "06", "creationDate":
"05/05/2014 12:38:41", "userId": "0000823179", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "10", "ataChapterCode": "35", "ataDesc": "Passenger Portable
Oxygen/Used", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "The mask and tubing must be secured to bottle
with a rubber band.", "decisionInd": "A", "defRemarks": "The mask and tubing must be
secured to bottle with a rubber band.", "efmTab": "M", "faaAcceptanceRequiredInd": "Y",
"faaComments": "NEF accepted 11/13/14 due to Description change. Clarified allowable
time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22
13:18:59.215404", "faaReviewStartTms": "2018-01-29 13:18:59.215404", "intExt": "IP",
"itemDesc": "Oxygen Bottle Mask Velcro Strap Damaged/Missing", "itemNotes": "Specify
the location of the oxygen cylinder in the log. This NEF item has a 10 day allowable time
limit.", "itemNotesInd": "Y", "itemNumber": "35-32-06", "lastUpdate": "2018-02-22
14:02:59.569328", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9710787", "mplIndicator": "Y", "oii": "N",

"rowInsertEmpNo": "0000684559", "rowInsertEmpNoDisplay": "00684559",
"rowInsertTms": "2014-05-05 12:29:15.566597", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00823179", "legacyFrc": "353206" }, { "sequenceNumber": "01", "creationDate":
"08/13/2019 14:42:29", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "36", "ataDesc": "Low Pressure
Supply Control (Valves, Controls, Sensors)", "ataSectCode": "13", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "The Thrust Reverser must still
be validated to deploy and PRSOV function using normal engine operations (B767-300
AMM 78-31-00-715-007-H00) to apply this NEF. If alternate procedures are not used to
validate the thrust reverser will deploy this NEF is not to be used, and MEL to inop the
Thrust Reverser must be considered, or the Thrust Reverser must be repaired. \n\n1.
Troubleshoot the affected System, referencing B767-300 WDM 36-11-51 (LH), or 36-11-52
(RH) and B767-300 SSM 36-11-05 (LH), or 36-11-06 (RH) to identify root cause. The root
cause must either be a faulty switch or start solenoid. No wiring faults are authorized.\n2.
Accomplish B767-300 AMM 78-31-00-715-007-H00 Thrust Reverser Operational Test
\u001A With Engine Operation", "decisionInd": "A", "defRemarks": "The Thrust Reverser
must still be validated to deploy and PRSOV function using normal engine operations
(B767-300 AMM 78-31-00-715-007-H00) to apply this NEF. If alternate procedures are not
used to validate the thrust reverser will deploy this NEF is not to be used, and MEL to inop
the Thrust Reverser must be considered, or the Thrust Reverser must be repaired. \n\n1.
Troubleshoot the affected System, referencing B767-300 WDM 36-11-51 (LH), or 36-11-52
(RH) and B767-300 SSM 36-11-05 (LH), or 36-11-06 (RH) to identify root cause. The root
cause must either be a faulty switch or start solenoid. No wiring faults are authorized.\n2.
Accomplish B767-300 AMM 78-31-00-715-007-H00 Thrust Reverser Operational Test
\u001A With Engine Operation", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:13:06.66833",
"faaReviewStartTms": "2022-03-08 09:13:06.66833", "intExt": "IP", "itemDesc": "The PRSOV
Ground Mtc Switch (on engine 767-300 only)", "itemNotes": "The PRSOV ground switch
(767-300 EQ. S2178) is not functioning; not allowing maintenance to deploy the Thrust
Reversers on the ground with APU air. This switch and associated circuitry is for
Maintenance function only, based on a review of B767 WDM 36-11-51 and 36-11-52. Item
can only be deferred on 1502, 1504-1506, 1521, 1601-1613, 1701-1708.", "itemNotesInd":
"Y", "itemNumber": "36-13-01", "lastUpdate": "2022-03-08 09:13:11.805468",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "Y", "logMultiplicity": "S",
"logpageNumber": "1220961", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000391283", "rowInsertEmpNoDisplay": "00391283", "rowInsertTms": "2019-08-13
14:40:20.129525", "sceptreAutoDefRemarks": "L/R PRSOV ground switch located on the

engine is inop.", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "361301" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "36", "ataDesc": "High Pressure Supply Control (Valves, Controls, Sensors HPSOV)", "ataSectCode": "14", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:13:27.970662", "faaReviewStartTms": "2022-03-08 09:13:27.970662", "intExt": "EX", "itemDesc": "HPSOV Jumper Damaged / Missing from MCO Pouch (B767)", "itemNotesInd": "N", "itemNumber": "36-14-01", "lastUpdate": "2022-03-08 09:13:33.564388", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "361401" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "36", "ataDesc": "Indicating/Sensing", "ataSectCode": "20", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Worn but still operative. See applicable AMM for other requirements.", "decisionInd": "A", "defRemarks": "Worn but still operative. See applicable AMM for other requirements.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:32.08193", "faaReviewStartTms": "2011-12-09 12:37:32.08193", "intExt": "EX", "itemDesc": "Temperature Tabs Worn", "itemNotesInd": "N", "itemNumber": "36-20-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "362001" }, { "sequenceNumber": "01", "creationDate": "07/29/2013 08:34:06", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Distribution (Lines/Valves/Faucets)", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-08-24 07:03:37.108", "faaReviewStartTms": "2013-07-31 07:03:37.128388", "intExt": "IG", "itemDesc": "Galley Spigot Aerator Damaged/Missing", "itemNotesInd": "N", "itemNumber": "38-12-01", "lastUpdate": "2013-07-31 07:30:12.181536", "lastUpdateDisplay": "07/31/2013", "legacyDeltaAirworthyInd": "N",

"logMultiplicity": "M", "logpageNumber": "0997017", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000300903", "rowInsertEmpNoDisplay": "00300903",
"rowInsertTms": "2013-07-29 08:32:34.92922", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00637639", "legacyFrc": "381201" }, { "sequenceNumber": "04", "creationDate":
"12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Distribution
(Lines/Valves/Faucets)", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2017-07-03 09:39:28.52",
"faaReviewStartTms": "2017-06-09 09:40:05.020215", "intExt": "IG", "itemDesc": "Galley
Water Spigot Will Not Turn ON(check MEL)", "itemNotes": "Check MEL prior to deferral.",
"itemNotesInd": "Y", "itemNumber": "38-12-04", "lastUpdate": "2017-07-05
10:37:50.374919", "lastUpdateDisplay": "07/05/2017", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00823179", "legacyFrc": "381204" }, { "sequenceNumber": "07",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc":
"Distribution (Lines/Valves/Faucets)", "ataSectCode": "12", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:32.664531", "faaReviewStartTms": "2011-
12-09 12:37:32.664531", "intExt": "IL", "itemDesc": "Lavatory Faucet Aerator Damaged /
Missing", "itemNotesInd": "N", "itemNumber": "38-12-07", "lastUpdate": "2011-12-09
12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "381207" }, { "sequenceNumber": "08",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc":
"Distribution (Lines/Valves/Faucets)", "ataSectCode": "12", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:32.791032", "faaReviewStartTms": "2011-
12-09 12:37:32.791032", "intExt": "IL", "itemDesc": "Lavatory Faucet Hot and Cold

Indicators Illegible or Missing", "itemNotesInd": "N", "itemNumber": "38-12-08",
"lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "381208" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "38", "ataDesc": "Indication", "ataSectCode": "13", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Indication must be
operational.", "decisionInd": "A", "defRemarks": "Indication must be operational.",
"efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial
FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01
09:14:14.023363", "faaReviewStartTms": "2022-03-08 09:14:14.023363", "intExt": "IG",
"itemDesc": "Water Quantity Gauge Lens Damaged", "itemNotesInd": "N", "itemNumber":
"38-13-01", "lastUpdate": "2022-03-08 09:14:18.950335", "lastUpdateDisplay":
"03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00324557", "legacyFrc": "381301" }, { "sequenceNumber": "04", "creationDate":
"09/30/2015 10:43:45", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Indication",
"ataSectCode": "13", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Homan", "faaReviewEndTms": "2022-04-01 09:15:28.844291", "faaReviewStartTms":
"2022-03-08 09:15:28.844291", "intExt": "IP", "itemDesc": "Water System Quantity
Indication Lights (B717 only)", "itemNotes": "This code is for the \"tank water level\" lights on
the potable water servicing panel on all B717 aircraft. The crew will need to check that
water pressure is present in the cabin prior to flight. If no water flows from the faucets in
the cabin then the MEL code for the potable water system must be used.", "itemNotesInd":
"Y", "itemNumber": "38-13-04", "lastUpdate": "2022-03-08 09:15:40.429238",
"lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2015-09-30
10:41:45.120173", "sceptreAutoDefRemarks": "Auto Generated Log NEF via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "381304" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",

"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Servicing", "ataSectCode": "15", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:33.729712", "faaReviewStartTms": "2011-12-09 12:37:33.729712", "intExt": "EX", "itemDesc": "Potable Water Dust Cover / Cap / Chain / Lanyard Damaged or Missing", "itemNotesInd": "N", "itemNumber": "38-15-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "381501" }, { "sequenceNumber": "01", "creationDate": "10/23/2013 15:11:30", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Waste System", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Handle can be loose but must be secure. The toilet flush handle and flush switch must operate normally.", "decisionInd": "A", "defRemarks": "Handle can be loose but must be secure. The toilet flush handle and flush switch must operate normally.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-11-22 05:20:57.649", "faaReviewStartTms": "2013-10-29 05:20:57.650045", "intExt": "IL", "itemDesc": "Lavatory Flush Handle Loose", "itemNotesInd": "N", "itemNumber": "38-30-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "1157597", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000910407", "rowInsertEmpNoDisplay": "00910407", "rowInsertTms": "2013-10-23 15:09:56.94691", "sceptreAutoDefRemarks": "Auto Generated Log OPN Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "383001" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Toilet Flushing/Vacuum/LCM (Logic Control Module)", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:33.90712", "faaReviewStartTms": "2011-12-09 12:37:33.90712", "intExt": "IL", "itemDesc": "Toilet Bowl Splash Pan Stuck", "itemNotesInd": "N", "itemNumber": "38-31-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":

"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "383102" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Toilet Flushing/Vacuum/LCM (Logic Control Module)", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:33.957044", "faaReviewStartTms": "2011-12-09 12:37:33.957044", "intExt": "IL", "itemDesc": "Toilet Bowl Strong Odor", "itemNotesInd": "N", "itemNumber": "38-31-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "383103" }, { "sequenceNumber": "05", "creationDate": "02/08/2016 14:33:46", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Toilet Flushing/Vacuum/LCM (Logic Control Module)", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:56:46.908767", "faaReviewStartTms": "2023-11-16 06:56:46.908767", "intExt": "IP", "itemDesc": "Toilet Foot Pedal Flush Inoperative/Foot Pedal Damaged (767)", "itemNotes": "This code applies to the foot pedal operation of the toilet flush. The toilet flush push button must be operational. See the MEL if the toilet flush push button is inoperative or if the toilet will not flush at all.", "itemNotesInd": "Y", "itemNumber": "38-31-05", "lastUpdate": "2023-11-16 06:57:27.180888", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "8211338", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2016-02-08 14:31:51.115497", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "383105" }, { "sequenceNumber": "06", "creationDate": "04/17/2019 10:39:20", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Toilet Flushing/Vacuum/LCM (Logic Control Module)", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPProcedure": "Troubleshoot the system in accordance applicable CMM and disconnect plug J107 and cap and stow in accordance with D6-54446 707, 727 Through

787 SWPM 20-10-11 requirements.", "decisionInd": "A", "defRemarks": "Troubleshoot the system in accordance applicable CMM and disconnect plug J107 and cap and stow in accordance with D6-54446 707, 727 Through 787 SWPM 20-10-11 requirements.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-05-17 08:55:44.552537", "faaReviewStartTms": "2019-04-23 08:55:44.552537", "intExt": "IL", "itemDesc": "Touchless flush inop (A/C 6801-6818 only)", "itemNotes": "This code applies to the IR touchless operation of the toilet flush. The manual toilet switch must be operational. See the MEL if the toilet flush switch is inoperative or if the toilet will not flush at all.", "itemNotesInd": "Y", "itemNumber": "38-31-06", "lastUpdate": "2019-04-23 09:30:06.644745", "lastUpdateDisplay": "04/23/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000905027", "rowInsertEmpNoDisplay": "00905027", "rowInsertTms": "2019-04-17 10:24:42.878632", "sceptreAutoDefRemarks": "Auto Generated Log NEF via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "383106" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Servicing/Servicing System", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-07 13:49:08.325", "faaReviewStartTms": "2014-11-13 13:49:08.325318", "intExt": "EX", "itemDesc": "Toilet Service Dust Cover/Cap/Chain/Lanyards Damaged/Missing", "itemNotes": "This item is for the external lav service panel components.", "itemNotesInd": "Y", "itemNumber": "38-32-01", "lastUpdate": "2014-11-13 13:49:11.787387", "lastUpdateDisplay": "11/13/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "383201" }, { "sequenceNumber": "02", "creationDate": "03/27/2024 07:06:17", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "38", "ataDesc": "Servicing/Servicing System", "ataSectCode": "32", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill.L.Williams", "faaReviewEndTms": "2024-11-15 11:56:59.3956", "faaReviewStartTms": "2024-10-22 11:56:59.3956", "intExt": "EX", "itemDesc": "Waste Ball Valve Cover - A220 ONLY, POST AA 3832-01115", "itemNotes": "This item applies to POST AA 3832-01115 A220 aircraft only. If the waste ball valve cover (PN 38-0156) is missing, maintenance may defer replacement for 10 days.", "itemNotesInd": "Y", "itemNumber":

"38-32-02", "lastUpdate": "2024-10-22 11:57:11.176474", "lastUpdateDisplay":
"10/22/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-03-27 06:53:52.745637",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "383202" },
{ "sequenceNumber": "01", "creationDate": "07/17/2015 07:32:33", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365",
"ataChapterCode": "38", "ataDesc": "Drain Systems-Toilets/FOD", "ataSectCode": "33",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-06-08 11:12:28.996599",
"faaReviewStartTms": "2018-05-15 11:12:28.996599", "intExt": "IP", "itemDesc": "Toilet
Bowl Non-Stick Coating Peeling", "itemNotes": "This NEF item has a 365 day allowable
time limit.", "itemNotesInd": "Y", "itemNumber": "38-33-01", "lastUpdate": "2018-05-15
11:12:43.01126", "lastUpdateDisplay": "05/15/2018", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "1882336", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467",
"rowInsertTms": "2015-07-17 07:31:04.89459", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00823179", "legacyFrc": "383301" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000268292", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System-
Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "decisionInd": "A", "efmTab": "T", "faaAcceptanceRequiredInd": "Y",
"faaReviewEndTms": "2015-05-15 07:57:39.222", "faaReviewStartTms": "2015-04-21
07:57:39.219302", "intExt": "IP", "itemDesc": "Door Sill Drain Plugged / Inop",
"itemNotesInd": "N", "itemNumber": "38-34-01", "lastUpdate": "2015-04-24
12:55:47.996756", "lastUpdateDisplay": "04/24/2015", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "1698214", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00268292", "legacyFrc": "383401" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc":
"Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-03-30 10:29:59.492",

"faaReviewStartTms": "2012-03-06 10:29:58.726521", "intExt": "IG", "itemDesc": "Galley Drain Noisy", "itemNotesInd": "N", "itemNumber": "38-34-02", "lastUpdate": "2012-03-06 10:30:03.070274", "lastUpdateDisplay": "03/06/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "383402" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Install placard in area of drain to inform cabin crew that it is inoperative.", "decisionInd": "A", "defRemarks": "Install placard in area of drain to inform cabin crew that it is inoperative.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2023-12-10 06:58:39.585832", "faaReviewStartTms": "2023-11-16 06:58:39.585832", "intExt": "IG", "itemDesc": "Galley Drain Plugged / Inop (B717/B737 only)", "itemNotes": "NEF for Galley Drain Plugged / Inop 717/737 only. For A319/320/321, A330 and A350 potable water system galley drains see the MEL for relief. Due to E/E flooding risk on 757/767 do not use this NEF please use MEL 38-30-01A.", "itemNotesInd": "Y", "itemNumber": "38-34-03", "lastUpdate": "2023-11-16 06:58:56.111478", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "383403" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "decisionInd": "A", "defRemarks": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2016-12-24 07:44:55.818", "faaReviewStartTms": "2016-11-30 07:44:55.820768", "intExt": "IG", "itemDesc": "Galley Drain Slow (Contact MCC)", "itemNotesInd": "N", "itemNumber": "38-34-04", "lastUpdate": "2016-11-30 07:52:15.495289", "lastUpdateDisplay": "11/30/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto

Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "383404" },
{ "sequenceNumber": "05", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode": "34",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:34.591732", "faaReviewStartTms": "2011-
12-09 12:37:34.591732", "intExt": "IL", "itemDesc": "Lavatory Drain Noisy", "itemNotesInd":
"N", "itemNumber": "38-34-05", "lastUpdate": "2011-12-09 12:36:53.842",
"lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "LOADJOB", "legacyFrc": "383405" }, { "sequenceNumber": "06",
"creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc":
"Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Contact MCC prior to deferral.
Ensure there is no risk of an overflow.", "decisionInd": "A", "defRemarks": "Contact MCC
prior to deferral. Ensure there is no risk of an overflow.", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "a", "faaReviewEndTms": "2016-12-24 07:59:17.827",
"faaReviewStartTms": "2016-11-30 07:59:17.828261", "intExt": "IL", "itemDesc": "Lavatory
Drain Slow (Contact MCC)", "itemNotesInd": "N", "itemNumber": "38-34-06", "lastUpdate":
"2016-11-30 08:00:17.761664", "lastUpdateDisplay": "11/30/2016",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "383406" },
{ "sequenceNumber": "07", "creationDate": "12/09/2011 12:36:53", "userId":
"0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode":
"34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure":
"Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "decisionInd": "A",
"defRemarks": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.",
"efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA
approved list.", "faaContactName": "a", "faaReviewEndTms": "2016-12-24 08:02:45.746",
"faaReviewStartTms": "2016-11-30 08:02:45.744925", "intExt": "IL", "itemDesc": "Lavatory

Sink Drain Screen Damaged / Missing (Contact MCC)", "itemNotesInd": "N",
"itemNumber": "38-34-07", "lastUpdate": "2016-11-30 08:03:04.703286",
"lastUpdateDisplay": "11/30/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00517467", "legacyFrc": "383407" }, { "sequenceNumber": "08",
"creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc":
"Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Contact MCC prior to deferral.
Ensure there is no risk of an overflow.", "decisionInd": "A", "defRemarks": "Contact MCC
prior to deferral. Ensure there is no risk of an overflow.", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaContactName": "a", "faaReviewEndTms": "2016-12-24 08:04:08.533",
"faaReviewStartTms": "2016-11-30 08:04:08.531917", "intExt": "IL", "itemDesc": "Lavatory
Sink Stoppers Damaged / Missing (Contact MCC)", "itemNotesInd": "N", "itemNumber":
"38-34-08", "lastUpdate": "2016-11-30 08:04:21.336341", "lastUpdateDisplay":
"11/30/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00517467", "legacyFrc": "383408" }, { "sequenceNumber": "09", "creationDate":
"12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System- Galley &
Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:34.870704", "faaReviewStartTms": "2011-12-09 12:37:34.870704", "intExt": "IL",
"itemDesc": "Lavatory Water Dispenser Drain slow", "itemNotesInd": "N", "itemNumber":
"38-34-09", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "383409" },
{ "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId":
"0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode":

"34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "decisionInd": "A", "defRemarks": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "a", "faaReviewEndTms": "2016-12-24 08:05:31.472", "faaReviewStartTms": "2016-11-30 08:05:31.470477", "intExt": "IL", "itemDesc": "Sink Drain Handles Inoperative (Contact MCC)", "itemNotesInd": "N", "itemNumber": "38-34-10", "lastUpdate": "2016-11-30 08:05:47.332798", "lastUpdateDisplay": "11/30/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "383410" }, { "sequenceNumber": "11", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 2/20/14. MMEL PL-128 letter rescinded.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-03-03 10:05:25.974", "faaReviewStartTms": "2014-02-07 10:05:25.970295", "intExt": "IL", "itemDesc": "Sink Handles / Faucets / Pull Knobs Damaged But Still Operational", "itemNotes": "The FAA has rescinded policy letter MMEL PL-128, Wheelchair Accessible Lavatories. Any and all restrictions which identified as more restrictive then the MMEL relief requirements have in regards to wheelchairs accessible lavatories have been removed.", "itemNotesInd": "Y", "itemNumber": "38-34-11", "lastUpdate": "2014-02-20 08:57:56.220417", "lastUpdateDisplay": "02/20/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "383411" }, { "sequenceNumber": "13", "creationDate": "12/09/2011 12:36:53", "userId": "0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "decisionInd": "A", "defRemarks": "Contact MCC prior to deferral. Ensure there is no risk of an overflow.", "efmTab": "G", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "a", "faaReviewEndTms": "2016-12-24 08:06:26.181",

"faaReviewStartTms": "2016-11-30 08:06:26.179589", "intExt": "IL", "itemDesc": "Sink Stopper Damaged / Missing (Contact MCC)", "itemNotesInd": "N", "itemNumber": "38-34-13", "lastUpdate": "2016-11-30 08:06:34.184812", "lastUpdateDisplay": "11/30/2016", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00517467", "legacyFrc": "383413" }, { "sequenceNumber": "14", "creationDate": "05/28/2013 17:34:16", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "38", "ataDesc": "Drain System- Galley & Sinks/Clogs", "ataSectCode": "34", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-12-15 08:50:33.088704", "faaReviewStartTms": "2024-11-21 08:50:33.088704", "intExt": "IP", "itemDesc": "Pilot Crew Rest Potable Water Drain Slow", "itemNotesInd": "N", "itemNumber": "38-34-14", "lastUpdate": "2024-11-21 08:50:38.220031", "lastUpdateDisplay": "11/21/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000316901", "rowInsertEmpNoDisplay": "00316901", "rowInsertTms": "2013-05-28 17:25:56.500782", "sceptreAutoDefRemarks": "Auto generated Log NEF via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "383414" }, { "sequenceNumber": "01", "creationDate": "07/19/2019 08:22:20", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "44", "ataDesc": "Cabin Services System/(Cabin Intercommunication Data System (CIDS)-A350 Only)", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If necessary, perform a reset of the following SSPCs to erase the Maintenance Message.\n\u001A CMS CABIN CTRL PRI \u001A CDC2\u001A7\u001A3\n\u001A CMS CABIN CTRL SEC \u001A CDC3\u001A5\u001A6", "decisionInd": "A", "defRemarks": "If necessary, perform a reset of the following SSPCs to erase the Maintenance Message.\n\u001A CMS CABIN CTRL PRI \u001A CDC2\u001A7\u001A3\n\u001A CMS CABIN CTRL SEC \u001A CDC3\u001A5\u001A6", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": ".", "faaReviewEndTms": "2022-04-01 09:16:48.106303", "faaReviewStartTms": "2022-03-08 09:16:48.106303", "intExt": "IP", "itemDesc": "Cabin Controller Tray Fan Fault", "itemNotesInd": "N", "itemNumber": "44-11-01", "lastUpdate": "2022-03-08 09:16:53.386978", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2019-07-19 08:07:43.877223",

"sceptreAutoDefRemarks": "Sceptre auto NEF deferral", "suggestedManDefCde": "NEF",
"userIdDisplay": "00324557", "legacyFrc": "441101" }, { "sequenceNumber": "01",
"creationDate": "11/02/2017 11:11:20", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "45", "ataDesc":
"Health Management", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-09-05 10:42:14.58805",
"faaReviewStartTms": "2024-08-12 10:42:14.58805", "intExt": "IP", "itemDesc": "Air
Conditioning Health Management System (ACHMS) inop", "itemNotesInd": "N",
"itemNumber": "45-10-01", "lastUpdate": "2024-08-12 10:42:21.458456",
"lastUpdateDisplay": "08/12/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "1111111", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000925787", "rowInsertEmpNoDisplay": "00925787", "rowInsertTms": "2017-11-02
11:10:14.66874", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "451001" },
{ "sequenceNumber": "02", "creationDate": "08/20/2024 12:40:40", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "45", "ataDesc": "Health Management", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure":
"DEACTIVATE SYSTEM BY PULLING AND COLLARING C/B P18-3 (E10) ACHM DCU PWR.",
"decisionInd": "A", "defRemarks": "DEACTIVATE SYSTEM BY PULLING AND COLLARING
C/B P18-3 (E10) ACHM DCU PWR.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams",
"faaReviewEndTms": "2024-09-14 09:18:52.705941", "faaReviewStartTms": "2024-08-21
09:18:52.705941", "intExt": "EX", "itemDesc": "ACHMS TEMPERATURE SENSORS
SWAPPED OR MIS-WIRED CAUSING MISSING OR INCORRECT DATA TO BE DISPLAYED",
"itemNotes": "NEF LIMIT IS 10 DAYS.", "itemNotesInd": "Y", "itemNumber": "45-10-02",
"lastUpdate": "2024-08-22 06:54:42.623093", "lastUpdateDisplay": "08/22/2024",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2024-08-20 12:28:38.722297",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "451002" },
{ "sequenceNumber": "01", "creationDate": "01/16/2014 13:55:58", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "45", "ataDesc": "Computer", "ataSectCode": "41", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",

"faaReviewEndTms": "2022-04-01 09:17:48.469489", "faaReviewStartTms": "2022-03-08 09:17:48.469489", "intExt": "EX", "itemDesc": "Portable Maintenance Access Terminal (PMAT) Inop", "itemNotes": "PMAT located in the E/E may be inop.", "itemNotesInd": "Y", "itemNumber": "45-41-01", "lastUpdate": "2022-03-08 09:17:51.76547", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5527974", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000953697", "rowInsertEmpNoDisplay": "00953697", "rowInsertTms": "2014-01-16 13:40:33.925704", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "454101" }, { "sequenceNumber": "01", "creationDate": "10/22/2019 14:10:56", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "46", "ataDesc": "Information Systems", "ataSectCode": "00", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "N/A", "decisionInd": "A", "defRemarks": "N/A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-11-16 10:47:51.159084", "faaReviewStartTms": "2019-10-23 10:47:51.159084", "intExt": "IP", "itemDesc": "Anti-skid (rubber, non-slip) Pads on the A350 Pilot Sliding Table and the Flight Deck OMT (A350 ONLY)", "itemNotes": "Some or all of the anti-skid pads can be missing on one or both Captain and First Officer folding Keyboard Assemblies", "itemNotesInd": "Y", "itemNumber": "46-00-01", "lastUpdate": "2019-10-24 06:18:02.153892", "lastUpdateDisplay": "10/24/2019", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2019-10-22 14:07:05.231553", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "460001" }, { "sequenceNumber": "01", "creationDate": "09/23/2013 09:06:51", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "30", "ataChapterCode": "46", "ataDesc": "RFID Tag Installation", "ataSectCode": "13", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Verify presence, condition, and expiration date of affected components prior to deferral of the RFID tag exception. Report the component type, the expiration date and installed location on the aircraft. Verify that the component has at least 30 days remaining before it expires. If the component has less than 30 days remaining before replacement is due, replace the component or defer the replacement to a monitor (MON) log. If RFID equipment is not available, and replacement components have less than 30 days life remaining, defer component replacement to a monitor (MON) log", "decisionInd": "A", "defRemarks": "Verify presence, condition, and expiration date of affected components prior to deferral of the RFID tag exception. Report the component type, the expiration date and installed location

on the aircraft. Verify that the component has at least 30 days remaining before it expires. If the component has less than 30 days remaining before replacement is due, replace the component or defer the replacement to a monitor (MON) log. If RFID equipment is not available, and replacement components have less than 30 days life remaining, defer component replacement to a monitor (MON) log, "efmTab": "C", "faaAcceptanceRequiredInd": "Y", "faaComments": "Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-04-28 14:08:23.089009", "faaReviewStartTms": "2018-04-04 14:08:23.089009", "intExt": "IP", "itemDesc": "RFID Tag Exceptions - Missing or Inoperative", "itemNotes": "Radio Frequency Identification (RFID) tag may be missing, damaged, not installed, not reporting or inoperative. This NEF code has a 30 day allowable deferral limit.", "itemNotesInd": "Y", "itemNumber": "46-13-01", "lastUpdate": "2018-04-04 14:08:38.56756", "lastUpdateDisplay": "04/04/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5189309", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-09-23 08:54:23.748228", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "461301" }, { "sequenceNumber": "01", "creationDate": "02/25/2019 10:31:28", "userId": "0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "46", "ataDesc": "Maintenance Information System", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2026-05-16 10:58:06.238003", "faaReviewStartTms": "2026-04-22 10:58:06.238003", "intExt": "IP", "itemDesc": "Flight Ops and Maintenance exchanger (FOMAX) system (Except A319/320/321)", "itemNotes": "Flight Ops and Maintenance exchanger (FOMAX) is an aircraft interface device that allows two way air-ground data communication. FOMAX collects aircraft parameter data and transmits it to Airbus ground servers via 4G connection at the end of every flight. The parameter data is used by Delta TechOps Predictive Maintenance Engineering (PME) team to assess aircraft health and impending system faults. This item is not applicable to the A319/320/321, reference MEL.", "itemNotesInd": "Y", "itemNumber": "46-30-01", "lastUpdate": "2026-04-22 11:00:04.634911", "lastUpdateDisplay": "04/22/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2019-02-25 10:17:06.862526", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00700872", "legacyFrc": "463001" }, { "sequenceNumber": "02", "creationDate": "05/05/2026 08:06:58", "userId": "0000700872", "activeInd": "A", "activeIndDisplay":

"Active", "allowableTime": "120", "ataChapterCode": "46", "ataDesc": "Maintenance Information System", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "14", "deactMOProcedure": "Open and collar circuit breakers FIN 6TM (Test Plug 2) and FIN 7TM (Test Plug 1) to deactivate the RMAX system and remove electrical power.", "decisionInd": "A", "defRemarks": "Open and collar circuit breakers FIN 6TM (Test Plug 2) and FIN 7TM (Test Plug 1) to deactivate the RMAX system and remove electrical power.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Dan Ratcliff", "faaReviewEndTms": "2026-06-20 17:48:10.399556", "faaReviewStartTms": "2026-05-27 17:48:10.399556", "intExt": "IP", "itemDesc": "RMAX system (A330 only)", "itemNotes": "Retro-fit Maintenance Exchanger (RMAX) system may be inoperative. Applies to the A330 CEO fleet only, may be installed on ships 3310-3331,3351-3361.", "itemNotesInd": "Y", "itemNumber": "46-30-02", "lastUpdate": "2026-05-28 10:22:18.19277", "lastUpdateDisplay": "05/28/2026", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000700872", "rowInsertEmpNoDisplay": "00700872", "rowInsertTms": "2026-05-05 08:01:24.334194", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00700872", "legacyFrc": "463002" }, { "sequenceNumber": "01", "creationDate": "07/18/2025 00:30:42", "userId": "0000899089", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120", "ataChapterCode": "46", "ataDesc": "Cabin Information network system", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "REF FOR COMPLETETION OF AA 2516-01019 \n\nREF MEL FOR EFB OUTLETS NOT WORKING", "defRemarks": "REF FOR COMPLETETION OF AA 2516-01019 \n\nREF MEL FOR EFB OUTLETS NOT WORKING", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2025-08-11 00:21:05.577225", "faaReviewStartTms": "2025-07-18 00:21:05.577225", "intExt": "IP", "itemDesc": "NEW EFB ADAPTER", "itemNotes": "EFB ADAPTER KIT MISSING", "itemNotesInd": "Y", "itemNumber": "46-41-01", "lastUpdate": "2025-07-18 00:21:05.577225", "lastUpdateDisplay": "07/18/2025", "logMultiplicity": "S", "logpageNumber": "100000", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000899089", "rowInsertEmpNoDisplay": "00899089", "rowInsertTms": "2025-07-18 00:21:05.577225", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00899089", "legacyFrc": "464101" }, { "sequenceNumber": "02", "creationDate": "07/18/2025 00:36:26", "userId": "0000899089", "activeInd": "N", "activeIndDisplay": "New", "allowableTime": "120", "ataChapterCode": "46", "ataDesc": "Cabin Information network system", "ataSectCode": "41", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "REF FOR COMPLETETION OF AA 2516-01019 \n\nREF MEL FOR EFB OUTLETS NOT WORKING", "defRemarks": "REF FOR

COMPLETETION OF AA 2516-01019 \n\nREF MEL FOR EFB OUTLETS NOT WORKING",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2025-08-11 00:28:08.498767",
"faaReviewStartTms": "2025-07-18 00:28:08.498767", "intExt": "IP", "itemDesc": "EFB
ADAPTER KIT", "itemNotes": "ALL OR PART OF EFB ADAPTER KIT MISSING",
"itemNotesInd": "Y", "itemNumber": "46-41-02", "lastUpdate": "2025-07-18
00:28:08.498767", "lastUpdateDisplay": "07/18/2025", "logMultiplicity": "S",
"logpageNumber": "100000", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"0000899089", "rowInsertEmpNoDisplay": "00899089", "rowInsertTms": "2025-07-18
00:28:08.498767", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00899089", "legacyFrc": "464102" },
{ "sequenceNumber": "01", "creationDate": "06/28/2018 07:49:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "49", "ataDesc": "Air Intake/Doors/Inlet FOD", "ataSectCode": "16",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 09:18:32.70656", "faaReviewStartTms": "2022-03-08
09:18:32.70656", "intExt": "IP", "itemDesc": "APU Inlet Lock Out Tool (CAP) Missing from
Flight Compartment (A330 Only)", "itemNotes": "NEF for 330 only. For spares order MPN
TER90693 STK 33-4900-3-0297", "itemNotesInd": "Y", "itemNumber": "49-16-01",
"lastUpdate": "2022-03-08 09:18:47.116984", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000823179",
"rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2018-06-28 07:49:44.9828",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "491601" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000700872", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Passenger/Galley", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPcedure": "If
applicable, apply tape over hole caused from missing plate.", "decisionInd": "A",
"defRemarks": "If applicable, apply tape over hole caused from missing plate.", "efmTab":
"T", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2026-06-04 09:59:58.652647", "faaReviewStartTms": "2026-05-11
09:59:58.652647", "intExt": "IP", "itemDesc": "Door Handle Trim Cover Plate Damaged /
Missing", "itemNotes": "The cover plate that hides the attaching hardware for door handle.
This NEF does not include 330 passenger door support arm hinge covers that are
disbonded. See ERA 632128-14TR.", "itemNotesInd": "Y", "itemNumber": "52-10-01",
"lastUpdate": "2026-05-11 10:00:12.928701", "lastUpdateDisplay": "05/11/2026",

"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00700872", "legacyFrc": "521001" },
{ "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Passenger/Galley", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "The aft
cabin door barrier strap is not a NEF item for B717 ref MEL 25-61-01 - Ventral Exit Door
Strap.", "decisionInd": "A", "defRemarks": "The aft cabin door barrier strap is not a NEF
item for B717 ref MEL 25-61-01 - Ventral Exit Door Strap.", "efmTab": "T",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2023-12-10 07:01:07.105389", "faaReviewStartTms": "2023-11-16
07:01:07.105389", "intExt": "IP", "itemDesc": "Door Safety Strap Damaged/Missing/Poor
Condition", "itemNotesInd": "N", "itemNumber": "52-10-02", "lastUpdate": "2023-11-16
07:01:18.40135", "lastUpdateDisplay": "11/16/2023", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc":
"521002" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Passenger/Galley", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab":
"T", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:35.507138", "faaReviewStartTms": "2011-
12-09 12:37:35.507138", "intExt": "IP", "itemDesc": "Entry Door Safety Strap Attach Point
Damaged / Poor Condition", "itemNotesInd": "N", "itemNumber": "52-10-03", "lastUpdate":
"2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "521003" },
{ "sequenceNumber": "04", "creationDate": "03/10/2017 10:09:08", "userId":
"0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Passenger/Galley", "ataSectCode": "10",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab":
"T", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",

"faaReviewEndTms": "2017-04-07 08:07:42.986", "faaReviewStartTms": "2017-03-14 08:07:42.99335", "intExt": "IP", "itemDesc": "Door mounted bustle delethalization pad (only effective for 6819-6823 3R door)", "itemNotes": "This NEF is only effective for 6819-6823 3R door delethalization pad(3 R pad on A/C 6819-6823 is installed for appearances only, not for head impact protection). NO other can be deferred all other are required for A/C certification.", "itemNotesInd": "Y", "itemNumber": "52-10-04", "lastUpdate": "2017-04-18 07:34:45.676263", "lastUpdateDisplay": "04/18/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000823179", "rowInsertEmpNoDisplay": "00823179", "rowInsertTms": "2017-03-10 10:02:53.375769", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "521004" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Passenger Door Leaks/Seal", "ataSectCode": "11", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added seal security in notes.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2025-06-22 10:27:35.245987", "faaReviewStartTms": "2025-05-29 10:27:35.245987", "intExt": "IP", "itemDesc": "Entry Door Dust Seal Damaged / Missing / Poor Condition(see notes)", "itemNotes": "Confirm that the dust seal does not interfere with the normal operation of the door.\nDuring NEF validation confirm the security of the dust seal and remove damaged section if seal security or additional migration has the possibility of interfering with normal door operation.", "itemNotesInd": "Y", "itemNumber": "52-11-01", "lastUpdate": "2025-05-29 10:27:52.773414", "lastUpdateDisplay": "05/29/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "521101" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Latch/Handle/Girt Bar Mechanisms", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPProcedure": "The \"Lower To Arm Slide\" placard must be legible. Cover is still secure and the Aft Door Arming Lever is still accessible for use.", "decisionInd": "A", "defRemarks": "The \"Lower To Arm Slide\" placard must be legible. Cover is still secure and the Aft Door Arming Lever is still accessible for use.", "efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-07-30 13:39:35.976995", "faaReviewStartTms": "2021-07-06 13:39:35.976995", "intExt": "IP", "itemDesc": "Aft Door

Arming Lever Cover Damaged / Poor Condition (B717 only)", "itemNotesInd": "N",
"itemNumber": "52-12-01", "lastUpdate": "2021-07-06 13:39:57.901721",
"lastUpdateDisplay": "07/06/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "521201" }, { "sequenceNumber": "06",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Latch/Handle/Girt Bar Mechanisms", "ataSectCode": "12", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:36.103238", "faaReviewStartTms": "2011-
12-09 12:37:36.103238", "intExt": "IL", "itemDesc": "Lavatory Door Close Spring Weak /
Inoperative", "itemNotesInd": "N", "itemNumber": "52-12-06", "lastUpdate": "2011-12-09
12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "521206" }, { "sequenceNumber": "01",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Insulation/Lining/Window Shade/Bustle", "ataSectCode": "13", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "T",
"faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-05 15:24:39.852",
"faaReviewStartTms": "2014-11-11 15:24:39.851491", "intExt": "IP", "itemDesc": "Door
Viewing Port Cover Damaged / Missing / Won't Stay Attached", "itemNotesInd": "N",
"itemNumber": "52-13-01", "lastUpdate": "2014-11-11 15:24:43.009587",
"lastUpdateDisplay": "11/11/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00637639", "legacyFrc": "521301" }, { "sequenceNumber": "02",
"creationDate": "02/16/2012 13:36:24", "userId": "0000700872", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "52", "ataDesc":
"Insulation/Lining/Window Shade/Bustle", "ataSectCode": "13", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "T",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Cosmetic damage.",

"faaContactName": "Biever", "faaReviewEndTms": "2026-06-04 09:57:36.453249",
"faaReviewStartTms": "2026-05-11 09:57:36.453249", "intExt": "IP", "itemDesc": "Door
Cover Minor / Insignificant Damage", "itemNotes": "This NEF does not include 330
passenger door support arm hinge covers that are disbonded. See ERA 632128-14TR.",
"itemNotesInd": "Y", "itemNumber": "52-13-02", "lastUpdate": "2026-05-11
09:58:02.145293", "lastUpdateDisplay": "05/11/2026", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N",
"rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639",
"rowInsertTms": "2012-02-16 13:23:03.801931", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00700872", "legacyFrc": "521302" }, { "sequenceNumber": "03", "creationDate":
"05/17/2012 03:23:14", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Insulation/Lining/Window Shade/Bustle", "ataSectCode": "13", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Attachment lanyard may be
missing or damaged but disarming pin fully functional.", "decisionInd": "A", "defRemarks":
"Attachment lanyard may be missing or damaged but disarming pin fully functional.",
"efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2014-03-06 08:07:18.534", "faaReviewStartTms": "2014-02-10
08:07:18.535764", "intExt": "IP", "itemDesc": "Slide Disarming Pin Attaching Lanyard
Missing or Damaged", "itemNotesInd": "N", "itemNumber": "52-13-03", "lastUpdate":
"2014-02-20 07:32:49.33569", "lastUpdateDisplay": "02/20/2014",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "8661734",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000665871",
"rowInsertEmpNoDisplay": "00665871", "rowInsertTms": "2012-05-17 03:17:40.334986",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "521303" },
{ "sequenceNumber": "04", "creationDate": "02/07/2013 02:53:45", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"52", "ataDesc": "Insulation/Lining/Window Shade/Bustle", "ataSectCode": "13",
"autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Door
slide disarming pin must be secured to door.", "decisionInd": "A", "defRemarks": "Door
slide disarming pin must be secured to door.", "efmTab": "T",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2013-03-09 07:39:44.365", "faaReviewStartTms": "2013-02-13
07:39:44.515702", "intExt": "IP", "itemDesc": "Passenger Door Slide Disarming Pin Pouch
Damaged/Missing", "itemNotesInd": "N", "itemNumber": "52-13-04", "lastUpdate": "2013-
12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd":

"N", "logMultiplicity": "S", "logpageNumber": "9364188", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000373285", "rowInsertEmpNoDisplay": "00373285",
"rowInsertTms": "2013-02-07 02:40:45.780059", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00245058", "legacyFrc": "521304" }, { "sequenceNumber": "05", "creationDate":
"02/16/2013 03:44:15", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Insulation/Lining/Window
Shade/Bustle", "ataSectCode": "13", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOProcedure": "Viewing window must be clear to view through.",
"decisionInd": "A", "defRemarks": "Viewing window must be clear to view through.",
"efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2013-04-27 15:12:24.053", "faaReviewStartTms": "2013-04-03
15:12:24.0524", "intExt": "IP", "itemDesc": "Passenger or Entry Service Door Liner Viewing
Window Clear Dust Cover Cracked", "itemNotes": "This is not door window inner or middle
pane. This is the door liner clear dust cover.", "itemNotesInd": "Y", "itemNumber": "52-13-
05", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "0739115",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000852807",
"rowInsertEmpNoDisplay": "00852807", "rowInsertTms": "2013-02-16 03:39:33.282579",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "521305" },
{ "sequenceNumber": "01", "creationDate": "08/29/2019 08:15:27", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Overwing Exits", "ataSectCode": "21", "autoDefCde":
"NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "we have this issue a lot
on a 319/20/21's it is not the pressure seal only cosmetic dust seal", "decisionInd": "A",
"defRemarks": "we have this issue a lot on a 319/20/21's it is not the pressure seal only
cosmetic dust seal", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2019-10-05 15:42:04.522512", "faaReviewStartTms": "2019-09-11
15:42:04.522512", "intExt": "IP", "itemDesc": "Emergency overwing exit dust seal",
"itemNotes": "overwing emergency exits dust seal loose torn or missing", "itemNotesInd":
"Y", "itemNumber": "52-21-01", "lastUpdate": "2019-09-12 06:18:48.258732",
"lastUpdateDisplay": "09/12/2019", "logMultiplicity": "M", "logpageNumber": "6069926",
"mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000576555",
"rowInsertEmpNoDisplay": "00576555", "rowInsertTms": "2019-08-29 08:15:03.24087",
"sceptreAutoDefRemarks": "yes", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "522101" }, { "sequenceNumber": "02", "creationDate":
"02/12/2012 12:19:55", "userId": "0000637639", "activeInd": "A", "activeIndDisplay":

"Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Emergency Exit Doors", "ataSectCode": "22", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "T", "faaAcceptanceRequiredInd": "Y", "faaComments": "Inflight use on the ground.", "faaContactName": "Biever", "faaReviewEndTms": "2014-12-05 15:20:39.015", "faaReviewStartTms": "2014-11-11 15:20:39.014931", "intExt": "IP", "itemDesc": "Door Disarm Pin Missing Locking Balls", "itemNotes": "Pin still servicable with steamer attached.", "itemNotesInd": "Y", "itemNumber": "52-22-02", "lastUpdate": "2014-11-11 15:20:43.789718", "lastUpdateDisplay": "11/11/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "8754898", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000316793", "rowInsertEmpNoDisplay": "00316793", "rowInsertTms": "2012-02-12 12:04:44.911935", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "522202" }, { "sequenceNumber": "01", "creationDate": "11/18/2012 10:52:28", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-12-12 12:03:19.302", "faaReviewStartTms": "2012-11-18 12:03:19.303662", "intExt": "EX", "itemDesc": "Cargo Door Assist Spring Damaged/Missing", "itemNotesInd": "N", "itemNumber": "52-30-01", "lastUpdate": "2012-11-18 12:03:26.339548", "lastUpdateDisplay": "11/18/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-11-18 10:44:05.503614", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "523001" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Must still be able to secure barrier door.", "decisionInd": "A", "defRemarks": "Must still be able to secure barrier door.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:36.739062", "faaReviewStartTms": "2011-12-09 12:37:36.739062", "intExt": "EX", "itemDesc": "Cargo Barrier Door Hold Open Latch or Hook Damaged", "itemNotesInd": "N", "itemNumber": "52-30-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",

"userIdDisplay": "00245058", "legacyFrc": "523002" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:36.856104", "faaReviewStartTms": "2011-12-09 12:37:36.856104", "intExt": "EX",
"itemDesc": "Cargo Compartment Door Actuator Cover Bracket Damaged",
"itemNotesInd": "N", "itemNumber": "52-30-03", "lastUpdate": "2012-06-25
14:51:18.276836", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "523003" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "If more than one bumper per aircraft is missing replacement
should be scheduled at the next convenient maintenance over night.", "decisionInd": "A",
"defRemarks": "If more than one bumper per aircraft is missing replacement should be
scheduled at the next convenient maintenance over night.", "efmTab": "O",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2014-11-15 15:21:33.5", "faaReviewStartTms": "2014-10-22
15:21:33.499949", "intExt": "EX", "itemDesc": "Cargo Door Handle Bumper
Damaged/Missing", "itemNotesInd": "N", "itemNumber": "52-30-04", "lastUpdate": "2014-
10-22 16:47:25.911836", "lastUpdateDisplay": "10/22/2014", "legacyDeltaAirworthyInd":
"N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "523004" }, { "sequenceNumber": "05",
"creationDate": "11/18/2012 10:54:00", "userId": "0000823179", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2018-11-05
11:08:39.039451", "faaReviewStartTms": "2018-10-12 11:08:39.039451", "intExt": "EX",
"itemDesc": "Cargo Door Handle Ice Shield Retract Spring Inoperative (NOT FOR 737)",
"itemNotes": "Not for use on 737 A/C. Use MEL 52-00-25.", "itemNotesInd": "Y",
"itemNumber": "52-30-05", "lastUpdate": "2018-10-12 11:08:49.259721",

"lastUpdateDisplay": "10/12/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-11-18 10:46:22.458841", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "523005" }, { "sequenceNumber": "06", "creationDate": "11/18/2012 11:13:24", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2018-11-05 11:09:16.20614", "faaReviewStartTms": "2018-10-12 11:09:16.20614", "intExt": "EX", "itemDesc": "Cargo Door Handle Knuckle Cover Plate Damaged or Missing (NOT for 737)", "itemNotes": "Not for use on 737 A/C. Use MEL 52-00-25.", "itemNotesInd": "Y", "itemNumber": "52-30-06", "lastUpdate": "2018-10-12 11:09:19.106287", "lastUpdateDisplay": "10/12/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-11-18 11:01:17.727067", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "523006" }, { "sequenceNumber": "07", "creationDate": "01/06/2013 12:37:11", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms": "2013-02-10 08:30:25.822", "faaReviewStartTms": "2013-01-17 08:30:25.82297", "intExt": "EX", "itemDesc": "Cargo Door Proximity Switch Cover Damaged/Missing", "itemNotesInd": "N", "itemNumber": "52-30-07", "lastUpdate": "2013-01-19 09:08:51.933609", "lastUpdateDisplay": "01/19/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2013-01-06 12:27:36.575535", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "523007" }, { "sequenceNumber": "08", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Ensure door latches securely in the full open position and uplock release operates manually.", "decisionInd": "A", "defRemarks": "Ensure door latches securely in the full open position and uplock release operates manually.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y",

"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:36.958933", "faaReviewStartTms": "2011-12-09 12:37:36.958933", "intExt": "EX", "itemDesc": "Cargo Door Release Lanyard Damaged / Missing (B737)", "itemNotes": "This item is for the white handle and bungee used to assist in releasing the door from the latched open position.", "itemNotesInd": "Y", "itemNumber": "52-30-08", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "523008" }, { "sequenceNumber": "09", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Required nets must be serviceable.", "decisionInd": "A", "defRemarks": "Required nets must be serviceable.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added C Series.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-22 14:09:16.250595", "faaReviewStartTms": "2018-09-28 14:09:16.250595", "intExt": "EX", "itemDesc": "Cargo Door Safety Nets Damaged / Missing(not for C series)", "itemNotes": "Not for use on C series. Must use MEL 50-22-01.", "itemNotesInd": "Y", "itemNumber": "52-30-09", "lastUpdate": "2018-10-11 09:53:59.538004", "lastUpdateDisplay": "10/11/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "523009" }, { "sequenceNumber": "10", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:37.109994", "faaReviewStartTms": "2011-12-09 12:37:37.109994", "intExt": "EX", "itemDesc": "Cargo Door Storage Pouches and MISC Contents Damaged / Missing", "itemNotes": "This item is for MISC items stored in cargo bins, i.e. purge tool, extra locks and pins etc.", "itemNotesInd": "Y", "itemNumber": "52-30-10", "lastUpdate": "2012-06-25 14:51:18.431757", "lastUpdateDisplay": "06/25/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "523010" }, { "sequenceNumber": "11", "creationDate": "11/18/2012 11:10:31", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "30", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Blanket attachment failure is limited to the periphery of the blanket.\n\u001ASurfaces where tape will be applied must be clean and free of dirt, oil, or other contaminants.\n\u001AThere must be a minimum tape overlap of 1 in. on the blanket and door frame.\n\u001AOnly tape that meets BMS 5-146 and/or 14 CFR 25.853(a) can be used.\nWorn or damaged blankets are to be permanently repaired per AMM 25-50-09-308-133.", "decisionInd": "A", "defRemarks": "Blanket attachment failure is limited to the periphery of the blanket.\n\u001ASurfaces where tape will be applied must be clean and free of dirt, oil, or other contaminants.\n\u001AThere must be a minimum tape overlap of 1 in. on the blanket and door frame.\n\u001AOnly tape that meets BMS 5-146 and/or 14 CFR 25.853(a) can be used.\nWorn or damaged blankets are to be permanently repaired per AMM 25-50-09-308-133.", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added AMM repair.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-22 08:00:48.429818", "faaReviewStartTms": "2018-09-28 08:00:48.429818", "intExt": "EX", "itemDesc": "Cargo Door Insulation Blanket Worn/Damaged (757-200 only)", "itemNotes": "This NEF item has a 30 day allowable time limit. Worn or damaged blankets are to be permanently repaired per AMM 25-50-09-308-133.", "itemNotesInd": "Y", "itemNumber": "52-30-11", "lastUpdate": "2018-09-28 08:00:51.737091", "lastUpdateDisplay": "09/28/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-11-18 11:06:45.226999", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00823179", "legacyFrc": "523011" }, { "sequenceNumber": "12", "creationDate": "11/18/2012 11:23:22", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "52", "ataDesc": "Cargo", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "efmTab": "O", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2012-12-13 07:43:55.826", "faaReviewStartTms": "2012-11-19 07:43:55.840958", "intExt": "EX", "itemDesc": "Cargo Door Insulation Blanket Contaminated", "itemNotes": "This NEF item has a 10 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "52-30-12", "lastUpdate": "2012-11-19 07:43:59.221234", "lastUpdateDisplay": "11/19/2012", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-11-18 11:08:31.891659",

"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "523012" },
{ "sequenceNumber": "16", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOPProcedure": "Hold open rod must be secure.", "decisionInd":
"A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:37.154967", "faaReviewStartTms": "2011-
12-09 12:37:37.154967", "intExt": "EX", "itemDesc": "Engine Pylon Door Hold Open Rods or
Lanyards Damaged / Missing", "itemNotesInd": "N", "itemNumber": "52-40-16",
"lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524016" },
{ "sequenceNumber": "17", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOPProcedure": "Hold open rod must be secure.", "decisionInd":
"A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:37.265447", "faaReviewStartTms": "2011-
12-09 12:37:37.265447", "intExt": "EX", "itemDesc": "Fuel Service Bay Door Hold Open Rod
or Lanyard Storage Device", "itemNotesInd": "N", "itemNumber": "52-40-17", "lastUpdate":
"2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay":
"LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524017" },
{ "sequenceNumber": "18", "creationDate": "12/09/2011 12:36:53", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y",
"daysCount": "0", "deactMOPProcedure": "Door must close and latch normally.",
"decisionInd": "A", "defRemarks": "Door must close and latch normally.", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved
list.", "faaReviewEndTms": "2012-01-02 12:37:37.309673", "faaReviewStartTms": "2011-
12-09 12:37:37.309673", "intExt": "EX", "itemDesc": "Fuel Service Bay Door Hold Open

Rods or Lanyards", "itemNotesInd": "N", "itemNumber": "52-40-18", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524018" }, { "sequenceNumber": "19", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:37.347471", "faaReviewStartTms": "2011-12-09 12:37:37.347471", "intExt": "EX", "itemDesc": "Ground Air Service Bay Door Hold Open Rod or Lanyard Storage Device", "itemNotesInd": "N", "itemNumber": "52-40-19", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524019" }, { "sequenceNumber": "20", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:37.432866", "faaReviewStartTms": "2011-12-09 12:37:37.432866", "intExt": "EX", "itemDesc": "Ground Air Service Bay Door Hold Open Rods or Lanyards", "itemNotesInd": "N", "itemNumber": "52-40-20", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524020" }, { "sequenceNumber": "21", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks":

"Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:37.552925", "faaReviewStartTms": "2011-12-09 12:37:37.552925", "intExt": "EX",
"itemDesc": "Hydraulic Service Bay Door Hold Open Rod or Lanyard Storage Device",
"itemNotesInd": "N", "itemNumber": "52-40-21", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524021" }, { "sequenceNumber": "22",
"creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:37.795579", "faaReviewStartTms": "2011-12-09 12:37:37.795579", "intExt": "EX",
"itemDesc": "Hydraulic Service Bay Door Hold Open Rods or Lanyards", "itemNotesInd": "N", "itemNumber": "52-40-22", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00245058", "legacyFrc": "524022" }, { "sequenceNumber": "23",
"creationDate": "02/19/2025 08:39:18", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Service", "ataSectCode": "40", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Ensure door integrity and operation is not compromised.", "decisionInd": "A", "defRemarks": "Ensure door integrity and operation is not compromised.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable, as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-03-15 13:41:31.791432", "faaReviewStartTms": "2025-02-19 13:41:31.791432",
"intExt": "EX", "itemDesc": "Waste Water or Potable Water Service Door Hold Open Rod Damaged / Missing - A350 ONLY", "itemNotes": "No damage permitted to door, hinges, or latches (seek alternate deferral relief). Hold-Open Rod only. Refer to M-IPD A350-A-52-42-69-01000-94AA-A, Item 060 or A350 M-IPD A350-A-52-42-74-01000-94AA-A, Item 220.",
"itemNotesInd": "Y", "itemNumber": "52-40-23", "lastUpdate": "2025-02-20 06:41:46.532415", "lastUpdateDisplay": "02/20/2025", "legacyDeltaAirworthyInd": "N",

"logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000324557", "rowInsertEmpNoDisplay": "00324557",
"rowInsertTms": "2025-02-19 08:35:15.243246", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00324557", "legacyFrc": "524023" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Electrical/Electronic",
"ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:37.899408", "faaReviewStartTms": "2011-12-09 12:37:37.899408", "intExt": "EX",
"itemDesc": "E & E Service Bay Door Hold Open Damaged", "itemNotesInd": "N",
"itemNumber": "52-42-01", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay":
"12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"LOADJOB", "legacyFrc": "524201" }, { "sequenceNumber": "02", "creationDate":
"12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active",
"allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Electrical/Electronic",
"ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "Door must be operative.", "decisionInd": "A", "defRemarks": "Door
must be operative.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":
"Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02
12:37:37.938887", "faaReviewStartTms": "2011-12-09 12:37:37.938887", "intExt": "EX",
"itemDesc": "E & E Service Bay Door Tracks Damaged", "itemNotesInd": "N",
"itemNumber": "52-42-02", "lastUpdate": "2013-12-04 14:08:53.562998",
"lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00245058", "legacyFrc": "524202" }, { "sequenceNumber": "03",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc":
"Electrical/Electronic", "ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOProcedure": "Door integrity and operation is not
compromised.", "decisionInd": "A", "defRemarks": "Door integrity and operation is not
compromised.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments":

"Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2024-11-08 08:53:39.996421", "faaReviewStartTms": "2024-10-15 08:53:39.996421", "intExt": "EX", "itemDesc": "External Power Door Hold Open Rod Damaged / Missing (A330 A350)", "itemNotes": "No damage permitted to door, hinges, or latches (seek alternate deferral relief). Hold-Open Rod only. For A330 ref IPC 52-42-01-01 or 52-42-01-01A Item 100. For A350 ref M-IPD A350-A-52-42-71-01000-94AA-A Item 70.", "itemNotesInd": "Y", "itemNumber": "52-42-03", "lastUpdate": "2024-10-15 08:53:46.776313", "lastUpdateDisplay": "10/15/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "524203" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Electrical/Electronic", "ataSectCode": "42", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:20:22.392756", "faaReviewStartTms": "2022-03-08 09:20:22.392756", "intExt": "EX", "itemDesc": "Forward Accessory Compartment Door Hold Open Damaged", "itemNotesInd": "N", "itemNumber": "52-42-04", "lastUpdate": "2022-03-08 09:20:27.070489", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "524204" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Air Conditioning", "ataSectCode": "45", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.15309", "faaReviewStartTms": "2011-12-09 12:37:38.15309", "intExt": "EX", "itemDesc": "Air Conditioning Service Bay Door Hold Open Rod or Lanyard Storage Device", "itemNotesInd": "N", "itemNumber": "52-45-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via

ACARS", "userIdDisplay": "00245058", "legacyFrc": "524501" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Air Conditioning", "ataSectCode": "45", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.228868", "faaReviewStartTms": "2011-12-09 12:37:38.228868", "intExt": "EX", "itemDesc": "Air Conditioning Service Door Bay Hold Open Rods or Lanyards", "itemNotesInd": "N", "itemNumber": "52-45-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524502" }, { "sequenceNumber": "03", "creationDate": "04/16/2020 03:17:05", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Air Conditioning", "ataSectCode": "45", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "If hooks are missing, no open holes through the LPGC Door are permitted (fasteners must remain installed through holes).", "decisionInd": "A", "defRemarks": "If hooks are missing, no open holes through the LPGC Door are permitted (fasteners must remain installed through holes).", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2020-05-10 07:06:30.887573", "faaReviewStartTms": "2020-04-16 07:06:30.887573", "intExt": "IP", "itemDesc": "LOW PRESSURE GROUND AIR CONNECTION DOOR SUPPORT HOOKS", "itemNotes": "Hooks used to temporarily stow the LPGC Cover during ground servicing. Located on the LPGC Door inner surface(A220 Only).", "itemNotesInd": "Y", "itemNumber": "52-45-03", "lastUpdate": "2020-04-16 09:05:20.816416", "lastUpdateDisplay": "04/16/2020", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000389354", "rowInsertEmpNoDisplay": "00389354", "rowInsertTms": "2020-04-16 03:14:18.167344", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "524503" }, { "sequenceNumber": "04", "creationDate": "07/13/2021 02:41:10", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Air Conditioning", "ataSectCode": "45", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "can not apply this NEF for low pressure ground connection (LPGC)

cover missing, refer to MEL.", "defRemarks": "can not apply this NEF for low pressure ground connection (LPGC) cover missing, refer to MEL.", "faaAcceptanceRequiredInd": "Y", "faaComments": "Acceptable as submitted.", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2021-08-06 08:01:02.178756", "faaReviewStartTms": "2021-07-13 08:01:02.178756", "intExt": "IP", "itemDesc": "Low pressure ground connection (LPGC) cover lanyard damage or missing (A220 only)", "itemNotes": "Lanyard used to retain the low pressure ground connection (lpgc) cover when removed can be damage or missing.", "itemNotesInd": "Y", "itemNumber": "52-45-04", "lastUpdate": "2021-07-13 09:23:48.957677", "lastUpdateDisplay": "07/13/2021", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "0000641480", "rowInsertEmpNoDisplay": "00641480", "rowInsertTms": "2021-07-13 02:34:26.404859", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "524504" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Empennage Access", "ataSectCode": "46", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.302251", "faaReviewStartTms": "2011-12-09 12:37:38.302251", "intExt": "EX", "itemDesc": "Aft Service Bay Door Hold Open Rod or Lanyard Storage Device", "itemNotesInd": "N", "itemNumber": "52-46-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524601" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Empennage Access", "ataSectCode": "46", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPprocedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.347381", "faaReviewStartTms": "2011-12-09 12:37:38.347381", "intExt": "EX", "itemDesc": "Aft Service Bay Door Hold Open Rods or Lanyards", "itemNotesInd": "N", "itemNumber": "52-46-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",

"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524602" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "APU Access Doors", "ataSectCode": "47", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.422959", "faaReviewStartTms": "2011-12-09 12:37:38.422959", "intExt": "EX", "itemDesc": "APU Service Bay Door Hold Open Rod or Lanyard Storage Device", "itemNotesInd": "N", "itemNumber": "52-47-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524701" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "APU Access Doors", "ataSectCode": "47", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Hold open rod must be secure.", "decisionInd": "A", "defRemarks": "Hold open rod must be secure.", "efmTab": "B", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.543425", "faaReviewStartTms": "2011-12-09 12:37:38.543425", "intExt": "EX", "itemDesc": "APU Service Bay Door Hold Open Rods or Lanyards", "itemNotesInd": "N", "itemNumber": "52-47-02", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "524702" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Flight Compartment/Security/ Access System", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "x", "faaReviewEndTms": "2022-04-01 09:20:58.165163", "faaReviewStartTms": "2022-03-08 09:20:58.165163", "intExt": "EX", "itemDesc": "Flight

Deck Door Hold Open Mechanism / Magnet Damaged / Inoperative", "itemNotesInd": "N", "itemNumber": "52-51-01", "lastUpdate": "2022-03-08 09:21:02.622088", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "525101" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Flight Compartment/Security/ Access System", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:21:11.934354", "faaReviewStartTms": "2022-03-08 09:21:11.934354", "intExt": "EX", "itemDesc": "Flight Deck Door Peep Hole Cover Damaged / Missing(see notes)", "itemNotes": "If damaged must be able to open and see thru peephole per CRF121.313.", "itemNotesInd": "Y", "itemNumber": "52-51-02", "lastUpdate": "2022-03-08 09:21:16.871598", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "525102" }, { "sequenceNumber": "03", "creationDate": "02/08/2012 13:51:26", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "52", "ataDesc": "Flight Compartment/Security/ Access System", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "This does not cover the seals that are required for smoke protection.", "decisionInd": "A", "defRemarks": "This does not cover the seals that are required for smoke protection.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaComments": "This cannot be accepted for the DC-9 fleet. Per the STC on the new flight deck doors the rubber seal on the bi-fold door of the DC-9 is a SMOKE seal not a \"dust\" seal and it is designed to keep smoke from the cabin infiltrating to the flight deck in case of smoke in the cabin. ***Added the word \"Felt\" to the title therefore this relief should not be mistaken for the rubber seal.***\nClarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:21:36.037619", "faaReviewStartTms": "2022-03-08 09:21:36.037619", "intExt": "EX", "itemDesc": "Flight Deck Door Dust Felt Seal Worn / Poor Condition", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "52-51-03", "lastUpdate": "2022-03-08 09:21:39.641592", "lastUpdateDisplay": "03/08/2022",

"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "0720166",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639",
"rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-02-08 13:49:41.105507",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "525103" },
{ "sequenceNumber": "04", "creationDate": "01/08/2014 14:58:42", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Flight Compartment/Security/ Access System",
"ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "Door lock switch must function normally.", "decisionInd": "A",
"defRemarks": "Door lock switch must function normally.", "efmTab": "D",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Homan", "faaReviewEndTms":
"2022-04-01 09:21:49.875111", "faaReviewStartTms": "2022-03-08 09:21:49.875111",
"intExt": "EX", "itemDesc": "Flight Deck Door Switch Guard Spring Broken or Missing",
"itemNotes": "Flight deck door lock switch guard spring broken or missing. Guard will not
stay in the upright position.", "itemNotesInd": "Y", "itemNumber": "52-51-04",
"lastUpdate": "2022-03-08 09:21:59.621334", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5520592",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000352228",
"rowInsertEmpNoDisplay": "00352228", "rowInsertTms": "2014-01-08 14:58:08.034534",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "525104" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "52", "ataDesc": "Lavatory", "ataSectCode": "52", "autoDefCde": "NEF",
"crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L",
"faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 2/20/14.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-03-08 11:42:55.258",
"faaReviewStartTms": "2014-02-12 11:42:55.260367", "intExt": "IL", "itemDesc": "Lavatory
Door Cosmetic Damage", "itemNotes": "Lav door seals are not covered under the NEF
program. Lav door and lav door seals are certified for smoke penetration. See NEF
Rejected item 25-40-08 - Lavatory Door Seal Strip.", "itemNotesInd": "Y", "itemNumber":
"52-52-01", "lastUpdate": "2014-02-20 09:01:35.199724", "lastUpdateDisplay":
"02/20/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00637639", "legacyFrc": "525201" }, { "sequenceNumber": "02", "creationDate":

"12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Lavatory", "ataSectCode": "52", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.81688", "faaReviewStartTms": "2011-12-09 12:37:38.81688", "intExt": "IL", "itemDesc": "Lavatory Door Hard To Open or Close - Door Still Operates", "itemNotesInd": "N", "itemNumber": "52-52-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "525202" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Lavatory", "ataSectCode": "52", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:38.863481", "faaReviewStartTms": "2011-12-09 12:37:38.863481", "intExt": "IL", "itemDesc": "Lavatory Door Hold Open Mechanism", "itemNotes": "Boeing Remarks: The hold open device is not part of certification and is installed simply as a convenience for the maintenance and ground crew. It is discretely located in the upper track of the door and placarding to \"unlatch\" the hold open was not considered necessary.", "itemNotesInd": "Y", "itemNumber": "52-52-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "525203" }, { "sequenceNumber": "04", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Lavatory", "ataSectCode": "52", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOPProcedure": "Door lock may be inoperative provided door latches closed.", "decisionInd": "A", "defRemarks": "Door lock may be inoperative provided door latches closed.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaComments": "NEF accepted 2/20/14. MMEL PL-128 letter rescinded.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-05-03 09:13:56.09239", "faaReviewStartTms": "2018-04-09 09:13:56.09239", "intExt": "IL", "itemDesc": "Lavatory Door Lock Inoperative", "itemNotes": "The FAA has rescinded policy letter MMEL PL-128, Wheelchair Accessible Lavatories. Any

and all restrictions which identified as more restrictive than the MMEL relief requirements have in regards to wheelchairs accessible lavatories have been removed. NEF cannot be used on the bi-fold door", "itemNotesInd": "Y", "itemNumber": "52-52-04", "lastUpdate": "2018-04-09 09:15:28.224011", "lastUpdateDisplay": "04/09/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "525204" }, { "sequenceNumber": "06", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Lavatory", "ataSectCode": "52", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Lav Door Latch Works Normal.", "decisionInd": "A", "defRemarks": "Lav Door Latch Works Normal.", "efmTab": "L", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-12-18 15:37:44.016", "faaReviewStartTms": "2014-11-24 15:37:44.018513", "intExt": "IL", "itemDesc": "Lavatory Door Occupied/Vacant Placard Misaligned in Window Or Worn", "itemNotes": "Lav door latch works normal but occupied / vacant placard misaligned in viewer window or worn.", "itemNotesInd": "Y", "itemNumber": "52-52-06", "lastUpdate": "2014-11-24 15:37:47.436075", "lastUpdateDisplay": "11/24/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "525206" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Crew Rest Door/Hatch", "ataSectCode": "56", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "Must be able to latch closed or must be secured.", "decisionInd": "A", "defRemarks": "Must be able to latch closed or must be secured.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Reviewed for A350.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:22:36.065379", "faaReviewStartTms": "2022-03-08 09:22:36.065379", "intExt": "IP", "itemDesc": "Crew Rest Storage Compartment Door / Latches Damaged or Inoperative(see notes)", "itemNotes": "No crew rest storage compartment or latch can be deferred per NEF if emergency equipment is installed inside the door. If so please contact engineering for possible deferral.", "itemNotesInd": "Y", "itemNumber": "52-56-01", "lastUpdate": "2022-03-08 09:22:44.602967", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo":

"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "525601" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "52", "ataDesc": "Crew Rest Door/Hatch", "ataSectCode": "56", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Security seal must be intact and door locked.", "decisionInd": "A", "defRemarks": "Security seal must be intact and door locked.", "efmTab": "R", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial", "faaReviewEndTms": "2022-04-01 09:23:14.037808", "faaReviewStartTms": "2022-03-08 09:23:14.037808", "intExt": "IP", "itemDesc": "Lower Deck Crew Rest Service Door Lock Handle Inop (A330)", "itemNotes": "This is for access from the cargo compartment only during servicing.", "itemNotesInd": "Y", "itemNumber": "52-56-02", "lastUpdate": "2022-03-08 09:23:32.635159", "lastUpdateDisplay": "03/08/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "525602" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "52", "ataDesc": "Service Door Warning", "ataSectCode": "75", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Secure the defective door & latch with speed tape over the latch and around the door edge. Clean surface per P.S. 900-1, No. 07 prior to taping. Apply 2 layers of speed tape (Min Width 2\u001A) to the latch side of service door with tape oriented running parallel to service door edge. Do not obscure any placards or markings with the tape (if obscured, defer or restore markings per appropriate NEF or other relief). If door is opened for servicing or maintenance, re-apply tape per these deferral remarks prior to further flight.", "decisionInd": "A", "defRemarks": "Secure the defective door & latch with speed tape over the latch and around the door edge. Clean surface per P.S. 900-1, No. 07 prior to taping. Apply 2 layers of speed tape (Min Width 2\u001A) to the latch side of service door with tape oriented running parallel to service door edge. Do not obscure any placards or markings with the tape (if obscured, defer or restore markings per appropriate NEF or other relief). If door is opened for servicing or maintenance, re-apply tape per these deferral remarks prior to further flight.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Excluded MD80/90, B717. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2024-04-11 09:54:06.521737", "faaReviewStartTms": "2024-03-18 09:54:06.521737", "intExt": "EX",

"itemDesc": "External Door Latch Spring, Broken or Missing (EXCLUDING B717)",
"itemNotes": "External Service Doors (doors used for maintenance or ground servicing, located external to the aircraft) may have one loose, broken, or missing latch (includes latch spring, push-button, striker, etc.) provided the following conditions are met: Door must be External and Non-Pressurized; Door must be hinged at the Forward Edge (hinge towards direction of flight); Door must have minimum 2 latches; No damage allowed to door hinge or remaining latch(es). Door must latch closed with all other latches and door must close flush and not have any part hanging out in the airstream. This NEF item has a 10 day allowable time limit. \n\nFor B717, refer to SRM Ch. 51-70-01.", "itemNotesInd": "Y",
"itemNumber": "52-75-01", "lastUpdate": "2024-03-18 09:54:15.543003",
"lastUpdateDisplay": "03/18/2024", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "527501" }, { "sequenceNumber": "01",
"creationDate": "08/28/2013 10:53:10", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "53", "ataDesc":
"Bulkheads", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "deactMOProcedure": "Ensure the damaged hose is secure and does not interfere with
anything in the gear well.", "decisionInd": "A", "defRemarks": "Ensure the damaged hose is
secure and does not interfere with anything in the gear well.", "efmTab": "B",
"faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2022-04-01 09:24:11.036749", "faaReviewStartTms": "2022-03-08
09:24:11.036749", "intExt": "EX", "itemDesc": "Canted Bulkhead Drain Hose
Torn/Damaged in The Gear Wheel Well", "itemNotesInd": "N", "itemNumber": "53-12-01",
"lastUpdate": "2022-03-08 09:24:16.490807", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "5058542",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000180306",
"rowInsertEmpNoDisplay": "00180306", "rowInsertTms": "2013-08-28 10:53:10.000807",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "531201" },
{ "sequenceNumber": "01", "creationDate": "03/03/2015 01:55:23", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "53", "ataDesc": "Auxiliary Structure", "ataSectCode": "20",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "No
structural damaged may exist. Any sharp edges must be addressed prior to deferral.",
"decisionInd": "A", "defRemarks": "No structural damaged may exist. Any sharp edges
must be addressed prior to deferral.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",

"faaContactName": "Hoogenhout", "faaReviewEndTms": "2022-04-01 09:24:38.225687",
"faaReviewStartTms": "2022-03-08 09:24:38.225687", "intExt": "IP", "itemDesc":
"Maintenance Platform Damaged", "itemNotes": "This is for integral interior maintenance
platforms only. This does not apply to the ventral stairway emergency walkway on MD88,
MD90 and B717 aircraft.", "itemNotesInd": "Y", "itemNumber": "53-20-01", "lastUpdate":
"2022-03-08 09:24:43.753216", "lastUpdateDisplay": "03/08/2022",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "6712508",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000336750",
"rowInsertEmpNoDisplay": "00336750", "rowInsertTms": "2015-03-03 01:50:42.281972",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "532001" },
{ "sequenceNumber": "01", "creationDate": "09/11/2012 22:30:40", "userId": "245058",
"activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode":
"53", "ataDesc": "Radome", "ataSectCode": "51", "autoDefCde": "NEF", "crewDefInd": "N",
"daysCount": "0", "deactMOProcedure": "Hold open rod must be secure and hold open
device must not be required to preform maintenance.", "decisionInd": "A", "defRemarks":
"Hold open rod must be secure and hold open device must not be required to preform
maintenance.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2013-03-09 15:40:33.917", "faaReviewStartTms":
"2013-02-13 15:40:33.919566", "intExt": "EX", "itemDesc": "Radome Hold Open Rod or
Lanyard Storage Device Damaged/Missing", "itemNotesInd": "N", "itemNumber": "53-51-
01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013",
"legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "8688093",
"mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000410844",
"rowInsertEmpNoDisplay": "00410844", "rowInsertTms": "2012-09-11 22:24:06.394246",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "535101" },
{ "sequenceNumber": "01", "creationDate": "10/12/2015 10:14:53", "userId":
"0000517467", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",
"ataChapterCode": "56", "ataDesc": "Sliding", "ataSectCode": "12", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Scuff plates may be missing
as long as a detailed visual inspection is accomplished to ensure bolt heads do not touch
the window assembly. Window must be able to operate normally.\r\n\r\nScuff plates may
be damaged as long as a detailed visual inspection is accomplished to ensure no binding
exists and the scuff plate is secured in place. Window must be able to operate normally.",
"decisionInd": "A", "defRemarks": "Scuff plates may be missing as long as a detailed visual
inspection is accomplished to ensure bolt heads do not touch the window assembly.
Window must be able to operate normally.\r\n\r\nScuff plates may be damaged as long as

a detailed visual inspection is accomplished to ensure no binding exists and the scuff plate is secured in place. Window must be able to operate normally.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2015-11-06 06:27:22.067", "faaReviewStartTms": "2015-10-13 06:27:22.0811", "intExt": "IP", "itemDesc": "Flight Compartment Sliding Window Scuff Plate Damaged/Missing (B737-700/800/900 Only)", "itemNotes": "This deferral is for the pilot and copilot sliding window scuff plates installed on the B737-700/800/900.", "itemNotesInd": "Y", "itemNumber": "56-12-01", "lastUpdate": "2015-10-13 14:11:14.75802", "lastUpdateDisplay": "10/13/2015", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000517467", "rowInsertEmpNoDisplay": "00517467", "rowInsertTms": "2015-10-12 09:59:00.953955", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00517467", "legacyFrc": "561201" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "56", "ataDesc": "Cabin Windows (Use 2522 for Shades and Inner Window)", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "deactMOProcedure": "This item does NOT apply to entry / service doors. This deferral item is for the inner plastic clear pane. May have crazing or moisture between panes, loose, damaged or missing interior window trim. The clear plastic pane must not be missing.", "decisionInd": "A", "defRemarks": "This item does NOT apply to entry / service doors. This deferral item is for the inner plastic clear pane. May have crazing or moisture between panes, loose, damaged or missing interior window trim. The clear plastic pane must not be missing.", "efmTab": "W", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaContactName": "Initial Approval", "faaReviewEndTms": "2018-10-19 09:17:19.296823", "faaReviewStartTms": "2018-09-25 09:17:19.296823", "intExt": "IP", "itemDesc": "Cabin Window Scratched / Crazed / Damaged", "itemNotes": "Item is for the inner plastic clear pane. See applicable AMM/SRM for other window limits.", "itemNotesInd": "Y", "itemNumber": "56-21-01", "lastUpdate": "2018-09-25 09:17:23.107631", "lastUpdateDisplay": "09/25/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "562101" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "365", "ataChapterCode": "56", "ataDesc": "Cabin Windows (Use 2522 for Shades and Inner Window)", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",

"deactMOProcedure": "This item does NOT apply to entry / service doors.", "decisionInd": "A", "defRemarks": "This item does NOT apply to entry / service doors.", "efmTab": "W", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list. Clarified allowable time.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-02-22 13:11:17.714785", "faaReviewStartTms": "2018-01-29 13:11:17.714785", "intExt": "EX", "itemDesc": "Cabin Window Moisture Between Panes", "itemNotes": "This NEF item has a 365 day allowable time limit.", "itemNotesInd": "Y", "itemNumber": "56-21-02", "lastUpdate": "2018-02-22 14:04:06.573586", "lastUpdateDisplay": "02/22/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "562102" }, { "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "56", "ataDesc": "Cabin Windows (Use 2522 for Shades and Inner Window)", "ataSectCode": "21", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0", "decisionInd": "A", "efmTab": "W", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:39.525325", "faaReviewStartTms": "2011-12-09 12:37:39.525325", "intExt": "IP", "itemDesc": "Cabin Window Trim Missing or Loose", "itemNotesInd": "N", "itemNumber": "56-21-03", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "N", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "562103" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "71", "ataDesc": "Cowling", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "A350 notes added.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-06-14 07:11:23.840145", "faaReviewStartTms": "2021-05-21 07:11:23.840145", "intExt": "EX", "itemDesc": "Cowl Hoist Covers Damaged / Missing(Not for A350/330 NEO)", "itemNotes": "For A350 see CDL 71-00-02 FOR A330-900 SEE CDL 71-00-05.", "itemNotesInd": "Y", "itemNumber": "71-10-02", "lastUpdate": "2021-05-21 07:11:37.569755", "lastUpdateDisplay": "05/21/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto

Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "711002" },
{ "sequenceNumber": "03", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "71", "ataDesc": "Cowling", "ataSectCode": "10", "autoDefCde": "NEF",
"crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Latch is still operative and
secures panel.", "decisionInd": "A", "defRemarks": "Latch is still operative and secures
panel.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "A350 notes
added.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-06-13
13:51:51.769168", "faaReviewStartTms": "2021-05-20 13:51:51.769168", "intExt": "EX",
"itemDesc": "Engine Access Panel Button for Latch Damaged / Missing(check CDL for
A350)", "itemNotes": "For A350 reference CDL 71-00 items", "itemNotesInd": "Y",
"itemNumber": "71-10-03", "lastUpdate": "2021-05-20 13:56:22.679515",
"lastUpdateDisplay": "05/20/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "711003" }, { "sequenceNumber": "04",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "71", "ataDesc":
"Cowling", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "deactMOProcedure": "Rod must stow normally or must be secured.", "decisionInd":
"A", "defRemarks": "Rod must stow normally or must be secured.", "efmTab": "X",
"faaAcceptanceRequiredInd": "Y", "faaComments": "Added A350 notes.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-06-13 13:47:35.96759",
"faaReviewStartTms": "2021-05-20 13:47:35.96759", "intExt": "EX", "itemDesc": "Engine
Cowl Hold Open Rod Clamps / Lanyards / Retaining Pin / Damage / Missing(Check CDL for
A350)", "itemNotes": "For A350 reference CDL 71-00 items.", "itemNotesInd": "Y",
"itemNumber": "71-10-04", "lastUpdate": "2021-05-20 13:56:40.023036",
"lastUpdateDisplay": "05/20/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "711004" }, { "sequenceNumber": "05",
"creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "71", "ataDesc":
"Cowling", "ataSectCode": "10", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "deactMOProcedure": "Not for C series fan cowl hold open rod see MEL 71-10-01.For
Airbus 319/320/321, 330-900NEO and 350 fan cowl hold open rod see the CDL for

deferral.\nMay be missing or broken provided other hold open device is used and can be safely operated. Rod must stow normally, be secured, or be removed if it cant be secured.", "decisionInd": "A", "defRemarks": "Not for C series fan cowl hold open rod see MEL 71-10-01.For Airbus 319/320/321, 330-900NEO and 350 fan cowl hold open rod see the CDL for deferral.\nMay be missing or broken provided other hold open device is used and can be safely operated. Rod must stow normally, be secured, or be removed if it cant be secured.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added C Series.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-06-13 13:49:18.329118", "faaReviewStartTms": "2021-05-20 13:49:18.329118", "intExt": "EX", "itemDesc": "Engine Fan/"3rd" Core Cowl Hold Open Rod Damaged / Missing(NOT FOR ANY T/R HOLD OPEN ROD/SEE NOTES FOR EFFECTIVITY)", "itemNotes": "This NEF is not authorized for Thrust Reverser hold open rods. Please contact engineering for T/R hold open rod deferral. NEF only valid for the hold open rods on the fan cowl and core cowl (3rd/ most aft light weight cowl). Not for C series fan cowl hold open rod see MEL 71-10-01. For Airbus 319/320/321, 330-900NEO and 350 fan cowl hold open rod see the CDL for deferral.", "itemNotesInd": "Y", "itemNumber": "71-10-05", "lastUpdate": "2021-05-20 13:57:14.04658", "lastUpdateDisplay": "05/20/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "711005" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "71", "ataDesc": "Fan", "ataSectCode": "12", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Confirm Assist Pin is in the closed and locked position.", "decisionInd": "A", "defRemarks": "Confirm Assist Pin is in the closed and locked position.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2021-06-13 13:52:42.169957", "faaReviewStartTms": "2021-05-20 13:52:42.169957", "intExt": "EX", "itemDesc": "Forward Fixed Fan Cowl Assist Pin Handle Damaged (A330)", "itemNotesInd": "N", "itemNumber": "71-12-01", "lastUpdate": "2021-05-20 13:57:34.40547", "lastUpdateDisplay": "05/20/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "711201" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "71", "ataDesc": "Hold-Open Devices", "ataSectCode": "15", "autoDefCde": "NEF", "crewDefInd": "N",

"daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Added NEF Item Notes.", "faaContactName": "Hoogenhout",
"faaReviewEndTms": "2017-07-03 10:40:24.804", "faaReviewStartTms": "2017-06-09
10:41:13.619696", "intExt": "EX", "itemDesc": "Cowl Hold Open Clips / Lanyards / Dust
Caps for Hyd Pumping System Damaged / Missing (check MEL/CDL)", "itemNotes": "Prior
to use please check MEL/ CDL for your specific item.", "itemNotesInd": "Y", "itemNumber":
"71-15-01", "lastUpdate": "2017-07-05 10:52:36.21079", "lastUpdateDisplay":
"07/05/2017", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber":
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":
"00823179", "legacyFrc": "711501" }, { "sequenceNumber": "01", "creationDate":
"12/09/2011 12:36:53", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "10", "ataChapterCode": "71", "ataDesc": "Open & Close
Mechanism", "ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "deactMOProcedure": "Fan Cowl Power Door Opening System (Electric Assist System,
\u001APDOS\u001A) may be inoperative, provided ALTERNATE PROCEDURES ARE USED.
See below for alternate procedures. No hazardous conditions (sharp edges, etc.) are
permitted. Deactivate/Reactivate PDOS per A350 AMM 71-13-XX.\n\nIf it is required to
open/close the Fan Cowl, use alternate manual procedure per A350 AMM A350-A-71-13-
XX-02ZZZ-398A-A\n\nNOT FOR A330-900 \u001A USE CDL 71-00-09\n\nNOT FOR THRUST
REVERSER COWL \u001A USE NEF 78-31-03\n\nFOR OTHER FLEETS, THERE IS NO FAN
COWL POWER OPENING SYSTEM INSTALLED", "decisionInd": "A", "defRemarks": "Fan
Cowl Power Door Opening System (Electric Assist System, \u001APDOS\u001A) may be
inoperative, provided ALTERNATE PROCEDURES ARE USED. See below for alternate
procedures. No hazardous conditions (sharp edges, etc.) are permitted.
Deactivate/Reactivate PDOS per A350 AMM 71-13-XX.\n\nIf it is required to open/close the
Fan Cowl, use alternate manual procedure per A350 AMM A350-A-71-13-XX-02ZZZ-398A-
A\n\nNOT FOR A330-900 \u001A USE CDL 71-00-09\n\nNOT FOR THRUST REVERSER COWL
\u001A USE NEF 78-31-03\n\nFOR OTHER FLEETS, THERE IS NO FAN COWL POWER
OPENING SYSTEM INSTALLED", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Contained in initial FAA approved list.", "faaContactName":
"Hoogenhout", "faaReviewEndTms": "2022-04-14 08:41:02.841403", "faaReviewStartTms":
"2022-03-21 08:41:02.841403", "intExt": "EX", "itemDesc": "Fan Cowl Power Opening
System (A350 ONLY)", "itemNotes": "Fan Cowl Power Door Opening System (Electric Assist
System, \u001APDOS\u001A) may be inoperative, provided ALTERNATE PROCEDURES
ARE USED. See below for alternate procedures. No hazardous conditions (sharp edges,
etc.) are permitted. Deactivate/Reactivate PDOS per A350 AMM 71-13-XX.\n\nIf it is

required to open/close the Fan Cowl, use alternate manual procedure per A350 AMM A350-A-71-13-XX-02ZZZ-398A-A\n\nNOT FOR A330-900 \u001A USE CDL 71-00-09\n\nNOT FOR THRUST REVERSER COWL \u001A USE NEF 78-31-03\n\n\nFOR OTHER FLEETS, THERE IS NO FAN COWL POWER OPENING SYSTEM INSTALLED", "itemNotesInd": "Y", "itemNumber": "71-16-01", "lastUpdate": "2022-03-21 08:41:13.101881", "lastUpdateDisplay": "03/21/2022", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00324557", "legacyFrc": "711601" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "LOADJOB", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "71", "ataDesc": "Open & Close Mechanism", "ataSectCode": "16", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-02 12:37:40.288533", "faaReviewStartTms": "2011-12-09 12:37:40.288533", "intExt": "EX", "itemDesc": "Engine Cowl Open Pumping System Dust Caps", "itemNotesInd": "N", "itemNumber": "71-16-02", "lastUpdate": "2011-12-09 12:36:53.842", "lastUpdateDisplay": "12/09/2011", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "LOADJOB", "legacyFrc": "711602" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "78", "ataDesc": "Thrust Reverser", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "All lock plates and bolts may be missing on the storage bracket on only one engine. Opposite engine storage bracket must have complete set of lock plates and bolts.", "decisionInd": "A", "defRemarks": "All lock plates and bolts may be missing on the storage bracket on only one engine. Opposite engine storage bracket must have complete set of lock plates and bolts.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-11-30 15:03:43.839", "faaReviewStartTms": "2014-11-06 15:03:43.840547", "intExt": "EX", "itemDesc": "Thrust Reverser Lockout Bolt and Lock Plate from Storage Bracket Missing", "itemNotes": "May be missing provided the reverser operates normally and is not needed for locking out reverser.", "itemNotesInd": "Y", "itemNumber": "78-30-01", "lastUpdate": "2014-11-06 15:03:47.859086", "lastUpdateDisplay": "11/06/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":

"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00637639", "legacyFrc": "783001" }, { "sequenceNumber": "02", "creationDate": "12/09/2011 12:36:53", "userId": "0000823179", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "78", "ataDesc": "Thrust Reverser", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "Inspect per AMM 78-36-00-210-801 before deferring", "decisionInd": "A", "defRemarks": "Inspect per AMM 78-36-00-210-801 before deferring", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Added C Series.", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2018-10-22 14:02:56.076246", "faaReviewStartTms": "2018-09-28 14:02:56.076246", "intExt": "EX", "itemDesc": "Thrust Reverser PDO System Inoperative - No Leaks(330 only)", "itemNotes": "A330 Only. Not for C Series PDOS was not option taken by Delta.", "itemNotesInd": "Y", "itemNumber": "78-30-02", "lastUpdate": "2018-10-11 09:56:40.756472", "lastUpdateDisplay": "10/11/2018", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00823179", "legacyFrc": "783002" }, { "sequenceNumber": "03", "creationDate": "01/20/2012 15:23:56", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "78", "ataDesc": "Thrust Reverser", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "May be in poor condition provided the reverser operates normally and is not needed for locking out the thrust reverser.", "decisionInd": "A", "defRemarks": "May be in poor condition provided the reverser operates normally and is not needed for locking out the thrust reverser.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Revisited by PPM and found acceptable with word change.", "faaContactName": "Biever", "faaReviewEndTms": "2012-04-16 10:44:34.464", "faaReviewStartTms": "2012-03-23 10:44:33.726696", "intExt": "EX", "itemDesc": "Thrust Reverser Lock Out Pin Nutplate Missing or Threads Damaged (B737)", "itemNotesInd": "N", "itemNumber": "78-30-03", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "0119200", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000637639", "rowInsertEmpNoDisplay": "00637639", "rowInsertTms": "2012-01-20 15:21:51.125894", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00245058", "legacyFrc": "783003" }, { "sequenceNumber": "08", "creationDate": "12/04/2019 08:47:16", "userId": "0000603060", "activeInd": "A", "activeIndDisplay":

"Active", "allowableTime": "10", "ataChapterCode": "78", "ataDesc": "Thrust Reverser",
"ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "Y", "daysCount": "0",
"deactMOProcedure": "MAY BE DEFERRED ONLY IF THE TOOL IS NOT REQUIRED FOR ANY
CURRENT MEL ITEMS OR MAINTENANCE TASKS.\nTHIS NEF ITEM HAS A 10 DAY LIMIT.",
"decisionInd": "A", "defRemarks": "MAY BE DEFERRED ONLY IF THE TOOL IS NOT
REQUIRED FOR ANY CURRENT MEL ITEMS OR MAINTENANCE TASKS.\nTHIS NEF ITEM
HAS A 10 DAY LIMIT.", "efmTab": "D", "faaAcceptanceRequiredInd": "Y",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2019-12-28 09:38:26.381536",
"faaReviewStartTms": "2019-12-04 09:38:26.381536", "intExt": "EX", "itemDesc": "Thrust
Reverser Isolation Valve Lock Dispatch Kit Missing (B757)", "itemNotes": "B757 Only -
Thrust Reverser Isolation Valve Lock Dispatch Kit, normally stowed in the flight deck gear
pouch, and only used for Thrust Reverser lock-out during maintenance activities or MEL
application, may be missing provided it is not required for any MEL or Maintenance
procedures.", "itemNotesInd": "Y", "itemNumber": "78-30-08", "lastUpdate": "2019-12-04
09:42:45.581076", "lastUpdateDisplay": "12/04/2019", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "0000603060", "rowInsertEmpNoDisplay": "00603060",
"rowInsertTms": "2019-12-04 08:45:23.113355", "sceptreAutoDefRemarks": "Auto
Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay":
"00603060", "legacyFrc": "783008" }, { "sequenceNumber": "09", "creationDate":
"06/01/2021 14:47:38", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":
"Active", "allowableTime": "120", "ataChapterCode": "78", "ataDesc": "Thrust Reverser",
"ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0",
"deactMOProcedure": "ONE ENGINE ONLY. One must always be present/operative. Swap
operative tool between engines if required for maintenance. No damage permitted to
mounting hardware or mounts on reverser structure.", "decisionInd": "A", "defRemarks":
"ONE ENGINE ONLY. One must always be present/operative. Swap operative tool between
engines if required for maintenance. No damage permitted to mounting hardware or
mounts on reverser structure.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",
"faaComments": "Acceptable as submitted.", "faaContactName": "Bill L. Williams",
"faaReviewEndTms": "2021-06-26 11:04:05.373858", "faaReviewStartTms": "2021-06-02
11:04:05.373858", "intExt": "EX", "itemDesc": "Thrust Reverser Closure Assist Assembly
Tool Missing/INOP (A220-100, 300)", "itemNotes": "Thrust Reverser Closure Assist
Assembly Tool (A220 PIPD PW1000G-A-78-36-20-01B-941A-A ITEM 30, MPN 999-3470-
501) may be missing/inoperative on ONE ENGINE ONLY. No damage permitted to
mounting hardware or mounts on reverser structure.", "itemNotesInd": "Y", "itemNumber":
"78-30-09", "lastUpdate": "2021-06-03 09:25:38.737216", "lastUpdateDisplay":
"06/03/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber":

"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000324557",
"rowInsertEmpNoDisplay": "00324557", "rowInsertTms": "2021-06-01 14:35:41.717692",
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "783009" },
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":
"0000324557", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "10",
"ataChapterCode": "78", "ataDesc": "Thrust Reverser Structure/Blocker Doors/Cascade
Vanes/Seals", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":
"0", "deactMOProcedure": "May be leaking provided Cowl opens normally and is supported
with the hold open safety device.", "decisionInd": "A", "defRemarks": "May be leaking
provided Cowl opens normally and is supported with the hold open safety device.",
"efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Reviewed for A350.",
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2021-06-13 13:54:53.722841",
"faaReviewStartTms": "2021-05-20 13:54:53.722841", "intExt": "EX", "itemDesc": "Thrust
Reverser C Duct, Cowl Pumper Hydraulic Connection Leaking / Damaged (NOT FOR 330-
NEO)", "itemNotes": "NOT FOR 330-NEO SEE CDL 78-00-34", "itemNotesInd": "Y",
"itemNumber": "78-31-01", "lastUpdate": "2021-05-20 13:58:57.79469",
"lastUpdateDisplay": "05/20/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",
"logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09
12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"userIdDisplay": "00324557", "legacyFrc": "783101" }, { "sequenceNumber": "02",
"creationDate": "12/09/2011 12:36:53", "userId": "0000637639", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "78", "ataDesc":
"Thrust Reverser Structure/Blocker Doors/Cascade Vanes/Seals", "ataSectCode": "31",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab":
"X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-11-30 15:02:26.6",
"faaReviewStartTms": "2014-11-06 15:02:26.601399", "intExt": "EX", "itemDesc": "Thrust
Reverser Deactivation Signal Plate Placard Screws Missing (A330 Only)", "itemNotes":
"Reverser Deactivation Signal Plate placard screws missing when the reverser is not on
MEL. These screws are only for retaining the Deactivation Signal Plate placard but should
be reinstalled to fill the holes after clearing the MEL. Ref AMM 78-30-00-991-0",
"itemNotesInd": "Y", "itemNumber": "78-31-02", "lastUpdate": "2014-11-06
15:02:32.32931", "lastUpdateDisplay": "11/06/2014", "legacyDeltaAirworthyInd": "N",
"logMultiplicity": "M", "logpageNumber": "9999999", "mplIndicator": "Y", "oii": "N",
"rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms":
"2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via
ACARS", "userIdDisplay": "00637639", "legacyFrc": "783102" }, { "sequenceNumber": "03",

"creationDate": "02/18/2012 14:30:32", "userId": "0000324557", "activeInd": "A",
"activeIndDisplay": "Active", "allowableTime": "10", "ataChapterCode": "78", "ataDesc":
"Thrust Reverser Structure/Blocker Doors/Cascade Vanes/Seals", "ataSectCode": "31",
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOProcedure": "No
leaks are permitted. No hazardous conditions (sharp edges, etc.) are permitted. If it is
required to open/close the thrust reverser cowl, use an alternate (manual or sling)
procedure per:\n\nB737NG: AMM 78-31-00-010-801-F00 & 78-31-00-010-804-F00\nB757:
AMM 78-31-00-912-017-P03\nB767-300 (PW): AMM 78-31-00-000-801-N00 & 78-31-00-
400-801-N00\nB767-300 (GE): AMM 78-31-00-000-801-H00 & 78-31-00-400-801-
H00\nB767-400: AMM 78-31-00-000-801-H00 & 78-31-00-400-801-H00\nA330 (PW): AMM
78-30-00-010-801-A & 78-30-00-410-801-A\nA350: A350-A-78-3X-XX-04001-398A-A &
A350-A-78-3X-XX-05001-398A-A\n\nNOT FOR A220 \u001A USE MEL 78-32-01\n\nNOT FOR
A319/320/321 \u001A USE CDL 78-00-01\n\nNOT FOR A330NEO \u001A USE CDL 78-00-
10\n\nNOT FOR A330CEO (GE) \u001A No Alternate Procedures Available\n\nNOT FOR B717 -
(Not Applicable)", "decisionInd": "A", "defRemarks": "No leaks are permitted. No
hazardous conditions (sharp edges, etc.) are permitted. If it is required to open/close the
thrust reverser cowl, use an alternate (manual or sling) procedure per:\n\nB737NG: AMM
78-31-00-010-801-F00 & 78-31-00-010-804-F00\nB757: AMM 78-31-00-912-017-
P03\nB767-300 (PW): AMM 78-31-00-000-801-N00 & 78-31-00-400-801-N00\nB767-300
(GE): AMM 78-31-00-000-801-H00 & 78-31-00-400-801-H00\nB767-400: AMM 78-31-00-
000-801-H00 & 78-31-00-400-801-H00\nA330 (PW): AMM 78-30-00-010-801-A & 78-30-00-
410-801-A\nA350: A350-A-78-3X-XX-04001-398A-A & A350-A-78-3X-XX-05001-398A-
A\n\nNOT FOR A220 \u001A USE MEL 78-32-01\n\nNOT FOR A319/320/321 \u001A USE CDL
78-00-01\n\nNOT FOR A330NEO \u001A USE CDL 78-00-10\n\nNOT FOR A330CEO (GE)
\u001A No Alternate Procedures Available\n\nNOT FOR B717 - (Not Applicable)", "efmTab":
"X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "biever", "faaReviewEndTms":
"2021-06-13 14:12:52.028592", "faaReviewStartTms": "2021-05-20 14:12:52.028592",
"intExt": "EX", "itemDesc": "Thrust Reverser Cowl Opening System (LIMITED EFFECTIVITY -
SEE REMARKS)", "itemNotes": "Thrust Reverser Cowl Opening System (hydraulic/electric
cowl opening assist for maintenance functions) may be inoperative, provided ALTERNATE
PROCEDURES ARE USED. See deferral remarks for alternate procedures. No leaks are
permitted. No hazardous conditions (sharp edges, etc.) are permitted.", "itemNotesInd":
"Y", "itemNumber": "78-31-03", "lastUpdate": "2021-05-20 14:13:36.25104",
"lastUpdateDisplay": "05/20/2021", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S",
"logpageNumber": "8664863", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":
"0000736461", "rowInsertEmpNoDisplay": "00736461", "rowInsertTms": "2012-02-18
14:20:46.586079", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",
"suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "783103" },

```
{ "sequenceNumber": "04", "creationDate": "01/26/2014 05:35:10", "userId":  
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "78", "ataDesc": "Thrust Reverser Structure/Blocker Doors/Cascade  
Vanes/Seals", "ataSectCode": "31", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":  
"0", "deactMOProcedure": "May be in broken provided the reverser operates normally and  
the handle is not needed for locking out the thrust reverser or thrust reverser  
maintenance.", "decisionInd": "A", "defRemarks": "May be in broken provided the reverser  
operates normally and the handle is not needed for locking out the thrust reverser or thrust  
reverser maintenance.", "efmTab": "X", "faaAcceptanceRequiredInd": "Y",  
"faaContactName": "Hoogenhout", "faaReviewEndTms": "2014-11-28 15:15:08.587",  
"faaReviewStartTms": "2014-11-04 15:15:08.587987", "intExt": "EX", "itemDesc": "Thrust  
Reverser Manual Lock Handle Broken/Missing (B757 only)", "itemNotes": "Maintenance  
unlock handle to unlock the thrust reverser on the locking actuator.", "itemNotesInd": "Y",  
"itemNumber": "78-31-04", "lastUpdate": "2014-11-04 15:15:15.080879",  
"lastUpdateDisplay": "11/04/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M",  
"logpageNumber": "5375927", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo":  
"0000308928", "rowInsertEmpNoDisplay": "00308928", "rowInsertTms": "2014-01-26  
05:34:21.49574", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS",  
"suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "783104" },  
{ "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId":  
"0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120",  
"ataChapterCode": "78", "ataDesc": "Actuation/Cables/Leaks", "ataSectCode": "32",  
"autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab":  
"X", "faaAcceptanceRequiredInd": "Y", "faaReviewEndTms": "2014-11-30 15:03:00.337",  
"faaReviewStartTms": "2014-11-06 15:03:00.339147", "intExt": "EX", "itemDesc": "Thrust  
Reverser Manual Drive Assembly Worn (A330 only)", "itemNotesInd": "N", "itemNumber":  
"78-32-01", "lastUpdate": "2014-11-06 15:03:03.725085", "lastUpdateDisplay":  
"11/06/2014", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber":  
"9999999", "mplIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB",  
"rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842",  
"sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay":  
"00637639", "legacyFrc": "783201" }, { "sequenceNumber": "01", "creationDate":  
"05/30/2012 16:36:42", "userId": "0000324557", "activeInd": "A", "activeIndDisplay":  
"Active", "allowableTime": "120", "ataChapterCode": "79", "ataDesc": "Engine Oil  
Servicing", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount":  
"0", "deactMOProcedure": "Remove and discard any remaining lanyard section(s) when  
applying this NEF.", "decisionInd": "A", "defRemarks": "Remove and discard any remaining  
lanyard section(s) when applying this NEF.", "efmTab": "X", "faaAcceptanceRequiredInd":
```

"Y", "faaContactName": "Bill L. Williams", "faaReviewEndTms": "2025-10-19 13:03:36.235661", "faaReviewStartTms": "2025-09-25 13:03:36.235661", "intExt": "EX", "itemDesc": "Engine Oil Service Cap Lanyard Broken/Missing", "itemNotesInd": "N", "itemNumber": "79-19-01", "lastUpdate": "2025-09-25 13:03:46.038647", "lastUpdateDisplay": "09/25/2025", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "M", "logpageNumber": "8633913", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000308928", "rowInsertEmpNoDisplay": "00308928", "rowInsertTms": "2012-05-30 16:32:56.226921", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00324557", "legacyFrc": "791901" }, { "sequenceNumber": "01", "creationDate": "12/09/2011 12:36:53", "userId": "245058", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "79", "ataDesc": "Indicating", "ataSectCode": "30", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "deactMOPProcedure": "Ref applicable AMM for other requirements", "decisionInd": "A", "defRemarks": "Ref applicable AMM for other requirements", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaComments": "Contained in initial FAA approved list.", "faaReviewEndTms": "2012-01-05 13:36:54.279", "faaReviewStartTms": "2011-12-12 13:36:53.588819", "intExt": "EX", "itemDesc": "Oil Line Temperature Tabs Worn", "itemNotesInd": "N", "itemNumber": "79-30-01", "lastUpdate": "2013-12-04 14:08:53.562998", "lastUpdateDisplay": "12/04/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9999999", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "LOADJOB", "rowInsertEmpNoDisplay": "LOADJOB", "rowInsertTms": "2011-12-09 12:36:53.842", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "userIdDisplay": "00245058", "legacyFrc": "793001" }, { "sequenceNumber": "01", "creationDate": "07/05/2013 03:07:18", "userId": "0000637639", "activeInd": "A", "activeIndDisplay": "Active", "allowableTime": "120", "ataChapterCode": "80", "ataDesc": "Oil Servicing (Starter)", "ataSectCode": "19", "autoDefCde": "NEF", "crewDefInd": "N", "daysCount": "0", "decisionInd": "A", "efmTab": "X", "faaAcceptanceRequiredInd": "Y", "faaContactName": "Hoogenhout", "faaReviewEndTms": "2013-08-10 07:04:02.425", "faaReviewStartTms": "2013-07-17 07:04:02.426209", "intExt": "EX", "itemDesc": "Engine Starter Dust Cap Damaged/Missing", "itemNotesInd": "N", "itemNumber": "80-19-01", "lastUpdate": "2013-07-17 07:37:06.863935", "lastUpdateDisplay": "07/17/2013", "legacyDeltaAirworthyInd": "N", "logMultiplicity": "S", "logpageNumber": "9925143", "mpIndicator": "Y", "oii": "N", "rowInsertEmpNo": "0000578202", "rowInsertEmpNoDisplay": "00578202", "rowInsertTms": "2013-07-05 03:05:57.81772", "sceptreAutoDefRemarks": "Auto Generated Log NEF Via ACARS", "suggestedManDefCde": "NEF", "userIdDisplay": "00637639", "legacyFrc": "801901" }] }, "messages": [] }

