

$L(f)$

Integrating phase noise to compute RMS jitter

$\int L(f) df$

(shaded area)

f_{low}

f_{high}

f

$$\sigma_t = (1/2\pi f_c) \sqrt{2 \times \text{shaded area}}$$

