

Freeswitch 1.0.6+Zaptel+ATCOM AX-4ET

Tested by Robert.Ao

06-11-2010

Test Environment

freeswitch-1.0.6

libpri-1.4.11.2

zaptel-1.4.12.1

Centos 5.4(kernel version: 2.6.18-164.el5)

E1 crossover cable ATCOM AX-4ET card

Software Installation

Install zaptel

./configure

make

make install

make config

Attention: Please download zaptel from ATCOM website

2. Install libpri

make

make install

3. In freeswitch-1.0.6/ modules.conf file, please uncomment the following line:

../../libs/openzap/mod_openzap

4. Install freeswitch and openzap

run "./configure " under the freeswitch-1.0.6/ directory

then run ./configure --with-libpri

make

make mod_openzap-install

in freeswitch-1.0.6/libs/openzap directory



run the following commands under the freeswitch-1.0.6/ directory to install freeswitch make make install make cd-sounds-install make cd-moh-install

5. Please add one line in /usr/local/freeswitch/conf/autoload_configs/modules.conf.xml (line 37)

<load module="mod_openzap"/>

6. Please use the following command to configure zaptel.conf file: genzaptelconf –sdvM

7. zaptel.conf

```
# Span 1: Tor2/0/1 "Tormenta 2 (PCI) Quad E1 Card 0 Span 1" (MASTER) span=1,1,0,ccs,hdb3
# termtype: te
bchan=1-15,17-31
dchan=16

# Span 2: Tor2/0/2 "Tormenta 2 (PCI) Quad E1 Card 0 Span 2"
span=2,2,0,ccs,hdb3
# termtype: te
bchan=32-46,48-62
dchan=47

# Span 3: Tor2/0/3 "Tormenta 2 (PCI) Quad E1 Card 0 Span 3"
```

span=3,3,0,ccs,hdb3

termtype: te

bchan=63-77,79-93

dchan=78

Span 4: Tor2/0/4 "Tormenta 2 (PCI) Quad E1 Card 0 Span 4"

span=4,4,0,ccs,hdb3

termtype: te

bchan=94-108,110-124

dchan=109



8. Please edit /usr/local/openzap/conf/openzap.conf file like the following:

[span zt PRI_1]

name => OpenZAP

number => 1

trunk_type => e1

b-channel => 1-15

d-channel => 16

b-channel => 17-31

[span zt PRI_2]

name => OpenZAP

number => 2

trunk_type => e1

b-channel => 32-46

d-channel => 47

b-channel => 48-62

[span zt PRI_3]

name => OpenZAP

number \Rightarrow 3

trunk_type => e1

b-channel => 63-77

d-channel => 78

b-channel => 79-93

[span zt PRI_4]

name => OpenZAP

number => 4

trunk_type => e1

b-channel => 94-108

d-channel => 109

b-channel => 110-124



9. Please edit /usr/local/freeswitch/conf/autoload_configs/openzap.conf.xml file like the following:

```
<configuration name="openzap.conf" description="OpenZAP Configuration">
   spans>
     <span name="PRI_1">
        <param name="node" value="net"/>
        <param name="switch" value="euroisdn"/>
        <param name="opts" value="none"/>
        <param name="dp" value="unknown"/>
        <param name="debug" value="all"/>
        <param name="dialplan" value="XML"/>
        <param name="context" value="from-internal"/>
      </span>
      <span name="PRI_2">
        <param name="node" value="net"/>
        <param name="switch" value="euroisdn"/>
        <param name="opts" value="none"/>
        <param name="dp" value="unknown"/>
        <param name="debug" value="all"/>
        <param name="dialplan" value="XML"/>
        <param name="context" value="from-internal"/>
      </span>
      <span name="PRI 3">
        <param name="node" value="cpe"/>
        <param name="switch" value="euroisdn"/>
        <param name="opts" value="none"/>
        <param name="dp" value="unknown"/>
        <param name="debug" value="all"/>
        <param name="dialplan" value="XML"/>
        <param name="context" value="from-pstn"/>
      </span>
      <span name="PRI 4">
        <param name="node" value="cpe"/>
        <param name="switch" value="euroisdn"/>
        <param name="opts" value="none"/>
        <param name="dp" value="unknown"/>
        <param name="debug" value="all"/>
        <param name="dialplan" value="XML"/>
        <param name="context" value="from-pstn"/>
      </span>
   spans>
</configuration>
```



10. Please run " /usr/local/freeswitch/bin/freeswitch " command to start freeswitch Run oz list, you should get the following span information you have configured freeswitch@localhost.localdomain> oz list

+OK

span: 1 (PRI_1)

type: isdn

chan_count: 31 dialplan: XML

context: from-internal

dial_regex:

fail_dial_regex:

hold_music:

analog_options none

+OK

span: 2 (PRI_2)

type: isdn

chan_count: 31

dialplan: XML

context: from-internal

dial_regex:

fail_dial_regex:

hold_music:

analog_options none

+OK

span: 3 (PRI_3)

type: isdn

chan_count: 31

dialplan: XML

context: from-pstn

dial_regex:

fail_dial_regex:

hold_music:

analog_options none

+OK

span: 4 (PRI_4)

type: isdn

chan_count: 31

dialplan: XML

context: from-pstn

dial_regex:

fail_dial_regex:

hold_music:

analog_options none



Loopback Test

- 1. Please connect port 1 to port 4 with a cross-over cable
- Please added dial-plans by creating two .xml files under the /usr/local/freeswitch/conf/dialplan directory

```
from-internal.xml
   <context name="from-internal">
    <extension name="from-internal">
      <condition field="destination_number" expression="^(.*)$">
         <action application="bridge" data="openzap/1/a/$1"/>
      </condition>
    </extension>
   </context>
   <context name="from-pstn">
    <extension name="from-pstn">
      <condition field="destination number" expression="^(.*)$">
         <action application="playback" data="ivr-welcome_to_freeswitch.wav"/>
         <action application="bridge" data="openzap/1/a/$1"/>
      </condition>
    </extension>
   </context>
3. Please use a registered sip phone to dial any number, then you should listen to the sound file
   30 times, and get the following output:
freeswitch@localhost.localdomain>
                                        2010-07-05
                                                          16:53:42.583403
                                                                                 [NOTICE]
                                      Channel
switch_channel.c:669
                           New
                                                     sofia/internal/1999@192.168.1.229:5060
[7ee30d1e-f240-4951-8623-b9564944d94b]
2010-07-05 16:53:42.591402 [INFO] mod_dialplan_xml.c:418 Processing 1999->1111 in context
from-internal
2010-07-05 16:53:42.592409 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:1
2010-07-05 16:53:42.592409 [INFO] ozmod zt.c:638 Setting echo cancel to 64 taps for 1:1
2010-07-05 16:53:42.593401 [NOTICE] switch_channel.c:669 New Channel OpenZAP/1:1/1111
[ee79b30a-d711-435b-8319-8a89ded4dfd5]
2010-07-05 16:53:42.608397 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 4:1
2010-07-05 16:53:42.608397 [NOTICE] ozmod_libpri.c:772 -- Ring on channel 4:1 (from 1999 to
1111)
2010-07-05 16:53:42.610398 [NOTICE] switch_channel.c:669 New Channel OpenZAP/4:1/1111
```



[d9dff21e-5985-4e6c-abc9-0cb8a3103525]

2010-07-05 16:53:42.610398 [INFO] mod_dialplan_xml.c:418 Processing Extension 1999->1111 in context from-pstn

2010-07-05 16:53:42.618394 [NOTICE] mod_openzap.c:1962 Pre-Answer OpenZAP/1:1/1111!

2010-07-05 16:53:42.625395 [INFO] switch_ivr_originate.c:3105 Sending early media

2010-07-05 16:53:42.628394 [NOTICE] mod_sofia.c:1907 Pre-Answer sofia/internal/1999@192.168.1.229:5060!

2010-07-05 16:53:42.634391 [NOTICE] switch_core_session.c:1753 Pre-Answer OpenZAP/4:1/1111!

2010-07-05 16:53:45.215890 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:2

2010-07-05 16:53:45.215890 [INFO] ozmod zt.c:638 Setting echo cancel to 64 taps for 1:2

2010-07-05 16:53:45.215890 [NOTICE] switch_channel.c:669 New Channel OpenZAP/1:2/1111 [08d563bb-2cd1-4c2c-b19a-a80c7f57461d]

2010-07-05 16:53:45.267872 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 4:2

2010-07-05 16:53:45.267872 [NOTICE] ozmod_libpri.c:772 -- Ring on channel 4:2 (from 1999 to 1111)

2010-07-05 16:53:45.267872 [NOTICE] switch_channel.c:669 New Channel OpenZAP/4:2/1111 [9a1a395d-6cd1-4bb1-9a1b-ad6cd042f5fb]

2010-07-05 16:53:45.269877 [INFO] mod_dialplan_xml.c:418 Processing Extension 1999->1111 in context from-pstn

2010-07-05 16:53:45.277871 [NOTICE] mod openzap.c:1962 Pre-Answer OpenZAP/1:2/1111!

2010-07-05 16:53:45.305864 [NOTICE] switch_core_session.c:1753 Pre-Answer OpenZAP/4:2/1111!

2010-07-05 16:53:47.887340 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:3

2010-07-05 16:53:47.887340 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:3

2010-07-05 16:53:47.887340 [NOTICE] switch_channel.c:669 New Channel OpenZAP/1:3/1111 [b194e39a-ee11-4fc5-8754-f49f54c4258d]

2010-07-05 16:53:47.925332 [INFO] ozmod zt.c:638 Setting echo cancel to 64 taps for 4:3

2010-07-05 16:53:47.925332 [NOTICE] ozmod_libpri.c:772 -- Ring on channel 4:3 (from 1999 to 1111)

2010-07-05 16:53:47.927335 [NOTICE] switch_channel.c:669 New Channel OpenZAP/4:3/1111 [c33a5659-07c7-449d-9036-063d7dd81291]

2010-07-05 16:53:47.927335 [INFO] mod_dialplan_xml.c:418 Processing Extension 1999->1111 in context from-pstn

2010-07-05 16:53:47.935331 [NOTICE] mod_openzap.c:1962 Pre-Answer OpenZAP/1:3/1111!

2010-07-05 16:53:47.965325 [NOTICE] switch_core_session.c:1753 Pre-Answer OpenZAP/4:3/1111!

......

2010-07-05 16:56:13.129176 [NOTICE] switch_channel.c:669 New Channel OpenZAP/1:29/1 [102f00a3-1e86-46a9-a252-da7546e27e5f]

2010-07-05 16:56:13.179181 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 4:29 2010-07-05 16:56:13.179181 [NOTICE] ozmod_libpri.c:772 -- Ring on channel 4:29 (from 1999 to 1)



2010-07-05 16:56:13.181239 [NOTICE] switch_channel.c:669 New Channel OpenZAP/4:29/1 [7a53b526-9df4-4227-8a99-a60e87ee7706]

2010-07-05 16:56:13.183226 [INFO] mod_dialplan_xml.c:418 Processing Extension 1999->1 in context from-pstn

2010-07-05 16:56:13.191164 [NOTICE] mod_openzap.c:1962 Pre-Answer OpenZAP/1:29/1!

2010-07-05 16:56:13.211163 [NOTICE] switch_core_session.c:1753 Pre-Answer OpenZAP/4:29/1!

2010-07-05 16:56:15.790642 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:30

2010-07-05 16:56:15.790642 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:30

2010-07-05 16:56:15.790642 [NOTICE] switch_channel.c:669 New Channel OpenZAP/1:30/1 [fc5a9261-4658-47ec-b00e-da59b4ae321e]

2010-07-05 16:56:15.847633 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 4:30 2010-07-05 16:56:15.847633 [NOTICE] ozmod_libpri.c:772 -- Ring on channel 4:30 (from 1999 to 1)

2010-07-05 16:56:15.847633 [NOTICE] switch_channel.c:669 New Channel OpenZAP/4:30/1 [01e167c9-b241-440f-98c2-33ee48f5cb82]

2010-07-05 16:56:15.850658 [INFO] mod_dialplan_xml.c:418 Processing Extension 1999->1 in context from-pstn

2010-07-05 16:56:15.856630 [NOTICE] mod_openzap.c:1962 Pre-Answer OpenZAP/1:30/1!

2010-07-05 16:56:15.877626 [NOTICE] switch_core_session.c:1753 Pre-Answer OpenZAP/4:30/1!

2010-07-05 16:56:18.460126 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:31

2010-07-05 16:56:18.460126 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 1:31

2010-07-05 16:56:18.460126 [NOTICE] switch_channel.c:669 New Channel OpenZAP/1:31/1 [c6da8a77-027d-404b-b1a9-d0ba19fa47d8]

2010-07-05 16:56:18.509195 [INFO] ozmod_zt.c:638 Setting echo cancel to 64 taps for 4:31

2010-07-05 16:56:18.509195 [NOTICE] ozmod_libpri.c:772 -- Ring on channel 4:31 (from 1999 to 1)

2010-07-05 16:56:18.511090 [NOTICE] switch_channel.c:669 New Channel OpenZAP/4:31/1 [b689a522-9959-4f91-9581-7a782eaed246]

2010-07-05 16:56:18.511090 [INFO] mod_dialplan_xml.c:418 Processing Extension 1999->1 in context from-pstn

2010-07-05 16:56:18.519144 [NOTICE] mod_openzap.c:1962 Pre-Answer OpenZAP/1:31/1!

2010-07-05 16:56:18.547085 [NOTICE] switch_core_session.c:1753 Pre-Answer OpenZAP/4:31/1!



Reference

 $\underline{http://wiki.freeswitch.org/wiki/OpenZAP\#OpenZAP_CLI_Commands}$

http://wiki.freeswitch.org/wiki/FreeSwitch_Dialplan_XML#Dial_plan_parser

 $\underline{http://wiki.freeswitch.org/wiki/Installation_Guide}$

http://wiki.freeswitch.org/wiki/Getting_Started_Guide