计算机组成小测2答案

1. Choose true or false

- a. In order to use the saved registers (s0-s11) in a function, we must store their values before using them and restore their values before returning. (T)
- b. jalr is a shorthand expression for a jal that jumps to the specified label and does not store a return address anywhere. (\mathbf{F})
- c. Assuming no compiler or operating system protections, it is possible to have the code jump to data stored at 0(a0) (offset 0 from the value in register a0) and execute instructions from there. (T)
- d. In the multiplication and division extension of RISC-V, the division instruction ensures that an exception will not be thrown even if the divisor is zero. (F)
- e. Each instruction in the RISC-V instruction set has two operating modes, 32-bit and 64-bit, corresponding to the processor's bit width. (F)

2. Answer the following questions briefly

a. Translate between C and RISC-V

С	RISC-V					
e.g.	e.g.					
// s0 -> a, s1 -> b	addi s0, x0, 1					
// s2 -> c	addi s1, x0, 2					
int $a = 1, b = 2, c;$	add s2, s0, s1					
c = a + b;						
// s0 -> a, s1-> b	addi s0, x0, 5					
	addi s1, x0, 10					
	addi t0, s0, s0					
int $a = 5$, $b = 10$;	beq t0, s1, if					
if $(a + a == b) a = 0;$	addi s1, s0, -1					
else $b = a - 1$;	jal x0, exit					
	if:					
	addi s0, x0, 0					
	exit:					
// a0 -> a, a1 -> b, result -> a0	func:					
	bge x0, a0, done					
	bge x0, a1, done					
	addi sp, sp, -4					
int f (int a, int b) {	sw ra, 0(sp)					
if $(a \le 0 b \le 0)$ return 0;	addi t0, a1, -2					
else return f(b-2, a-b);	sub a1, a0, a1					
}	addi a0, t0, 0					
	jal ra, func					
	lw ra, 0(sp)					
	jalr x0, 0(ra)					
	done:					
	addi a0, x0, 0					
	jalr x0, 0(ra)					

- b. Convert the following single-precision floating point numbers from hexadecimal to decimal or from decimal to hexadecimal. (Use IEEE 754)
 - 1) -∞
- 2) 65.3125
- 3) -0.3
- 4) 0x7FABCDEF
- 1) 0xFF800000 2) 0x4282A000 3) 0xBE99999A 4) NaN
- 3. Consider the following loop in RISC-V:

LOOP:

blt x6, x0, DONE addi x6, x6, -1 addi x5, x5, 3 jal x0, LOOP

DONE:

addi x0, x0, 0

3	1 25	24 20	19	15	14	12	11	7	6	0
R	funct7	rs2	rs1		funct3		rd		opcode	
- 1	imm[11	rs1		funct3		rd		opcode		
l*	funct7	imm[4:0]	rs1		funct3		rd		opcode	
S	imm[11:5]	rs2	rs1		funct3		imm[4:0]		opcode	
В	imm[12 10:5]	rs2	rs1		funct3		imm[4:1	11]	opcode	
U	imm[31:12]					rd		opcode		
J	imm[20 10:1 11 19:12]						rd		opcode	\neg

a. Assume that the register x6 is initialized to the value 100. What is the final value in register x5 assuming the x5 is initially zero?

303

b. For the loop written in RISC-V assembly above, assume that the register x6 is initialized to the value N. How many RISC-V instructions are executed?

4N+6

c. Assume that the PC value to label "LOOP" is 0x04, write the machine binary code of the first and second instruction of this LOOP.

J-Type opcode: 0x6F; I-Type opcode: 0x13, addi-funct3: 0; B-Type opcode: 0x63, blt-funct3: 0x4 **e.g.** addi, x0, x0, 0 -> 0x00000013

blt x6, x0, DONE --> 0x00034863 addi x6, x6, -1 --> 0xFFF30313