

1. GENERAL

1.1. ATIS

D-ATIS Arrival 128.2  
D-ATIS Departure 127.05

1.2. UNSERVICABILITY OF ACFT OR GROUND EQUIPMENT

1.2.1. ARRIVALS

In case of ACFT equipment u/s, request ATC assistance.  
In case of ground equipment u/s, ATC will provide an alternative arrival clearance or assist by vectoring.

1.2.2. DEPARTURES

In case of ACFT equipment u/s, request ATC assistance.  
In case of ground equipment u/s, ATC will provide an alternative departure clearance or assist by vectoring.

1.3. LOW VISIBILITY PROCEDURES (LVP)

1.3.1. GENERAL

LVP are established for operations in a visibility of less than RVR 550m or a cloudbase of less than 200ft.  
Special procedures and safeguards will be applied during CAT II/III operations to protect ACFT operating in low visibility and to avoid interference to the ILS signals.  
Pilots shall be informed when:

- Meteorological reports preclude ILS CAT I operations;
- Low Visibility Procedures are in operation;
- There is any unserviceability in a promulgated facility so that they may amend their minima.

Pilots who wish to carry out an ILS CAT III approach shall inform Approach Control on initial contact. Pilots may carry out a practice ILS CAT II/III approach at any time, but the full safeguarding procedures will not be applied and pilots should anticipate the possibility of ILS signal interference.

1.3.2. ARRIVAL

All RWY exit TWYs are available.  
All RWY exits have TWY centerline lead-off lights that are colour coded (green/yellow) to indicate that portion of the TWY that is within the ILS sensitive area. Pilots are to delay the ~~the~~ call until the ACFT has completely vacated the ILS sensitive area and passed the end of the colour coded TWY centerline lights.

1.3.3. DEPARTURE

ACFT shall normally enter:

- RWY 07L via TWYs C1 or C2;
- RWY 07C via TWYs A1, A2 or F1, F2;
- RWY 07R via TWYs J1, J2 or K1;
- RWY 25L via TWYs J10, J11 or K7;
- RWY 25C via TWYs A11, A12 or F7, F8;
- RWY 25R via TWYs C11 or C12.

VHHH/HKG

JEPPESEN

HONG KONG, PR OF CHINA

HONG KONG INTL

22 NOV 24

10-1P1

Eff 28 Nov

AIRPORT BRIEFING

## 1. GENERAL

- RWY 07R/25L:  
Holding positions on TWY J1, J2, J10 and J11 are CAT I/II holding positions. RWY 25L holding position on TWY K is CAT I/II holding position. Separate CATII holding positions are provided on TWYs K1 and K for RWY 07R.
- RWY 07C/25C:  
Holding positions on TWY A1 and A2 are CAT I/II holding positions and holding positions on TWYs A11 and A12 are CAT I/II/III holding positions. Separate CAT II holding positions are provided on TWYs F1 and E, and TWYs F2 and F for RWY 07C. Separate CAT II/III holding positions are provided on TWYs F7 and F, and TWYs F8 and E for RWY 25C.
- RWY 07L/25R:  
Holding positions on TWYs C1 and C2 are CAT I/II/III holding positions.

### 1.4. USE OF MODE S TRANSPONDER AFTER LANDING

ACFT equipped with a 卅eight on wheel?switch must continue to have its transponder operating on "AUTO" or "XPNDR" until fully parked at a stand.

### 1.5. RWY OPERATIONS

#### 1.5.1. THREE-RWY OPERATIONS

When all three RWYs are available (normally between 0000-1459UTC daily), the following operating mode will normally be adopted to allow simultaneous operations of all three RWYs:

##### RWY 07

- 07L: Arrivals only.
- 07C: Departures only (flight planned to North, Northeast or East via BEKOL, LEKEN - V601/V611 or DALOL - V621/V631).
- 07R: Mixed Arrivals and Departures (flight planned to Southeast, South or West via DALOL - V641/V651 or PECAN - V10/V11/V12).

##### RWY 25

- 25R: Arrivals only.
- 25C: Departures only (flight planned to East, Southeast, South or West via DALOL - V621/V631/V641/V651 or PECAN - V10/V11/V12).
- 25L: Mixed Arrivals and Departures (flight planned to North or Northeast via BEKOL or LEKEN - V601/V611).

Arrivals will operate via dependent parallel approaches to RWYs 07L/07R or RWYs 25R/25L.

ATC will assign landing RWY based on expected parking location and other operational factors. ACFT parking at South Cargo apron or Business Aviation Center facility will be preferentially assigned the South RWY (07R/25L) subject to prevailing traffic conditions. All other arrival flights should anticipate landing on North RWY (07L/25R) and should refrain from making requests for an alternative RWY unless operationally required.

ATC will confirm the landing RWY to arriving ACFT on first contact with Approach Control.

Independent parallel departures will normally be conducted on RWY 07C/07R or RWY 25C/25L and will be broadcasted on Departure ATIS.

ACFT operators should base on the RWY allocation strategies above for operational planning to enable most efficient use of RWY capacity.

VHHH/HKG  
HONG KONG INTL

22 NOV 24

JEPPESEN  
10-1P2

HONG KONG, PR OF CHINA  
Eff 28 Nov  
AIRPORT BRIEFING

## 1. GENERAL

### 1.5.2. DUAL AND SINGLE RWY OPERATIONS

Between 1500-2259UTC daily, South RWY (07R/25L) is not available for normal operations.

Between 1500-1659UTC daily, North RWY (07L/25R) and Center RWY (07C/25C) will operate in segregated mode, i.e. one RWY for arrival and one RWY for departure. The North RWY (07L/25R) is the normal arrival RWY and the Center RWY (07C/25C) is the normal departure RWY. RWY 07C SIDs with "T" designator will not be issued between 1500-2259UTC for noise mitigation purposes.

Between 1700-2259UTC daily, only one RWY, either North RWY (07L/25R) or Center RWY (07C/25C), will remain operational in Mixed Arrivals and Departures Mode.

Between 2300-2359UTC daily, dual RWY operations will resume using a combination of North/Center, Center/South or North/South RWYs depending on the maintenance schedule.

Scheduled RWY maintenance will normally be arranged on a rotational basis across the three RWYs between 1700-2359UTC daily. The scheduled maintenance periods are published in AIP Supplements and any amendments are promulgated by NOTAM.

### 1.6. TAXI PROCEDURES

Taxi with extreme CAUTION and MIM required engines power only.

### 1.7. PARKING INFORMATION

#### 1.7.1. GENERAL

All stands on passenger terminal aprons, except stand W126, are equipped with Safegate Docking System for wide-body ACFT.

ACFT Docking Guidance System (ADGS) is available at most of the frontal and remote stands to enable ACFT to park at the correct main centerline position on the parking stand (except W126 and X459). However, the ADGS is not provided at Main Cargo apron and all off-centerline parking positions of stands.

#### 1.7.2. FRONTAL PARKING STANDS

Frontal parking stands are those stands which are served by airbridges with direct access to the passenger terminal building. Frontal parking stands that can accommodate wide-body types of ACFT have continuous yellow nosewheel guidance lines to indicate the correct parking centerline.

Some frontal parking stands can also accommodate narrow-body types of ACFT at a separate parking bay location displaced 30?9m to the RIGHT of the wide-body centerline and indicated by a dashed yellow guidance line. The narrow-body parking stand is referred to by a "R" suffix, e.g. S25R. The following parking stands can accommodate narrow-body types of ACFT:

- South apron: S1R, S2R, S3R, S25R, S27R, S29R, S31R, S33R, S35R, S41R, S43R, S45R, S47R and S49R.
- North apron: N6R, N7R, N24R, N26R, N28R, N30R, N32R, N34R, N60R, N62R, N64R, N66R, N68R and N70R
- West apron: W40R, W42R, W44R, W46R, W48R, W61R, W63R, W65R, W67R, W69R and W71R.

VHHH/HKG

JEPPesen

HONG KONG, PR OF CHINA

HONG KONG INTL

22 NOV 24

10-1P3

Eff 28 Nov

AIRPORT BRIEFING

## 1. GENERAL

### 1.7.3. REMOTE PARKING STANDS

All remote parking stands on the North and South aprons have continuous yellow nosewheel guidance lines.

The remote parking stands on the West apron are configured to accommodate up to 5 wide-body type ACFT or up to 7 narrow-body type ACFT, or a combination of wide and narrow-body type ACFT. The wide-body parking locations have continuous yellow nosewheel guidance lines to indicate the correct parking centerline.

The remote parking stands D301 thru D310 on Midfield apron are configured to accommodate up to 10 wide-body type ACFT to MAX 18 narrow-body type ACFT, or a combination of wide and narrow-body type ACFT. The wide-body parking locations have continuous yellow nosewheel guidance lines to indicate the correct parking centerline.

The narrow-body parking locations are displaced to the Left and the Right of the wide-body centerline and are indicated by dashed yellow nosewheel guidance lines. These narrow-body parking stands are referred to by a "L" or "R" suffix, e.g. W121L or W123R.

### 1.8. OTHER INFORMATION

#### 1.8.1. AVAILABILITY OF RNP 1 AND CONTINGENCY SID/STARs

RNP 1 SID/STARs have been implemented in Hong Kong TMA. All ACFT departing/arriving, other than those specified below, shall be equipped with appropriate systems and approved by the relevant State of Registry in accordance with ICAO RNP 1 standard. Carriage of a certified GNSS receiver is mandatory.

RNP 1 operational approval or compliance documentation shall be readily available for inspections.

The following categories of flights are granted exemptions from the RNP 1 requirement, and approved to operate in/out of VHHH using contingency procedures described on STAR charts and RAMEN & RUMSY SIDs:

- Humanitarian or SAR flights;
- State ACFT;
- Flight check;
- Maintenance or delivery flights;
- Air tests (e.g. post maintenance);
- Flights with specific prior approval by Director-General of Civil Aviation;
- Flights with failure or degradation of RNP 1 system before departure.

In case of failure of RNP 1 when airborne pilots must notify ATC with the phraseology "UNABLE RNP 1 [DUE TO (reason)]" as soon as possible. Dependent upon the nature of the reported system failure or degradation, continued operation with the current ATC clearance may be possible in many circumstances. When this cannot be achieved, ATC assistance would be provided as necessary.

#### 1.8.2. LOCAL WIND EFFECTS

##### 1.8.2.1. GENERAL WARNING

Due to the proximity of the hilly terrain of Lantau Island to the South and East of APT, significant low-level wind shear and moderate to severe turbulence can be expected along the approaches to and departures from the RWYs when winds blow off these hills, i.e. from East through Southwest at about 15 KT or more. As the hills to the North are further away, they play a less significant role, but nonetheless can create local wind effects when strong winds blow off these hills, i.e. from Northwest through Northeast, at about 20 KT or more.

VHHH/HKG

JEPPESEN

HONG KONG, PR OF CHINA

HONG KONG INTL

28 MAR 25

10-1P4

AIRPORT BRIEFING

## 1. GENERAL

The terrain-induced wind disturbances from nearby hills can be of very small scale, sporadic and transient in nature. Whilst these wind disturbances may be small in physical dimension and correspond to only several seconds of flight time, significant headwind changes (i.e. RWY-orientated wind speed losses and/or gains being 15 KT or greater), can be expected as the ACFT flies through them. The sporadic and transient nature of the terrain-induced wind disturbances results in some ACFT experiencing wind shear and/or turbulence, whilst others do not, even though the broad meteorological conditions are the same. Successive ACFT which experience wind shear and/or turbulence may also encounter a different sequence of events.

Surface winds at the APT are generally not good indicators of the wind that may be experienced during the final phase of the approach. Winds at approximately 2000ft may be a better representation of the prevailing wind conditions in the region.

Generally, mean wind speed should decrease towards lower altitudes but isolated strong gusts may be expected. Wind direction would also change with altitude due to blocking of the general wind flow by nearby hills or in the presence of low-level temperature inversion which occurs mostly in the cool season (about half of the time or more from November to April). It is possible for the magnitude of wind shear and turbulence to increase towards final approach, resulting in deteriorating rather than improving conditions prior to touchdown.

### 1.8.2.2. EASTERLY THROUGH SOUTHWESTERLY WINDS

When prevailing winds are from the East through Southwest and with a speed in excess of 15 KT, significant wind shear and moderate turbulence can be expected on the approaches to or on departure from the RWYs. Larger magnitude wind shear and turbulence is possible when the wind speed is in excess of 30 KT. Because of the proximity to the hills of Lantau, wind shear and turbulence are more significant over the South RWY (RWY 07R/25L).

Low-level wind shear and turbulence are expected to be more significant when the wind is from the direction 130-210°, especially in the presence of low-level temperature inversion or when the wind speed is more than 30 KT.

### 1.8.2.3. NORTHWESTERLY THROUGH NORTHEASTERLY WINDS

Significant low-level wind shear and moderate turbulence can be expected when wind speeds exceed 20 KT, especially for approaches to RWY 25 and along the departure and missed approach corridors from RWY 07 as these approach/departure corridors are closer to the hills to the North as compared with approaches to RWY 07 or departure from RWY 25. Larger magnitude wind shear and turbulence over these approach and departure corridors is possible if the wind speed exceeds 30KT, especially around the last 15NM from the THR when on final approach to RWY 25.

### 1.8.2.4. LAND-SEA BREEZE

Land-sea breeze is not a strong wind phenomenon but it can create a complex wind field in the vicinity of the APT and it can cause a significant change in wind direction within a distance of a few kilometers along the approach/departure areas. If the sea breeze opposes the prevailing wind flow, it can result in significant wind shear even in fine weather conditions.

### 1.8.2.5. LOW-LEVEL JET IN COOL SEASON

During a surge of the winter monsoon, strong low-level jets of northeasterly wind with speeds up to 50 KT occasionally affect the APT. Under such circumstances significant wind shear along the departure corridors of RWY 07 can be expected.

VHHH/HKG  
HONG KONG INTL

JEPPESEN  
28 MAR 25 10-1P5

HONG KONG, PR OF CHINA  
AIRPORT BRIEFING

## 1. GENERAL

### 1.8.2.6. LOW-LEVEL WIND EFFECTS

Pilots should be aware of the possibility of building-induced mechanical turbulence and wind shear effects when landing on:

- RWY 25L in strong northwesterly/northerly winds;
- RWY 25C in strong southwesterly/southerly/southeasterly winds;
- RWY 25C in northwesterly/northerly/northeasterly winds with a background speed of about 15 KT or more;
- RWY 25R in strong southerly winds; and
- RWY 07R TDZ in northwesterly/northerly winds with a background speed of about 15 KT or more.

Pilots should be aware of the possibility of building-induced mechanical turbulence and wind shear effects when taking off beyond the mid-point of RWY 07C in northwesterly/northerly/northeasterly winds with a background speed of about 15 KT or more.

### 1.8.3. WIND SHEAR AND TURBULENCE WARNING SYSTEM (WTWS)

#### 1.8.3.1. MICROBURST/WIND SHEAR ALERTS

The Microburst or Wind Shear Alert passed by ATC includes the type of alert (i.e. microburst or wind shear), the magnitude of the RWY-orientated wind speed difference and the location (final approach, departure or RWY area as appropriate).

When more than one occurrence of wind shear is detected for a particular RWY corridor, WTWS provides a consolidated Microburst or Wind Shear Alert for that particular RWY corridor based on a priority system which takes into consideration the severity of the alerts and the confidence level of the different data sources which generate the alerts.

E.g., if a microburst with an intensity of minus 30 KT and a wind shear with an intensity of plus 15 KT are detected, only a Microburst Alert will be issued.

Gain and loss events can co-exist within the same RWY corridor, particularly for terrain-induced wind shear. The WTWS is designed to assign a higher priority to a Wind Shear Alert of wind loss than a Wind Shear Alert of wind gain. If the former is issued, pilots are reminded that they may still encounter wind gain events.

#### 1.8.3.2. TURBULENCE ALERTS

The Turbulence Alert passed by ATC includes the intensity and type of alert (i.e. moderate or severe turbulence), and the location (final approach, departure or RWY area as appropriate).

#### 1.8.3.3. MICROBURST/WIND SHEAR ALERT COMBINED WITH TURBULENCE ALERT

When a "Microburst Alert" or a "Wind Shear Alert" is given for a particular RWY and turbulence is also detected for that particular RWY, a "Turbulence Alert" will be passed by ATC together with the "Microburst Alert" or "Wind Shear Alert".

#### 1.8.4. LIGHTNING WARNING SYSTEM

When the system predicts or detects a lightning strike on the APT platform, APT authority will issue a Red Lightning Warning. When airlines and handling agents receive a Red Lightning Warning, they should advise inbound flights of the warning.

If the period of the Red Lightning Warning is forecast to be prolonged, a message will be included on the ATIS broadcast advising of delays to parking and/or push-back.

Due to ground crew operations being suspended, the wheels will not be chocked. APU should remain in operation. If APU is inoperative, pilot shall keep one starboard engine running. ACFT unable to comply with this procedure shall notify Ground Movement Control on initial contact.

Ground crews will not commence a push-back when a Red Lightning Warning is in force.

1. GENERAL

1.8.5. LOW LEVEL TCAS ALERTS WITH HONG KONG CONTROL ZONE

IFR flights sometimes experience TCAS alerts, these may be caused by transponder-equipped VFR or Special VFR flights operating on low-level routes in the vicinity of APT.

Even though separation is provided, ATC will, under such circumstances, issue traffic information to the ACFT concerned whenever practicable so that pilots will be aware of the possible TCAS alerts.

1.8.6. ILS COVERAGE

Pilots are warned that during ILS CAT I operations RWY 07R and RWY 25L GP signals may be liable to interference from ACFT taxiing in the vicinity of the GP aerial. Pilots should therefore closely monitor their ILS approach profile and rate of descent.

Due to terrain and obstacles some of the ILS LOC and GP signals at HONG KONG INTL APT do not have the standard ICAO protected areas. Pilots shall refer to flight procedure charts for service volume restrictions of LOC and GP. Using ILS signals outside of the coverage areas stated on flight procedure charts may lead to false capture or reverse sense indications.

Insert Paragraph:

1.8.7. RUN-UP TESTS

- Engine run-ups are subject to the following conditions:
- An engine ground run is defined as any engine start-up not associated with a planned ACFT departure.
  - Engine ground runs at ground idle power of not more than two engines at a time and for a duration not exceeding 10 minutes may be carried out on the Passenger apron or Cargo apron.
  - Engine runs above ground idle power shall be carried out in the run-up facility and engine ground runs at idle power for a duration in excess of 10 minutes shall only be carried out in approved locations.
  - All engine ground runs must be fully supervised by ground staff.
  - Maintenance or test running of jet engines not mounted on an ACFT is prohibited unless performed in a test cell of adequate design.

Engine Ground Run Procedures

Initial request for a ground engine run should be made to the APT Authority Apron Control Center (Tel. No.: 2910 1112). The airline, ACFT maintenance agent engineer or mechanic in charge of the engine test is responsible for ensuring that all safety precautions against injury to persons or damage to properties, ACFT, vehicles and equipment in the vicinity are adopted.

When ready to conduct the engine run, the pilot or authorized engineer shall obtain start-up clearance from Apron Control on 121.775 and a listening watch shall be maintained on the frequency throughout the engine run. The ACFT anti-collision beacons must be activated for the entire duration of the ground engine run and Apron Control should be advised on its completion.

The ground crew in charge must maintain communication with cockpit personnel and be able to stop the engine run immediately if directed.

VHHH/HKG

JEPPesen

HONG KONG, PR OF CHINA

HONG KONG INTL

22 NOV 24

10-1P7

Eff 28 Nov

AIRPORT BRIEFING

**2. ARRIVAL****2.1. CAT II/III OPERATIONS**

RWYs 07C, 07 R and 25L approved for CAT II, RWY 07L and 25C for CAT II/III operations, special aircrew and ACFT certification required.

**2.2. RWY OPERATIONS****2.2.1. RWY UTILIZATION**

Vacate RWY as quickly as practicable.

To facilitate minimum RWY occupancy time, each RWY has multiple rapid exit TWYs. Vacate via the first available rapid exit TWY commensurate with operational conditions, or as instructed.

ACFT vacating the RWY should not stop on the exit TWY until the entire ACFT has passed the RWY holding point.

**2.2.2. REDUCED RWY SEPARATION MINIMUMS (RRSM)**

RRSM may be applied between a departing ACFT and a succeeding landing ACFT or between two successive landing ACFT on the same RWY provided the following conditions exist:

- visibility of at least 5km;
- ceiling in the departure/missed approach area 3000' or more;
- during daylight hours from 30 minutes after local sunrise to 30 minutes before local sunset;
- the second ACFT able to see the first ACFT clearly and continuously until the first is clear of the RWY;
- no unfavorable surface wind conditions including significant tailwind/turbulence or wind shear, and/or braking action not adversely affected by water or other contaminants, i.e. RRSM will be suspended whenever RWY is wet or there is pilot report of poor braking action.

When RRSM is applied, the successive landing ACFT may be given clearance to land before the first ACFT has cleared the RWY-in-use after landing or crossed the RWY end on departure provided there is reasonable assurance that the following separation distances will exist when the landing ACFT crosses the THR:

**RWY 07L/25R**

- Landing following departure:

The departing ACFT is/will be airborne and has passed a point at least 2400m from THR (ABEAM TWY C8 for RWY 07L or TWY C5 for RWY 25R).

- Landing following landing:

The preceding ACFT has landed and has passed a point at least 2400m from THR (ABEAM TWY C8 for RWY 07L or TWY C5 for RWY 25R), is in motion and will vacate the RWY without backtracking.

**RWY 07C/25C**

- Landing following departure:

The departing ACFT is/will be airborne and has passed a point at least 2400m from THR (ABEAM TWY F6/A8 for RWY 07C or TWY F3 for RWY 25C).

- Landing following landing:

The preceding ACFT has landed and has passed a point at least 2400m from THR (ABEAM TWY F6/A8 for RWY 07C or TWY F3 for RWY 25C), is in motion and will vacate the RWY without backtracking.



VHHH/HKG

HONG KONG INTL

JEPPESEN

22 NOV 24

10-1P8

HONG KONG, PR OF CHINA

Eff 28 Nov

AIRPORT BRIEFING

## 2. ARRIVAL

### RWY 07R/25L

- Landing following departure:

The departing ACFT is/will be airborne and has passed a point at least 2900m from THR (ABEAM TWY K6 for RWY 07R or TWY K2 for RWY 25L).

- Landing following landing:

The preceding ACFT has landed and has passed a point at least 2900m from THR (ABEAM TWY K6 for RWY 07R or TWY K2 for RWY 25L), is in motion and will vacate the RWY without backtracking.

ATC will provide warning to the second ACFT when issuing the landing clearance in line with ICAO standard phraseology, e.g:

- (Callsign....), preceding B737 landing about to vacate the RWY, surface wind 090 degrees/11 KT, cleared to land.
- (Callsign....), departing A320 ahead about to rotate, surface wind 230 degrees/6 KT, cleared to land.

Pilots must notify ATC in advance if they anticipate not being able to comply with any of the above requirements.

## 2.3. OTHER INFORMATION

### 2.3.1. DESCENT RATE

For Terminal Transition Routes, RNAV and contingency STARs, a minimum descent rate of 500' per minute is assumed, if unable inform ATC.

### 2.3.2. NOTIFICATION OF ARRIVAL DELAY AND DIVERSION PLANNING

ATC will issue a NOTAM to advise operators of extent of holding delays when expected average delay is in excess of 20 minutes in the terminal area.

A delay notification message will be included in the Arrival ATIS when the arrival delay is expected to be 30 minutes or more, e.g. "Expect 30 minutes holding due to traffic/extensive frontal weather conditions in the terminal area".

ATC will supplement this information as required on first contact on radiotelephony should there be a possibility of further delay, e.g. high rate of unsuccessful approaches, forecast weather deteriorations etc. to assist pilots to determine if they have sufficient holding fuel to continue or if a diversion is imminent. ATC will update flights that continue inbound with further revisions to their onward clearance times as traffic situation develops.

Flights that are diverting to VHHH may be subjected to ATFM restrictions imposed at FIR entry points in addition to the prevalent holding requirements.

Unless informed by the pilots, ATC will consider flights that continue inbound to VHHH have the required holding fuel for the notified delay and will provide further updates to onward clearance times as needed.

In case of delay caused by extensive inclement weather conditions, operators should take into account that other APTs in the Pearl River Delta region would likely be affected by the same weather system and the possibility of using these APTs as alternates could be severely reduced. Operators should consider nominating APTs outside the region as a suitable alternate APT under such circumstances.

ATC will only accept diversions on emergency basis when inclement weather conditions have already caused prolonged traffic holding and/or extensive ground delays at VHHH. A NOTAM to this effect will be issued to warn operators when such restrictions apply.

VHHH/HKG  
HONG KONG INTL

22 NOV 24

JEPPESEN  
10-1P9

Eff 28 Nov

HONG KONG, PR OF CHINA  
AIRPORT BRIEFING

### 3. DEPARTURE

#### 3.1. APT COLLABORATIVE DECISION-MAKING (A-CDM)

##### 3.1.1. INTRODUCTION

Target Off Block Time (TOBT) is the most important time in the A-CDM turn-around process and this time is essential for calculation of ATC departure release and Target Start-up Approval Time (TSAT).

TOBT submitted to A-CDM system reflects the progress of the turnaround process. Estimated Off Block Time (EOBT) in flight plan filed to ATC shall be revised to maintain overall system integrity when EOBT deviates from TOBT significantly.

The latest version of the A-CDM Operations guidelines is available for download from <https://extranet.hongkongairport.com/> (click "Procedure Manual" icon, followed by "A-CDM Operations Guidelines").

##### 3.1.2. VALIDITY OF TOBT AND TSAT

TOBT has a tolerance of  $\pm 5$  minutes. It is the responsibility of the Airline Operators/Ground Handlers (AO/GH) to assess situation and update TOBT.

Departure flights will not be considered ready if submitted TOBT differs from Actual Ready Time (ARDT) for more than 5 minutes.

ATC will advise flight crew to update TOBT if invalid TOBT is noted. Frequency change and/or start-up clearances would be withheld until a proper TOBT update is observed.

Flight crew shall update TOBT through the AO/GH under normal circumstances. However, flight crew shall report to ATC if they encounter difficulties in updating TOBT through published procedures.

ACFT can expect to start up and push back within 10 minutes of issued TSAT, as displayed in A-CDM system (issued TSAT  $\pm 10$  minutes). Actual start-up and push-back time may fall outside this TSAT window because of ATC operational conditions.

##### 3.1.3. REQUIREMENTS TO SUBMIT DELAY (DLA) MESSAGES OR RE-FILE FLIGHT PLAN

If TOBT is earlier than EOBT of filed flight plan by 30 minutes or more, the AO/GH is required to inform Aeronautical Information Management Center (AIMC) the updated EOBT by telephone (Tel: +852 2910 6174), so that a Cancellation (CNL) message can be sent by AIMC. The AO/GH shall then re-file a flight plan with an updated EOBT.

If TOBT is later than EOBT of filed flight plan by 15 minutes or more, the AO/GH is required to inform AIMC the updated EOBT by telephone, so that a Delay (DLA) message can be sent by AIMC.

The requirements stated above are exempted when a flight is regulated by Air Traffic Flow Management (ATFM) measures (flow control), i.e. a Calculated Take Off Time (CTOT) has been issued. In that case a new flight plan that aims to revise EOBT should NOT be filed as it might result in a further delayed CTOT.

#### 3.2. START-UP AND PUSH-BACK PROCEDURES

##### 3.2.1. START-UP PROCEDURES

All ACFT other than helicopters and locally light ACFT shall obtain an ATC clearance prior to engine start. Pilots are to inform HONG KONG Ground/Delivery, as appropriate, of callsign, parking stand number/location, identifier of the latest ATIS received unless it has been included in the Request for Departure Clearance Downlink (RCD) message via data link, proposed flight level if it is different from the filed flight plan and when applicable, special requirements (e.g. request for another departure RWY or inability to comply with SID climb profile).

Radius-to-Fix SIDs BEKOL 1X/1Z, DALOL 1X/1Z, LEKEN 1X/1Z or PECAN 3X/2Z) are issued as default H24 from RWY 07L/R.

VHHH/HKG

JEPPesen

HONG KONG, PR OF CHINA

HONG KONG INTL

22 NOV 24

10-1P10

Eff 28 Nov

AIRPORT BRIEFING

### 3. DEPARTURE

RWY 07C departures can expect to be assigned SIDs with 慣?designator (ADLAD1T, LARIT 1T, DUMEP 1T, XEMEK 1T or SOSLU 1T) during three-RWY operations and Radius-to-Fix SIDs BEKOL 1Y, DALOL 1Y, LEKEN 1Y or PECAN 1Y during noise mitigating period (1500-2300 UTC).

If unable to fly Radius-to-Fix SIDs, make voice request to HONG KONG Delivery for non-Radius-to-Fix SID. When using two-way Pre-Departure Clearance (PDC) data-link service, make such voice request prior sending RCD message.

A two-way PDC data link service is available to approved operators. Pilots should send a RCD to ATC not more than 20 minutes prior to EOBT. If the Departure Clearance Uplink (CLD) message is not received within 5 minutes or there is any problem with data link exchange, pilot shall inform HONG KONG Delivery.

Pilots not participating in the PDC service shall contact HONG KONG Delivery 5 minutes prior to start to put their ATC clearance on request. Upon receipt of the ATC clearance, the pilot shall read back the following information:

- Callsign,
- Destination,
- Route,
- SID,
- Transponder code.

Pilots shall comply with instructions issued by HONG KONG Delivery regarding when to contact the relevant HONG KONG Ground frequency.

Once an ATC clearance has been received, unless there is a specific time restriction included in the clearance, any delay in being ready to push-back, start engines or taxi may result in the clearance being cancelled.

#### 3.2.2. PUSH-BACK PROCEDURES

ACFT should not commence start-up, push-back, or any other maneuver on the apron, unless they have obtained approval from HONG KONG Ground.

Prior to requesting for push-back or taxi from a parking stand, pilots of ACFT equipped with a "weight-on-wheel" switch must ensure the transponder is operating (on "AUTO" or "XPNDR", and not "STDBY" or "OFF") and the assigned Mode A code is selected. ACFT with Mode S transponder capable of reporting ACFT Identification should have its identification in the ICAO flight plan format entered via FMS or Control Panel.

The majority of parking stands have two standard push-back procedures, push-back BLUE and push-back RED. The normal push-back procedure is to the taxi-lane ABEAM the adjacent parking stand, but where this would result in the ACFT entering a critical area, the push-back is extended to a tug stop point clear of the critical area. Stands N7, N24, N30, N60, N142, N143, S2, S25, S31, S43, S102 thru S104, S108, S110 and W65 have a push-back/tow-forward procedure, push-back GREEN.

Under certain traffic conditions it may be necessary for HONG KONG Ground to issue non-standard push-back instructions to expedite to flow of traffic. Pilots will be issued a "non-standard push-back" to a defined location and direction.

Pilots shall ensure that the push-back colour code or non-standard push-back instructions issued by HONG KONG Ground are accurately relayed to their ground crew before push-back or engine start commences.

There is a restriction to the starting of engines for ACFT in parking stands S103, S108 and W123. If ACFT in these stands are required to push-back through 180°, only one engine shall be started during the push-back, other engines shall only be started when the push-back maneuver has been completed.

When known conditions exist which necessitate that engine start-up is carried out in the parking stand prior to the commencement of push-back, or greater than idle engine thrust will be required during engine start (e.g. cross-bleed start procedure), the pilot shall advise HONG KONG Ground of the fact when engine start or push-back clearance is requested.

3. DEPARTURE

Whilst push-back procedure is being conducted, it is essential for safety reasons that communication contact is maintained between pilot and ground engineer in charge. ATC clearance will not normally be issued to ACFT whilst being pushed back, unless the pilot so requests.

To avoid delay to other traffic using the apron, ACFT should be ready to taxi as soon as the push-back maneuver and engine start procedure are completed. The standard push-back for stands N68 and N70 is into TWY B. Therefore to avoid delays to other traffic, it is essential that the ACFT should be ready to taxi as soon as the push-back maneuver is complete. If ACFT are unable to comply with this procedure, pilots shall immediately inform HONG KONG Ground in order that alternative taxi instructions may be issued to other traffic.

Pilots are reminded that they should always use minimum power when starting engines or maneuvering within the apron area. It is especially important when commencing to taxi that break-away thrust is kept to an absolute minimum and then reduced to idle thrust as soon as practicable.

3.3. RWY OPERATIONS

3.3.1. RWY UTILIZATION

When instructed to enter the RWY, pilots should commence the maneuver without delay.

Pilots should commence take-off roll as soon as take-off clearance is issued by ATC.

To enable efficient handling of departures, all RWYs have a pair of TWYs at the beginning of the RWY. For application of wake turbulence longitudinal separation, ATC considers ACFT using these two TWYs as departing from a similar position.

| RWY | Pair of TWYs           |
|-----|------------------------|
| 07L | C1 and C2              |
| 25R | C11 and C12            |
| 07C | A1 and A2; F1 and F2   |
| 25C | A11 and A12; F7 and F8 |
| 07R | J1 and J2              |
| 25L | J10 and J11            |

To provide an expeditious departure sequence, ATC may request a flight to depart from an intersection TWY with a reduced RWY length. In this case and when applicable, the intermediate (intersection) departure wake turbulence longitudinal separation shall be applied.

If pilot is unable to comply, he must inform ATC prior to entering RWY.

3.4. OTHER INFORMATION

3.4.1. GENERAL

Due to the proximity of the FIR boundary to the West, pilots departing RWY 25C or RWY 25R are advised to maintain a careful cross-check of ACFT position after passing HH421 and HH422. In the event of any weather avoidance maneuver, permission must be obtained from ATC prior to making any turn away from the prescribed departure track.

3.4.2. CLIMB RATE

For Terminal Transition Routes, RNAV and contingency SIDs, a minimum climb rate of 500' per minute is assumed, if unable inform ATC.

VHHH/HKG  
HONG KONG INTL

22 NOV 24

JEPPESEN  
10-1P12

HONG KONG, PR OF CHINA  
Eff 28 Nov  
AIRPORT BRIEFING

### 3. DEPARTURE

#### 3.4.3. TERRAIN CLEARANCE FOR ARRIVING AND DEPARTING ACFT

##### 3.4.3.1. ADHERENCE TO SID AND IAP/MAP

In general, ATC can only provide limited assistance to pilots whilst ACFT is below Minimum Sector Altitude (MSA).

To ensure ACFT maintain clearance from terrain it is essential that pilots ensure correct SID for correct departure RWY has been programmed prior to departure.

Once airborne, pilots are further reminded to remain on SID track and follow appropriate waypoint until passing MSA, unless otherwise instructed by ATC.

Likewise, pilots should ensure correct IAP for correct arrival RWY has been programmed prior to commencing approach.

In the event a missed approach is initiated, it is equally essential for pilots to closely follow published MAP until passing MSA, unless otherwise instructed by ATC.

##### 3.4.3.2. ATC INTERVENTION

The Hong Kong Air Traffic Management System (ATMS) is equipped with an Approach/Departure Path Monitor (APM/DPM), which provides ATC with an audio and visual warning when an arrival or departure, as appropriate, deviates off the defined final approach path or SID path.

In the event of receiving an APM/DPM alarm, ATC will provide pilot with a terrain alert, for example:

“(Call sign) TERRAIN ALERT, CLIMB IMMEDIATELY TO (altitude)”;

“(Call sign) LOW ALTITUDE WARNING, CHECK YOUR ALTITUDE IMMEDIATELY”.

Due to proximity of terrain, ATC vectoring is only available at or above the ATC Surveillance Minimum Altitude (also known as Minimum Vectoring Altitude).

Relevant information has been published on 10-1R chart.

Should a pilot inadvertently deviate from assigned SID or IAP/MAP, they can expect the following warning from ATC:

- When below MSA:

“(Call sign) TERRAIN ALERT, CLIMB IMMEDIATELY TO (altitude)”.

- When above MSA:

“(Call sign) TURN (left or right) HEADING (heading)”.

##### 3.4.4. DEPARTURE SPEED REQUIREMENT

To comply with the speed requirement, crossing PORPA, ROVER, HH412, HH421, PRAWN or POVEG at MIM 205 KT, it is recommended that the NADP 2 (see also 10-4) or the manufacturer抯 recommended procedure be used.

Pilots shall inform ATC prior to entering the RWY if they will not be able to comply with the departure speed requirement due to ACFT performance limitations or other factors for safety consideration.

##### 3.4.5. READBACK OF SID PRIOR TO DEPARTURE

Pilots departing from RWY 07C should note the existence of alternative SID procedures with either LEFT or RIGHT turns after departure for use with difference RWY operating modes.

In particular during independent parallel departure operations of RWY 07C and RWY 07R, which may be conducted in full IMC conditions, it is imperative that the correct SID is selected and entered into the FMS to ensure separation with simultaneous departure on the adjacent RWY.

To mitigate against incorrect SID selection when independent parallel departure operations are in progress, flight departing from RWY 07C will be instructed by HONG KONG Ground to report assigned SID to HONG KONG Tower on first contact. Pilots should verify that the correct SID has been entered and that the expected turn direction is valid.

3. DEPARTURE

3.4.6. CLIMB REQUIREMENT

Hong Kong SID and STAR procedures are designed in accordance with the ICAO guidance for Continuous Climb Operations (CCO) and Continuous Descent Operations (CDO).

Level requirements/restrictions are stipulated at key waypoints to ensure vertical separation is strategically achieved between arrivals and departures and adjacent FIR airspace.

The table below lists, the most critical waypoints for achievement of strategic separation.

| ADLAD Departures                  |                                                                                                           |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------|
| RWY 07C                           | Cross BEKOL at or above 4800m (FL157).                                                                    |
| BEKOL Departures                  |                                                                                                           |
| RWY 07R/07C/07L                   | Cross BEKOL at or above 4 800 m (FL157).                                                                  |
| RWY 25L                           | Cross HH481 at or above 7000?<br>Cross HH482 at or above FL110.<br>Cross BEKOL at or above 4800m (FL157). |
| RWY 25C/25R                       | Cross HH485 at or above FL130.<br>Cross BEKOL at or above 4800m (FL157).                                  |
| DALOL and LEKEN Departures        |                                                                                                           |
| RWY 07R/07C/07L                   | Cross VEDVO at or above FL110.<br>Cross SEGPO at or above FL140.                                          |
| RWY 25L                           | Cross HH471 at or above 9000?<br>Cross SUDVA at or above FL140.                                           |
| RWY 25C/25R                       | Cross SUPAD at or above FL150.<br>Cross HH477 at or above FL160.                                          |
| DUMEP, LARIT and XEMEK Departures |                                                                                                           |
| RWY 07C                           | Cross VEMSO at or above 9000?<br>Cross SAMED at or above FL130.<br>Cross LUBMO at or above FL160.         |
| PECAN Departures                  |                                                                                                           |
| RWY 07R/07C/07L                   | Cross VEDVO at or above FL110.<br>Cross SEGPO at or above FL140.                                          |
| RWY 25L                           | Cross HH471 at or above 9000?<br>Cross HH477 and HH478 at FL140.                                          |
| RWY 25C/25R                       | Cross SUGAP at or above FL140.                                                                            |
| SOSLU Departures                  |                                                                                                           |
| RWY 07C                           | Cross VEMSO at or above 9000?<br>Cross SAMED at or above FL130.<br>Cross SEGPO at or above FL140.         |

Upon SID issuance, pilots of departing flights shall review their ACFT 性能 capability to achieve the published climb requirements and inform HONG KONG Delivery prior to start-up if unable to comply. Pilots should advise the first requirement which cannot be complied with and what altitude/level is achievable at that way-point so that alternative procedures/actions can be coordinated.

