

OMDB/DXB

DUBAI INTL

JEPPesen

25 OCT 24

10-1P

Eff 31 Oct

DUBAI, UAE

AIRPORT BRIEFING

1. GENERAL

1.1. ATIS

D-ATIS Arrival 126.275
D-ATIS Departure 131.7

1.2. NOISE ABATEMENT PROCEDURES

Except for passenger operations, ACFT not in possession of noise certification in accordance with Annex 16 to the ICAO and/or ACFT whose noise certification does not conform to the minimum standards set out in Annex 16, Chapter 3, Part 2, Volume 1 are not permitted to operate to/from Dubai APT.

1.3. LOW VISIBILITY PROCEDURES (LVP)

LVP become effective when:

- Touchdown RVR is 600m or less;
- VIS 600m or less, if instrumented RVR is not available; and/or
- Ceiling 300' or less.

Regulations require serviceable surface movement radar for operations to continue when VIS or RVR is 300m or less. Any unserviceability may result in delays in the affected areas of coverage.

During LVP, pilots are required to use the CAT II/III holding points and take-off from:

- TWY N10/TWY M14A for RWY 30R;
- TWY M4/TWY K1 for RWY 12R;
- TWY N1A/TWY M1A for RWY 12L;
- TWY K17/TWY M20 for RWY 30L.

For arriving ACFT available RWY exits will be illuminated.

Arriving ACFT shall delay reporting "RWY vacated" until the ACFT has completely passed the end of the green/amber coded TWY centerline lights.

Pilots shall follow ATC clearances in combination with selected high intensity TWY centerline lights. Pilots shall not continue taxiing if high intensity TWY centerline lights are not illuminated.

1.4. FLIGHT PROCEDURES

1.4.1. ENHANCED WAKE TURBULENCE SEPARATION (eWTS)

The ICAO unified eWTS minima RECAT system is applied within DUBAI CTA and airspace controlled by DUBAI Approach. It distinguishes seven (A to G) Wake Turbulence Groups (WTG) of ACFT based on wake generation and resistance characteristics of the ACFT depending primarily on maximum certificated take-off mass, wing characteristics and speeds.

The eWTS system includes distance-based Wake Turbulence Separation minima for ACFT being provided with an ATS surveillance service in the approach and departure phases of flight and time-based separations on departure for the take-off phase of flight.

In order to benefit from this reduction of separation minima, pilots are to fully comply with assigned speeds, particularly on final approach, and to minimize RWY occupancy time. When crews are unable to maintain any assigned speeds, they must inform ATC as soon as possible.

The implementation of the ICAO eWTS scheme does not affect pilot procedures, flight management or changes to the format for completion or filling out a flight plan. The WTC designator on the ICAO flight plan does not change. Pilots are to continue to fill in the flight plan WTC in item 9 with the ICAO ACFT CAT, H, M or L, and J for SUPER HEAVY CAT.

All ACFT operating within the DUBAI CTA must enter the appropriate ACFT type designator. The use of incorrect ACFT type designator may result in possible delays due to RDR system flight plan rejection or system allocation of an unknown ACFT type resulting in larger separation application by ATC.

OMDB/DXB
DUBAI INTL

25 OCT 24

 **JEPPesen**
10-1P1**Eff 31 Oct****DUBAI, UAE**
AIRPORT BRIEFING

1. GENERAL

For ACFT in the ICAO SUPER or HEAVY WTC, the suffix of 'SUPER' or 'HEAVY' does not change. On first transmission, the word "SUPER" or "HEAVY" shall still be included, as appropriate, immediately after the ACFT call sign in the initial radiotelephony contact between such ACFT and the ATS units.

Peak traffic periods at OMDB involving a high proportion of (Super) Heavy type ACFT often occur at times when local atmospheric conditions (e.g. quartering tailwinds) favour longer lasting wake at low levels. Pilots are therefore to use caution when quartering tailwinds of 5 KT or less exist as possible transient sporadic low level wake turbulence may persist in the RWY corridor. Pilots are to be alert to larger ACFT upwind from their approach and take-off flight paths. Should unfavourable quartering tailwinds associated with wake encounter reports be prolonged, ATC will consider a RWY direction change.

TWY V is used for helicopter operations and is parallel to RWY 12R/30L ACFT operations. Pilots are to exercise caution and be prepared to receive traffic information from ATC about departing/arriving helicopters in order to avoid reaction to possible TCAS RA and TA.

1.5. MODES OF RWY OPERATION

The parallel RWYs at Dubai International APT are spaced 1263'/385m apart and staggered. The RWY spacing restrict operations to Segregated Operations on Parallel RWYs (Mode 4).

Normal operations at Dubai International APT will be conducted as segregated RWY operations with simultaneous arrivals and departures from closely spaced parallel RWYs. Simultaneous operations will be restricted to the following weather conditions:

- Cloud base is 1500' or above;
- Visibility is 5km or greater.

Available approaches during dual RWY operations when visibility is 3000m or greater is as follows:

- RWY 12 in use:
 - RWY 12L ILS (RNP);
 - RWY 12R RNP (VISUAL) (ILS switched OFF).
- RWY 30 in use:
 - RWY 30L ILS (RNP);
 - RWY 30R RNP (ILS) (VISUAL).

Approaches to non-standard arrival RWYs (RWY 12R or RWY 30R) will be either an RNP or a Visual Approach on request with ATC. ILS RWY 30R will be issued at ATC discretion during times when arrival traffic is offloaded to RWY 30R. During single RWY operations or when the visibility reduces below 3000m, an ILS approach will be available onto the arrival RWY in use.

In order to facilitate simultaneous operations departing ACFT may be issued with departure instructions in accordance with chart (10-3J) Omnidirectional Deps. Departing ACFT shall not change frequency until advised.

Pilots shall be aware of the proximity of arriving and departing traffic particularly in the event of a missed approach or baulked landing situation.

Both arriving and departing ACFT may be issued with instructions to turn on to a heading away from the adjacent RWY at any time in order to ensure separation from conflicting ACFT. Turns have been evaluated for obstacle clearance from 800' for all RWYs. For departing traffic, this turn may initially take an ACFT away from its planned departure track. ACFT should expedite climb and comply with ATC instructions without delay.

Pilots requiring full length for departure for RWY 12R or RWY 30R shall advise ATC of the required departure point on first contact and can expect delays at peak times due to RWY dependencies.

Practice autolands may be conducted in CAT I conditions when LVP are not in effect. In these cases, no safeguarding measures will be in force. Subject to operator requirements, it is not necessary to inform ATC when carrying out a practice autoland. The operator and flight crew are considered solely responsible for these practice autolands and must recognize that changes in the ILS signal may occur without warning.

OMDB/DXB

DUBAI INTL

17 JAN 25



JEPPesen

10-1P2

Eff 23 Jan

DUBAI, UAE

AIRPORT BRIEFING

1. GENERAL

1.6. TAXI PROCEDURES

1.6.1. GENERAL

All ACFT operating on the movement area of an aerodrome shall display lights intended to attract attention to the ACFT.

Taxilanes J, J1, J2, J3, U, W, Y, Z MAX 15 KT.

ACFT are not permitted to carry out 180° turn on a TWY. In some circumstances, depending on ACFT type, TWY width and location, Airside Operations may approve such a maneuver with the assistance of a marshaller.

ACFT on TWY M and TWY N are not permitted to taxi behind ACFT holding at any RWY Holding Position (RHP). This is applicable to all ACFT types.

All TWYs are code F compliant except for taxilane Q which is code C and TWYs U1 thru U6, Y1, W1, taxilanes J4, J5, U, W, Y, and Z1 which are code E.

180° turns on RWYs not permitted for ACFT larger than A320.

Crew should not take any crossovers unless specifically instructed to by ATC (this applies for arrival and departure traffic).

For arriving traffic, taxiing onto parking stands from outer parallel TWY is permitted, only when instructed by ATC.

Flight crew shall follow the TWY centerline at all times.

No live Acft movements permitted on Apron S (engine starts and taxiing under own power are prohibited within the Apron S boundaries, towed movements only).

1.6.2. WINGTIP CLEARANCE

To ensure wingtip clearance behind, flight crew are to hold as close as possible to RHP/IHP to remain visual with RHP/IHP paint markings and stopbar lights.

Pilots to use minimum power when using any 90° link northbound from taxilane Z flight/towing crew are responsible for maintaining wingtip clearance. If in doubt crew should stop, advice ATC and await further instructions.

Minimum wingtip clearance of 24.6'/7.5m for code F operations on TWY N abeam TWY P5 (due to presence of substation South side of TWY N).

In order to ensure safe wingtip clearance, crossover TWYs are used only when authorized by ATC.

1.6.3. ACFT CODE RESTRICTIONS

Code E ACFT and code F ACFT not permitted on adjacent taxilane curves at the same time in any direction.

Code F ACFT pushed onto taxilane J South of concourse B and C must align/report on centerline before an ACFT can pass on taxilane U.

Code F ACFT cannot be on taxilane J and J1 curve at the same time as code E ACFT on taxilane U and taxilane Y curve.

Code F ACFT cannot be on taxilane J and J2 curve at the same time as code E ACFT on taxilane U and W curve.

Code F ACFT cannot be on sections of taxilane W and J2 between TWY K and taxilane Z at the same time.

Code F ACFT cannot be on sections of taxilane J1 and TWY Y between TWY K and taxilane Z at the same time.

Code F ACFT are only permitted to taxi behind when code D or smaller ACFT is at the RHP at TWY K1, K2, K3, K4 and K5.

1.6.4. MULTIPLE APRON RAMP SYSTEM (MARS) STANDS

Stand C51L/C51/C51R is a Multiple Apron Ramp System (MARS) stand. The following must be noted as there is a potential for stand signage confusion.

- Stand lead-in line for C51L and C51 starts from TWY K and taxilane Z. Taxiing westbound, C51 lead-in line is beyond the C51L lead-in line.
- Stand lead-in line for C51R originates from taxilane Z1.

1.6.5. JET BLAST

Due to jet blast concerns, flight crew must use minimum power when taxiing in vicinity of apron areas.

TWY J4 link between taxilane Z and TWY K operational. Northbound powered ACFT movements are not permitted on this link turning from taxilane Z due to jet blast concerns. Pilots to follow ATC instructions.

OMDB/DXB**DUBAI INTL****JEPPesen**

17 JAN 25

10-1P3

Eff 23 Jan

DUBAI, UAE**AIRPORT BRIEFING**

1. GENERAL

1.6.6. TURN RESTRICTIONS

Heading South - Right turn onto taxilane Z not available from TWYs K10 and Y.

Heading East - Left turn onto TWY R not available from TWY N.

Heading South - Right turn onto TWY N not available from TWY R.

Heading North - Right turn onto TWY R not available from TWY R1.

Heading West - Right turn onto taxilane S not available from TWY M.

Heading West - Left turn onto TWY M not available from taxilane S.

Heading South - Left turn onto TWY N not available from TWY P8.

Heading South - Left/Right turns onto taxilane Z not available from TWY W.

Heading West - Left turns onto TWY K4 not available from TWY Z11.

Heading South - Left turn onto TWY K not available from TWY K18.

Heading North - Left turn onto TWY K10 not available from taxilane Z.

1.6.7. TAXI GUIDANCE SYSTEM

ATC will use the phraseology "Follow the greens..." when issuing a clearance to pilots to taxi along the directional guidance provided by the green TWY centerline lights. The controller may use the expression "Follow the greens" in a taxi clearance instead of detailing the route to be followed. The instruction however will always include a clearance limit, e.g. "EMIRATES 12 TAXI TO HOLDING POINT M13A RWY 30R FOLLOW GREENS".

1.6.8. REDUCED ENGINE/SINGLE ENGINE TAXI

Reduced Engine/Single-engine for Code C ACFT taxi-in/out allowed except on Apron Q.

If RWY crossing is required, crew are expected to be able to expedite the crossing.

Pilots must consider the additional thrust required for manoeuvring and the potential for asymmetrical thrust, special attention must be given to ensuring adequate braking capability and maintaining control during turns and while taxiing in adverse weather conditions.

1.7. PARKING INFORMATION**1.7.1. GENERAL**

In the event that ACFT comes to a complete halt whilst entering a parking stand or taking a turn towards an adjoining TWY, aircrew must hold position and contact ATC for assistance to ensure the area behind is free from effects of jet blast.

ACFT stands A1, A10, B15 thru B27 (including B18L, B18R, B21L, B21R, B26L and B26R), C25 thru C47, C49 thru C51 (including C51L and C51R), C53 thru C64 (excluding C53L, C53R, C54L, C54R, C55L and C55R), D1 thru D10, F5, F17 and G1 thru G21 have less than 12'/3.75m clearance from the ACFT tail to the apron safety line at the rear of stand.

1.8. WIND SHEAR WARNINGS**1.8.1. WIND SHEAR REPORTS PASSED BY ATC**

On receipt of any report of wind shear, ATC will:

- Immediately relay the report to other ACFT potentially affected;
- Pass the full report to the MET Office; and
- Pass the information to other ATC units that may be affected.

Wind shear reports that are relayed by ATC to other ACFT will contain as many of the following details as possible:

- ACFT type that reported the wind shear;
- Description of event (e.g. light/moderate/severe, or positive/negative);
- Height/altitude wind shear encountered;
- Phase of flight;
- RWY;
- Time of encounter;
- MET/operational information as received from the reporting pilot.

1. GENERAL

Examples of the phraseology used by ATC to pass on wind shear reports:

- "CAUTION WIND SHEAR. AT (TIME) (ACFT TYPE) REPORTED STRONG WIND AT (HEIGHT/ALTITUDE) FEET ON APPROACH RWY (DESIGNATOR). MAX THRUST REQUIRED."
- "CAUTION WIND SHEAR. AT (TIME) (ACFT TYPE) REPORTED AFTER DEPARTING RWY (DESIGNATOR) AT (HEIGHT/ALTITUDE) FEET AIRSPEED LOSS OF (NUMBER) KNOTS, STRONG (LEFT/RIGHT) DRIFT."

1.8.2. WIND SHEAR WARNINGS ON ATIS

Wind shear warning issued by the National Centre of Meteorology (NCM) or received from an ACFT will be broadcast on both the departure and arrival ATIS. Regardless of any relevant information being broadcast on the ATIS, during final approach and prior to take-off, ATC will transmit to ACFT without delay:

- The latest information on wind shear in the approach, final approach, take-off and climb out area;
- Any significant variations in the current surface wind, expressed in terms of minimum and maximum values.

1.8.3. PILOT REPORTS OF WIND SHEAR

For the benefit of subsequent ACFT and for validation and further enhancement of the low-level wind shear warning, pilots are requested to inform ATC if they experience any wind shear on arrival or departure, irrespective of whether a warning has been given. ATC will pass reports to following ACFT and the MET Office.

ATC will continue to transmit information on wind shear until it is confirmed, either by three (3) consecutive subsequent ACFT reports or by advice from the MET Office that conditions are no longer a hazard to the operations.

1.8.4. LOW LEVEL WIND SHEAR

Caution, transient and sporadic low level wind shear is possible between 1800-0300UTC on the approach and climb out due to land and sea breeze interaction resulting in possible airspeed loss/gain of 10 KT or more.

1.8.5. 1000' AND BELOW WINDS

If a wind shear warning has been issued, ACFT may be requested by ATC to state the 1000' and below winds when able.

ATC will then subsequently pass this information onto following ACFT whilst the wind shear warning is in force.

1.9. OTHER INFORMATION

Birds.

RWYs 12L and 12R right-hand circuit.

2. ARRIVAL

2.1. SPEED RESTRICTIONS

ATC has zero tolerance with regards to the compliance with speed control instructions. Pilots shall adhere to the speed approved or assigned by ATC and shall request ATC approval before making any changes thereto. When an immediate speed adjustment is required for the safe operation of the flight, ATC shall be notified as soon as possible.

Pilots unable to maintain the last assigned speed during any particular phase of flight, e.g. for ACFT safety or performance reasons, shall inform ATC as soon as possible.

Pilots can expect the following speed control restrictions to be enforced by ATC:

- a) 210 - 250 KT: From CTA entry to downwind;
- b) 180 - 230 KT: From downwind to base leg;
- c) 160 - 210 KT: On base leg and closing heading to final approach;
- d) 160 - 190 KT: 10NM from touchdown;
- e) 160 KT: 4NM from touchdown.

Pilots must advise ATC if a speed adjustment is considered excessive or contrary to ACFT operating specifications.

2. ARRIVAL

2.2. CAT II/III OPERATIONS

All RWYs approved for CAT II/III operations, special aircrew and ACFT certification required.

2.3. RWY OPERATIONS

When on approach to RWY 30R, pilots shall reconfirm DME/GP information and ensure that they have correctly identified the landing RWY. Do not confuse with staggered parallel RWY 30L with THR approximately 1.5NM East of RWY 30R.

2.3.1. RWY OCCUPANCY TIME

Unless otherwise advised by ATC, expect to vacate the RWY via a Rapid Exit TWY.

ATC will advise ACFT on final approach of the expected RWY exit point. This will normally be a Rapid Exit TWY and pilots must advise ATC as soon as practicable if unable to comply.

ACFT are expected to vacate the RWY expeditiously and pilots are reminded to keep moving until the ACFT is completely clear of the RWY stop bars on exiting.

Distance (m) from DTHR to assigned Rapid Exit TWY							
RWY 12L		RWY 12R		RWY 30L		RWY 30R	
Vacate LEFT	Vacate RIGHT	Vacate LEFT	Vacate RIGHT	Vacate LEFT	Vacate RIGHT	Vacate LEFT	Vacate RIGHT
N5A 1825	M7A 1825	M16 2144	K13 2154	K9 2029	M12B 2029	M6 1775	N5 1775
N6 2143	M9 2143	M18 2745	K15 2845	K8 2390	M11 2387	M3A 2351	N3A 2356
N8 2759	M12A 2759	-	-	K6 2881	M8 2746	M3 2745	N3 2745

Notes:

1. ATC will assign a RWY exit point upon first contact with DUBAI Tower.
2. Pilots are expected to vacate the RWY at the assigned exit point.
3. Pilots must advise ATC if unable to comply for performance reasons.
4. During dual RWY 30 operations, all arrivals landing RWY 30L shall vacate LEFT unless otherwise instructed.
5. Pilots shall remain on DUBAI Tower frequency until instructed to change.

2.3.2. REDUCED RWY SEPARATION MINIMA (RRSM)

2.3.2.1. GENERAL

Dubai Intl APT applies special landing procedures over H24 period for RWYs 12L/30R and 12R/30L.

In order that ATC can plan final approach spacing accordingly, inbound arrivals shall advise DUBAI Arrivals on first contact if their airline Standard Operating Procedures prevent them from participating in these procedures.

It is essential that aircrew adhere to paragraph 2.3.1. "RWY Occupancy Time" to ensure the efficiency of operations during RRSM.

OMDB/DXB
DUBAI INTL

JEPPesen

24 NOV 23

10-1P6

Eff 30 Nov

DUBAI, UAE

AIRPORT BRIEFING

2. ARRIVAL

2.3.2.2. CONDITIONS FOR THE APPLICATION OF RRSM

RRSM may be applied H24 between:

- a departing ACFT and a succeeding landing ACFT using a single RWY; or
- two successive landing ACFT; or
- two successive departing ACFT;

provided:

- Tail wind does not exceed 5 KT, and there are no reports of wind shear.
- Met visibility shall be equal to or greater than 5km, the cloud ceiling shall not be lower than 1000?and the ATC is satisfied that the pilot of the following ACFT will be able to observe the relevant traffic clearly and continuously.
- The pilot of the following ACFT is warned.
- The RWY is dry and there is no evidence that the braking action may be adversely affected.
- The controller is able to assess separation visually or by radar-derived information.
- Wake turbulence separation minima shall be applied.
- Minimum separation continues to exist between two departing ACFT immediately after take-off of the second ACFT.

2.3.2.3. SINGLE RWY MODE PROCEDURE

When the RWY-in-use is temporarily occupied by other traffic, landing clearance may be issued to an arriving ACFT, provided that the controller has reasonable assurance that the following separation distances/criteria will be met when the landing ACFT crosses the RWY THR:

Landing following Landing

- RWY 12L/30R:

The preceding landing ACFT has landed and has vacated the RWY or has passed a point at least 8202?2500m from the THR of the RWY (abeam TWYs N7 and M10A for RWY12L, abeam the RWY exit points for TWYs N3A and M3A for RWY 30R) and is in motion and will vacate the RWY without stopping and/or backtracking.

Landing RRSM will only be applied between two successive arrivals provided both ACFT have been instructed to vacate at published Rapid Exit TWYs.

- RWY 12R/30L:

The preceding landing ACFT has landed and has passed a point at least 8202?2500m from THR of the RWY (abeam TWYs M17 and K14 for RWY 12R, abeam the RWY exit points for TWYs M11 and K8 for RWY 30L) and is in motion and will vacate the RWY without stopping and/or backtracking.

Landing RRSM will only be applied between two successive arrivals provided both ACFT have been instructed to vacate at published Rapid Exit TWYs.

Landing following Departure

- RWY 12L/30R:

The preceding departing ACFT will be airborne and has passed a point at least 8202?2500m from the THR of the RWY (abeam TWYs N7 and M10A for RWY12L, abeam the RWY exit points for TWYs N3A and M3A for RWY 30R), or if not airborne, will be at least 8202?2500m from THR of the RWY.

- RWY 12R/30L:

The preceding departing ACFT will be airborne and has passed a point at least 8202?2500m from THR of the RWY (abeam TWYs M17 and K14 for RWY 12R, abeam the RWY exit points for TWYs M11 and K8 for RWY 30L), or if not airborne, will be at least 8202?2500m from THR of the RWY.

OMDB/DXB
DUBAI INTL

JEPPESEN

24 NOV 23

10-1P7

Eff 30 Nov

DUBAI, UAE

AIRPORT BRIEFING

2. ARRIVAL

2.3.2.4. DUAL DEPENDENT RWY MODE PROCEDURE (BOTH DIRECTIONS)

The procedures described in the previous section for single RWY operations for "Landing following landing" shall be applied in the same manner on respective RWYs during dual RWY operations. The exception for dual RWY operations is when the RWY mode becomes dependent in VMC (when ACFT are departing from full RWY length 12R from TWY K1, K2, M4, M5B; or from full length RWY 30R from TWY M15, M15A, N11 or N12). Therefore the difference from single RWY operations, is in the scenario Landing following Departure. In RWY 12 direction, a preceding ACFT off RWY 12R must have passed abeam TWYs M10B and K7, prior to the landing ACFT crossing the THR of RWY 12L. In RWY 30 direction, a preceding departing ACFT off RWY 30R must have passed abeam TWYs M10A and N7, prior to the landing ACFT crossing the THR of RWY 30L.

2.3.3. VISUAL APPROACH WITH OWN SEPARATION

When visual meteorological conditions exist, visual approach may be requested by arrivals on final approach. When requesting a visual approach, the pilot must be able to report the preceding ACFT in sight and accept to maintain own separation from that ACFT.

ATC may initiate a visual approach, provided that the pilot concurs, has the preceding ACFT in sight and accepts to maintain own separation from that ACFT. Whenever deemed necessary, ATC will issue a caution of possible wake turbulence.

Pilot request or acceptance of a visual approach means the pilot can maintain visual reference to the terrain and accepts responsibility for establishing a safe landing interval behind preceding ACFT as well as responsibility for wake turbulence avoidance.

It is pilot responsibility to inform ATC if they are operating their ACFT other than in a normal manner.

2.4. TRANSPONDER OPERATION

Transponder shall remain switched on and transmit last assigned code until parked on stand.

2.5. OTHER

Pilots commencing a descent in accordance with ATC instruction shall immediately advise ATC if their rate of descent during level change will be less than 500' per minute.

Coordinated Arrival Slot Time

Due to capacity constraints from 0000-0259UTC and 1800-2200UTC, airlines and flight crews shall arrange their flights to arrive at their coordinated slot time (STA). This time should be planned using a nominal holding time of 8 minutes.

Caution: Possible signal fluctuation during ILS GP CAT I conditions for arrival ACFT due to taxiing, towing and departing ACFT. Pilots should anticipate possible GP interference and monitor ILS profile, FLT display indications and autopilot behavior during manual or coupled ILS APCH.

OMDB/DXB
DUBAI INTL

11 APR 25

JEPPesen
10-1P8

Eff 17 Apr

DUBAI, UAE
AIRPORT BRIEFING

3. DEPARTURE

3.1. SPEED RESTRICTIONS

ATC has zero tolerance with regards to the compliance with speed control instructions. Pilots shall adhere to the speed approved or assigned by ATC and shall request ATC approval before making any changes thereto. When an immediate speed adjustment is required for the safe operation of the flight, ATC shall be notified as soon as possible.

Pilots unable to maintain the last assigned speed during any particular phase of flight, e.g. for ACFT safety or performance reasons, shall inform ATC as soon as possible.

3.2. START-UP, PUSH-BACK AND TAXI PROCEDURES

3.2.1. START-UP PROCEDURES

Departing ACFT shall contact DUBAI Delivery 10 minutes prior to start-up and pass the following information:

ACFT callsign, ACFT type, parking stand, requested flight level, destination, SID (and departure speed if unable to comply with SID minimum speed restrictions) and ACFT routing via M318 to report crossing level for GABKO if below FL150.

Engine runs on stands are permitted at IDLE only and typically MAX 5 minutes only. If engine runs on stands (in IDLE power) are required for more than 5 minutes (including for cabin cooling purposes where all engines may be operated), this must be explicitly requested by the Airline Engineering.

High power engine runs are permitted at predesignated areas. Prior approval is required for both IDLE and high power engine runs. Request shall be made to Dubai Airports Aerodrome Operations. Engine runs on stand above IDLE is prohibited.

Requests shall be made at least 30 minutes prior to start-up.

ACFT will normally be expected to start-up during push-back. ACFT wishing to start engines either before or after push-back should notify ATC.

ACFT requiring a start on stand may only start 50% of their total engines on stand. The remaining engine(s) are only to be started once the push-back has been completed, ACFT is on the TWY centerline and parking brakes applied.

3.2.2. PUSH-BACK PROCEDURES

PUSH-BACK ATC INSTRUCTION AND ASSOCIATED STOP POSITIONS

STANDARD PUSH: Push abeam adjacent stand or up to one stand distance.

Example of ATC phraseology: "Push-back approved, face (direction)." No reference to "STANDARD" or a stop position will be included in ATC clearance. Ground crew will know where to stop.

SHORT PUSH: Push and pull abeam the departure stand.

Example of ATC phraseology: "Short push-back approved, face (direction)." No reference to stop position will be included in ATC clearance. Ground crew will know where to stop.

Short push is in fact a push and pull on the TWY and does not involve the traditional "S" like or dog-leg maneuver which is initiated inside the stand before entering the TWY. The "S" like maneuver inside the stand is prohibited.

LONG PUSH: Push up to two stand distance.

Example of ATC phraseology: "Long push approved, face (direction)." No reference to stop position will be included in ATC clearance. Ground crew will know where to stop.

PUSH AND PULL: Push and pull abeam the stand in front.

Example of ATC phraseology: "Push-back and pull forward approved, face (direction)." No reference to stop position will be included in ATC clearance. Ground crew will know where to stop.

Deviations to the above have been published in Dubai APTs' Airside Operating Regulation (AOR).

Where a pull forward maneuver is involved, consider starting ACFT engines only after completing the pull forward maneuver to minimize forward stress on the push-back tractor during the pull.

3. DEPARTURE

SIMULTANEOUS PUSH OF MULTIPLE ACFT IN CLOSE VICINITY

For simultaneous push from adjacent stands or alternate stands with one stand in between:

- ATC will alert the crew of all involved ACFT about the simultaneous push;
- ATC will provide a combination of different push-back instructions (Standard, Long etc.) such that there is a separation of about two (2) stands between the ACFT in the final stop positions on the TWY.

ACFT are required to switch on transponders when commencing push-back. ACFT not requiring push-back shall switch on transponders prior to commencing taxiing. If no push-back is required due to ACFT facing nose out, this must be notified to DUBAI Delivery on first contact.

Dubai National Air Travel Agency, Jet Aviation and certain operating companies with own trained drivers are the only approved agencies for executing push-backs.

Their procedures are mandatory. However, it is the pilot's responsibility, to obtain push-back approval from ATC and relay the same to their ground engineer prior to commencing push-back.

Push-back approval includes instructions to face North, East, South or West as appropriate.

PUSH-BACK RESTRICTIONS

Push-back onto taxilane J and taxilane U:

- Code F will push back onto taxilane J and code E will push back onto taxilane U. Note that taxilane U is code E compatible and taxilane J is code F compatible.
- Due to proximity of taxilane J and taxilane U (south of B stands), pilots on taxilane J and taxilane U must adhere to centerline at all times and must confirm ACFT aligned on centerline prior to reporting push-back complete.
- Due to code F push-back onto taxilane J, a code E on taxilane U in the vicinity of the pushing code F shall keep clear and hold position until the code F pilot reports to ATC that the push-back is complete on taxilane J. Follow ATC instructions at all times.
- Code E ACFT on taxilane U shall not pass code F ACFT during push-back onto taxilane J.

ACFT are permitted to push back and start up on the push or to start one engine on stand at idle power before push-back.

In the event of simultaneous push-back from adjacent stands, ground crew may ask to delay the engine start until the ground crew on the ACFT behind is clear of the forward ACFT's jet blast zone.

Under normal circumstances push-backs onto the outer TWYs are not permitted. Exceptions to this are B stands servicing A380 or WIP restrictions.

3.2.3. TAXI PROCEDURES

ACFT taxiing via TWYs K16 and K17 for departure RWY 30L shall use minimum power due to proximity of apron H.

After disconnecting, push-back tug will hold on taxilane J centerline in view of the pushed ACFT until completion of engine start. Once cleared by ATC, the tug will cross taxilane U to return to the stand on the North. Pushed ACFT to initiate taxi only after the tug has vacated taxilane J. ACFT taxiing on taxilane U to exercise caution due crossing tugs.

"HOLD SHORT" instruction expectation is when ATC issues instruction to "hold short of stand" to accommodate incoming traffic, the ACFT must stop its nose landing gear on the centerline of the adjacent stand, thus ensuring adequate clearance between the ACFT and the designated stand.

OMDB/DXB
DUBAI INTL

JEPPESEN

24 NOV 23

10-1P10

Eff 30 Nov

DUBAI, UAE

AIRPORT BRIEFING

3. DEPARTURE

3.3. RWY OPERATIONS

3.3.1. REDUCED RWY SEPARATION MINIMA (RRSM)

3.3.1.1. GENERAL

Special departing procedures may be utilized at Dubai Intl APT for RWY 12L/30R and 12R/30L.

3.3.1.2. SINGLE RWY MODE PROCEDURE

Take-off clearance may be issued to a departing ACFT, commencing its take-off roll from full length, before the preceding departure has passed the upwind end of the RWY, provided:

- **RWY 12L/30R:**

The preceding ACFT is airborne and has passed a point at least 8202?2500m from the THR of the RWY (abeam TWYs N7 and M10A for RWY12L, abeam the RWY exit points for TWYs N3A and M3A for RWY 30R), and minimum separation continues to exist, constant or increasing, between the two departing ACFT immediately after take-off of the second ACFT.

- **RWY 12R/30L:**

The preceding ACFT is airborne and has passed a point at least 8202?2500m from THR of the RWY (abeam TWYs M17 and K14 for RWY 12R, abeam the RWY exit points for TWYs M11 and K8 for RWY 30L), and minimum separation continues to exist, constant or increasing, between the two departing ACFT immediately after take-off of the second ACFT.

Due to displaced THRs, the succeeding departure may commence its take-off roll subject to the same provisions above when departing off

- RWY 12R from M4 to M7B or K1 to K4;
- RWY 30L from K17, K18 to M20, M21;
- RWY 12L from M1 to M1B or N1 to N1B;
- RWY 30R from M15 to M15A or N11 to N12.

3.3.1.3. DUAL DEPENDENT RWY MODE PROCEDURE (BOTH DIRECTIONS)

The procedures described in the previous section for single RWY operations shall be applied in the same manner on respective RWYs during dual RWY operations.

3.3.2. RWY OCCUPANCY TIME

eWTS time based wake turbulence separation will be applied.

On receipt of the line-up clearance, ACFT shall taxi into position expeditiously.

If pilots require more separation than the eWTS time-based standard, or extra time for any other reason, advise ATC early prior to entering the RWY, not when on the RWY. When informed, ATC may be able to make changes in the departure sequence, if necessary, to minimize delays to other succeeding departures.

Cockpit checks shall be complete prior to line-up.

Once ATC issues a take-off clearance, if there is any unreasonable delay in the ACFT commencing the take-off roll, ATC may cancel the take-off clearance and reposition the ACFT in the departure sequence. When cleared for take-off, ATC will expect and will have planned on seeing movement within 8 to 10 seconds of the take-off clearance being issued.

ACFT that cannot comply with these requirements are to notify ATC as soon as possible.