
(a)
Independence / true,
P(at least one input lost)
2.25
2.00
1.75
1.50
1.25
1.00
2 inputs
5 inputs
10 inputs
20 inputs
0.1
1
10
100
Common-cause dispersion α_c
(b)
True / independence,
P(both sources lost)
10
5
2
1
$\mu = 0.01$
$\mu = 0.05$
$\mu = 0.2$
$1 + 1/\alpha_c$
0.1
1
10
100
Common-cause dispersion α_c
(c)
Common-cause importance of
the group (percentage points)
10
5
0
−5
−10
all six needed
fewer than two lost
any one suffices
pairwise formula
0.1
1
10
100
Common-cause dispersion α_c