

## Stepper Motor

Control motion in small steps Multiple control lines Control can be simplified with driver chip Often provided with gearbox



## Servo

Control position
Single control wire uses special timing
Inbuilt gearbox
Hardware gives smoothest motion



## **Electric Motor**

Control speed (within limits)
Control direction with a "H-Bridge" circuit
Runs fast so need gearbox

