



MS5351M + 78M33 + BSS123. Crystal, direct TCXO, C3, headers and SMA connectors unfitted.



Sources: QRP Labs Synth Rev6 manual pp.1-5; Rev6 repair note; Ruimeng MS5351M p3.
C4 value and exact regulator maker unresolved. (doc) = documented value, not a measurement.



QRP Labs circuit; independent documentation model

Sheet: /Synthesizer Rev6/

File: Synth Rev6.kicad_sch

Title: QRP Labs synthesizer – photographed Rev6 population

Size: A4	Date: 2026-10-06
----------	------------------

Rev: Model 1

SIZE: A1	
KiCad E.D.A. 10.0.6	

Id: 2/3