
### **Water Level Sensor**



### **Hardware Overview**

The sensor has ten exposed copper traces, five of which are power traces and the remaining five are sense traces. These traces are interlaced so that there is one sense trace between every two power traces.

Normally, power and sense traces are not connected, but when immersed in water, they are bridged.




There is a Power LED on the board, which will light up when the board is powered.

#### **How Does a Water Level Sensor Work?**

The operation of the water level sensor is fairly simple.

The power and sense traces form a variable resistor (much like a potentiometer) whose resistance varies based on how much they are exposed to water.




This resistance varies inversely with the depth of immersion of the sensor in water:

- The more water the sensor is immersed in, the better the conductivity and the lower the resistance.
- The less water the sensor is immersed in, the poorer the conductivity and the higher the resistance.

The sensor generates an output voltage proportional to the resistance; by measuring this voltage, the water level can be determined.

#### **Water Level Sensor Pinout**

The water level sensor is extremely simple to use and only requires three pins to connect.



S (Signal) is an analog output pin that will be connected to one of your Arduino's analog inputs.

+ (VCC) pin provides power to the sensor. It is recommended that the sensor be powered from 3.3V to 5V. Please keep in mind that the analog output will vary depending on the voltage supplied to the sensor.

– (GND) is the ground pin.

#### Wiring a Water Level Sensor to an Arduino

Let's hook up the water level sensor to the Arduino.

To begin, connect the + (VCC) pin on the module to 5V on the Arduino and the – (GND) pin to ground.


One well-known issue with these sensors is that they have a shorter lifespan because they are constantly exposed to moisture. Moreover, constantly applying power to the sensor while immersed in water significantly accelerates the rate of corrosion.

To avoid this, it is recommended that the sensor be turned on only when taking readings.

One easy way to do this is to connect the sensor's power pin to a digital pin on an Arduino and set it to HIGH or LOW as needed. So, we'll connect the + (VCC) pin to the Arduino's digital pin #7.

Finally, connect the S (Signal) pin to the Arduino's A0 ADC pin.

The wiring is shown in the image below.



Use a digital pin to power the sensor only when taking a reading to reduce corrosion.


### **Basic Arduino Example**

After constructing the circuit, upload the following sketch to your Arduino.

```
// Sensor pins
#define sensorPower 7
#define sensorPin A0
// Value for storing water level
int val = 0;
void setup() {
       // Set D7 as an OUTPUT
       pinMode(sensorPower, OUTPUT);
       // Set to LOW so no power flows through the sensor
       digitalWrite(sensorPower, LOW);
       Serial.begin(9600);
}
void loop() {
       //get the reading from the function below and print it
       int level = readSensor();
       Serial.print("Water level: ");
       Serial.println(level);
       delay(1000);
}
//This is a function used to get the reading
int readSensor() {
       digitalWrite(sensorPower, HIGH); // Turn the sensor ON
       delay(10);
                                      // wait 10 milliseconds
       val = analogRead(sensorPin); // Read the analog value form sensor
       digitalWrite(sensorPower, LOW);// Turn the sensor OFF
```

```
return val; // send current reading }
```

After uploading the sketch, open the Serial Monitor window to view the output. When the sensor is dry, it will output a value of 0; however, as the sensor is immersed in water, the output will gradually increase.



This sensor is not intended to be fully submerged. So, when installing it, make sure that only the exposed traces on the PCB come into contact with the water.

## Code Explanation:

The sketch begins with the declaration of the Arduino pins to which the sensor's + (VCC) and S (signal) pins are connected.

```
#define sensorPower 7
#define sensorPin A0
```

Following that, we define a variable val to store the current water level.

```
int val = 0;
```

In the Setup section, we first configure the sensor's power connection to behave as an output, then we set it low to keep the sensor off initially. We establish serial communication as well.

```
pinMode(sensorPower, OUTPUT);
digitalWrite(sensorPower, LOW);
Serial.begin(9600);
```

In the loop section, we call the readSensor() custom function once every one second and print the result.

```
Serial.print("Water level: ");
Serial.println(readSensor());
delay(1000);
```

The readSensor() custom function simply turns on the sensor, waits 10 milliseconds, reads the analog value from the sensor, turns it off, and returns the analog value.

```
int readSensor() {
         digitalWrite(sensorPower, HIGH);
         delay(10);
        val = analogRead(sensorPin);
         digitalWrite(sensorPower, LOW);
        return val;
}
```

### Finding the threshold values


To estimate the water level, record the values of your sensor output when the sensor is completely dry, partially immersed, and fully immersed in water.

Simply run the above sketch and take your readings.


Keep in mind that your sensor may be more or less sensitive depending on the type of water you use. As you may know, pure water is not conductive; it is the minerals and impurities in water that make it conductive.

When you run the sketch, you should see readings similar to the ones below:


- when the sensor is dry (0)
- when the sensor is partially immersed in water (~420)
- when the sensor is fully immersed in water (~520)



Status: Dry Test Reading: ~0



Status: Partially immersed Test Reading: ~420



Status: Fully immersed Test Reading: ~520

This test may require some trial and error. Once you have the readings, you can use them as a threshold to trigger an action.

# **Arduino Project – Water Level Indicator**


For our next example, we'll build a simple water level indicator that will light up LEDs based on the level of the water.

## Wiring

We'll reuse the previous example's circuit. We only need to add some LEDs this time.

Connect three LEDs to digital pins #2, #3, and #4 using 220 ohm resistors.

Connect your circuit as shown below:



#### Arduino Code

After constructing the circuit, upload the following sketch to your Arduino.

This sketch defines two variables: lowerThreshold and upperThreshold. These variables represent our thresholds.

If the output falls below the lower threshold, the red LED will light up, if it rises above the upper threshold, the green LED will light up, and if it falls somewhere in the middle, the yellow LED will light up.

```
/* Change these values based on your calibration values */
int lowerThreshold = 420;
int upperThreshold = 520;

// Sensor pins
#define sensorPower 7
#define sensorPin A0

// Value for storing water level
int val = 0;

// Declare pins to which LEDs are connected
int redLED = 2;
int yellowLED = 3;
int greenLED = 4;
```

```
void setup() {
    Serial.begin(9600);
    pinMode(sensorPower, OUTPUT);
    digitalWrite(sensorPower, LOW);

    // Set LED pins as an OUTPUT
    pinMode(redLED, OUTPUT);
    pinMode(yellowLED, OUTPUT);
    pinMode(greenLED, OUTPUT);
```