


Motion Analyzer -- Calibration Checkerboard

Inner corners: 9 x 6 | Square size: 20 mm | Grid: 10 x 7 squares | Board: 200 x 140 mm



How to use -- Motion Analyzer Tab 1 (Calibration):

1. Print at exactly 100% scale -- do NOT use "fit to page."
2. Measure the scale bar (right): it must be exactly 20 mm.
3. Place board flat, square to the camera lens.
4. App settings: Inner Cols = 9, Inner Rows = 6, Square = 20 mm.
5. Click 2 points spanning N squares, enter N, click Calculate.

